

## **FIELD SERVICE REPORT**

FSR NO. 020088974

End User / Officer's Signature Over Printed Name

SOFTWARE HARDWARE	OTHERS	* 1 H 200F
Customer: MDC (304)	Time Arrived: 4:30	PM Date Attended:
Address: Lax Piras Perpetual	Time Started: 4:30	PM Time Ended: 5:30+M
Contact Person :		DIC 2-25-111 2020FF
Unit / Description :	INCIDENT No.:	PLS-20250114-102853
Nature of Call/Problem:	Units/Materials Cor	mplete Details :
TOSH4 CPU has no power		
10 #1 10 0 10 100		
Actions Taken:		
Replaced power adapter of TOSHYCE	/	
Observed and tested		
Status: Glan		
garria.		hu 1
Date of Carcia	Andr	Chen.

SE's Signature Over Printed Name