Quiz

- What does Calibration really accomplish?
 Helps align the true value with the observed value within the process.
- An Observed Variation has two sources: Actual and Measurement

True

- Gage Stability is the drift in the absolute output of a measurement device over time.

 True
- What is <u>not</u> a source of variation?
 Checking for the mean drift is the same as variation
 The operator conducting the measurements
 The measuring device itself
 Other sources such as environmental
- Accuracy is how close the agreement is between the mean of one or more measured results to that of a reference or standard value

True

Quiz

• If you see a tolerance of plus or minus 5 thousandths of an inch in a drawing, what is this referring to?

Accuracy

• Repeatability and Reproducibility are a part of

Operator variability

 Total variability is the sum of the part-to-part variability (or actual variability) and the measurement variability.

True