- 4° a Donot is Not Activated anymore.
To the total and
- Installed in rougible for annealing Started oven @ 1/345
Started oven @ n/345
D 455 by 1415
powered off over @ 2037
1
7/10/22
La Pressing.
- Cut Donut inter 1/4 5 and pressed to 2000 psi
Control of the pressure of the
on Gauge
Set will your waiting 1/2 Mr. To kemove will stay
- Set @ 1700 Waiting 1/2 hv to Remove. W// Stay @ 2000 psi for dovation.

1755; Precised Pellet Looks acceptable
Muss: 1,3466 9
00 = 12.77-12.78 mm t = 5.42 mm