



POD cross-position failure vs PINN generalization

(a) POD center -> Center Q120



(b) POD center -> Ecc. Q120 (blind)



(c) PINN joint -> Ecc. Q120

