Firmware 64

Firmware hacking and breaking

Solution for 'multiple definition of yylloc' error

8 August, 2020 • Banana Pi M4 • devel

When building BPi-M4 BSP, if you are facing the following error,

```
usr/bin/ld: scripts/dtc/dtc-parser.tab.o:
(.bss+0x10): multiple definition of
```

'yylloc'; scripts/dtc/dtc-lexer.lex.o:

(.bss+0x0): first defined here

collect2: error: ld returned 1 exit

status

edit the file ./linux-rtk/scripts/dtc/dtc-lexer-lex.c

Find the line 'YYLTYPE yylloc' and change it to 'extern

YYLTYPE yylloc'

reference: https://lkml.org/lkml/2020/4/1/1206

SEARCH

CATEGORIES

Banana Pi M4 (1)

Consumer

Electronics (1)

Manjaro Linux (1)

Mumble (2)

Windows 10 (1)

1 of 2 6/27/21, 00:55

Solution for 'multiple definition of yylloc' error | Firmware 64 https://fw64.net/solution-for-multiple-definition-of-yylloc-...

Copyright © 2021 fw64.net

2 of 2 6/27/21, 00:55