USB Type-C ENGINEERING CHANGE NOTICE

Title: Debug Accessory Appendix Applied to: USB Type-C Specification Release 1.2, March 25, 2016

Brief description of the functional changes:
Section 4.5.2.2.12.2 incorrectly lists the exit condition from TryWait.SRC to Attached.SRC as waiting for tCCDebounce. This should be corrected to tPDDebounce.
Benefits as a result of the changes:
Corrects text to match state diagram and avoid confusion
An assessment of the impact to the existing revision and systems that currently conform to the USB specification:
No impact
An analysis of the hardware implications:
An analysis of the software implications:
An analysis of the compliance testing implications:

USB Type-C ENGINEERING CHANGE NOTICE

Actual Change

(a). Section 4.5.2.2.12.2

From Text:

4.5.2.2.12.2 Exiting from TryWait.SRC State

The port shall transition to Attached.SRC when VBUS is at vSafe0V and the SRC.Rd state is detected on exactly one of the CC pins for at least tCCDebounce.

The port shall transition to Unattached.SNK after tDRPTry if neither of the CC1 or CC2 pins are in the SRC.Rd state.

To Text:

4.5.2.2.12.2 Exiting from TryWait.SRC State

The port shall transition to Attached.SRC when VBUS is at vSafe0V and the SRC.Rd state is detected on exactly one of the CC pins for at least tCCDebounce tPDDebounce.

The port shall transition to Unattached.SNK after tDRPTry if neither of the CC1 or CC2 pins are in the SRC.Rd state.