# **USB Type-C ENGINEERING CHANGE NOTICE**

**Title: Correction for Attached.SNK** Applied to: USB Type-C Specification Release 1.2 Draft, December, 2015

Brief description of the functional changes:
Figure B-5 incorrectly labels AttachedDeb.SNK as TryDeb.SRC (exit path from TryWaitDeb.SNK). Correcting figure
Benefits as a result of the changes:
Corrects flow to match text and avoid confusion
An assessment of the impact to the existing revision and systems that currently conform to the USB specification:
No impact
An analysis of the hardware implications:
An analysis of the software implications:
An analysis of the compliance testing implications:


### **USB Type-C ENGINEERING CHANGE NOTICE**

## **Actual Change**

#### (a). Figure B-5

#### From Figure:

Figure Error! No text of specified style in document.-1 Connection State Diagram: DTS DRP



## **USB Type-C ENGINEERING CHANGE NOTICE**

### To Figure:

Figure Error! No text of specified style in document.-2 Connection State Diagram: DTS DRP

