2/26/2019 scara_manip

```
% MEC529 Matlab Homework 3 Problem 2 part(i) Codes Created by Yongxin Guo
addpath('/Users/guoyongxin/Desktop/Assignment Academics/Senior Second semester/MEC529/Myfunctions');
close all
clear
clc
% assign configuration constants.
10 = 0.2;
11 = 0.6;
12 = 0.3;
theta1 = pi/4;
theta2 = pi/4;
theta3 = pi/4;
theta4 = 0.1;
theta = [theta1;theta2;theta3;theta4];
% create gst0 matrix.
R0 = eye(3);
P0 = [0;11+12;10];
gst0 = [R0, P0; [0 0 0], 1];
% create axis of motion.
axis1 = [0;0;1];
axis2 = [0;0;1];
axis3 = [0;0;1];
axis4 = [0;0;1];
axis_joints = [axis1,axis2,axis3,axis4];
% create q matrix.
q1 = [0;0;0];
q2 = [0;11;0];
q3 = [0;11+12;0];
q4 = [0;0;0];
q_joints = [q1,q2,q3,q4];
% create matrix for the type of joints
type_joints = ["R";"R";"R";"P"];
% compute gst(theta)
gst theta = manipdkin(gst0, axis joints, q joints, type joints, theta);
disp("The gst(theta) transformation matrix is shown below: ");
disp(gst theta);
```

Published with MATLAB® R2018b

2/26/2019 scara_manip