Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-18T00:00:00Z Currency: USD

Total Project Cost: USD 297.80

Estimate reasoning

Image shows a restroom toilet with broken toilet paper dispenser components in the bowl and on the floor; no visible water intrusion or leaks. Scope focuses on replacing the vandalized dispenser with a high-grade double-roll commercial unit, one hour of accessory installer labor to mount and secure the new unit, and heavy cleaning of the toilet due to debris and sanitation needs. Avoided far fetched plumbing or partition work because no such damage is visible.

ID	Item	Qty	Unit	Unit Price	Tax	Total	Categ
TPD-001	R&R Toilet paper dispenser - double roll - High grade	1	EA	USD 176.39	USD 7.50	USD 183.89	Acce ssori es
LAB-AC C-001	Toilet & Bath Accessories Installer - per hour	1	HR	USD 72.14	USD 0.00	USD 72.14	Labor
CLN-TLT -HEAVY- 001	Clean toilet - Heavy	1	EA	USD 39.41	USD 2.36	USD 41.77	Clea ning

Appendix: Item Details

TPD-001 — R&R; Toilet paper dispenser - double roll - High grade

Replace vandalized double-roll commercial dispenser with high-grade unit; includes materials.

Tags: replace, vandalism

LAB-ACC-001 — Toilet & Bath Accessories Installer - per hour

Labor to mount new dispenser, verify alignment, and secure to wall backing with appropriate anchors.

Tags: replace

CLN-TLT-HEAVY-001 — Clean toilet - Heavy

Heavy cleaning to remove broken plastic fragments and waste from bowl and surrounding area after vandalism.

Tags: fix