Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-22T00:00:00Z Currency: USD

Total Project Cost: USD 703.72

Estimate reasoning

Bathroom shows significant water contamination and staining of sheet vinyl and underlayment near toilet and tub. Area impacted exceeds 40% of the floor; therefore, full flooring system replacement is warranted. Limited drywall flood cut assumed along tub wall due to likely wicking. Detach/reset plumbing fixtures required for continuous flooring installation. Antimicrobial and sealing steps included to ensure sanitary restoration.

| ID | Item | Qty | Unit | Unit Price | Tax | Total | Category |
|-----|--|-----|-------------------|------------|---------------|---|----------|
| 191 | R&R Vinyl floor covering (sheet goods) | 40 | USD 3.50 | USD 0.00 | USD 140.00 | Water (walls, ceilings, floors) | |
| 192 | R&R Underlayment - 1/4" lauan/mahogany plywood | 40 | USD 1.51 | USD 0.00 | USD 60.40 | Water (walls, ceilings, floors) | |
| 198 | Toilet - Detach & reset | 1 | USD 151.0 2 | USD 0.27 | USD 151.29 | Water (walls, ceilings, floors) | |
| 194 | Sink faucet - Detach & reset | 1 | USD 74.20 | USD 0.00 | USD 74.20 | Water (walls, ceilings, floors) | |
| 195 | P-trap assembly - Detach & reset | 1 | USD 47.28 | USD 0.00 | USD 47.28 | Water (walls, ceilings, floors) | |
| 206 | Contents - move out then reset | 1 | USD 50.12 | USD 0.00 | USD 50.12 | Water (walls, ceilings, floors) | |
| 201 | Apply anti-microbial agent to the surface area | 40 | USD 0.20 | USD 0.02 | USD 8.02 | Water (walls, ceilings, floors) | |
| 202 | Seal the surface area w/latex based stain blocker - one coat | 40 | USD 0.54 | USD 0.04 | USD 21.64 | Water (walls, ceilings, floors) | |
| 463 | Tear out wet drywall, cleanup, bag for disposal | 16 | USD 0.87 | USD 0.11 | USD 14.03 | Water mitigation and remediation | |

| ID | Item | Qty | Unit | Unit Price | Tax | Total | Category |
|-----|---|-----|-------------------|------------|---------------|---|----------|
| 200 | R&R 5/8" drywall - hung, taped, floated, ready for paint | 16 | USD 2.34 | USD 0.34 | USD 37.78 | Water (walls, ceilings, floors) | |
| 205 | Texture drywall - light hand texture | 16 | USD 0.48 | USD 0.00 | USD 7.68 | Water (walls, ceilings, floors) | |
| 260 | Seal/prime then paint (2 coats) | 40 | USD 0.58 | USD 0.00 | USD 23.20 | Water (walls, ceilings, floors) | |
| 189 | R&R Baseboard - 2 1/4" | 10 | USD 2.22 | USD 0.00 | USD 22.20 | Water (walls, ceilings, floors) | |
| 190 | Paint baseboard - one coat | 10 | USD 0.57 | USD 0.00 | USD 5.70 | Water (walls, ceilings, floors) | |
| 462 | Haul debris - per pickup truck load - including dump fees | 1 | USD 111.6 0 | USD 0.00 | USD 111.60 | Water mitigation and remediation | |

Appendix: Item Details

191 — R&R; Vinyl floor covering (sheet goods)

Replace water-contaminated vinyl sheet flooring. Bathroom approx. 5' x 8' = 40 SF. Over 40% of floor impacted; full replacement.

Tags: water, flooring, bathroom | Source: file: KB, page: 1

192 — R&R; Underlayment - 1/4" lauan/mahogany plywood

Replace underlayment beneath sheet vinyl due to water damage, same footprint as flooring.

Tags: water, underlayment, bathroom | Source: file: KB, page: 1

198 — Toilet - Detach & reset

Required to access and replace flooring/underlayment beneath toilet footprint.

Tags: plumbing, fixture, reset | Source: file: KB, page: 1

194 — Sink faucet - Detach & reset

Allow for detach/reset of sink faucet if vanity base removal is needed to replace continuous sheet vinyl edges.

Tags: fixture, reset, bathroom | Source: file: KB, page: 1

195 — P-trap assembly - Detach & reset

Detach/reset to facilitate vanity movement if needed for flooring replacement.

Tags: plumbing, reset | Source: file: KB, page: 1

206 — Contents - move out then reset

Move small bathroom items to access flooring; replace after completion.

Tags: contents, mobilization | Source: file: KB, page: 1

201 — Apply anti-microbial agent to the surface area

Apply EPA-registered antimicrobial to subfloor after demo to inhibit microbial growth.

Tags: antimicrobial, mitigation | Source: file: KB, page: 1

202 — Seal the surface area w/latex based stain blocker - one coat

Prime/seal stained subfloor surfaces prior to installing new underlayment.

Tags: primer, sealer | Source: file: KB, page: 1

463 — Tear out wet drywall, cleanup, bag for disposal

Remove up to 2' flood cut along 8 LF of lower wall adjacent to tub/wet area where wicking likely occurred (approx 8 LF x 2' = 16 SF).

Tags: demo, drywall, bathroom | Source: file: KB, page: 1

200 — R&R; 5/8" drywall - hung, taped, floated, ready for paint

Replace removed lower drywall sections at 8 LF x 2' height.

Tags: drywall, repair | Source: file: KB, page: 1

205 — Texture drywall - light hand texture

Feather texture to match surrounding walls.

Tags: texture, finish | Source: file: KB, page: 1

260 — Seal/prime then paint (2 coats)

Prime and paint lower wall areas after drywall patch; includes blend. Quantity covers approx. 10 LF perimeter x 4' average height impacted.

Tags: paint, prime | Source: file: KB, page: 1

189 — R&R; Baseboard - 2 1/4"

Replace wetted baseboard along affected walls, approx. 10 LF.

Tags: trim, baseboard | Source: file: KB, page: 1

190 — Paint baseboard - one coat

Finish new baseboard to match.

Tags: paint, trim | Source: file: KB, page: 1

462 — Haul debris - per pickup truck load - including dump fees

Disposal of removed flooring, underlayment, drywall, and trim.

Tags: debris, disposal | Source: file: KB, page: 1