Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-19T00:00:00Z Currency: USD

Total Project Cost: USD 751.18

Estimate reasoning

Water staining observed at shower threshold indicates moisture intrusion; selected limited demo and rebuild at the wet wall area. Toilet seat broken and base likely compromised by leak; chose replacement of toilet assembly to include new wax seal. Quantities set to small standard bathroom repairs (20 SF wall area).

ID	Item	Qty	Unit	Unit Price	Tax	Total	Category
			USD				
1	R&R Toilet	1	541.5 3	USD 19.65	USD 561.18	Plumbing	
2	Drywall remove (damaged up to 2 ft)	20	USD 2.25	USD 0.00	USD 45.00	Demolition	
3	Drywall install MR 1/2"	20	USD 3.00	USD 0.00	USD 60.00	Drywall	
4	Tape & float L4	20	USD 1.50	USD 0.00	USD 30.00	Drywall	
5	Prime stain-blocker	20	USD 0.60	USD 0.00	USD 12.00	Painting	
6	Paint wall (2 coats)	20	USD 1.40	USD 0.00	USD 28.00	Painting	
7	Antimicrobial treatment	20	USD 0.75	USD 0.00	USD 15.00	Mitigation	

Appendix: Item Details

1 — R&R; Toilet

Replace standard two-piece toilet including wax ring, supply reconnect, and disposal of failed unit. Seat visibly broken in photo; replacement chosen.

Tags: toilet, replace | Source: file: KB-Shared, page: 1

2 — Drywall remove (damaged up to 2 ft)

Selective removal of wet gypsum behind shower curb/adjacent wall up to 24 inches where moisture intrusion observed at shower threshold.

Tags: drywall, remove, water | Source: file: KB-Shared, page: 1

3 — Drywall install MR 1/2"

Install moisture-resistant 1/2 in. drywall to replaced areas.

Tags: drywall, install, MR | Source: file: KB-Shared, page: 1

4 — Tape & float L4

Finish new drywall to Level 4 ready for paint.

Tags: drywall, finish | Source: file: KB-Shared, page: 1

5 — Prime stain-blocker

Apply stain-blocking primer to new drywall.

Tags: primer, stain | Source: file: KB-Shared, page: 1

6 — Paint wall (2 coats)

Two finish coats to affected wall sections; color match to nearest break.

Tags: paint, wall | Source: file: KB-Shared, page: 1

7 — Antimicrobial treatment

Apply antimicrobial to exposed framing/backing after demo.

Tags: antimicrobial, treatment | Source: file: KB-Shared, page: 1