

Low Pressure sensor
High Pressure sensor
My Board
Third wire to bazer
Motor
DC 24V
Transformer
AC 220V