

Slicer Settings Quick Guide

This guide gives starting profiles for common materials on a 0.4 mm nozzle. Fine-tune with temperature towers and retraction tests.

Starting Profiles by Material

Material	Nozzle	Bed	Speed	Fan	Layer h.	Walls	Infill
PLA+	210 C	60 C	100 mm/s	100%	0.20 mm	3	15%
PETG	240 C	80 C	80 mm/s	40%	0.20 mm	3	20%
ABS	250 C	100 C	70 mm/s	0-20%	0.20 mm	4	25%
ASA	255 C	100 C	70 mm/s	20%	0.20 mm	4	25%
TPU 95A	225 C	50 C	30 mm/s	60%	0.20 mm	2	15%

Infill Pattern Selection

Pattern	Strength	Speed	Best for
Grid	Medium	Fast	General prints
Gyroid	High, isotropic	Medium	Functional parts, flexible prints
Cubic	High	Medium	Tall parts
Lightning	Low	Very fast	Decorative, top-surface support only

Supports

Use tree supports for figurines and organic shapes; they use less material and leave fewer marks. Use normal supports for flat overhangs on mechanical parts. Set support Z distance to 0.2 mm for PLA and 0.25 mm for PETG so supports peel off cleanly. Overhangs under 45 degrees usually print without supports.

Layer Height vs. Quality

0.12 mm gives fine detail for miniatures but doubles print time compared to 0.24 mm. 0.20 mm is the best balance for most prints. Layer height should not exceed 75% of nozzle diameter.