
(a) Base after switch-off at 70 µs
(b) Displacement since switch-off
Reference
Jet off
Jet off, dry
On again at 95 µs
Base x (mm)
t (µs)
Base displacement (mm)
Time after switch-off (µs)
Reduced, off at 70 µs
Reduced, off at 165 µs
Crop, off at 50 µs
Reduced, dry
Crop, plug removed