
Zero-pad first to prevent wrap-around
x[n]
zero-pad to N
N-point FFT
X[k]
Pointwise product
X[k]H[k]
IFFT
y[n]
h[n]
zero-pad to N
N-point FFT
H[k]