
Coordinator
Issue point_id
Join READY states
Release acquisition
QC + archive
PC A
Set source / band / optics
Readback + READY
Reference spectrum
PC B
Set T / B / Vg; settle
Readback + READY
Lock-ins + PD
Barrier
Electrical ref.
f_l: master oscillator -> follower REF; select harmonic n
Optical ref.
fchop: chopper controller -> BVPE lock-in REF