
# Анализ моделей машинного обучения для предсказания PassOrFail

## Описание данных:

Количество наблюдений: 1256

0 0.025478

# Распределение классов в датасете




#### Предобработка данных:


- 1. Загрузка и фильтрация данных
- 2. Преобразование целевой переменной
- 3. Анализ типов данных
- 4. Удаление нечисловых колонок
- 5. Удаление колонок с нулевыми значениями
- 6. Удаление колонок с одной уникальной переменной
- 7. Удаление колонок с высокой долей пропущенных значений
- 8. Анализ корреляций
- 9. Удаление коррелирующих признаков
- 10. Обработка пропущенных значений
- 11. Обработка выбросов
- 12. Нормализация признаков

Barrel_Temperature_5 float64 Barrel_Temperature_6 float64 Hopper_Temperature float64 Mold_Temperature_3 float64 Mold_Temperature_4 float64	PART_FACT_SERIAL PassOrFail Injection_Time Filling_Time Plasticizing_Time Cycle_Time Clamp_Close_Time Cushion_Position Switch_Over_Position Plasticizing_Position Max_Injection_Speed Max_Screw_RPM Average_Screw_RPM Average_Screw_RPM Max_Injection_Pressure Max_Switch_Over_Pressure Max_Switch_Over_Pressure Average_Back_Pressure Average_Back_Pressure Barrel_Temperature_1  AHAIMSPINACE Barrel_Temperature_3 Barrel_Temperature_4	int64 int64 float64
Hopper_Temperature float64 Mold_Temperature_3 float64	Barrel_Temperature_5	float64
Mold_Temperature_3 float64	_ · · —	
_ · · _	· · · — ·	
	_ · · · — · · · · · · · · · · · · · · ·	

# Количество пропущенных значений по признакам



## Матрица корреляций



1.00

0.75

- 0.50

- 0.25

0.00


<del>-</del>0.25


-0.50


- -0.75

PART FACT SERIAL	0
PassOrFail	32
<pre>Injection_Time</pre>	0
Filling_Time	0
Plasticizing_Time	22
Cycle_Time	0
Clamp_Close_Time	0
Cushion_Position	0
Switch_Over_Position	0
Plasticizing_Position	0
<pre>Max_Injection_Speed</pre>	0
Max_Screw_RPM	0
Average_Screw_RPM	0
<pre>Max_Injection_Pressure</pre>	0
<pre>Max_Switch_Over_Pressure</pre>	3
Max_Back_Pressure	0
Average_Back_Pressure	0
Barrel_Temperature_1	0
<b>Анализ</b> рвыбросов: Barrel_Temperature_3	0
	169
Barrel_Temperature_4	0
Barrel Temperature 5 Количество выбросов по Barrel Temperature 6	50
Barret_Temperature_6	TIPVISAIGRAM.
<pre>Hopper_Temperature</pre>	0
Mold_Temperature_3	0
Mold_Temperature_4	0

# Boxplot признаков







PART FACT SERIAL Injection Time Filling Time Plasticizing Time Cycle Time Clamp Close Time Cushion Position Switch Over Position Plasticizing Position Max\_Injection\_Speed Итоговый набор признаков: Average\_Screw\_RPM Max Injection Pressure Max Switch Over Pressure Average Back Pressure Barrel Temperature 1 Карпич<u>е</u>терия <u>на</u>жов после предобработки: 25 Barrel Temperature 3 Barrel Temperature 4 Barrel Temperature 5 Оставщиеся признаки: Barrel Temperature 6

Hopper\_Temperature Mold\_Temperature\_3 Mold Temperature 4

#### Использованные модели:

- 1. Logistic Regression
- 2. Random Forest
- 3. Gradient Boosting
- 4. SVM
- 5. KNN
- 6. XGBoost
- 7. LightGBM
- 8. CatBoost
- 9. AdaBoost
- 10. Decision Tree
- 11. Extra Trees
- 12. Bagging

## Методы балансировки классов:

- 1. Original (без балансировки)
- 2. SMOTE
- 3. Random UnderSampling
- 4. SMOTEENN
- 5. ADASYN
- 6. BorderlineSMOTE
- 7. Class Weight

## **ROC-кривые моделей:**

ROC-кривая показывает соотношение между:

- True Positive Rate (TPR)
- False Positive Rate (FPR)

AUC-ROC показывает общую производительность модели

# Результаты моделей:

Лучшая модель: Gradient Boosting

Метод балансировки: UnderSampling

AUC-ROC: 0.843

Precision: 1.000

Recall: 0.532

F1-score: 0.695

#### Важность признаков:

Анализ важности признаков показывает:

- 1. Какие признаки наиболее значимы для предсказания
- 2. Какие признаки можно исключить
- 3. Взаимосвязи между признаками

#### Итоговый пайплайн:

- 1. Предобработка данных
- 2. Нормализация признаков
- 3. Балансировка классов
- 4. Обучение модели
- 5. Предсказание

Спасибо за внимание!