
a Profiles, plane reference
wear depth (mm)
5.0
2.5
0.0
−2.5
−5.0
−400
−200
0
200
400
lateral position (mm, centred)
tread 1
tread 2
tread 3
tread 4
tread 5
b Reference-model sensitivity
central wear depth (mm)
plane
quad
edge
5
0
−5
1
2
3
4
5
tread