HONEYCOMB Technologies (PTY) LTD

Date: 19/2/2024

Page

1

Document No: 136

ATT: The Campus (Princeton)

Deliver to:

Account	Reference No.		Sales Code
B0136			

Code	Description	Quantity	Ur	nit Price		Ne	ett Price
	Callout fee Check faulty gate motor Re-adjust motor and guide roller,	1	R	650.00		R	650.00
	reset gate limits and test Labour	1	R	180.00		R	180.00

If you require any information on this document, feel free to contact me at any time.

Mr.M. Rensburg

Cell: 082 852 4155 Office: (011)672-5235

P.O.BOX 2112 FLORIDA Hills 1716

No. 3. 6th Avenue Florida Lake Gardens

Honey Comb Technologies					
Banking Details:					
First National Bank	Clear Water	251141			
Acc: 63013816400					
Received in good order					
Signed		Date			

Sub Total	R	830.00

Total	R	830.00