

Dragging slowly	Lost Signals	Total Signals	Received Signals	% Received Signals	Average Accuracy	
Test 1	2	23	21	91.30434783	97.54754381	
Test 2	1	61	60	98.36065574		
Test 3	0	90	90	100		
Test 4	4	89	85	95.50561798		
Test 5	3	139	136	97.84172662		
Test 6	5	263	258	98.09885932		
Test 7	0	246	246	100		
Test 8	6	324	316	97.5308642		
Test 9	9	428	419	97.89719626		
Test 10	3	282	279	98.93617021		
Flicking Buttons	Lost Signals	Total Signals	Received Signals	% Received Signals	Average Accuracy	
Test 1	1	12	11	91.66666667	91.10215236	
Test 2	5	184	179	97.2826087		
Test 3	46	269	223	82.89962825		
Test 4	7	117	110	94.01709402		
Test 5	6	118	112	94.91525424		
Test 6	78	477	399	83.64779874		
Test 7	11	231	220	95.23809524		
Test 8	1	96	95	98.95833333		
Test 9	90	657	567	86.30136986		
Test 10	47	338	291	86.09467456		