

i	$a_{\{i-1\}}$	$\alpha_{\{i-1\}}$	d_i	θ_i
1	0	0	0.0600	$q_1 + 1.5834$
2	0.0800	$+\frac{\pi}{2}$	0.0800	$q_2 - 1.5724$
3	0.3500	$-\pi$	0.1000	$q_3 + \pi$
4	0.3000	$+\frac{\pi}{2}$	0.0700	$q_4 - \pi$
5	0	0	0.0200	q_5

$${}^0T_1 = \begin{pmatrix} \cos(q_1+1.5834) & -\sin(q_1+1.5834) & 0 & 0 \\ \sin(q_1+1.5834) & \cos(q_1+1.5834) & 0 & 0 \\ 0 & 0 & 1 & 0.0600 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^1T_2 = \begin{pmatrix} \cos(q_2-1.5724) & 0 & \sin(q_2-1.5724) & 0.0800*\cos(q_2-1.5724) \\ \sin(q_2-1.5724) & 0 & -\cos(q_2-1.5724) & 0.0800*\sin(q_2-1.5724) \\ 0 & 1 & 0 & 0.0800 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^2T_3 = \begin{pmatrix} \cos(q_3+\pi) & \sin(q_3+\pi) & 0 & 0.3500*\cos(q_3+\pi) \\ \sin(q_3+\pi) & -\cos(q_3+\pi) & 0 & 0.3500*\sin(q_3+\pi) \\ 0 & 0 & -1 & 0.1000 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^3T_4 = \begin{pmatrix} \cos(q_4-\pi) & 0 & \sin(q_4-\pi) & 0.3000*\cos(q_4-\pi) \\ \sin(q_4-\pi) & 0 & -\cos(q_4-\pi) & 0.3000*\sin(q_4-\pi) \\ 0 & 1 & 0 & 0.0700 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^4T_5 = \begin{pmatrix} \cos(q_5) & -\sin(q_5) & 0 & 0 \\ \sin(q_5) & \cos(q_5) & 0 & 0 \\ 0 & 0 & 1 & 0.0200 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^0T_5 = \{\}^0T_1 * \{\}^1T_2 * \{\}^2T_3 * \{\}^3T_4 * \{\}^4T_5$$