

NATIONAL DISASTER INTELLIGENCE AGENCY

SITUATIONAL ASSESSMENT: EXECUTIVE


Report ID:	DIR-2026-0917-mumbai-A20AB	Generated:	2026-09-17 10:47
Target Zone:	Mumbai Mithi Coastal Lowland	Audit Window:	7D

1. EXECUTIVE SUMMARY

This Official Intelligence Report provides a comprehensive multi-hazard assessment for Mumbai Mithi Coastal Lowland. The area is currently exhibiting a MODERATE threat level concerning LANDSLIDE. Conditions should be monitored continuously, but do not warrant immediate emergency escalation at this time. All data presented herein is derived from the Virtual Sensor Fusion Engine, integrating real-time meteorological, seismic, and hydrological telemetry.

2. QUANTITATIVE RISK ASSESSMENT

The following table and chart outline the deterministic severity scores computed by the multi-hazard risk fusion engine based on live telemetry.



Hazard Vector	Score	Level	Primary Drivers (Explainability)
LANDSLIDE	35	MODERATE	- Saturated soil conditions detected - Steep slope vulnerability (38°)
FLOOD	15	LOW	River level normal

EARTHQUAKE	30	MODERATE	• Moderate seismic hazard zone • No recent major events
CYCLONE	10	LOW	• No active cyclone track nearby
VOLCANO	5	LOW	• No active volcano in proximity

2.1 ROOT CAUSE ANALYSIS & DRIVER EXPLANATION

LANDSLIDE CAUSAL FACTORS:

- **Saturated soil conditions detected:** Geotechnical vulnerability detected: Saturated soil conditions detected. Extreme soil saturation compromises the underlying friction angle of the slope. The resulting hydrostatic pressure acts as a primary destabilizing force.
- **Steep slope vulnerability (38°):** Topographical vulnerability: Steep slope vulnerability (38°). The inherent steepness of this region naturally predisposes it to gravitational shear failure when subjected to external kinematic or hydrological triggers.

EARTHQUAKE CAUSAL FACTORS:

- **Moderate seismic hazard zone:** Tectonic instability: Moderate seismic hazard zone. Subsurface lithospheric stress concentrations are presenting anomalous readings, increasing the probabilistic likelihood of a sudden energy release along local fault lines.
- **No recent major events:** The telemetry indicates no recent major events. This structural anomaly significantly alters the stability threshold of the surrounding topography. When combined with current meteorological load, it exponentially accelerates the likelihood of a hazard event.

3. VIRTUAL SENSOR TELEMETRY

Raw meteorological and geospatial telemetry utilized during the generation of this report.

No telemetry recorded.

4. TACTICAL RESPONSE DIRECTIVES

Standard Operating Procedures (SOPs) dynamically prescribed based on the current hazard evaluation.

IMMEDIATE RESPONSE ACTIONS:

- Continue routine monitoring

SHORT TERM RESPONSE ACTIONS:

- Review readiness protocols