Work order P-2022-0158

The control panel at site Grumoren was tested according to procedure PO-55012 and meets the requirements.