Inspection report for compressor unit seven

The valve was replaced and tested on site

Second page of the report

Work order P-2021-0042 was closed