Scanner & Printer





Quick Barcodes

Technical Support

Test label

Zebra Technologies – Print Test



Print Configuration

~WC




Reset Printer

! U1 do "device.reset" ""



Scan and Print

Printing over Bluetooth to a Zebra printer, this file requires the "WORKING-scanandprint.scncfg" which creates ADF rules with ZPL variables (1.ZPL with the ^FN1 should be previously loaded to the printer). This Datamatrix deletes all previous ADF rules and applies new ones below. Set the printer to master mode and pair through the MAC ADDRESS.





Bluetooth Serial Port Profile (Master)



C464E3E3FE5E (Bluetooth Address of the remote device)

Begin New Rule 1. Send ASCII Key <^>

2.	Send	ASCII	Key	<x></x>
----	------	-------	-----	---------

9. Send Numeric Keypad <1>

11. Send ASCII Key <Z>

16. Send ASCII Key <s>

20. Send Numeric Keypad <1>

21. Send Numeric Keypad <1>

22. Send ASCII Key <^>

24. Send ASCII Key <d>

25. Send All that remains

26. Send ASCII Key <^>

27. Send ASCII Key <f>

28. Send ASCII Key <s>

29. Send ASCII Key <^>

30. Send ASCII Key <x>

31. Send ASCII Key <z>

Save Rule