

Yes, we know that the polarity is flipped going in to the VR interface chips. While originally on accident, it's no big deal since they invert anyway: When VR+ transitions to a higher voltage than VR-, VR_OUT will output a rising edge. See issue https://github.com/mck1117/proteus/issues/57 for more detail R25 R27 R34 MAX9924 VR1+D-4.7k COUT -DVR1_OUT +5٧ VR1-D 4.7k ZERO_EN +5٧ BIAS K GND U10 C25 +5٧ C24 1u Optional setting in Mode C for no adaptive threshold timeout — See MAX9924 Datasheet Components as specified put chip in mode A1. Flip jumper and install R1219+R2020 for mode C. FutureProofPerformance.com Sheet: /VR Conditioner/ File: VR Conditioner.kicad_sch Title: Polygonus Universal 88p Size: A4 Date: 2023-11-12 Rev: v1.0 KiCad E.D.A. 9.0.3 ld: 4/10















