

Assembly Manual

CSAimBot Electronics

Enclosure




Table of Contents:

- 1. Base Module - Right Side 3
- 2. Base Module - Center 6
- 3. Base Module - Left Side7
- 4. Base Modules Assembly..... 9
- 5. Electronics Installation11
- 6. Front Panel Assembly - Left Side 13
- 7. Front Panel Assembly - Right Side..... 15
- 8. Top Panel Assembly - Left Side..... 17
- 9. Top Panel Assembly - Right Side 18
- 10. Parts List 19



IMPORTANT: BEFORE STARTING ASSEMBLY
Before proceeding with the mechanical assembly of the modules and closing the enclosure, ensure that all wires have been routed through the appropriate mounting holes and connected strictly according to the wiring diagram.

Symbols used in the manual:



Apply glue (e.g., cyanoacrylate)




Melt-in

1. Base Module - Right Side


Required components:

- Base Body - Right x1
- Side Logo x1
- M3×5mm Threaded Insert x11


1



2



3




2. Base Module - Center


Required components:

- Base Body - Center x1
- M3×5mm Threaded Insert x5

1



2




3. Base Module - Left Side


Required components:


- Base Body - Left x1
- M3×5mm Threaded Insert x7

1



2






4. Base Modules Assembly


Required components:

- Assembled Module from Step 1 ×1
 - Assembled Module from Step 2 ×1
 - Assembled Module from Step 3 ×1
 - M3×12 mm Screw x3
 - M3×6 mm Screw x1
-

1



2




5. Electronics Installation



Required components:

- Power Supply x1
 - DSM51 Driver x3
 - ESP32 Module with Expansion Board x1
 - Prototyping PCB x1
 - Relay Module x1
 - XL4015 Step-down Converter x1
 - LM2596 Step-down Converter x1
- PCB Cover x1
 - ESP32 Cover x1
 - Relay Cover x1
 - Converters Cover x1
 - M5×10 mm Screw x6
 - M5 Hex Nut x6
 - M3×6 mm Screw x8


1




2




3




4




5



6







6. Front Panel Assembly - Left Side

Required components:

- Front Panel - Left x1
- M3×5mm Threaded Insert x1
- M3×6 mm Screw x4




7. Front Panel Assembly - Right Side


Required components:

- Front Panel - Right x1
- M3×5mm Threaded Insert x1
- M3×6 mm Screw x4

1



2




8. Top Panel Assembly -Left Side

Required components:

- Top Panel - Left x1
- Top Logo x1
- M3×6 mm Screw x4

1




9. Top Panel Assembly - Right Side

Required components:

- Top Panel - Right x1
- M3×6 mm Screw x4


1



10. Parts List:


Fasteners:

M3×6 mm Screw




25x

M3×12 mm Screw




3x

M5×10 mm Screw



6x

M5 Hex Nut



6x


M3×5mm Threaded Insert



25x


Electronics:

DSM51 Driver




3x

ESP32 Module with Expansion Board




1x

Prototyping PCB




1x

Power Supply




1x

Relay Module




1x

XL4015 Step-down Converter



1x


LM2596 Step-down Converter



1x


Structural Parts:

Base Body - Right




1x

Base Body - Center




1x

Base Body - Left




1x

Front Panel - Left




1x

Front Panel - Right




1x

Top Panel - Left




1x

Top Panel - Right




1x

Side Logo




1x

Top Logo




1x

ESP32 Cover




1x

Relay Cover




1x

Converters Cover



1x

PCB Cover



1x