



Annual Inspection Report

1400 Alderpath Ave. Torrance, CA 90503

May 2026

UNITS

28

ACTION REQ'D

19

NO ACTION

5

NOT INSPECTED

4

WORK ORDERS

19

INSPECTOR

Marisol Vega

CERTIFICATION #

10241

MANAGER

Dana Whitfield

REGIONAL PROPERTY SUPERVISOR

Elena Marsh

PERIOD

May 2026

REPORT DATE

May 15, 2026

Property Inspection Summary

1400 Alderpath Ave. Torrance, CA 90503 | Inspector: Marisol Vega | May 2026

UNITS 28	ACTION REQUIRED 19	NO ACTION 5	NOT INSPECTED 4	WORK ORDERS 19
--------------------	------------------------------	-----------------------	---------------------------	--------------------------

Most common issues


Count of findings by category

Smoke / CO Alarms		7
Flooring		7
HVAC		6
Kitchen		5
Paint & Walls		4
Front Door		3
Appliances		3

Unit status

19 of 28

units require action



Immediate attention priorities



Priority categories from this inspection, most serious first

- Smoke / CO Alarms need attention**
Unit 03, 05, 14, 16, 23, 27 +1 more
- HVAC needs attention**
Unit 21
- Paint & Walls need attention**
Unit 16, 22

Unit 01

Inspected May 11, 2026 · Marisol Vega



Inspection photos (2)



Unit 02

Inspected May 12, 2026 · Daniel Okonkwo

Inspection photos (2)




Unit 03

Inspected May 13, 2026 • WO #412602 • Priya Raman


● Front Door REPAIR

The unit number is missing from the front door.



● Smoke / CO Alarms REPLACE

The carbon monoxide alarm is chirping on a low battery.




Unit 05

Inspected May 15, 2026 · WO #412604 · Marisol Vega


● Smoke / CO Alarms REPLACE

Smoke detectors are missing from the hallway.



● Kitchen REPAIR

Several kitchen cabinet hinges are loose.






Unit 06

Inspected May 11, 2026 · WO #412605 · Daniel Okonkwo

● Flooring REPAIR

The carpet tack strip is missing screws.



Unit 07

Inspected May 12, 2026 • WO #412606 • Priya Raman



● Kitchen REPAIR

A kitchen drawer is damaged.



● Paint & Walls REPAIR

The drywall in the dining room, behind the kitchen wall, is damaged.



● HVAC REPAIR

The control knob on the living room wall heater is broken.




Unit 08

Inspected May 13, 2026 • WO #412607 • Tomas Herrera



● Kitchen REPAIR

Several kitchen cabinet hinges are loose.



● Flooring REPAIR

The hallway floor is damaged.



Unit 09

Inspected May 14, 2026 · WO #412608 · Marisol Vega

● Flooring REPAIR

Floor planks are lifting in the living room.




Unit 10

Inspected May 15, 2026 • WO #412609 • Daniel Okonkwo

● Appliances REPAIR

The burners on the right side of the stove do not turn on.




● Kitchen REPAIR

The painted finish on the kitchen countertop is peeling.



● HVAC REPAIR



The control knob on the living room wall heater is broken.



Unit 11

Inspected May 11, 2026 · Priya Raman

Inspection photos (2)




Unit 13

Inspected May 13, 2026 · WO #412612 · Marisol Vega


● Flooring REPAIR

Floor planks are lifting in the living room.



● HVAC REPAIR

The control knob on the living room wall heater is broken.



Unit 14

Inspected May 14, 2026 • WO #412613 • Daniel Okonkwo


● Smoke / CO Alarms REPLACE

The carbon monoxide alarm is chirping on a low battery.




● Kitchen REPAIR

A kitchen drawer is damaged.



● Flooring REPAIR

Floor planks are lifting in the living room.




Unit 15

Inspected May 15, 2026 · WO #412614 · Priya Raman

● Front Door REPAIR

The unit number is missing from the front door.




Unit 16

Inspected May 11, 2026 · WO #412615 · Tomas Herrera


● Smoke / CO Alarms REPLACE

The carbon monoxide alarm is chirping on a low battery.



● Paint & Walls REPAIR

The dining room ceiling fan is broken and is not secured to its mount.





Unit 17

Inspected May 12, 2026 • WO #412616 • Marisol Vega




● Appliances REPAIR

The refrigerator door seal is torn.



● Windows REPAIR


The bedroom window does not stay open on its own.



Unit 18

Inspected May 13, 2026 · Daniel Okonkwo

Inspection photos (2)






Unit 19

Inspected May 14, 2026 · WO #412618 · Priya Raman

● Appliances REPAIR

The burners on the right side of the stove do not turn on.




Unit 21

Inspected May 11, 2026 · WO #412620 · Marisol Vega


● Front Door REPAIR

The unit number is missing from the front door.



● Plumbing REPAIR

The garbage disposal does not run, and the bathtub and bathroom sink are missing drain strainers.



● Paint & Walls REPAIR

There is a water stain on the ceiling outside the bathroom.




● Flooring REPAIR

The carpet tack strip is missing screws.



● HVAC REPAIR

The water heater closet is blocked by stored boxes.




Unit 22

Inspected May 12, 2026 • WO #412621 • Daniel Okonkwo


● Plumbing REPAIR

The tub spout in the hallway bathroom is missing caulk where it meets the wall.




● Windows REPAIR

The kitchen window screen is damaged.




● Paint & Walls REPAIR

The dining room ceiling fan is broken and is not secured to its mount.




● Flooring REPAIR

The carpet tack strip is missing screws.



● HVAC REPAIR

The control knob on the living room wall heater is broken.




Unit 23

Inspected May 13, 2026 · WO #412622 · Priya Raman

● Smoke / CO Alarms REPLACE



Smoke detectors are missing throughout the unit.



Unit 24

Inspected May 14, 2026 · Tomas Herrera

Inspection photos (2)




Unit 25

Inspected May 15, 2026 · WO #412624 · Marisol Vega

● Plumbing REPAIR

The bathroom sink drains slowly.



Unit 27

Inspected May 12, 2026 · WO #412626 · Priya Raman


● Smoke / CO Alarms REPLACE

Smoke detectors are missing from the hallway.



● HVAC REPAIR

The control knob on the living room wall heater is broken.




Unit 28

Inspected May 13, 2026 · WO #412627 · Tomas Herrera

● Smoke / CO Alarms REPLACE

The carbon monoxide alarm is chirping on a low battery.



Repairs Needed

Every flagged item, sorted by priority — highest first.

PRIORITY	UNIT	ITEM	ACTION	DETAIL
High	03	Smoke / CO Alarms	Replace	The carbon monoxide alarm is chirping on a low battery.
High	05	Smoke / CO Alarms	Replace	Smoke detectors are missing from the hallway.
High	14	Smoke / CO Alarms	Replace	The carbon monoxide alarm is chirping on a low battery.
High	16	Smoke / CO Alarms	Replace	The carbon monoxide alarm is chirping on a low battery.
High	16	Paint & Walls	Repair	The dining room ceiling fan is broken and is not secured to its mount.
High	21	HVAC	Repair	The water heater closet is blocked by stored boxes.
High	22	Paint & Walls	Repair	The dining room ceiling fan is broken and is not secured to its mount.
High	23	Smoke / CO Alarms	Replace	Smoke detectors are missing throughout the unit.
High	27	Smoke / CO Alarms	Replace	Smoke detectors are missing from the hallway.
High	28	Smoke / CO Alarms	Replace	The carbon monoxide alarm is chirping on a low battery.
Medium	07	Paint & Walls	Repair	The drywall in the dining room, behind the kitchen wall, is damaged.
Medium	07	HVAC	Repair	The control knob on the living room wall heater is broken.
Medium	08	Flooring	Repair	The hallway floor is damaged.
Medium	09	Flooring	Repair	Floor planks are lifting in the living room.
Medium	10	Appliances	Repair	The burners on the right side of the stove do not turn on.
Medium	10	HVAC	Repair	The control knob on the living room wall heater is broken.

PRIORITY	UNIT	ITEM	ACTION	DETAIL
Medium	13	Flooring	Repair	Floor planks are lifting in the living room.
Medium	13	HVAC	Repair	The control knob on the living room wall heater is broken.
Medium	14	Flooring	Repair	Floor planks are lifting in the living room.
Medium	17	Appliances	Repair	The refrigerator door seal is torn.
Medium	17	Windows	Repair	The bedroom window does not stay open on its own.
Medium	19	Appliances	Repair	The burners on the right side of the stove do not turn on.
Medium	21	Plumbing	Repair	The garbage disposal does not run, and the bathtub and bathroom sink are missing drain strainers.
Medium	21	Paint & Walls	Repair	There is a water stain on the ceiling outside the bathroom.
Medium	22	Plumbing	Repair	The tub spout in the hallway bathroom is missing caulk where it meets the wall.
Medium	22	HVAC	Repair	The control knob on the living room wall heater is broken.
Medium	27	HVAC	Repair	The control knob on the living room wall heater is broken.
Low	03	Front Door	Repair	The unit number is missing from the front door.
Low	05	Kitchen	Repair	Several kitchen cabinet hinges are loose.
Low	06	Flooring	Repair	The carpet tack strip is missing screws.
Low	07	Kitchen	Repair	A kitchen drawer is damaged.
Low	08	Kitchen	Repair	Several kitchen cabinet hinges are loose.
Low	10	Kitchen	Repair	The painted finish on the kitchen countertop is peeling.
Low	14	Kitchen	Repair	A kitchen drawer is damaged.
Low	15	Front Door	Repair	The unit number is missing from the front door.
Low	21	Front Door	Repair	The unit number is missing from the front door.
Low	21	Flooring	Repair	The carpet tack strip is missing screws.
Low	22	Windows	Repair	The kitchen window screen is damaged.
Low	22	Flooring	Repair	The carpet tack strip is missing screws.

PRIORITY	UNIT	ITEM	ACTION	DETAIL
Low	25	Plumbing	Repair	The bathroom sink drains slowly.

Units Not Inspected

The following units could not be inspected during this visit. Fernwater will schedule a follow-up where access becomes available.

Unit 04 — Cancel - Unable to inspect

Unit 12 — Cancel - Unable to inspect

Unit 20 — Cancel - Unable to inspect

Unit 26 — Cancel - Unable to inspect

FERNWATER RESIDENTIAL — PROPERTY INSPECTION DISCLAIMER

Our inspections are visual assessments intended to identify general maintenance needs and are not a substitute for evaluations by licensed specialists. As the property owner, you are solely responsible for ensuring your property is safe, well-maintained, and compliant with all applicable laws and codes. Fernwater Residential is not liable for conditions that were not visible at the time of inspection or for any damages arising from unaddressed maintenance items. Any issues identified in our reports should be addressed promptly to protect both your tenants and your investment. We appreciate your trust in Fernwater Residential and are committed to keeping your property in great shape.

Inspector Certification

Proof of certification for inspectors who contributed to this report.

INSPECTOR

Marisol Vega

CERTIFICATION #

10241

CERTIFICATE OF COMPLETION

Residential Maintenance Inspection

Awarded to

Marisol Vega

Certification No. 10241

Issued March 2026 Valid through March 2029

SAMPLE - SYNTHETIC DATA

Not a real certification. Generated for demonstration only.

CERTIFICATE OF COMPLETION

Residential Maintenance Inspection

Awarded to

Daniel Okonkwo

Certification No. 10255

Issued March 2026 Valid through March 2029

SAMPLE - SYNTHETIC DATA

Not a real certification. Generated for demonstration only.

CERTIFICATE OF COMPLETION

Residential Maintenance Inspection

Awarded to

Priya Raman

Certification No. 10268

Issued March 2026 Valid through March 2029

SAMPLE - SYNTHETIC DATA

Not a real certification. Generated for demonstration only.

CERTIFICATE OF COMPLETION

Residential Maintenance Inspection

Awarded to

Tomas Herrera

Certification No. 10273

Issued March 2026 Valid through March 2029

SAMPLE - SYNTHETIC DATA

Not a real certification. Generated for demonstration only.