







3V3 Buck/Boost




UART to USB




SWD Debug Connector






Feather Pinout



Reset Push-Button




User LED

Decoupling




place C7 near to pin 1 (VCL) of RAOE1 place C9 near to pin 7 (VCC) of RAOE1

Zalmotek Sheet: / File: RAO.kicad sch Title: RAOE1 Feather SoM



Buck/Boost 3v3



Zalmotek


Sheet: /power/ File: power.kicad_sch

Title: RAOE1 Feather SoM

 Size: A4
 Date: 2025-04-11
 Rev: 1.0

 KiCad E.D.A. 8.0.9
 Id: 3/4

LiPo Charging





Za	lmot	ek
0 :		

Sheet: /lipo_charging/ File: lipo_ch.kicad_sch

Title: RAOE1 Feather SoM

 Size: A4
 Date: 2025-04-11
 Rev: 1.0

 KiCad E.D.A. 8.0.9
 Id: 4/4