

Pracownia systemów i urządzeń sieciowych

Temat: Konfiguracja VLAN



Imię i Nazwisko

klasa/grupa/ rok szk.

Amelia Kawik
Tymoteusz Wilczyński
Krzesław Wolański
Ksawery Zelek
Marcin Madanowicz
Adrian Starostka

3 TI 2/4/4/4 2022.r


Konfiguracja switcha p1

The screenshot shows the TP-Link web management interface for a TL-SG105E switch. The left sidebar contains navigation links: System, Switching, Monitoring, VLAN, QoS, Save Config, and Logout. The main content area displays the 'System Info' section with a table of device details:


System Info	
Device Description	TL-SG105E
MAC Address	80:4E:26:F8:D6:44
IP Address	192.168.0.20
Subnet Mask	255.255.255.0
Default Gateway	0.0.0.0
Firmware Version	1.0.0 Build 20160715 Rel.38805
Hardware Version	TL-SG105E 3.0

Below the table, there is a 'Note' section stating: 'The length of device description should not be more than 32 characters.' At the bottom of the interface, the copyright information for TP-LINK Technologies Co., Ltd. is visible.


konfiguracja switcha p2




Konfiguracja kart sieciowych



Konfiguracja router i rezerwacja adresów



Pingowanie urządzeń



Vlan 20 i 10

The screenshot shows the TP-Link T1600G-28TS web interface. The left sidebar contains a menu with options: System, Switching, VLAN, 802.1Q VLAN, MAC VLAN, Protocol VLAN, Spanning Tree, Multicast, Routing, QoS, ACL, Network Security, SNMP, LLDP, Maintenance, Save Config, Index, and Logout. The main content area is titled 'VLAN Config' and 'Port Config'. It displays a 'Vlan Table' with the following data:

Select	VLAN_ID	Name	Members	Operation
☐	1	System-VLAN	1/0/1-28	Edit Detail
☐	10	VLAN10	1/0/1,10/4	Edit Detail
☐	20	VLAN20	1/0/4-5	Edit Detail

Below the table are buttons: All, Create, Delete, and Help. A status bar at the bottom indicates 'Total VLAN: 3'. The bottom of the page shows a copyright notice: 'Copyright © 2016 TP-LINK Technologies Co., Ltd. All rights reserved.'

Vlan 20 i 10

The screenshot shows the TP-Link TL-SG105E web interface. The left sidebar contains a menu with options: System, Switching, Monitoring, VLAN, MTU VLAN, Port Based VLAN, 802.1Q VLAN, 802.1Q PVID Setting, QoS, Save Config, and Logout. The main content area is titled '802.1Q VLAN Configuration'. It shows a configuration page for '802.1Q VLAN Configuration' with 'Enable' selected. Below this is a table for port configuration:

VLAN ID	Port	Untagged	Tagged	Not Member
1	Port 1	☐	☐	☒
10	Port 2	☐	☐	☒
20	Port 3	☐	☐	☒
	Port 4	☐	☐	☒
	Port 5	☐	☐	☒

Below the table are buttons: Add/Modify, Help, Select All, and Delete. The bottom of the page shows a copyright notice: 'Copyright © 2016 TP-LINK Technologies Co., Ltd. All rights reserved.'

Pingi po VLAN'ach

```
Administrator: Wiersz polecenia

ping statistics for 192.168.0.18:
    Packets: Sent = 2, Received = 2, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 0ms, Maximum = 0ms, Average = 0ms
Control-C
^C
C:\WINDOWS\system32>ping 192.168.0.20

Pinging 192.168.0.20 with 32 bytes of data:
Reply from 192.168.0.20: bytes=32 time=1ms TTL=64
Reply from 192.168.0.20: bytes=32 time=1ms TTL=64

Ping statistics for 192.168.0.20:
    Packets: Sent = 2, Received = 2, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 1ms, Maximum = 1ms, Average = 1ms
Control-C
^C
C:\WINDOWS\system32>ping 192.168.0.30

Pinging 192.168.0.30 with 32 bytes of data:
Reply from 192.168.0.30: bytes=32 time=1ms TTL=64
Reply from 192.168.0.30: bytes=32 time=1ms TTL=64

Ping statistics for 192.168.0.30:
    Packets: Sent = 2, Received = 2, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 1ms, Maximum = 1ms, Average = 1ms
Control-C
^C
C:\WINDOWS\system32>ping 192.168.0.40

Pinging 192.168.0.40 with 32 bytes of data:
Reply from 192.168.0.170: Destination host unreachable.

Ping statistics for 192.168.0.40:
    Packets: Sent = 1, Received = 1, Lost = 0 (0% loss),
Control-C
^C
C:\WINDOWS\system32>ping 192.168.0.60

Pinging 192.168.0.60 with 32 bytes of data:
Reply from 192.168.0.170: Destination host unreachable.

Ping statistics for 192.168.0.60:
    Packets: Sent = 1, Received = 1, Lost = 0 (0% loss),
Control-C
^C
C:\WINDOWS\system32>ping 192.168.0.70

Pinging 192.168.0.70 with 32 bytes of data:
Reply from 192.168.0.70: bytes=32 time<1ms TTL=64
Reply from 192.168.0.70: bytes=32 time<1ms TTL=64
Reply from 192.168.0.70: bytes=32 time<1ms TTL=64

Ping statistics for 192.168.0.70:
    Packets: Sent = 3, Received = 3, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 0ms, Maximum = 0ms, Average = 0ms
Control-C
^C
C:\WINDOWS\system32>
```