

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarization imaging

MsCV - Module 5 - Sensors & Digitization

Olivier Morel

Laboratory Le2i - UMR CNRS 6306

October 2, 2012

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

Problem statement

As human eye, the conventional cameras are only sensitive to:

- intensity
- hue (wavelength)

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

Problem statement

As human eye, the conventional cameras are only sensitive to:

- intensity
- hue (wavelength)

Solution

Reveal the polarization effects with:

- linear polarizer
- birefringent crystal

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

linear polarizer

- Effect of a polarizer on reflected light:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

linear polarizer

- Effect of a polarizer on reflected light:



- Effects of a polarizing filter on the sky:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Preamble

Birefringent crystal

Definition

Birefringence, or double refraction, is the decomposition of a ray of light into two rays when it passes through certain anisotropic materials, such as crystals of calcite or boron nitride.



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Preamble

Birefringent crystal

Definition

Birefringence, or double refraction, is the decomposition of a ray of light into two rays when it passes through certain anisotropic materials, such as crystals of calcite or boron nitride.



- Birefringent Iceland spar = Viking sun-stone ?
 - Instead of using the polarization skylight, they used the Iceland spar as a depolarizer
 - [Ropars et al., 2011]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

Human eye can see Polarization !

Haidinger's brush (1844)

- entoptic phenomenon
- macula's dichroism
- birefringence of the cone's outer layer

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Preamble

Human eye can see Polarization !

Haidinger's brush (1844)

- entoptic phenomenon
- macula's dichroism
- birefringence of the cone's outer layer



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1 How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2 Some applications

- Unpolarized lightning
- Polarized lightning

3 Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4 Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarization contrast measurement

Applications

In many applications of polarization imaging, especially when polarized lighting is used, the polarization contrast measurement is generally sufficient.

Goal

Take 2 different images of an object or a scene with 2 orthogonal views of the polarizer: I_{\parallel} and I_{\perp} .

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarization contrast measurement

Applications

In many applications of polarization imaging, especially when polarized lighting is used, the polarization contrast measurement is generally sufficient.

Goal

Take 2 different images of an object or a scene with 2 orthogonal views of the polarizer: I_{\parallel} and I_{\perp} .

- The following parameters can be measured:
 - Total light Intensity: $I_{\parallel} + I_{\perp}$
 - Polarization contrast: $I_{\parallel} - I_{\perp}$
 - Polarization contrast ratio: $\frac{I_{\parallel} - I_{\perp}}{I_{\parallel} + I_{\perp}}$
- [Kalayjian et al., 1996, Kalayjian et al., 1997] developed a 1D polarization contrast retina

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1 How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2 Some applications

- Unpolarized lightning
- Polarized lightning

3 Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4 Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype



Catadioptric calibration

Conclusion

Bibliography

Simplified polarization imaging

- In nature, the light is generally not polarized or at least partially linearly polarized:
 - Polarization by reflection
 - Polarization by scattering



How to measure polarization?
? Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Simplified polarization imaging

- In nature, the light is generally not polarized or at least partially linearly polarized:
 - Polarization by reflection
 - Polarization by scattering



- In this case, three parameters must be estimated:

$$\mathbf{s} = \begin{pmatrix} s_0 \\ s_1 \\ s_2 \\ 0 \end{pmatrix} = \begin{pmatrix} I \\ I\rho \cos 2\varphi \\ I\rho \sin 2\varphi \\ 0 \end{pmatrix}$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Description of the parameters

(for a partially linearly polarized light)

Total light intensity I

$$I = s_0$$

Degree of polarization ρ

$$\rho = \frac{\sqrt{s_1^2 + s_2^2}}{s_0}$$

Angle of polarization φ

$$\varphi = \frac{1}{2} \arg(s_1 + is_2),$$

with $i^2 = -1$.

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

How to measure a part. lin. pol. light ?

Principle

In the case of a part. lin. pol. light a simple rotating polarizer in front of the sensor is sufficient.



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

How to measure a part. lin. pol. light ?

Principle

In the case of a part. lin. pol. light a simple rotating polarizer in front of the sensor is sufficient.



Purpose

For every pixels try to estimate the sinusoid that gives the polarization parameters.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Wolff and Andreou, 1995]

Initial idea

A sinusoid is determined by 3 points \Rightarrow 3 images are required to estimate the polarization parameters.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Wolff and Andreou, 1995]

Initial idea

A sinusoid is determined by 3 points \Rightarrow 3 images are required to estimate the polarization parameters.

- [Wolff and Andreou, 1995] suggest taking 3 images corresponding to polarizer orientations of 0° , 45° and 90° :

$$\bullet \quad I = I_0 + I_{90}$$

$$\bullet \quad \rho = \frac{I_{90} - I_0}{(I_{90} + I_0) \cos 2\varphi}$$

$$\bullet \quad \varphi = \frac{1}{2} \arctan \left(\frac{I_0 + I_{90} - 2I_{45}}{I_{90} - I_0} \right) + 90^\circ$$

if $(I_{90} < I_0)$ [if $(I_{45} < I_0)$ $\varphi = \varphi + 90^\circ$ else $\varphi = \varphi - 90^\circ$]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Wolff and Andreou, 1995]

Initial idea

A sinusoid is determined by 3 points \Rightarrow 3 images are required to estimate the polarization parameters.

- [Wolff and Andreou, 1995] suggest taking 3 images corresponding to polarizer orientations of 0° , 45° and 90° :
 - $I = I_0 + I_{90}$
 - $\rho = \frac{I_{90} - I_0}{(I_{90} + I_0) \cos 2\varphi}$
 - $\varphi = \frac{1}{2} \arctan \left(\frac{I_0 + I_{90} - 2I_{45}}{I_{90} - I_0} \right) + 90^\circ$
if $(I_{90} < I_0)$ [if $(I_{45} < I_0)$ $\varphi = \varphi + 90^\circ$ else $\varphi = \varphi - 90^\circ$]
- The proposed configuration leads to a set-up with 2 Twisted Nematic Liquid Crystal [Wolff et al., 1997]

Best configuration

[Tyo, 1998] proved that for a three-channel PVS (Polarization-sensitive Vision/imaging System) the optimum is obtained for a configuration: -60° , 0° and 60°

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype



Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Wolff and Andreou, 1995]



- When an ac voltage is applied across the liquid crystal faces, the helices straighten out so that the plane of linear polarized light is not rotated in this state
- The switching or “relaxation” time of TN liquid crystals is on the order of 1/30 sec.

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


How to measure a part. lin. pol. light ?

Stereo polarization camera

Main idea

A quite significant speed-up in generating polarization images can be achieved by parallelizing the sensing of polarization components using 2 or more cameras.

● Polarizing beamsplitter:



How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Cataadioptric calibration

Conclusion

Bibliography


How to measure a part. lin. pol. light ?

Stereo polarization camera

Main idea

A quite significant speed-up in generating polarization images can be achieved by parallelizing the sensing of polarization components using 2 or more cameras.

● Polarizing beamsplitter:



- 7.5 images per second [Wolff and Andreou, 1995]
- automatic calibration process developed by [Terrier and Devlaminck, 2001]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Saito et al., 1999]



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to measure a part. lin. pol. light ?

[Saito et al., 1999]



$$\begin{cases} I_p(\alpha) = \frac{I_{max} + I_{min}}{2} \left(1 + \frac{I_{max} - I_{min}}{I_{max} + I_{min}} \cos(2\alpha - 2\varphi) \right) \\ I_p(\alpha) = \frac{I}{2} (1 + \rho \cdot \cos(2\alpha - 2\varphi)) \end{cases}$$

- ➊ take several images with different orientations of the polarizer
- ➋ for every pixels
 - ➌ take the max and the min to compute I and ρ
 - ➍ when the minimum occurs, the angle of polarization φ is given by the angle of the linear polarizer α .

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods for computing the parameters

- Example of a sphere lit with a diffuse dome light:

AOP φ			
DOP ρ			

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Methods for computing the parameters

- Example of a sphere lit with a diffuse dome light:



[Wolff and Andreou, 1995]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Methods for computing the parameters

- Example of a sphere lit with a diffuse dome light:



[Wolff and Andreou, 1995] [Saito et al., 1999]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Methods for computing the parameters

- Example of a sphere lit with a diffuse dome light:



[Wolff and Andreou, 1995] [Saito et al., 1999]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Mueller calculus

Recall



- Let be $M(\alpha)$ the mueller matrix of the linear polarizer:

$$M(\alpha) = \frac{1}{2} \begin{bmatrix} 1 & \cos 2\alpha & \sin 2\alpha & 0 \\ \cos 2\alpha & \cos^2 2\alpha & \cos 2\alpha \sin 2\alpha & 0 \\ \sin 2\alpha & \cos 2\alpha \sin 2\alpha & \sin^2 2\alpha & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Mueller calculus

Recall



- Let be $M(\alpha)$ the mueller matrix of the linear polarizer:

$$M(\alpha) = \frac{1}{2} \begin{bmatrix} 1 & \cos 2\alpha & \sin 2\alpha & 0 \\ \cos 2\alpha & \cos^2 2\alpha & \cos 2\alpha \sin 2\alpha & 0 \\ \sin 2\alpha & \cos 2\alpha \sin 2\alpha & \sin^2 2\alpha & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

$$\underbrace{\begin{bmatrix} s_{p_0} & s_{p_1} & s_{p_2} & s_{p_3} \end{bmatrix}}_{\mathbf{s}_p}^t = M(\alpha) \cdot \underbrace{\begin{bmatrix} s_0 & s_1 & s_2 & 0 \end{bmatrix}}_{\mathbf{s}}^t$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Mueller calculus

Recall



- Let be $M(\alpha)$ the mueller matrix of the linear polarizer:

$$M(\alpha) = \frac{1}{2} \begin{bmatrix} 1 & \cos 2\alpha & \sin 2\alpha & 0 \\ \cos 2\alpha & \cos^2 2\alpha & \cos 2\alpha \sin 2\alpha & 0 \\ \sin 2\alpha & \cos 2\alpha \sin 2\alpha & \sin^2 2\alpha & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

$$\underbrace{\begin{bmatrix} s_{p_0} & s_{p_1} & s_{p_2} & s_{p_3} \end{bmatrix}}_{\mathbf{s}_p}^t = M(\alpha) \cdot \underbrace{\begin{bmatrix} s_0 & s_1 & s_2 & 0 \end{bmatrix}}_{\mathbf{s}}^t$$

- Since the sensor is only sensitive to light intensity $s_{p_0} = I_p$:

$$I_p = \frac{1}{2} (s_0 + s_1 \cos 2\alpha + s_2 \sin 2\alpha)$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Least Mean Square method in details

Notations

- N images: $i = 1 \dots N$
- N values for the polarizer angle: $\alpha_1 \dots \alpha_2$
- $M = r \times c$ pixels: $j = 1 \dots M$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Least Mean Square method in details

Notations

- N images: $i = 1 \dots N$
- N values for the polarizer angle: $\alpha_1 \dots \alpha_2$
- $M = r \times c$ pixels: $j = 1 \dots M$

For every pixels: $j = 1 \dots M$

$$\begin{aligned} P_1^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_1 + s_2^j \sin 2\alpha_1) \\ P_2^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_2 + s_2^j \sin 2\alpha_2) \\ \vdots &= \vdots \\ P_N^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_N + s_2^j \sin 2\alpha_N) \end{aligned}$$

EndFor

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Least Mean Square method in details

Notations

- N images: $i = 1 \dots N$
- N values for the polarizer angle: $\alpha_1 \dots \alpha_2$
- $M = r \times c$ pixels: $j = 1 \dots M$

For every pixels: $j = 1 \dots M$

$$P_1^j = 0.5(s_0^j + s_1^j \cos 2\alpha_1 + s_2^j \sin 2\alpha_1)$$

$$P_2^j = 0.5(s_0^j + s_1^j \cos 2\alpha_2 + s_2^j \sin 2\alpha_2)$$

$$\vdots = \vdots$$

$$P_N^j = 0.5(s_0^j + s_1^j \cos 2\alpha_N + s_2^j \sin 2\alpha_N)$$

EndFor

$$\begin{bmatrix} P_1^j \\ P_2^j \\ \vdots \\ P_N^j \end{bmatrix} = \frac{1}{2} \underbrace{\begin{bmatrix} 1 & \cos 2\alpha_1 & \sin 2\alpha_1 \\ 1 & \cos 2\alpha_2 & \sin 2\alpha_2 \\ \vdots & \vdots & \vdots \\ 1 & \cos 2\alpha_N & \sin 2\alpha_N \end{bmatrix}}_A \cdot \underbrace{\begin{bmatrix} s_0^j \\ s_1^j \\ s_2^j \end{bmatrix}}_X$$

How to measure polarization?
Polarization contrast measurement

Simplified polarization imaging
Stokes polarization imaging

Polarization cameras
Some applications

Unpolarized lightning
Polarized lightning

Shape from Polarization

Principle
Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Least Mean Square method in details

Notations

- N images: $i = 1 \dots N$
- N values for the polarizer angle: $\alpha_1 \dots \alpha_2$
- $M = r \times c$ pixels: $j = 1 \dots M$

For every pixels: $j = 1 \dots M$

$$\begin{aligned} P_1^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_1 + s_2^j \sin 2\alpha_1) \\ P_2^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_2 + s_2^j \sin 2\alpha_2) \\ \vdots &= \vdots \\ P_N^j &= 0.5(s_0^j + s_1^j \cos 2\alpha_N + s_2^j \sin 2\alpha_N) \end{aligned}$$

EndFor

$$\underbrace{\begin{bmatrix} P_1^j \\ P_2^j \\ \vdots \\ P_N^j \end{bmatrix}}_Y = \frac{1}{2} \underbrace{\begin{bmatrix} 1 & \cos 2\alpha_1 & \sin 2\alpha_1 \\ 1 & \cos 2\alpha_2 & \sin 2\alpha_2 \\ \vdots & \vdots & \vdots \\ 1 & \cos 2\alpha_N & \sin 2\alpha_N \end{bmatrix}}_A \cdot \underbrace{\begin{bmatrix} s_0^j \\ s_1^j \\ s_2^j \end{bmatrix}}_X$$

$$\Rightarrow X = (A^t A)^{-1} A^t Y$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

An automatic optical device

By using a LCVR (Liquid Crystal Variable Retarder)



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

An automatic optical device

By using a LCVR (Liquid Crystal Variable Retarder)



- Mueller calculus gives:

$$\mathbf{s}_r = M_{pola} \cdot M_{ret}(\delta, 45^\circ) \cdot M_{\lambda/4} \cdot \mathbf{s}_{in}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

An automatic optical device

By using a LCVR (Liquid Crystal Variable Retarder)



- Mueller calculus gives:

$$\mathbf{s}_r = M_{pola} \cdot M_{ret}(\delta, 45^\circ) \cdot M_{\lambda/4} \cdot \mathbf{s}_{in}$$

- Thus, the measured intensity I_r is:

$$I_r(\delta) = \frac{1}{2}(s_0 + s_1 \cos \delta + s_2 \sin \delta) = \frac{I}{2}(1 + \rho \cdot \cos(\delta - 2\varphi))$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

An automatic optical device

By using a LCVR (Liquid Crystal Variable Retarder)



- Mueller calculus gives:

$$\mathbf{s}_r = M_{pola} \cdot M_{ret}(\delta, 45^\circ) \cdot M_{\lambda/4} \cdot \mathbf{s}_{in}$$

- Thus, the measured intensity I_r is:

$$I_r(\delta) = \frac{1}{2}(s_0 + s_1 \cos \delta + s_2 \sin \delta) = \frac{I}{2}(1 + \rho \cdot \cos(\delta - 2\varphi))$$

- by taking $\delta = 2\alpha \implies$ this system is equivalent to the previous one

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to represent images of polarization parameters

Color representation

$$2\varphi \rightarrow H$$

$$I \rightarrow L$$

$$\rho \rightarrow L$$

[Wolff and Andreou, 1995]

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to represent images of polarization parameters

Color representation

$$2\varphi \rightarrow H$$

$$I \rightarrow L$$

$$\rho \rightarrow L$$

[Wolff and Andreou, 1995]

- Example:



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

How to represent images of polarization parameters

Color representation

$$2\varphi \rightarrow H$$

$$I \rightarrow L$$

$$\rho \rightarrow L$$

[Wolff and Andreou, 1995]

- Example:



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype



Catadioptric calibration

Conclusion

Bibliography

How to represent images of polarization parameters

- Example: dielectric sphere lit by unpolarized light



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to represent images of polarization parameters

- Example: dielectric sphere lit by unpolarized light



Other color representation

$$\begin{aligned} 2\varphi &\rightarrow H \\ I_{\parallel} + I_{\perp} &\rightarrow L \\ I_{\parallel} - I_{\perp} &\rightarrow S \end{aligned}$$

[Tyo et al., 1998]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging**
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Stokes polarization imaging

Static set-up

- 2 steps process:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Stokes polarization imaging

Static set-up

- 2 steps process:



- Stokes vector computed for every pixels according to:

$$\begin{bmatrix} I_0^\circ + I_{90^\circ} \\ I_0^\circ - I_{90^\circ} \\ I_{45^\circ} - I_{135^\circ} \\ I_{45^\circ, \pi/2} - I_{135^\circ, \pi/2} \end{bmatrix}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Stokes polarization imaging

Dynamic set-up

- The process is fully automatic by using 2 LCVRs



Mueller Computation

$$M_{dyn}(\delta_1, \delta_2) = M_{pola}(\alpha) \cdot M_{ret}(\delta_2, \psi_2) \cdot M_{ret}(\delta_1, \psi_1)$$

- α, ψ_1, ψ_2 are fixed. Several pairs of (δ_1, δ_2) are used to estimate $[s_0, s_1, s_2, s_3]$ from:

$$I(\delta_1, \delta_2) = M_{dyn}^{11}s_0 + M_{dyn}^{12}s_1 + M_{dyn}^{13}s_2 + M_{dyn}^{14}s_3$$

Optimized pairs can be used to improve the SNR
[Tyo, 2000, De Martino and Laude-Boulesteix, 2004]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Polarization cameras

Samba - Bossa Nova Tech

Specifications

- Polarization-difference imaging
- observed scene illuminated by a controlled source
- 10kHz polarization analysis



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Polarization cameras

Salsa - Bossa Nova Tech

Specifications

- Full Stokes [Vedel et al., 2011]
- Ferroelectric crystals (FLC)
- 8 polarization frames/second



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


Polarization cameras

FluxData - Bossa Nova Tech

Specifications

- 3 different images
- No Ferroelectric crystal
- 30 polarization frames/second

Schematic View of 3-CCD Camera



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Unpolarized lightning

Physical principle

After being reflected, an unpolarized light wave becomes partially linearly polarized, depending on the surface normal and on the refractive index of the media it impinges on [Wolff and Boult, 1991].

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Unpolarized lightning

Physical principle

After being reflected, an unpolarized light wave becomes partially linearly polarized, depending on the surface normal and on the refractive index of the media it impinges on [Wolff and Boult, 1991].

Polarization imaging system

- Simplified: if the three parameters are required
- Contrast ratio otherwise

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Unpolarized lightning

Physical principle

After being reflected, an unpolarized light wave becomes partially linearly polarized, depending on the surface normal and on the refractive index of the media it impinges on [Wolff and Boult, 1991].

Polarization imaging system

- Simplified: if the three parameters are required
- Contrast ratio otherwise

Applications

- Vision through semi-reflecting media
- Material classification
- Separation of reflection components

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Vision through semi-reflecting media

Purpose

Looking out a car (or room) window, one can see both the outside world (real object) and a semi-reflection of the objects inside (virtual objects).



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Vision through semi-reflecting media

Purpose

Looking out a car (or room) window, one can see both the outside world (real object) and a semi-reflection of the objects inside (virtual objects).

real object



[Schechner et al., 2000]

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Vision through semi-reflecting media

Example in Cairo 2009 - ICIP



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Material classification

- The **diffuse component** of the reflected light is assumed to be unpolarized[Wolff and Boult, 1991]
- Expression of I_{max} and I_{min} seen through a rotating polarizer:

$$I_{max} = \frac{R_F}{R_F + 1} I_s + \frac{1}{2} I_d, \quad I_{min} = \frac{1}{R_F + 1} I_s + \frac{1}{2} I_d.$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Material classification

- The **diffuse component** of the reflected light is assumed to be unpolarized[Wolff and Boult, 1991]
- Expression of I_{max} and I_{min} seen through a rotating polarizer:

$$I_{max} = \frac{R_F}{R_F + 1} I_s + \frac{1}{2} I_d, \quad I_{min} = \frac{1}{R_F + 1} I_s + \frac{1}{2} I_d.$$

$$I_{max} = R_F I_{min} + \frac{1 - R_F}{2} I_d$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Material classification

- The **diffuse component** of the reflected light is assumed to be unpolarized [Wolff and Boult, 1991]
- Expression of I_{max} and I_{min} seen through a rotating polarizer:

$$I_{max} = \frac{R_F}{R_F + 1} I_s + \frac{1}{2} I_d, \quad I_{min} = \frac{1}{R_F + 1} I_s + \frac{1}{2} I_d.$$

$$I_{max} = R_F I_{min} + \frac{1 - R_F}{2} I_d$$

- Difficult in practice to estimate the Fresnel ratio R_F
- Dichromatic reflectance model [Nayar, 1997]
 - available for dielectrics (non-conductors)
 - the diffuse and specular components generally have different spectral distributions

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Polarized lightning

Crossed polarization

- Frequently met in machine vision application
- Improvement of:
 - color constancy
 - image segmentation



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Polarized lightning

Crossed polarization

- Frequently met in machine vision application
- Improvement of:
 - color constancy
 - image segmentation



[Bolle et al., 1996]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Depolarization effect

Principle

A linearly polarized light wave reflected by a diffuse surface becomes unpolarized contrary to specular or metallic surfaces.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


Polarized lightning

Depolarization effect


Principle

A linearly polarized light wave reflected by a diffuse surface becomes unpolarized contrary to specular or metallic surfaces.

- Discrimination on specular metallic surfaces between dust and surface defects:



Parallel polarizer



Crossed polarizer



DOP

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Depolarization effect in NIR

- A simplified Degree of Polarization is computed from 2 images according to:

$$D_p = \frac{I_{\parallel} - I_{\perp}}{I_{\parallel} + I_{\perp}}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Depolarization effect in NIR

- A simplified Degree of Polarization is computed from 2 images according to:

$$D_p = \frac{I_{\parallel} - I_{\perp}}{I_{\parallel} + I_{\perp}}$$

- $D_p = 0 \Rightarrow$ depolarization effect (natural objects, lambertian surfaces)
- $D_p = 1 \Rightarrow$ metallic surfaces, glass

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography



Polarized lightning

Depolarization effect in NIR

- A simplified Degree of Polarization is computed from 2 images according to:

$$D_p = \frac{I_{\parallel} - I_{\perp}}{I_{\parallel} + I_{\perp}}$$

- $D_p = 0 \Rightarrow$ depolarization effect (natural objects, lambertian surfaces)
- $D_p = 1 \Rightarrow$ metallic surfaces, glass



[Alouini et al., 2004]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Polarized light in Laser-scanning

Goal

Improving depth image acquisition by using polarized light to discriminate between primary and secondary reflection

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Polarized light in Laser-scanning

Goal

Improving depth image acquisition by using polarized light to discriminate between primary and secondary reflection

- the laser line is linearly polarized
- an analyzer is placed in front of the sensor
- the polarization state of the reflected ray depends on both the incident angles and the number of interreflections
- [Clark et al., 1997, Wallace et al., 1999]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Material classification

Drawbacks of the Wolff method

- the angle of incidence is in the range 30-80 degree
- diffuse reflections must be negligible

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarized lightning

Material classification

Drawbacks of the Wolff method

- the angle of incidence is in the range 30-80 degree
 - diffuse reflections must be negligible
-
- [Chen and Wolff, 1998] have used a linearly polarized light source

Physical principles

When the linearly polarized light is reflected by a dielectric surface, it remains linearly polarized whereas it becomes elliptically polarized by a metallic surface

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Polarized lightning

Material classification - polarization set-up

- Ellipticity of light has to be measured



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Polarized lightning

Material classification - polarization set-up

- Ellipticity of light has to be measured



$$M_{chen} = \frac{1}{2} \begin{bmatrix} 1 & 0 & \sin 2\alpha & \cos 2\alpha \\ \cos 2\alpha & 0 & \cos 2\alpha \sin 2\alpha & \cos^2 2\alpha \\ \sin 2\alpha & 0 & \sin^2 2\alpha & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

partially linearly polarized light

- Intensity of measured light:

$$I_p = \frac{1}{2}(s_0 + s_2 \sin 2\alpha + s_3 \cos 2\alpha)$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Polarized lightning

Material classification - polarization set-up

- Ellipticity of light has to be measured



partially linearly polarized light

- Intensity of measured light:

$$I_p = \frac{1}{2}(s_0 + s_2 \sin 2\alpha + s_3 \cos 2\alpha)$$

- Phase measurement:

$$\delta = \arctan s_3 / s_2$$

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Medical imagery

Polarimetric imaging for the diagnosis of cervical cancer

Diagnosis of Cervical cancer detection

- current strategy for the early detection and therapy:
 - Pap smear followed by a colposcopy if anomalous
- colposcopy is very difficult and operator-dependent ⇒ significant proportion of wrong colposcopic diagnoses

How to measure polarization?
?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Medical imagery


Polarimetric imaging for the diagnosis of cervical cancer

Diagnosis of Cervical cancer detection

- current strategy for the early detection and therapy:
 - Pap smear followed by a colposcopy if anomalous
- colposcopy is very difficult and operator-dependent ⇒ significant proportion of wrong colposcopic diagnoses

[Anastasiadou et al., 2008]

- Polarization contrast measurement $\frac{I_{||} - I_{\perp}}{I_{||} + I_{\perp}}$



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Medical imagery

Polarimetric imaging for the diagnosis of cervical cancer

- The precancerous lesions appearing less depolarizing



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

Principle

Propagation of light through a biological tissue causes changes due to tissue birefringence and scattering:

- light that propagates deeply escape with random polarization state
- on superficial tissue, polarization almost remains (region where cancer developps)

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Imaging skin pathology

Principle

Propagation of light through a biological tissue causes changes due to tissue birefringence and scattering:

- light that propagates deeply escape with random polarization state
- on superficial tissue, polarization almost remains (region where cancer developps)



[Jacques et al., 2002]

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

- When the polarizer is parallel to the polarized light source

$$I_{\parallel} = I_0 T_{mel} \left(R_s + \frac{1}{2} R_d \right)$$

- where T_{mel} is the absorption coefficient linked to the epidermal melanin effect
- R_s is the superficially reflected light
- R_d is the "deeply penetrating" light

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

- When the polarizer is parallel to the polarized light source

$$I_{\parallel} = I_0 T_{mel} \left(R_s + \frac{1}{2} R_d \right)$$

- where T_{mel} is the absorption coefficient linked to the epidermal melanin effect
- R_s is the superficially reflected light
- R_d is the "deeply penetrating" light

- When the polarizer is perpendicular to the polarized source

$$I_{\perp} = I_0 T_{mel} \frac{1}{2} R_d$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

- When the polarizer is parallel to the polarized light source

$$I_{\parallel} = I_0 T_{mel} \left(R_s + \frac{1}{2} R_d \right)$$

- where T_{mel} is the absorption coefficient linked to the epidermal melanin effect
- R_s is the superficially reflected light
- R_d is the "deeply penetrating" light

- When the polarizer is perpendicular to the polarized source

$$I_{\perp} = I_0 T_{mel} \frac{1}{2} R_d$$

- The polarization ratio is finally given by:

$$\frac{I_{\parallel} - I_{\perp}}{I_{\parallel} + I_{\perp}} = \frac{R_s}{R_s + R_d}$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype






Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

Results on normal skin



The structural details of the superficial layer are emphasized.

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype





Catadioptric calibration

Conclusion

Bibliography

Imaging skin pathology

Results on burn scar



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Imaging skin pathology

Results on carcinoma



Malignant basal cell carcinoma



Squamous cell carcinoma

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1 How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2 Some applications

- Unpolarized lightning
- Polarized lightning

3 Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4 Catadioptric calibration

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Introduction

Goal

The aim of Shape from Polarization is to provide the 3D shape of an object from polarization imaging.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Introduction

Goal

The aim of Shape from Polarization is to provide the 3D shape of an object from polarization imaging.

Main interests

Extract the 3D information of the surface from:

- Translucent objects
- Highly reflective objects

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Introduction


Goal

The aim of Shape from Polarization is to provide the 3D shape of an object from polarization imaging.

Main interests

Extract the 3D information of the surface from:

- Translucent objects
- Highly reflective objects



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Introduction

Goal

The aim of Shape from Polarization is to provide the 3D shape of an object from polarization imaging.

Main interests

Extract the 3D information of the surface from:

- Translucent objects
- Highly reflective objects



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

History

- **Koshikawa:** reflection of a circularly polarized wave to get the orientation of planar surfaces [Koshikawa, 1979]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

History

- **Koshikawa:** reflection of a circularly polarized wave to get the orientation of planar surfaces [Koshikawa, 1979]

- **Wolff:** reflection of an unpolarized light [Wolff and Boult, 1991]

- Reconstruction of dielectric surfaces:

- [Miyazaki et al., 2004, Rahmann, 2003, Atkinson and Hancock, 2006]

- Reconstruction of specular metallic surfaces

- [Morel et al., 2006]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization
Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Physical principle

Used by Wolff and the rest

After being reflected, an unpolarized light wave becomes **partially linearly polarized**, depending on the surface normal and on the refractive index of the media it impinges on.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Physical principle

Used by Wolff and the rest

After being reflected, an unpolarized light wave becomes **partially linearly polarized**, depending on the surface normal and on the refractive index of the media it impinges on.

- ❶ polarization parameters measurement
- ❷ surface normals
- ❸ height from gradients

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens

$$\vec{n} = \begin{pmatrix} p = \tan \theta_r \cos \phi \\ q = \tan \theta_r \sin \phi \\ 1 \end{pmatrix} \Rightarrow (\phi, \theta_r) ?$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens

$$\vec{n} = \begin{pmatrix} p = \tan \theta_r \cos \phi \\ q = \tan \theta_r \sin \phi \\ 1 \end{pmatrix} \Rightarrow (\phi, \theta_r) ?$$

Fresnel's coefficients:

- Angle of polarization:
 $\varphi \Rightarrow \phi$
- Degree of polarization:
 $\rho \Rightarrow \theta_r$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Recall of some basic optical laws

- Snell-Descartes' Law:



$$\left\{ \begin{array}{l} \theta_i = \theta_r, \\ n_1 \sin \theta_i = n_2 \sin \theta_t. \end{array} \right.$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Recall of some basic optical laws

- Snell-Descartes' Law:



$$\begin{cases} \theta_i = \theta_r, \\ n_1 \sin \theta_i = n_2 \sin \theta_t. \end{cases}$$

- Fresnel formulae:

$$\begin{cases} f_{\perp} = \frac{R_{\perp}}{A_{\perp}} = -\frac{\sin(\theta_i - \theta_t)}{\sin(\theta_i + \theta_t)}, \\ f_{\parallel} = \frac{R_{\parallel}}{A_{\parallel}} = \frac{\tan(\theta_i - \theta_t)}{\tan(\theta_i + \theta_t)}. \end{cases}$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Proof

By using the Mueller calculus once again

Mueller matrix of the specular reflection

The Mueller matrix of the specular reflection is given by the product of two matrices: Mueller matrix of a partial polarizer and the Mueller matrix of a perfect retarder.

$$M_{refl} = M_{pp}(F_{\perp}, F_{\parallel}) \cdot M_{ret}(\delta, 0)$$

with $F_{\perp} = |f_{\perp}|^2$, $F_{\parallel} = |f_{\parallel}|^2$ and $\delta = \arg(f_{\parallel} - f_{\perp})$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Proof

By using the Mueller calculus once again

Mueller matrix of the specular reflection

The Mueller matrix of the specular reflection is given by the product of two matrices: Mueller matrix of a partial polarizer and the Mueller matrix of a perfect retarder.

$$M_{refl} = M_{pp}(F_{\perp}, F_{\parallel}) \cdot M_{ret}(\delta, 0)$$

with $F_{\perp} = |f_{\perp}|^2$, $F_{\parallel} = |f_{\parallel}|^2$ and $\delta = \arg(f_{\parallel} - f_{\perp})$

$$M_{refl} = \frac{1}{2} \begin{bmatrix} F_{\perp} + F_{\parallel} & F_{\perp} - F_{\parallel} & 0 & 0 \\ F_{\perp} - F_{\parallel} & F_{\perp} + F_{\parallel} & 0 & 0 \\ 0 & 0 & 2\sqrt{F_{\perp}F_{\parallel}} \cos \delta & 2\sqrt{F_{\perp}F_{\parallel}} \sin \delta \\ 0 & 0 & -2\sqrt{F_{\perp}F_{\parallel}} \sin \delta & 2\sqrt{F_{\perp}F_{\parallel}} \cos \delta \end{bmatrix}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

Conclusions

- the reflected light is **partially polarized** since:

$$s_0^2 \geq s_1^2 + 0 + 0$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

Conclusions

- the reflected light is **partially polarized** since:

$$s_0^2 \geq s_1^2 + 0 + 0$$

- degree of polarization: $\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$ ($F_{\perp} \geq F_{\parallel}$)

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

Conclusions

- the reflected light is **partially polarized** since:
 $s_0^2 \geq s_1^2 + 0 + 0$
- degree of polarization: $\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$ ($F_{\perp} \geq F_{\parallel}$)
- light intensity: $I = \frac{I_0}{2} \cdot (F_{\perp} + F_{\parallel})$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

Conclusions

- the reflected light is **partially polarized** since:
 $s_0^2 \geq s_1^2 + 0 + 0$
- degree of polarization: $\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$ ($F_{\perp} \geq F_{\parallel}$)
- light intensity: $I = \frac{I_0}{2} \cdot (F_{\perp} + F_{\parallel})$
- ellipticity: $\chi = 0 \Rightarrow$ **linearly polarized**

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Reflection of an unpolarized light

- Incident light is assumed to be unpolarized:

$$\mathbf{s}^{(i)} = [I_0 \quad 0 \quad 0 \quad 0]^t$$

- The reflected light can be written:

$$\mathbf{s}^{(r)} = M_{refl} \cdot \mathbf{s}^{(i)} = \frac{I_0}{2} [F_{\perp} + F_{\parallel} \quad F_{\perp} - F_{\parallel} \quad 0 \quad 0]^t$$

Conclusions

- the reflected light is **partially polarized** since:
 $s_0^2 \geq s_1^2 + 0 + 0$
- degree of polarization: $\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$ ($F_{\perp} \geq F_{\parallel}$)
- light intensity: $I = \frac{I_0}{2} \cdot (F_{\perp} + F_{\parallel})$
- ellipticity: $\chi = 0 \Rightarrow$ **linearly polarized**
- angle of polarization: $\varphi = 0 \Rightarrow$ the linearly polarized component is **orthogonal** to the plane of incidence

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- **Surface normals**
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

Degree of polarization

$$\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$$

- From the Fresnel formulae, we know that F_{\perp} and F_{\parallel} depend of θ_i and θ_t

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

Degree of polarization

$$\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$$

- From the Fresnel formulae, we know that F_{\perp} and F_{\parallel} depend of θ_i and θ_t
- And from the Snell-Descartes' law, one can write:

$$\theta_t = \arcsin \left(\frac{1}{n} \sin \theta_i \right)$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

Degree of polarization

$$\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$$

- From the Fresnel formulae, we know that F_{\perp} and F_{\parallel} depend of θ_i and θ_t
- And from the Snell-Descartes' law, one can write:

$$\theta_t = \arcsin \left(\frac{1}{n} \sin \theta_i \right)$$

- Therefore, since $\theta_i = \theta_r$ we can deduce that F_{\perp} and F_{\parallel} depend of θ_r and n

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

Degree of polarization

$$\rho = \frac{F_{\perp} - F_{\parallel}}{F_{\perp} + F_{\parallel}}$$

- From the Fresnel formulae, we know that F_{\perp} and F_{\parallel} depend of θ_i and θ_t
- And from the Snell-Descartes' law, one can write:

$$\theta_t = \arcsin \left(\frac{1}{n} \sin \theta_i \right)$$

- Therefore, since $\theta_i = \theta_r$ we can deduce that F_{\perp} and F_{\parallel} depend of θ_r and n
- If the object refractive index n is known we have $\rho(\theta_r)$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

For dielectric surfaces:

$$\rho = \frac{2 \sin^2 \theta \sqrt{n^2 - \sin^2 \theta - n^2 \sin^2 \theta + \sin^4 \theta}}{n^2 - \sin^2 \theta - n^2 \sin^2 \theta + 2 \sin^4 \theta}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Degree of polarization $\rho \Rightarrow \theta_r$

For dielectric surfaces:

$$\rho = \frac{2 \sin^2 \theta \sqrt{n^2 - \sin^2 \theta - n^2 \sin^2 \theta + \sin^4 \theta}}{n^2 - \sin^2 \theta - n^2 \sin^2 \theta + 2 \sin^4 \theta}$$

For metallic surfaces

$$\rho(\theta) = \frac{2n \tan \theta \sin \theta}{\tan^2 \theta \sin^2 \theta + |\hat{n}|^2},$$

where \hat{n} is the complex refractive index and according the approximation $|\hat{n}|^2 = n^2(1 + \kappa^2) \gg 1$ [Born and Wolf, 1999]

How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Relationship between ρ and θ for dielectric surfaces



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Relationship between ρ and θ for dielectric surfaces



- Ambiguity problem to be solved
 - with two images [Miyazaki et al., 2004]: normal position and tilted with small angle position
 - with thermal imagery [Miyazaki et al., 2002]

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype




Catadioptric calibration

Conclusion

Bibliography

Disambiguation by thermal imagery

[Miyazaki et al., 2002]



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Relationship between ρ and θ for metallic surfaces



How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Relationship between ρ and θ for metallic surfaces



How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Relationship between ρ and θ for metallic surfaces



- θ_{lim} : principal angle of incidence
- $\theta_{lim} \simeq 80^\circ$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Angle of polarization $\varphi \Rightarrow \phi$



Property

The reflected light is partially linearly polarized orthogonally to the plane of incidence.

$$\phi = \varphi \pm \frac{\pi}{2}$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Cataadioptric calibration

Conclusion

Bibliography

Angle of polarization $\varphi \Rightarrow \phi$



Property

The reflected light is partially linearly polarized orthogonally to the plane of incidence.

$$\phi = \varphi \pm \frac{\pi}{2}$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Cataadioptric calibration

Conclusion

Bibliography

Angle of polarization $\varphi \Rightarrow \phi$



Property

The reflected light is partially linearly polarized orthogonally to the plane of incidence.

$$\phi = \varphi \pm \frac{\pi}{2}$$

\Rightarrow ambiguity in the determination of ϕ

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Solving the ambiguity

By using ϕ at the occluding boundary
[Miyazaki et al., 2004]

- object must be closed
- the normal has to be computed at the occluding boundary
- this initial condition has to be propagated throughout the surface
- it assumes that all local parts of the surface are not concave toward the camera direction.



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Active lighting



$$\beta \in]0, \pi/2[$$

How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype



Catadioptric calibration

Conclusion

Bibliography

Active lighting

• E/W Segmentation



$$\beta \in]0, \pi/2[$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion


Bibliography

Active lighting




$$\beta \in]0, \pi/2[$$

- E/W Segmentation



- N/S Segmentation



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion


Bibliography

Active lighting




$$\beta \in]0, \pi/2[$$

- E/W Segmentation



- N/S Segmentation



- Segmented image I_{quad}



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Active lighting

① $\phi = \varphi - \pi/2$



$$\phi \in [\pi]$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Active lighting


① $\phi = \varphi - \pi/2$



$$\phi \in [\pi]$$

② $\phi = \phi + \pi$, if :

- $I_{quad} = 1$
- $(I_{quad} = 3) \wedge (\phi \geq 0)$
- $(I_{quad} = 0) \wedge (\phi \leq 0)$



$$I_{quad}$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Active lighting


① $\phi = \varphi - \pi/2$




$$\phi \in [\pi]$$

② $\phi = \phi + \pi$, if :

- $I_{quad} = 1$
- $(I_{quad} = 3) \wedge (\phi \geq 0)$
- $(I_{quad} = 0) \wedge (\phi \leq 0)$



$$\phi \in [2\pi]$$



$$I_{quad}$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Active lighting


① $\phi = \varphi - \pi/2$




$$\phi \in [\pi]$$

② $\phi = \phi + \pi$, if :


- $I_{quad} = 1$
- $(I_{quad} = 3) \wedge (\phi \geq 0)$
- $(I_{quad} = 0) \wedge (\phi \leq 0)$



$$\phi \in [2\pi]$$



$$I_{quad}$$



$$\text{theoretical value of } \phi$$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Constraints

- Smooth surface, described by a continuous function f , of C^2 class
- The height z can be written:

$$\begin{aligned} f : U &\rightarrow \mathbb{R} \\ (x, y) &\mapsto z = f(x, y) \end{aligned}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Constraints

- Smooth surface, described by a continuous function f , of C^2 class
- The height z can be written:
$$\begin{aligned} f : U &\rightarrow \mathbb{R} \\ (x, y) &\mapsto z = f(x, y) \end{aligned}$$

Expression of the normal \vec{n} for every points (x, y, z) of the surface:

$$\vec{n} = \begin{pmatrix} p = \tan \theta \cos \phi \\ q = \tan \theta \sin \phi \\ 1 \end{pmatrix}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Constraints

- Smooth surface, described by a continuous function f , of C^2 class
- The height z can be written:
$$\begin{aligned} f : U &\rightarrow \mathbb{R} \\ (x, y) &\mapsto z = f(x, y) \end{aligned}$$

Expression of the normal \vec{n} for every points (x, y, z) of the surface:

$$\vec{n} = \begin{pmatrix} p = \tan \theta \cos \phi \\ q = \tan \theta \sin \phi \\ 1 \end{pmatrix} = \begin{pmatrix} -\frac{\partial f(x,y)}{\partial x} \\ -\frac{\partial f(x,y)}{\partial y} \\ 1 \end{pmatrix}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Example in 1D

- Example in 1D

- Continuous representation of the derivative:

$$p(x) = -\frac{df(x)}{dx}$$

- Discrete approximation of the derivative: $p_i = -\frac{z_i - z_{i-1}}{\epsilon}$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Example in 1D

- Example in 1D

- Continuous representation of the derivative:

$$p(x) = -\frac{df(x)}{dx}$$

- Discrete approximation of the derivative: $p_i = -\frac{z_i - z_{i-1}}{\epsilon}$

- Integration process: $z_i = z_{i-1} - \epsilon p_i$

- cumulative sum along a path

- z is obtained up to a constant

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Principle

Example in 1D

- Example in 1D

- Continuous representation of the derivative:

$$p(x) = -\frac{df(x)}{dx}$$

- Discrete approximation of the derivative: $p_i = -\frac{z_i - z_{i-1}}{\epsilon}$

- Integration process: $z_i = z_{i-1} - \epsilon p_i$

- cumulative sum along a path

- z is obtained up to a constant

- From 2 gradient images compute 1 surface...

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Local methods

Rectangular integration



How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Local methods

Rectangular integration



- For a **rectangular** integration, we get:

$$\begin{cases} z_{i,j} = z_{i-1,j} - \epsilon \cdot p_{i-1,j} \\ z_{i,j} = z_{i,j-1} - \epsilon \cdot q_{i,j-1} \end{cases}$$

Local rectangular integration

$$z_{i,j} = \frac{z_{i-1,j} + z_{i,j-1}}{2} - \epsilon \frac{p_{i-1,j} + q_{i,j-1}}{2}$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Local methods

Trapezoidal integration

- For a **trapezoidal** integration, we get:

$$\begin{cases} z_{i,j} = z_{i-1,j} - \epsilon \cdot p_{i-1,j} - \frac{\epsilon^2}{2} \cdot p'_{i-1,j} \\ z_{i,j} = z_{i,j-1} - \epsilon \cdot q_{i,j-1} - \frac{\epsilon^2}{2} \cdot q'_{i,j-1} \end{cases}$$

- p' and q' can be determined by:

$$\begin{cases} p'_{i-1,j} = \frac{p_{i,j} - p_{i-1,j}}{\epsilon} \\ q'_{i,j-1} = \frac{q_{i,j} - q_{i,j-1}}{\epsilon} \end{cases}$$

How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Local methods

Trapezoidal integration

- For a trapezoidal integration, we get:

$$\begin{cases} z_{i,j} = z_{i-1,j} - \epsilon \cdot p_{i-1,j} - \frac{\epsilon^2}{2} \cdot p'_{i-1,j} \\ z_{i,j} = z_{i,j-1} - \epsilon \cdot q_{i,j-1} - \frac{\epsilon^2}{2} \cdot q'_{i,j-1} \end{cases}$$

- p' and q' can be determined by:

$$\begin{cases} p'_{i-1,j} = \frac{p_{i,j} - p_{i-1,j}}{\epsilon} \\ q'_{i,j-1} = \frac{q_{i,j} - q_{i,j-1}}{\epsilon} \end{cases}$$

Local trapezoidal integration

$$z_{i,j} = \frac{z_{i-1,j} + z_{i,j-1}}{2} - \epsilon \frac{p_{i,j} + p_{i-1,j} + q_{i,j} + q_{i,j-1}}{4}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Local methods

Ben Slimane



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Local methods

Ben Slimane



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Local methods

Ben Slimane



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods

Ben Slimane



Coleman-Jain



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods

Ben Slimane



Coleman-Jain



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods

Ben Slimane



Coleman-Jain



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods


Ben Slimane



Coleman-Jain



Rodehorst



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods


Ben Slimane



Coleman-Jain



Rodehorst



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods


Ben Slimane



Coleman-Jain



Rodehorst



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods


Ben Slimane



Coleman-Jain



Rodehorst



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion


Bibliography

Local methods


Ben Slimane




Coleman-Jain




Rodehorst




Reconstruction error of a gradient field computed from a plane
 $z = 0$



MSE=0.0477



MSE=0.0444



MSE=0.0273

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

Principle

Integration of the surface by minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x,y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x,y)}{\partial y} \right) - q \right)^2 dx dy$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

Principle

Integration of the surface by minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x,y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x,y)}{\partial y} \right) - q \right)^2 dx dy$$

- Comes from “Shape from Shading” algorithms
[Ikeuchi, 1983, Horn and Brooks, 1986]

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

Principle

Integration of the surface by minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x,y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x,y)}{\partial y} \right) - q \right)^2 dx dy$$

- Comes from “Shape from Shading” algorithms
[Ikeuchi, 1983, Horn and Brooks, 1986]

Iterative scheme

$$f(x,y)^{n+1} = \bar{f}(x,y)^n - \rho \left(\frac{\partial p}{\partial x} + \frac{\partial q}{\partial y} \right)$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

• Jacobi

$$\begin{aligned} z_{i,j}^{n+1} = & \frac{1}{4} (z_{i-1,j}^n + z_{i+1,j}^n + z_{i,j-1}^n + z_{i,j+1}^n) \\ & - \frac{\epsilon}{4} (p_{i+1,j} - p_{i,j} + q_{i,j+1} - q_{i,j}) \end{aligned}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

- Jacobi
- Gauss-Seidel

$$\begin{aligned} z_{i,j}^{n+1} &= \frac{1}{4} \left(z_{i-1,j}^{n+1} + z_{i+1,j}^n + z_{i,j-1}^{n+1} + z_{i,j+1}^n \right) \\ &\quad - \frac{\epsilon}{4} (p_{i+1,j} - p_{i,j} + q_{i,j+1} - q_{i,j}) \end{aligned}$$

⇒ the average is done on the most recent data

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

- Jacobi
- Gauss-Seidel
- SOR

$$z_{i,j}^{n+1} = (1 - \omega)z_{i,j}^n + \frac{\omega}{4} \left(z_{i-1,j}^{n+1} + z_{i+1,j}^n + z_{i,j-1}^{n+1} + z_{i,j+1}^n \right) - \frac{\omega\epsilon}{4} (p_{i+1,j} - p_{i,j} + q_{i,j+1} - q_{i,j})$$

⇒ where ω is an “over relaxation” parameter: $1 < \omega < 2$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Methods based on relaxation

- Jacobi
- Gauss-Seidel
- SOR
- Generalization on a higher neighborhood

$$z_{i,j}^{n+1} = (1 - \omega)z_{i,j}^n + \frac{\omega}{S} H \tilde{z}_{i,j}^n - \frac{\omega a \epsilon}{2S} (p_{i+1,j} - p_{i,j} + q_{i,j+1} - q_{i,j})$$

⇒ where H is a symmetric averaging filter, S is the sum of the filter coefficients and a is a constant given by:

$$a = \sum_u \sum_v H(u, v) u^2 = \sum_u \sum_v H(u, v) v^2$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Methods based on relaxation

- Jacobi
- Gauss-Seidel
- SOR
- Generalization on a higher neighborhood

Example:



$MSE \leq 0.001$

method	neighborhood	nb of iterations	time(s)
Jacobi	4	6475	11.64
	8	3374	3.67
Gauss-Seidel	4	890	1.01
	8	592	0.87
SOR	4	43	0.047
	8	42	0.045

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Basis projections

[Kovesi, 2003]

Correlation between the gradient and the gradients of basis functions gradients \Leftrightarrow direct correlation between the surface and the basis functions.

- Robust method
- Reconstruction up to a scale factor

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Basis projections

[Kovesi, 2003]

Correlation between the gradient and the gradients of basis functions gradients \Leftrightarrow direct correlation between the surface and the basis functions.

- Robust method
- Reconstruction up to a scale factor

[Karaçali and Snyder, 2003]

Projection of the surface gradients on a subset of gradient field.

- Reconstruction by part
- Very very time consuming

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

Principle

Minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x, y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x, y)}{\partial y} \right) - q \right)^2 dx dy$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

Principle

Minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x, y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x, y)}{\partial y} \right) - q \right)^2 dx dy$$

- Fourier transform of the surface:

$$\tilde{f}(u, v) = \int \int f(u, v) e^{-j(ux+vy)} dx dy$$

- The Parseval theorem:

$$\int \int |h(x, y)|^2 dx dy = \frac{1}{2\pi} \int \int |\tilde{h}(u, v)|^2 du dv$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

Principle

Minimizing the functional:

$$W = \int \int \left(\left(-\frac{\partial f(x, y)}{\partial x} \right) - p \right)^2 + \left(\left(-\frac{\partial f(x, y)}{\partial y} \right) - q \right)^2 dx dy$$

- Fourier transform of the surface:

$$\tilde{f}(u, v) = \int \int f(u, v) e^{-j(ux+vy)} dx dy$$

- The Parseval theorem:

$$\int \int |h(x, y)|^2 dx dy = \frac{1}{2\pi} \int \int |\tilde{h}(u, v)|^2 du dv$$

- Parseval theorem applied to the functional:

$$W = \frac{1}{2\pi} \int \int |-ju\tilde{f}(u, v) - \tilde{p}|^2 + |-jv\tilde{f}(u, v) - \tilde{q}|^2 du dv$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

- By expanding we get:

$$W = \frac{1}{2\pi} \int \int (u^2 + v^2) \tilde{f} \tilde{f}^* + ju \tilde{p}^* \tilde{f} - ju \tilde{p} \tilde{f}^* + jv \tilde{q}^* \tilde{f} - jv \tilde{q} \tilde{f}^* + \tilde{p} \tilde{p}^* + \tilde{q} \tilde{q}^* du dv$$

where \tilde{p} and \tilde{q} are the Fourier transforms of the gradient.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

- By expanding we get:

$$W = \frac{1}{2\pi} \int \int (u^2 + v^2) \tilde{f} \tilde{f}^* + ju \tilde{p}^* \tilde{f} - ju \tilde{p} \tilde{f}^* + jv \tilde{q}^* \tilde{f} - jv \tilde{q} \tilde{f}^* + \tilde{p} \tilde{p}^* + \tilde{q} \tilde{q}^* du dv$$

where \tilde{p} and \tilde{q} are the Fourier transforms of the gradient.

- Differentiating the above expression with respect to \tilde{f} and \tilde{f}^* we can deduce the minimal conditions for the cost function:

$$\begin{cases} (u^2 + v^2) \tilde{f}^* + ju \tilde{p}^* + jv \tilde{q}^* = 0, \\ (u^2 + v^2) \tilde{f} - ju \tilde{p} - jv \tilde{q} = 0. \end{cases}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

- By expanding we get:

$$W = \frac{1}{2\pi} \int \int (u^2 + v^2) \tilde{f} \tilde{f}^* + ju \tilde{p}^* \tilde{f} - ju \tilde{p} \tilde{f}^* + jv \tilde{q}^* \tilde{f} - jv \tilde{q} \tilde{f}^* + \tilde{p} \tilde{p}^* + \tilde{q} \tilde{q}^* dudv$$

where \tilde{p} and \tilde{q} are the Fourier transforms of the gradient.

- Differentiating the above expression with respect to \tilde{f} and \tilde{f}^* we can deduce the minimal conditions for the cost function:

$$\begin{cases} (u^2 + v^2) \tilde{f}^* + ju \tilde{p}^* + jv \tilde{q}^* = 0, \\ (u^2 + v^2) \tilde{f} - ju \tilde{p} - jv \tilde{q} = 0. \end{cases}$$

- Adding the above 2 equations together, then subtracting the second one from the first one, this results in:

$$\begin{cases} (u^2 + v^2)(\tilde{f} + \tilde{f}^*) + ju(\tilde{p}^* - \tilde{p}) + jv(\tilde{q}^* - \tilde{q}) = 0, \\ (u^2 + v^2)(\tilde{f} - \tilde{f}^*) + ju(\tilde{p}^* + \tilde{p}) + jv(\tilde{q}^* + \tilde{q}) = 0. \end{cases}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

- Solving the previous equations except for $(u, v) \neq (0, 0)$ ([Frankot and Chellappa, 1988]):

Frankot Chellappa relation

$$\tilde{f}(u, v) = \frac{-ju\tilde{p}^* - jv\tilde{q}^*}{u^2 + v^2}$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

- Solving the previous equations except for $(u, v) \neq (0, 0)$ ([Frankot and Chellappa, 1988]):

Frankot Chellappa relation

$$\tilde{f}(u, v) = \frac{-ju\tilde{p}^* - jv\tilde{q}^*}{u^2 + v^2}$$

- What about the mean values of the gradients: $\tilde{p}(0, 0) = \bar{p}$ and $\tilde{q}(0, 0) = \bar{q}$?
- reconstruction of surfaces with a null mean slant

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Global methods

Fourier transform

$$\begin{cases} p(x, y) = p_0(x, y) + \bar{p} \\ q(x, y) = q_0(x, y) + \bar{q} \end{cases}$$

- Integration process is linear:

$$f(x, y) = f_0(x, y) + g(x, y) \text{ where } g(x, y) = x\bar{p} + y\bar{q}$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


Global methods

Fourier transform


$$\begin{cases} p(x, y) = p_0(x, y) + \bar{p} \\ q(x, y) = q_0(x, y) + \bar{q} \end{cases}$$

- Integration process is linear:


$$f(x, y) = f_0(x, y) + g(x, y) \text{ where } g(x, y) = x\bar{p} + y\bar{q}$$



f



f_0



g

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion




Bibliography

Comparisons

Method



Surfaces



Comparisons

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

	kpix/s	Surf1	Surf2	Surf3
Coleman-Jain	410	0.1402	0.1016	0.0886
Rodehorst	82.1	0.0494	0.0535	0.1145
Gauss-Seidel 8N	0.1	0.0188		
SOR 8V	8.3	0.0162		
Frankot-Chellappa	145	0.0219	0.0193	0.0287
Karaçali-Snyder	20.8	0.0737	0.0909	0.1250

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Further method to be investigated

More general approach of Height from Gradients

- Shape from [Polarization, Shading, Texture],
Deflectometry require reconstructing a surface from an
estimated gradient field

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Further method to be investigated

More general approach of Height from Gradients

- Shape from [Polarization, Shading, Texture],
Deflectometry require reconstructing a surface from an estimated gradient field
- Gradient processing [Agrawal and Raskar, 2007]



- HDR compression, local illumination change, shadow removal, etc.

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Further method to be investigated

More general approach of Height from Gradients

- Shape from [Polarization, Shading, Texture], Deflectometry require reconstructing a surface from an estimated gradient field
- Gradient processing [Agrawal and Raskar, 2007]



- HDR compression, local illumination change, shadow removal, etc.
- The main problem remains: the gradients are generally **non-integrable**

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Further method to be investigated

- Least squares formulation:

$$J(z) = \int \int \left((z_x - p)^2 + (z_y - q)^2 \right) dx dy$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Further method to be investigated

- Least squares formulation:

$$J(z) = \int \int \left((z_x - p)^2 + (z_y - q)^2 \right) dx dy$$

- Extremum points are given by the Euler-Lagrange equation:

$$\frac{\partial J}{\partial z} - \frac{d}{dx} \frac{\partial J}{\partial z_x} - \frac{d}{dy} \frac{\partial J}{\partial z_y} = 0$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Further method to be investigated

- Least squares formulation:

$$J(z) = \int \int \left((z_x - p)^2 + (z_y - q)^2 \right) dx dy$$

- Extremum points are given by the Euler-Lagrange equation:

$$\frac{\partial J}{\partial z} - \frac{d}{dx} \frac{\partial J}{\partial z_x} - \frac{d}{dy} \frac{\partial J}{\partial z_y} = 0$$

- Poisson equation is obtained by substituting J from (1) in (2):

$$0 - 2 \frac{\partial}{\partial x} (z_x - p) - 2 \frac{\partial}{\partial y} (z_y - q) = 0$$

$$z_{xx} - p_x + z_{yy} - q_y = 0$$

$$\nabla^2 z = \text{div}(p, q)$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

More general approach of Height from Gradients

- New functionnal J to minimize [Agrawal et al., 2009]:

$$J = \int \int E(z, p, q, z_x, z_y) dx dy$$

where E is a continuous differentiable function.

- By using Euler-Lagrange equations and considering the following form:

$$\begin{cases} \frac{\partial E}{\partial z_x} = f_1(z_x, z_y) - f_3(p, q) \\ \frac{\partial E}{\partial z_y} = f_2(z_x, z_y) - f_4(p, q) \end{cases}$$

where f_i are 4 different functions that should satisfy the integrability constraint $\frac{\partial^2 E}{\partial z_y \partial z_z} = \frac{\partial^2 E}{\partial z_z \partial z_y}$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

More general approach of Height from Gradients

- New functionnal J to minimize [Agrawal et al., 2009]:

$$J = \int \int E(z, p, q, z_x, z_y) dx dy$$

where E is a continuous differentiable function.

- By using Euler-Lagrange equations and considering the following form:

$$\begin{cases} \frac{\partial E}{\partial z_x} = f_1(z_x, z_y) - f_3(p, q) \\ \frac{\partial E}{\partial z_y} = f_2(z_x, z_y) - f_4(p, q) \end{cases}$$

where f_i are 4 different functions that should satisfy the integrability constraint $\frac{\partial^2 E}{\partial z_y \partial z_z} = \frac{\partial^2 E}{\partial z_z \partial z_y}$

New formulation

$$\operatorname{div}(f_1(z_x, z_y), f_2(z_x, z_y)) - \frac{\partial E}{\partial z} = \operatorname{div}(f_3(p, q), f_4(p, q))$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

More general approach of Height from Gradients

- This generalized equation represent a continuum of solutions:
 - Poisson solver,
 - Frankot-Chelappa algorithm,
 - and more solutions

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

More general approach of Height from Gradients

- This generalized equation represent a continuum of solutions:
 - Poisson solver,
 - Frankot-Chelappa algorithm,
 - and more solutions

The diagram illustrates a spectrum of methods from **Isotropic** to **Anisotropic**. It features four icons representing different approaches: **Poisson Solver** (a yellow circle), **Alpha-Surface** (a plus sign), **M-estimator** (a cross with a plus sign), and **Diffusion** (a plus sign). Below this, the word **Scaling** is centered.

	$f_1(z_x, z_y)$	$f_2(z_x, z_y)$	$f_3(p, q)$	$f_4(p, q)$
Poisson solver	Z_x	Z_y	p	q
1. α -surface	$b_x Z_x$	$b_y Z_y$	$b_x p$	$b_y q$
2. M-estimators	$w_x Z_x$	$w_y Z_y$	$w_x p$	$w_y q$
3. Regularization	$w_x Z_x$	$w_y Z_y$	p	q
4. Diffusion	$d_x Z_x + d_y Z_y$	$d_x Z_x + d_y Z_y$	$d_x p + d_y q$	$d_x p + d_y q$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outline

1

How to measure polarization ?

- Polarization contrast measurement
- Simplified polarization imaging
- Stokes polarization imaging
- Polarization cameras

2

Some applications

- Unpolarized lightning
- Polarized lightning

3

Shape from Polarization

- Principle
- Surface normals
- Height from gradient
- A prototype

4

Catadioptric calibration

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Experimental set-up

- Object to inspect:



- Experimental set-up:



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Software overview (LabVIEW)



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration


Conclusion

Bibliography

Software overview (LabVIEW)



ρ



φ

- Time:
- 3.6s

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Software overview (LabVIEW)



p



q

- Time:
- 3.6s
- 2.4s + 0.5s

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Software overview (LabVIEW)



z

- Time:
- 3.6s
- 2.4s + 0.5s
- 1.2s

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Software overview (LabVIEW)



z

$\Rightarrow 7.7\text{s}$

- Time:
- 3.6s
- 2.4s + 0.5s
- 1.2s

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Calibration step

Constraint

The relationship between the degree of polarization ρ and the angle θ depends on the refractive index of the object.

- refractive index known
- calibration step

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Calibration step


Constraint

The relationship between the degree of polarization ρ and the angle θ depends on the refractive index of the object.

- refractive index known
- calibration step



degree of polarization ρ



zenith angle θ

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion



Bibliography

Calibration step

Constraint

The relationship between the degree of polarization ρ and the angle θ depends on the refractive index of the object.

- refractive index known
- calibration step



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration


Conclusion

Bibliography

Quantitative evaluation of the method



$$\hat{n} = 1.5 + 2.89i, \chi^2 = 3.95 \times 10^{-7}$$



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration


Conclusion

Bibliography


Quantitative evaluation of the method



$$\hat{n} = 1.5 + 2.89i, \chi^2 = 3.95 \times 10^{-7}$$



- Computed error: $\|\vec{e}\| = \|\vec{n}_{th} - \vec{n}_m\|$



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Quantitative comparisons

- Comparisons with the Replica and the Minolta scanners:



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Quantitative comparisons

- Comparisons with the Replica and the Minolta scanners:



	Prototype	Replica	Minolta
$\ \vec{e}\ $	0.0572	0.0620	0.0765
θ	0.0239	0.0401	0.0455
ϕ	0.2359	0.1388	0.2554

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Inspection

- Reference object:



- Object to inspect:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Inspection


- Reference object:



- Object to inspect:



- Map deviation:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Brief conclusion

Pros

- 3D reconstruction of highly reflective surfaces
- Easy to implement (if the optical device is available)
- Sensitive to the surface gradients

Cons

- Refractive index is required or must be estimated
- Smooth surface (because of the integration process)
- The resolution cannot be estimated

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion


Bibliography

Introduction

This work was initiated by the Ca.Vi.A.R. (Catadioptric VIision for Aerial Robots) project: 2006-2009.

Catadioptric

- dioptric: science of refracting elements (lenses)
 - catoptric: science of reflecting surfaces (mirrors)
-
- Evaluation of the panoramic vision contribution for aerial robots:
 - Image processing applied to catadioptric image formation
 - **Calibration of catadioptric sensors**
 - 3D reconstruction, SLAM (Simultaneous Localization And Mapping)



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Main idea

PhD thesis

- Shape from Polarization applied to specular metallic surfaces
 - Mirrors used in Catadioptric sensors are specular
→ Try to use polarization imaging to provide useful information for the calibration process

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Main idea

PhD thesis

- Shape from Polarization applied to specular metallic surfaces
 - Mirrors used in Catadioptric sensors are specular
 → Try to use polarization imaging to provide useful information for the calibration process
- Common calibration methods for omnidirectional catadioptric sensors assume that:
 - ① mirror shape is perfectly known
 - ② alignment of the sensor is perfect
 - ③ projection model can be easily parametrized

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Main idea

PhD thesis

- Shape from Polarization applied to specular metallic surfaces
 - Mirrors used in Catadioptric sensors are specular
 → Try to use polarization imaging to provide useful information for the calibration process
- Common calibration methods for omnidirectional catadioptric sensors assume that:
 - ① mirror shape is perfectly known
 - ② alignment of the sensor is perfect
 - ③ projection model can be easily parametrized
- Relax these three constraints by using:
 - the generic concept developed by [Sturm, 2005]
 - polarization imaging

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Polarization parameters of common mirrors



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration

Conclusion

Bibliography

Recall of the relationship between the normals and the polarization parameters



Required conditions

- Unpolarized lightning
- Highly reflective surface
- Telecentric lens

$$\vec{n} = \begin{pmatrix} p = \tan \theta \cos \phi \\ q = \tan \theta \sin \phi \\ 1 \end{pmatrix} \Rightarrow (\phi, \theta) ?$$

Fresnel's coefficients

- Angle of polarization: $\varphi \Rightarrow \phi$
- Degree of polarization:
 $\rho \Rightarrow \theta$

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography


Recall of the relationship between the normals and the polarization parameters

- From the degree of polarization ρ to the θ angle



$$\rho(\theta) = \frac{2n \tan \theta \sin \theta}{\tan^2 \theta \sin^2 \theta + |\hat{n}|^2}$$

- From the angle of polarization φ to the ϕ angle



$$\phi = \varphi \pm \frac{\pi}{2}$$

⇒ambiguity in the determination of ϕ

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to solve the ambiguity ?

- computation of a segmented image I_{quad} :



- the center is approximately detected

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to solve the ambiguity ?

- computation of a segmented image I_{quad} :



- the center is approximately detected
- the segmented image is created
(orientation between 0 and $\pi/2$)

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

How to solve the ambiguity ?

- computation of a segmented image I_{quad} :



- the center is approximately detected
- the segmented image is created
(orientation between 0 and $\pi/2$)
- combination of the I_{quad} image and the φ image

- algorithm:

$$\textcircled{1} \quad \phi = \varphi - \pi/2$$

$$\textcircled{2} \quad \phi = \phi + \pi, \text{ if }$$

- $I_{quad} = 1$
- $(I_{quad} = 3) \wedge (\phi \geq 0)$
- $(I_{quad} = 0) \wedge (\phi \leq 0)$



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Non-parametric calibration

Generic concept

- [Sturm and Ramalingam, 2004]
- A camera is fully described by:
 - the coordinates of the rays (given in some local coordinate frame)
 - the mapping between rays and pixels (basically a simple indexing)



Sturm

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Non-parametric calibration

Generic concept

- [Sturm and Ramalingam, 2004]
- A camera is fully described by:
 - the coordinates of the rays (given in some local coordinate frame)
 - the mapping between rays and pixels (basically a simple indexing)



Sturm

- A light ray can be described by a pair of points:

$$\mathbf{A} = [\begin{array}{ccc} x_a & y_a & z_a \end{array}]^T, \mathbf{B} = [\begin{array}{ccc} x_b & y_b & z_b \end{array}]^T$$

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Height computation

- Point **A** on the surface of the mirror:
⇒ the 3D surface is computed by integrating the surface normals [Frankot and Chellappa, 1988] :

Frankot Chellappa

$$\tilde{f}(u, v) = \frac{-ju\tilde{p}^* - jv\tilde{q}^*}{u^2 + v^2}$$

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


Height computation

- Point **A** on the surface of the mirror:
⇒ the 3D surface is computed by integrating the surface normals [Frankot and Chellappa, 1988] :

Frankot Chellappa

$$\tilde{f}(u, v) = \frac{-ju\tilde{p}^* - jv\tilde{q}^*}{u^2 + v^2}$$

- Example of reconstruction (hyperbolic mirror):



How to measure polarization?
Polarization contrast measurement
Simplified polarization imaging
Stokes polarization imaging
Polarization cameras

Some applications
Unpolarized lightning
Polarized lightning

Shape from Polarization
Principle
Surface normals
Height from gradient
A prototype

Catadioptric calibration


Conclusion

Bibliography

3D ray computation

- Point B:

$$\mathbf{B} = \mathbf{A} + k \begin{bmatrix} \tan 2\theta \cos \phi \\ \tan 2\theta \sin \phi \\ 1 \end{bmatrix}$$



where k is a non-null constant

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

3D ray computation


- Point B:

$$\mathbf{B} = \mathbf{A} + k \begin{bmatrix} \tan 2\theta \cos \phi \\ \tan 2\theta \sin \phi \\ 1 \end{bmatrix}$$



where k is a non-null constant

- Triangulation:



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Simulation of the 3D reconstruction error

- ① Give 3D points
- ② Compute points reflected on the mirror
- ③ Simulate polarization calibration
(noise added on the parameters)
- ④ Triangulate and compute the average error reconstruction
 - Linear Eigen method
 - Mid-Point method



How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Simulation of the 3D reconstruction error

- ① Give 3D points
- ② Compute points reflected on the mirror
- ③ Simulate polarization calibration (noise added on the parameters)
- ④ Triangulate and compute the average error reconstruction
 - Linear Eigen method
 - Mid-Point method



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Simulation of the 3D reconstruction error

- ① Give 3D points
- ② Compute points reflected on the mirror
- ③ Simulate polarization calibration
(noise added on the parameters)
- ④ Triangulate and compute the average error reconstruction
 - Linear Eigen method
 - Mid-Point method



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Simulation of the 3D reconstruction error

- ① Give 3D points
- ② Compute points reflected on the mirror
- ③ Simulate polarization calibration
(noise added on the parameters)
- ④ Triangulate and compute the average error reconstruction
 - Linear Eigen method
 - Mid-Point method



How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype



Cataadioptric calibration

Conclusion

Bibliography

Influence of the polarization parameters measurement

- Calibration by polarization imaging
 - the two angles θ and ϕ are measured
 - the height z of the mirror is computed by integration
- Parameters used for the simulation
 - misalignment of 7 degrees
 - 100 reconstructions of the scene for each noise level
- Average error reconstruction of the scene
 - without the shape of the mirror (no integration process)
 - with the shape of the mirror (with integration process)



[Morel and Fofi, 2007]

How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Reconstruction error

induced by noisy measurement of the θ angle



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Reconstruction error

induced by noisy measurement of the ϕ angle



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Reconstruction error

induced by noisy computation of the mirror height z



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype


Catadioptric calibration

Conclusion

Bibliography

Indoor scene

- Catadioptric system on a 4 axis stage:



- x [0, 1370mm]
- y [0, 990mm]
- z [0, 440mm]
- θ [-160, 160]

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration


Conclusion

Bibliography

3D reconstruction of some interest points



Hyperbolic mirror



Spherical mirror

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient


A prototype

Catadioptric calibration


Conclusion

Bibliography

3D reconstruction of some interest points



Hyperbolic mirror



Spherical mirror

Reconstruction errors due to:

- small displacement of the sensor in the scene
- points are manually selected
- “direct” triangulation

How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outdoor scene

Mensi[©] 3D scanner used to:

- locate the catadioptric sensor
- provide a ground truth map



How to measure polarization

?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Outdoor scene

Mensi[©] 3D scanner used to:

- locate the catadioptric sensor
- provide a ground truth map



How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient




A prototype

Catadioptric calibration

Conclusion

Bibliography

Outdoor scene



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Conclusion

- Polarimetric cameras are increasing applications of polarization imaging
 - Robotics
 - Medical imaging

How to measure polarization ?

Polarization contrast measurement

Simplified polarization imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration


Conclusion

Bibliography

Conclusion


- Polarimetric cameras are increasing applications of polarization imaging
 - Robotics
 - Medical imaging
- Polacatadioptric sensor

Polarization by reflection



⇒ Outdoor water hazard detection

Polarization by scattering



⇒ attitude estimation (such as bees)

How to measure polarization

?

Polarization contrast
measurementSimplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography


Conclusion

More applications in Robotics

- Polarization by reflection: road tracking



- Polarization by scattering: coarse depth estimation
[Schechner et al., 2003]



How to measure polarization
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography I



Agrawal, A. and Raskar, R. (2007).

Gradient domain manipulation techniques in vision and graphics.
ICCV course.



Agrawal, A., Raskar, R., and Chellappa, R. (2009).

Surface reconstruction from gradient fields via gradient transformation.

International Journal of Computer Vision.



Alouini, M., Dolfi, D., Grisard, A., Lallier, E., Goudail, F., and Réfrégier, P. (2004).

Imagerie polarimétrique et multispectrale active : vers la détection et la reconnaissance d'objets de très faible contraste.

In *GDR Journées Imagerie Polarimétrique*.



Anastasiadou, M., Martino, A. D., Clement, D., Liège, F., Laude-Boulesteix, B., Quang, N., Dreyfuss, J., Huynh, B., Nazac, A., Schwartz, L., and Cohen, H. (2008).

Polarimetric imaging for the diagnosis of cervical cancer.

physica status solidi (c), 5(5):1423–1426.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography II



Atkinson, G. and Hancock, E. R. (2006).

Recovery of surface orientation from diffuse polarization.

IEEE Trans. Image Processing, 15(6):1653–1664.



Bolle, R., Connell, J., Haas, N., Mohan, R., and Taubin, G. (1996).

Veggievision: A produce recognition system.

In *Workshop on Applications of Computer vision*, pages 244–251.



Born, M. and Wolf, E. (1999).

Principles Of Optics.

Cambridge, 7 edition.



Chen, H. and Wolff, L. (1998).

Polarization phase based method for material classification in computer vision.

International Journal of Computer Vision, 28(1):73–83.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography III



Clark, J., Trucco, E., and Wolff, L. (1997).

Using light polarization in laser-scanning.

Image and Vision Computing, 15(2):107–117.



De Martino, A. and Laude-Boulesteix, B. (2004).

Polarimètre de mueller, imageur à cristaux liquides.

In *GDR Journées Imagerie Polarimétrique*.



Frankot, R. and Chellappa, R. (1988).

A method for enforcing integrability in shape from shading algorithms.

IEEE Trans. Pattern Analysis and Machine Intelligence, 10(4):439–451.



Horn, B. and Brooks, M. (1986).

The variational approach to shape from shading.

Computer Vision Graphics and Image Processing, 33(2):174–208.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography IV



Ikeuchi, K. (1983).

Constructing a depth map from images.

In *MIT AI Memo*.



Jacques, S. L., Ramella-Roman, J. C., and Lee, K. (2002).

Imaging skin pathology with polarized light.

Journal of Biomedical Optics, 7(3):329–340.



Kalayjian, Z., Andreou, A.G. and Wolff, L., and Sheppard, N. (1996).

A polarization contrast retina that uses patterned iodine-doped pva film.

In *European Solid-State Circuits Conference*, pages 308–311,
Neuchatel, Switzerland.



Kalayjian, Z., Andreou, A.G. and Wolff, L., and Sheppard, N. (1997).

1d polarization retina.

Electronic Letters, 33(1):38–40.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography V



Karaçali, B. and Snyder, W. (2003).

Reconstructing discontinuous surfaces from a given gradient field using partial integrability.

Computer Vision and Image Understanding, 92(1):78–111.



Koshikawa, K. (1979).

A polarimetric approach to shape understanding.

In *International Joint Conference on Artificial Intelligent*, pages 493–495, Tokyo, Japan.



Kovesi, P. (2003).

Shapelets correlated with surface normals produce surfaces.

Technical report, School of Computer Science & Software Engineering.



Miyazaki, D., Kagesawa, M., and Ikeuchi, K. (2004).

Transparent surface modeling from a pair of polarization images.

IEEE Trans. Pattern Analysis and Machine Intelligence, 26(1):73–82.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography VI



Miyazaki, D., Saito, M., Sato, Y., and Ikeuchi, K. (2002).

Determining surface orientations of transparent objects based on polarization degrees in visible and infrared wavelengths.

Journal of the Optical Society of America A, 19(4):687–694.



Morel, O. and Fofi, D. (2007).

Calibration of catadioptric sensors by polarization imaging.

In *IEEE International Conference on Robotics and Automation*, Roma, Italy.

ACTi C 07- 37.



Morel, O., Stoltz, C., Meriaudeau, F., and Gorria, P. (2006).

Active lighting applied to 3d reconstruction of specular metallic surfaces by polarization imaging.

Applied Optics, 45(17):4062–4068.

ACL C 06- 6.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography VII



Nayar, S. K. (1997).

Catadioptric omnidirectional camera.

In *CVPR '97: Proceedings of the 1997 Conference on Computer Vision and Pattern Recognition (CVPR '97)*, page 482, Washington, DC, USA. IEEE Computer Society.



Rahmann, S. (2003).

Reconstruction of quadrics from two polarization views.

In *Iberian Conference on Pattern Recognition and Image Analysis (IbPRIA03)*, Springer, LNCS 2652, Mallorca, Spain, pages 810–820.



Ropers, G., Gorre, G., Floch, A. L., Enoch, J., and Lakshminarayanan, V. (2011).

A depolarizer as a possible precise sunstone for viking navigation by polarized skylight.

Proceedings of The Royal Society.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography VIII



Saito, M., Sato, Y., Ikeuchi, K., and Kashiwagi, H. (1999).

Measurement of surface orientations of transparent objects using polarization in highlight.

Journal of the Optical Society of America, 16(9):2286–2293.



Schechner, Y., Kiryati, N., and Basri, R. (2000).

Separation of transparent layers using focus.

International Journal of Computer Vision, 39(1):25–39.



Schechner, Y. Y., Narasimhan, S. G., and Nayar, S. K. (2003).

Polarization-based vision through haze.

Applied O, 42(3):511–525.



Sturm, P. (2005).

Multi-view geometry for general camera models.

In *IEEE Computer Vision and Pattern Recognition*, volume 1, pages 206–212, Washington, DC, USA. IEEE Computer Society.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography IX



Sturm, P. and Ramalingam, S. (2004).

A generic concept for camera calibration.

In *European Conference on Computer Vision*, volume 2, pages 1–13, Prague, Czech Republic. Springer.



Terrier, P. and Devlaminck, V. (2001).

A self calibrated image acquisition system for polarization estimation.

In *International Conference on Physics in Signal and Image Processing*, Marseille, France.



Tyo, J. (1998).

Optimum linear combination strategy for an n-channel polarization-sensitive imaging or vision system.

Journal of the Optical Society of America A, 15(2):359–366.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography X



Tyo, J. (2000).

Noise equalization in stokes parameter images obtained by use of variable-retardance polarimeters.

Optics Letters, 25:16.



Tyo, J., E.N. Pugh, J., and Engheta, N. (1998).

Colorimetric representation for use with polarization-difference imaging of objects in scattering media.

Journal of the Optical Society of America A, 15(2):367–374.



Vedel, M., Breugnot, S., and N., L. (2011).

Full stokes polarization camera.

In *SPIE Optical Engineering and Applications*, volume 8160.



Wallace, A., Liang, B., Trucco, E., and Clark, J. (1999).

Improving depth image acquisition using polarized light.

International Journal of Computer Vision, 32(2):87–109.

How to measure polarization?
?

Polarization contrast
measurement

Simplified polarization
imaging

Stokes polarization imaging

Polarization cameras

Some applications

Unpolarized lightning

Polarized lightning

Shape from Polarization

Principle

Surface normals

Height from gradient

A prototype

Catadioptric calibration

Conclusion

Bibliography

Bibliography XI



Wolff, L. B. and Andreou, A. (1995).

Polarization camera sensors.

Image and Vision Computing, 13(6):497–510.



Wolff, L. B. and Boult, T. E. (1991).

Constraining object features using a polarization reflectance model.

IEEE Trans. Pattern Analysis and Machine Intelligence,
13(7):635–657.



Wolff, L. B., Mancini, T. A., Pouliquen, P., and Andreou, A. G. (1997).

Liquid crystal polarization camera.

IEEE Trans. Robotics and Automation, 13(12):195–203.