


Continuity test

Check continuity between points connected in the two images:

3.3V net



Supply 3.3V power to the V+ pin and the GND (G) pin at the highlighted test points. Verify all boards behave “normally”: no magic smoke, draws nonzero current, does not draw more than 0.3A. Components may be warm but should not be hot to touch after running for any amount of time.

