


VEILINK 六轴机械臂

VEILINK Arm

零位运动学模型
Kinematic Model - Zero Pose



箭头方向：关节正轴 $+z_{i-1}$ ，正转方向按右手定则
Arrow: Positive joint axis $+z_{i-1}$, positive rotation follows the right-hand rule