

Inspection field record

Report DEMO-IR-001 | Revision B | Page 1 of 2

This sample contains invented equipment and observations.

It is not an MRPL record, standard, or engineering instruction.

Inspection date: 01 September 2026

Equipment scope: DEMO-P-101, DEMO-L-201, DEMO-V-301

Purpose: rehearse confidential-document review locally.

Observations

DEMO-P-101: visible staining near the pump flange.

The leak source has not been confirmed.

DEMO-L-201: surface corrosion visible at measurement point T1.

DEMO-V-301: instrument reading written without a unit.

Field measurements are recorded on page 2.

No maintenance estimate or approval was supplied.

Inspection field record

Report DEMO-IR-001 | Revision B | Page 2 of 2

Recorded measurements

DEMO-L-201 / T1: measured wall thickness = 8.2 mm

Measurement method: ultrasonic spot reading.

DEMO-V-301: instrument reading = 18 [unit not recorded].

DEMO-P-101: flange staining; no leak-rate measurement.

Training review references

Use the supplied DEMO-SOP-001 for review steps.

No retirement thickness or design limit is provided.

Do not infer safe operation or equipment acceptance.

Unresolved fields

Cost estimate: not provided.

Responsible owner: not assigned.

Due date: not assigned.

Engineering approval: not granted.