
说明

汇报CEID List, VID List, AlarmList

在Host通过S1F13和S1F14连接到Equipment后,

- Host会通过S5F5询问Alarm List, Equipment要发送S5F6汇报Alarm List, 这个表示向主机汇报所有的定义的Alarm
- Host会通过S5F7询问Enable Alarm List, Equipment要发送S5F8汇报Enable Alarm List, 这个表示向主机汇报所有 启用的Alarm



■ Host会通过S1F23询问CEID List, Equipment要发送S1F24汇报CEID List


Tests GEM Capab	ilities	ties Messages			
Alarms	Colle	ction Events:			
Collection Events >	ID	Name	Enabled	Associated Variables	
Event Reports	0	ControlStateLocal			
Status Variables	1	ControlStateRemote			
Equipment Constants	2	EquipmentOffline			
Data Variables	3	MaterialReceived			
Recipes	4	MaterialRemoved			
Trace Reports	5	MessageRecognition	✓		
Terminal	6	OperatorCommandIssued		6	
	7	PPChange		3, 4	
	8	PPSelected			

- Host会通过S1F11询问SVID List, Equipment要发送S1F12汇报SVID List
- Host会通过S1F3询问SVID的值, Equipment要发送S1F4汇报SVID的值


Tests GEM Capabilities Messages								
Alarms	ID	Name	Format	Value				
Collection Events	15	LastPPRequested	A					
Event Reports	801	SV1	U4	5				
Status Variables >	802	SV2	A	Hello world				
Equipment Constants	803	SV3	Во	True				
Data Variables	804	SV4	11	0				
Recipes	805	SV5	F4	0				
Trace Reports	2004	Clock	A	2023021717105155				
Terminal 2008		MDLN	A	MODEL				
	2009	PPExecName	A					
	2015	SOFTREV	A	00.01				
	2016	SpoolCountActual	U4	0				
	2017	SpoolCountTotal	U4	0				
	2018	SpoolFullTime	A					
	2019	SpoolStartTime	A					
	2026	AL ADMOCNIADI ED	ı					

■ Host会通过S2F29询问ECID List, Equipment要发送S2F30汇报ECID List

■ Host会通过S2F13询问ECID的值,Equipment要发送S2F14汇报ECID的值



■ Host会通过S1F21询问DVID List, Equipment要发送S1F22汇报DVID List



■ Host会通过S7F19询问设备Recipe文件的目录,Equipment要发送S7F20汇报PPID的列表

必备命令如下:

S5F6, S5F8, S1F24, S1F12, S1F4, S2F30, S2F14, S1F22, S7F20

Recipe的格式说明

需要写一个文档,告诉通富的IT,传送的Recipe怎么解析。传送Recipe时,不是直接传送文件,是传送文件里的内容。