Exception Report

Team Unknown: Noah McMichael, Zhaoning Qiu, Christopher Bailey

Current quirks include:

- Leaving in old unused variables since it's late and down want to break current code.
- Retaining the old 2000-character file input buffer from a previous iteration that could read directly from files since it could impact the code in a negative way.
- Old test_2.s68 filename in beginning of code, left to not break things.
- Old commented out methods that are inconsequential.
- No 32-bit displacement maybe?
- If the instruction is MOVEM D0-D7, it will print D0/D1/D2/D3/D4/D5/D6/D7.
- Sometimes extra leading zeros.