

# **Daily Construction Report**

Project:	Sherwood Forest Elemen	tary Scho	ol					Job:		14-02-002
Location:	4801 Maid Marion Drive							Report #:		1
Fair Working	Days To Date:							Date:		10/25/2014
Weather Del	ays To Date:			Weath	er Condition	1:		Day:		Saturday
Is Today Clai	med as Weather Day?		N	Precipi	tation Amo	unt:		Temp:	Lov	v High
Critical Path	Work Effected?		N							
		Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q Sch

Project:	Sherwood Forest Elementary School					Job:	14-	02-002
Location:	4801 Maid Marion Drive				Rep	ort #:		1
Fair Working	Days To Date:					Date:	02/2	2/2015
Weather Dela	ays To Date:		Weather Condition:	No Work		Day:		Sunday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		1	Temp:	Low	High
Critical Path V	Work Effected?	Ν						

Project:	Sherwood Forest Elementary School				Jo	<b>b:</b> 1	14-02-002	
Location:	Location: 4801 Maid Marion Drive Fair Working Days To Date:						1	
Fair Working	Days To Date:				Da	nte: 09	9/16/2014	
Weather Dela	ays To Date:		Weather Condition:	Humid	D	ay:	Tuesday	
Is Today Clair	med as Weather Day?	Ν	Precipitation Amount:		Ter	np: Low	High	
Critical Path	Work Effected?	N				77	91	

Employee Work Accomplished

Tanner Broughton

Tanner Broughton

Alisha White

Remarks: SUBMITTED DAC SUBMITTAL TO City of NO.

Communication with Subcontractors: Met with Malone Electric.

Met with Discount Permits, set up SWPPP.

Visitors: Met with Entergy Onsite

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	tion: 4801 Maid Marion Drive  Working Days To Date:  Weather Condition: Hot - Humid				Report #	:	1
Fair Working	Days To Date:				Date	: 10,	/09/2014
Weather Dela	ays To Date:		Weather Condition:	Hot - Humid	Day		Thursday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path	Work Effected?	N				78	90

Employee						Work Accomplished	
Tanner Broughton							
George Caillouet							
Chuck Hutchinson							
Tanner Broughton							
George Caillouet							
Chris Cole							
Chuck Hutchinson							
				2nd	2nd		
	Sub	Sub		Tier	Tier		S O Sch
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S Q Sch
Bayou Tree Service Inc.	1	4					
Dading, Marques & Associates LLC	2	6					
Phoenix Constructors LLC	3	8					
Phoenix Constructors LLC	3	8					
Ace Fence & Gate LLC	3	6	_				
	12	32	_				

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	10/	13/2014
Weather Dela	ays To Date:		Weather Condition:	Warm/Windy/Rain in the Evenir	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				60	87

Employee						Work Accomplished		
Tanner Broughton								_
Chuck Hutchinson								
Mark Murphy								
Chris Cole								
Tanner Broughton								
Mark Murphy								
George Caillouet								
Chuck Hutchinson								
Alisha White								
Chris Cole								
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
Phoenix Constructors LLC	4	8					E	OS
Phoenix Constructors LLC	5	8	_					
	9	16						

Project:	Sherwood Forest Elementary So	hool			Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	10/	/20/2014
Weather Dela	ays To Date:	0	Weather Condition:	Clear	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				61	79

Employee						Work Accomplished			
Tanner Broughton									
Chuck Hutchinson									
Mark Murphy									
Chuck Hutchinson									
Tanner Broughton									
Mark Murphy									
Alisha White									
Alisha White									
Chuck Hutchinson									
Mark Murphy									
Tanner Broughton									
Chuck Hutchinson									
Tanner Broughton									
Chuck Hutchinson									
Tanner Broughton									
, and the second				2nd	2nd				
<b>-</b>	Sub	Sub		Tier	Tier			_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q	Sch
Dading, Marques & Associates LLC	3	8				Laying out for test pile	F -	F	OS
Phoenix Constructors LLC	1	8				Cut building pad	F -		
Phoenix Constructors LLC	1	8				Clearing Building pad	E		
Phoenix Constructors LLC	3	8				Finishing Silt Fence	E F		00
Phoenix Constructors LLC	4 2	8				Building Haul Road at South Section of site.	F		os os
Phoenix Constructors LLC  Gulf South Engineering & Testing Inc	2	8				Finishing Haul Rd	E		OS
Gulf South Engineering & Testing Inc	2	8				Preparing for testing piles.  Testing Piles as installed.	E		03
Gulf South Engineering & Testing Inc	2	8				Monitoring Installaion of Test Pile	F		OS
Gulf South Engineering & Testing Inc	1	4				Finishing, cleaning up from testing work.	F		00
Berkel & company Contractors Inc	6	8				Offloading, mobilizing Crane	F	Е	OS
Berkel & company Contractors Inc	7	8				Mobilizing, setting up crane	F	E	OS
Berkel & company Contractors Inc	8	8				Installed 8 Test Pile.	E	Ε	OS
Berkel & company Contractors Inc	8	8				Completed Test Pile INstallation	E	E	OS
GWJ Construction and Industrial Supply LLC	5	8	CMC Delivered Stra	i		Off loading, stocking material	E		OS
GWJ Construction and Industrial Supply LLC	5	8	CMC Rebar Supplie	ď		Finished Tying Rebar cages for piles	E	F	
	5 5	8	CMC Rebar Supplie	ı,		Finished Tying Rebar cages for piles Finished tying test Pile cages.	E E	F F	os

Material Delivered: Grout for Piles

Project:	<b>Sherwood Forest Elementary School</b>				Job	14	4-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	: 10,	/27/2014
Weather Dela	ys To Date:		Weather Condition:	Partly Cloudy	Day	:	Monday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path V	Vork Effected?	N				68	81

_								
Employee						Work Accomplished		
Chuck Hutchinson								
Tanner Broughton								
Mark Murphy								
Mark Murphy								
Chuck Hutchinson								
Tanner Broughton								
Chuck Hutchinson								
Mark Murphy								
Tanner Broughton								
Chuck Hutchinson								
Mark Murphy								
Tanner Broughton								
Chuck Hutchinson								
Mark Murphy								
Tanner Broughton								
Chris Cole								
				2nd	2nd			
	Sub	Sub		Tier	Tier		_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
Bernhard Mechanical Contractors, L.L.C.	1	4				Hooked up water to trailers.	F	
Phoenix Constructors LLC	4	4				Cleaning up Silt Fence	F	
Gulf South Engineering & Testing Inc	2	8	GLR Testing			PIT Testing	F	
Gulf South Engineering & Testing Inc	2	8	GLR			PIT Testing	F	
	9	24						

Project:	Sherwood Forest Elementary School				Jol	<b>):</b> 1	14-02-002
Location:	4801 Maid Marion Drive				Report	<b>#:</b>	1
Fair Working	Days To Date:				Dat	<b>e:</b> 11	1/03/2014
Weather Dela	ays To Date:		Weather Condition:	Clear	Da	y:	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Tem	<b>p:</b> Low	High
Critical Path	Work Effected?	N				64	75

Employee						Work Accomplished		
Tanner Broughton								
Chuck Hutchinson								
Mark Murphy								
Alisha White								
Chris Cole								
Chuck Hutchinson								
Mark Murphy								
Tanner Broughton								
Alisha White								
Cole Chris								
Alisha White								
Chuck Hutchinson								
Tanner Broughton								
Mark Murphy								
Mark Murphy								
Chuck Hutchinson								
Tanner Broughton								
Chris Cole								
				2nd	2nd			
Subcontractor	Sub	Sub	2nd Tier	Tier	Tier	NA/anda A accomplished	S	Q Sch
	Wrkrs	Hrs	zna Her	Wrkrs	Hrs	Work Accomplished		
Phoenix Constructors LLC	2	8				Putting Silt Fence at Tree Protection Areas	F	OS
Phoenix Constructors LLC	1	8				Hauled Off Spoils	F	
Multivista Construction Documentation	1	1				Taking Photos	F	
Berkel & company Contractors Inc	8	8				Installed Reaction Pile	F	
Berkel & company Contractors Inc	8	8				Installing steel for test pile program.	F	
	20	33						

Project:	Sherwood Forest Elementary School				Jo	b:	14-02-0	002
Location:	4801 Maid Marion Drive				Report	#:		1
Fair Working	Days To Date:				Da	<b>te:</b> 1	1/10/2	014
Weather Del	ays To Date:		Weather Condition:	Clear/Cold	D	ау:	Mon	day
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Ten	np: Low	, Н	ligh
Critical Path	Work Effected?	Ν				58	3	70

**Work Accomplished** 

Tanner Broughton  Alisha White  Chuck Hutchinson									
Chuck Hutchinson									
				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
Phoenix Constructors LLC	3	24				Cut trees down	F	F	OS
Berkel & company Contractors Inc	1	8				Set Up Instruments start loading pile	F	F	
Berkel & company Contractors Inc	2	16				Set Up and Layout	F	F	OS
Berkel & company Contractors Inc	2	16	0			Test Piles Assembly	F	F	OS

Remarks:

8

64

**Employee** 

Chuck Hutchinson

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/	19/2014
Weather Dela	ays To Date:		Weather Condition:	Sunny Mild	Day:	Wed	dnesday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				31	58

Employee						Work Accomplished		
Gary McCaan								
Gary McCaan								
Gary McCaan						Excavated existing soil and install fabric and stone for apron.		
				2nd	2nd			
	Sub	Sub		Tier	Tier		_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
Phoenix Constructors LLC	1	8	0			Clean up site, dress up silt fence	F	F OS
GWJ Construction and Industrial Supply LLC	1		_			Visit		
	2	8						

Communication with Subcontractors: Discussed rebar delivery schedule for monday. Time of delivery, equipment and crew to unload.

Certified operator required for forklift

**Material Delivered:** None **Visitors:** George White JR.

Notes: Phoenix cleans site, dresses up silt fence.

Phx scheduled for monday to complete cleaning site. Piles and spils from test pile operations. Will fill low spots in building footprint. Rain is forecasted this weekend.

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/7	24/2014
Weather Dela	ys To Date:		Weather Condition:	Mild and Windy	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				60	68

Employee						Work Accomplished			
Gary McCaan									
Horace Morman									
Chris Cole						Half Day			
Gary McCaan									
Gary McCaan									
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	s	Q	Sch
Phoenix Constructors LLC	2	2	0			Picked up skid steer and mini exc. Hauled to diff site due to rain	F	F	OS
Phoenix Constructors LLC	1	8				Leveling building pad. Moving dirt to stockpile areas	F	F	OS
<b>LayDown</b> GWJ Construction and Industrial Supply LLC	2	6	0			Unloaded rebar deliver and staged material	F	F	OS
GWJ Construction and Industrial Supply LLC	8	64	8			Tying rebar cages for auger piles.	F	F	OS
GWJ Construction and Industrial Supply LLC	5	40	5			Tie rebar cages for piles	F	F	OS
	18	120	_						

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/	01/2014
Weather Dela	ays To Date:		Weather Condition:	Mild, Overcast, early Fog	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				65	72

Employee	Work Accomplished
Gary McCaan	Onsite Supervision
Horace Morman	
Chris Cole	
Tanner Broughton	
Gary McCaan	Onsite Supervision
Horace Morman	Rodman for Layout crew.
Chris Cole	
Tanner Broughton	
Gary McCaan	Onsite Supervision
Horace Morman	Rodman for Layout crew.
Chris Cole	
Alisha White	
Tanner Broughton	
Alisha White	
Mark Murphy	
Tanner Broughton	
Chris Cole	
Horace Morman	Establish top of pile elevations with Berkel.
Benny Boudreaux	Establish top of pile elevations with Berkel.
Gary McCaan	Jobsite Supervision
Eugene Naquin	Performed Orientation
Alisha White	
Mark Murphy	
Tanner Broughton	
Chris Cole	
Horace Morman	
Benny Boudreaux	
Gary McCaan	
Eugene Naquin	
Mark Murphy	
Tanner Broughton	
Chris Cole	
Horace Morman	
Benny Boudreaux	
Gary McCaan	
Area A Benny Boudreaux	
Benny Boudreaux	Laid out control points for Area A. Descrpency found at Property Corners.
· • • · · · · · · · · · · · · · · · · ·	Resolved with Land Surveyor. No issue.
Benny Boudreaux	Laid out control points for Area A. Descrpency found at Property Corners.  Resolved with Land Surveyor. No issue.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/	05/2014
Weather Dela	ays To Date:		Weather Condition:	Partly Cloudy Warm	Day:		Friday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				60	78
			2nd 2nd				

				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
Dading, Marques & Associates LLC	3	12				Layout Pile Locations	F	F	OS
Dading, Marques & Associates LLC	0					Layout Pile Locations	F	F	OS
Gulf South Engineering & Testing Inc	3	10				Grout Testing and observing Pile Installation.	F		
Berkel & company Contractors Inc	1	8				Setting up equipment, planning for install.			
Area A									
Dading, Marques & Associates LLC	3	8				Started Layout for Pile.		F	
Dading, Marques & Associates LLC	3	8				Laying out piles at A and B.		F	
Dading, Marques & Associates LLC	3	8				Laying out piles at A and B.		F	
Phoenix Constructors LLC	2	16				Grease Machines, move spoil material, clean machines	F	F	OS
Phoenix Constructors LLC	2	10				Removing Spoils for Pile Drilling operation.	F	F	OS
Phoenix Constructors LLC	1	10				Remove grout and spoil material from augered piles	F	F	OS
Phoenix Constructors LLC	2	16				Remove grout and spoil material from augered piles	F	F	OS
Gulf South Engineering & Testing Inc	3	30				Grout Testing and drilling observations	F	Е	OS
Gulf South Engineering & Testing Inc	2	20				Testing grout material, observing rebar setting	F	F	OS
Gulf South Engineering & Testing Inc	1	8				Testing grout material, observing rebar setting	F	F	OS
Berkel & company Contractors Inc	7	10	Carlo Ditta			1st Day of auger cast installation. Orientation. Started drilling at 10am.	F	F	OS
Berkel & company Contractors Inc	10	100				Drilled and Pump Augered Piles	F	F	OS
Berkel & company Contractors Inc	10	100				Drilled and Pump Augered Piles	F	F	OS
LayDown									
GWJ Construction and Industrial Supply LLC	8	8	CMC			Tying cages for Augercast Piles	F	F	OS
GWJ Construction and Industrial Supply LLC	7	8	CMC			Tying cages for Augercast Piles	F	F	OS
GWJ Construction and Industrial Supply LLC	7	8	CMC			Tying cages for Augercast Piles	F	F	OS
GWJ Construction and Industrial Supply LLC	12	8	CMC Rebar			Pretying Cages for Auger Piles	F	F	OS
GWJ Construction and Industrial Supply LLC	11	100				Tie Rebar Cages for Piles	F	F	OS
GWJ Construction and Industrial Supply LLC	0		_			Tie Rebar Cages for Piles	F	F	OS
	101	506							

Notes: Grout Material is only delivered until noon. Short day (not 10)

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/	08/2014
Weather Dela	nys To Date:		Weather Condition:	Partly Cloudy Warm	Day:		Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				47	66

March Mulphy	Employee					Work Accomplished			
Control	Mark Murphy								
Rease Name	Tanner Broughton								
Remy Routers	Chris Cole								
Remy Reudmank  Nack Alumphy  Chest Cole  Chest Cole  Gay McCana  Florenge Bourdman  Nack Alumphy  Chest Cole  Chest Cole  Tamer Broughton  Tam	Gary McCaan								
Camer Broughton	Horace Morman								
Carrier Resultance	Benny Boudreaux								
Carry M.Coan  From South Carry  From From South Carry  From From South Carry  From From From From From From From From	Mark Murphy								
Mary Michan   Province   Provin	Tanner Broughton								
Process Anname	Chris Cole								
Marica   M	Gary McCaan								
Mark Murphy	Horace Morman								
Mark Murphy	Benny Boudreaux								
Mark Murphy         5         1 <td< td=""><td>Alisha White</td><td></td><td></td><td></td><td></td><td>Worked on Pay App #4</td><td></td><td></td><td></td></td<>	Alisha White					Worked on Pay App #4			
Gary McCaan         1 <td< td=""><td>Tanner Broughton</td><td></td><td></td><td></td><td></td><td>Meetings with Subcontractors. Revised Pay Application #4</td><td></td><td></td><td></td></td<>	Tanner Broughton					Meetings with Subcontractors. Revised Pay Application #4			
Chris Cole         1         1         Layout at Piles           Benny Boudreaux         1         1         Layout at Piles           Gary McCaan         5         1         1         1           Horace Morman         5         1	Mark Murphy								
Horace Moman	Gary McCaan					Onsite Supervision.			
Renny Boudreaux	Chris Cole								
Consider Control Con	Horace Morman					Layout at Piles.			
Horace Morman	Benny Boudreaux					Layout at Piles			
Renny Boudreaux	Gary McCaan					Onsite Supervision			
Tanner Broughton           Mark Murphy           Alisha White         1 <t< td=""><td>Horace Morman</td><td></td><td></td><td></td><td></td><td>Set Pile Elevations</td><td></td><td></td><td></td></t<>	Horace Morman					Set Pile Elevations			
Mark Murphy           Alisha White           Tanner Broughton           Mark Murphy           Chris Cole           Horace Morman         Image: Setting Pile Elevations.           Benry Boudreaux         Image: Setting Pile Elevations.           Horace Morman         Image: Setting Pile Elevations.           Benry Boudreaux         Image: Setting Pile Elevations.           Horace Morman         Image: Setting Pile Elevations.           Browning Spoils         Image: Setting Pile Elevations.           Image: Setting Pile Elevations.         Image:	Benny Boudreaux					Control Line Layout			
Alisha White         Tanner Broughton         Image: Constructors LLC         Image: Constructor LLC	Tanner Broughton								
Tanner Broughton  Mark Murphy  Chris Cole  Horace Morman  Benny Boudreaux  Gary McCaan  Benny Boudreaux  Gary McCaan  Benny Boudreaux  Horace Morman  Benny Boudreaux  Benny Belevations at pile  Benny Boudreaux  Benny Boudreaux  Benny Belevations.	Mark Murphy								
Mark Murphy Chris Cole Horace Morman Benny Boudreaux Gary McCaan Benny Boudreaux Gary McCaan Benny Boudreaux B	Alisha White								
Chris Cole Horace Morman Benny Boudreaux Gary McCaan Benny Boudreaux Horace Morman  Setting Pile Elevations.  Layout Consite Supervision  Layout QC.  Horace Morman  Sub Sub Wrkrs Wrkrs Wrkrs Vand Tier Wrkrs Wrkra Wrkrs Wrkra Wrkrs Wrk	Tanner Broughton								
Horace Morman Benny Boudreaux Gary McCaan Benny Boudreaux Gary McCaan Benny Boudreaux Horace Morman  Sub Sub Wrkrs Sub Zund Tier Wrkrs In Tier	Mark Murphy								
Benny Boudreaux  Gary McCaan  Benny Boudreaux  Horace Morman  Sub Wrkrs VR 2nd Tier VR 2nd	Chris Cole								
Gary McCaan  Benny Boudreaux  Horace Morman  Sub Sub Sub Wrkrs Hrs 2nd Tier Wrkrs Hrs Work Accomplished  Subcontractor  Dading, Marques & Associates LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Sub Cary NCC.  Layout, QC.  Onsite Supervision. Setting elevations at pile.  Work Accomplished  Sub Work Accomplished  Sub Sub Verification Setting elevations at pile.  Subcontractor  Sub Sub Sub Verification Setting elevations at pile.  Sub Verification Setting elevations at pile.  Subcontractor Tier Tier Wrkrs Hrs  Subcontractor  Sub	Horace Morman					Setting Pile Elevations.			
Benny Boudreaux Horace Morman  Sub Wrkrs Wrk Accomplished  S Q Sch  S Q Sch  F F F Phoenix Constructors LLC Removing Spoils	Benny Boudreaux					Layout			
Horace Morman  Sub Sub Wrkrs Hrs 2nd Tier Wrkrs Hrs Work Accomplished  Dading, Marques & Associates LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Removing Spoils  Onsite Supervision. Setting elevations at pile.  Stockpiling spoils.  F  Removing Spoils	Gary McCaan					Onsite Supervision			
Subcontractor Wrkrs Hrs 2nd Tier Wrkrs Hrs Work Accomplished  Subcontractor  Dading, Marques & Associates LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Removing Spoils	Benny Boudreaux					Layout, QC.			
Subcontractor  Sub Wrkrs  Wrkrs  Proceeding, Marques & Associates LLC  Dading, Marques & Associates LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Removing Spoils  Tier Wrkrs  Hrs  Work Accomplished  S Q Sch  Stockpiling spoils.  F  Removing Spoils	Horace Morman					Onsite Supervision. Setting elevations at pile.			
Subcontractor  Wrkrs Hrs 2nd Tier Wrkrs Hrs Work Accomplished  S Q Sch  Dading, Marques & Associates LLC  Dading, Marques & Associates LLC  Phoenix Constructors LLC  1 10  Stockpiling spoils.  Removing Spoils			6.1						
Dading, Marques & Associates LLC  Dading, Marques & Associates LLC  Phoenix Constructors LLC  1 10 Stockpiling spoils.  F  Phoenix Constructors LLC  Removing Spoils	Subcontractor			2nd Tier		Work Accomplished	s	Q	Sch
Dading, Marques & Associates LLC       Phoenix Constructors LLC     1 10     Stockpiling spoils.     F       Phoenix Constructors LLC     Removing Spoils	Dading, Marques & Associates LLC								
Phoenix Constructors LLC     1     10     Stockpiling spoils.     F       Phoenix Constructors LLC     Removing Spoils     F									
		1	10			Stockpiling spoils.	F		
Phoenix Constructors LLC 2 Removing Spoils	Phoenix Constructors LLC					Removing Spoils			
	Phoenix Constructors LLC	2				Removing Spoils			

Project: Sherwood Forest Element	ary Scho	ol			Job:		14-0	02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:			1
Fair Working Days To Date:					Date:		12/13	3/2014
Weather Delays To Date:			Weather Condition:	Sunny	Day:		Sa	turday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov	N	High
Critical Path Work Effected?		N				5	55	75
Phoenix Constructors LLC	1	10		Removing Spoils				
Gulf South Engineering & Testing Inc	1	8	Recording Pile Drivi			F		
Gulf South Engineering & Testing Inc	3	10	GRL	Recording Drilling and Pumping. Setting thermal rods for testing.				
C. If Co. III Facility in the Particular	2		CDI	Collecting data from piles.				
Gulf South Engineering & Testing Inc	3		GRL	Recording Pile Data, Recording Drilling Data				
Gulf South Engineering & Testing Inc	2	40	C   P'''	Monitoring Pile installation.		_		
Berkel & company Contractors Inc	8	10	Carlo Ditta	Installing Auger Cast piles. 25 today.		F		
Berkel & company Contractors Inc	8	10	Carlo Ditta	Installing Auger Cast Pile. 22 Pile today.				
Area A Gulf South Engineering & Testing Inc	2	20		Test and record grout data and observe rebar setting		F	Е	os
Gulf South Engineering & Testing Inc	2	24	1	Test and record grout data and observe rebar setting		F	Ε	OS
Berkel & company Contractors Inc	11	110		Drove 31 augered piles Areas A and B		F	F	OS
Berkel & company Contractors Inc	7	70		Drove 27 augered piles Areas A and B		F	F	OS
Area B								
Phoenix Constructors LLC	1	10		Remove spoils from augered piles for operation		F	F	OS
Phoenix Constructors LLC	1	10		Remove spoils from augered piles for operation		F	F	OS
Gulf South Engineering & Testing Inc	2	8	GRL	Installed Thermal Test Probes. 6 locations today.		F	F	
Area C Berkel & company Contractors Inc	7	10	Carlo Ditta	lestallian Avenue and Bila. 10 and av		F	F	
	8	10	Carlo Ditta	Installing Auger cast Pile. 19 today.		F	-	05
Berkel & company Contractors Inc	0	10	Cario Dilla	Installing Auger Cast Piles. 23 in Area C		F	F	OS
<b>LavDown</b> GWJ Construction and Industrial Supply LLC	11	110		Tie rebar cages for piles		F	F	OS
GWJ Construction and Industrial Supply LLC	11	110		Tie rebar cages for piles		F	F	OS
GWJ Construction and Industrial Supply LLC	8	8		Tied renar cages for Auger cast piles.		F	F	AS
	100	558	_					

**Communication with Subcontractors:** Met with Quality Iron regarding scope.

Met with Cordiero Concrete regarding contract.

Material Delivered: Grout for Auger cast piles.

Equipment Rented by CORE: 1-Bobcat - Phoenix

1 Crane - Berkel 1 Forklift - Berkel

**Visitors:** Bright Moments came by at 12noon.

**Notes:** Cordiero Meeting Reviewed Scope. Quality Steel Meeting Reviewed scope

Project:	Sherwood Forest Elementary School				J	ob:	14-0	2-002
Location:	4801 Maid Marion Drive				Repoi	t #:		1
Fair Working	Days To Date:				D	ate:	12/15	/2014
Weather Dela	ays To Date:		Weather Condition:	Overcast	C	ay:	Мо	onday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Te	<b>mp:</b> Lo	)W	High
Critical Path \	Work Effected?	N					57	73

Employee						Work Accomplished			
Alisha White									
Horace Morman						Setting elevations at piles.			
Gary McCaan						Field Supervision			
Benny Boudreaux						Layout.			
Tanner Broughton									
Chris Cole									
Alisha White									
Tanner Broughton									
Mark Murphy									
Benny Boudreaux									
Horace Morman									
Gary McCaan									
Alisha White									
Gary McCaan									
Chris Cole									
Mark Murphy									
Tanner Broughton									
Benny Boudreaux									
Horace Morman									
Alisha White						Office Administration			
Tanner Broughton									
Mark Murphy									
Benny Boudreaux						Field Engineering			
Gary McCaan						Field Supervision			
Horace Morman						Setting Pile Elevations			
Alisha White						Office Administration			
Mark Murphy									
Tanner Broughton									
Benny Boudreaux						Layout/QC Fied Engineering			
Gary McCaan						Field Supervision			
Horace Morman						Dewatering			
				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	;	s	Q Sch
Phoenix Constructors LLC	1	10		141113	.113	Hauling Spoils		F	F
Gulf South Engineering & Testing Inc	2					Monitoring Pile Installation			
Gulf South Engineering & Testing Inc						Monitoring Pile Installation			
Gulf South Engineering & Testing Inc	2	10				Monitoring Pile INstallation			
Berkel & company Contractors Inc	8	10	Carlo Ditta			Installing Auger cast pile. 30 Pile installed today.		F	
Area C Phoenix Constructors LLC	1	10				Stockpiling Spoils		F	F OS

Project:	Sherwood Forest Elemen	tary Scho	ol			Job:		14-0	02-002
Location:	4801 Maid Marion Drive					Report #:			1
Fair Working	Days To Date:					Date:		12/1	7/2014
Weather Dela	ays To Date:			Weather Condition:		Day:		Wedi	nesday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Lo	W	High
Critical Path	Work Effected?		N						
Phoenix Constr	uctors LLC	1	10		Hauling Spoils		F	F	os
Phoenix Constr	uctors LLC	1	10		Hauling Spoils		F	F	OS
Phoenix Constr	uctors LLC	1	10		Hauling SPoils		F	F	OS
Gulf South Engi	neering & Testing Inc	2	10		Monitoring Pile Installation		F	F	OS
Gulf South Engi	neering & Testing Inc	2	10		Monitoring Pile Installation		F	F	OS
Berkel & compa	any Contractors Inc	8	10	Carlo Ditta	Installed 13 Pile in Area C		F	F	OS
Berkel & compa	any Contractors Inc	6	10	Carlo Ditta	Installing Auger Piles		F	F	OS
Berkel & compa	any Contractors Inc	6	10	Carlo Ditta	Installing Auger Cast Pile		F	F	OS
Berkel & compa	any Contractors Inc	7	10	Carlo Ditta	Installed 21 Auger Cast Piles		F	F	OS
		48	130						

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/7	22/2014
Weather Dela	ys To Date:		Weather Condition:	Rain/Lightning	Day:	ı	Monday
Is Today Clair	ned as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	Υ				55	70

Employee	Work Accomplished
Alisha White	
Tanner Broughton	
Benny Boudreaux	Dewatering
Horace Morman	Dewatering
Gary McCaan	Dewatering

Project:	Sherwood Forest Elementary Schoo				Joh	: 1	4-02-002
Location:	4801 Maid Marion Drive				Report :	k:	1
Fair Working	Days To Date:				Dat	<b>::</b> 12	2/29/2014
Weather Dela	ays To Date:		Weather Condition:	Overcast	Da	<i>r</i> :	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Tem	Low	High
Critical Path	Work Effected?	N				52	63

Employee						Work Accomplished			
Mark Murphy									
Alisha White						Office Administration			
Tanner Broughton						Scheduling/Reviewing Contracts			
Horace Morman						Dewatering			
Benny Boudreaux						Layout/Engineering			
Gary McCaan						Field Supervision			
Mark Murphy									
Alisha White						Office Administration			
Tanner Broughton						Scheduling/Reviewing Contracts			
Horace Morman						Dewatering			
Benny Boudreaux						Layout/Engineering			
Gary McCaan						Field Supervision			
Mark Murphy									
Tanner Broughton									
Chris Cole									
Benny Boudreaux						Layout			
Horace Morman						Setting Elevations at Piles			
Gary McCaan									
				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
Phoenix Constructors LLC									
Phoenix Constructors LLC									
Gulf South Engineering & Testing Inc						Monitoring Pile Driving			
Berkel & company Contractors Inc			Carlo Ditta			Installing Auger Cast Pile			
Berkel & company Contractors Inc			Carlo Ditta			Installing Auger Cast Pile			
GWJ Construction and Industrial Supply LLC									
GWJ Construction and Industrial Supply LLC									
<b>Area D</b> Phoenix Constructors LLC	1	4				Stock piling auger cast pile	F	F	OS
Berkel & company Contractors Inc	6	4	Carlo Ditta			Installed 14 auger cast pile	F	F	OS
	7	8	_						

Remarks: Rained out at Noon.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	01/	05/2015
Weather Dela	ays To Date:		Weather Condition:	Overcast/Cold	Day:		Monday
Is Today Clair	med as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				48	52

Formlassa						Worls Assessmilished			
Employee						Work Accomplished			
Alisha White						Office Administration			
Tanner Broughton						Jobsite Administration			
Mark Murphy									
Benny Boudreaux						Field Engineer/Layout			
Horace Morman						Dewatering			
				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished	s	0	Sch
Subcontractor	WIKIS	піз	Ziiù Tiei	Wrkrs	Hrs	Work Accomplished			
CORE Construction Services, LLC	7	10				Complete PIT Pile layout in AM. Maintained PIT Pile excavation & cleaned & preped pile tops. Cleaning PIT pile tops (preparing for tests)	F	F	OS
CORE Construction Services, LLC	2	10				Jobsite supervision and Auger pile elevations and monitoring, also dewatered site where ponding.	F	F	OS
Phoenix Constructors LLC	1	10				Stock piled augur pile spoils.	F	F	OS
Phoenix Constructors LLC	1	10				Stock piled Auger pile spoils	F	F	
Gulf South Engineering & Testing Inc	2	10				Auger pile inspections and thermal testing	F	F	
Gulf South Engineering & Testing Inc	2	10				Auger pile grout and reinforcing inspections. Thermal testing devices setting and recording.	F	F	
Gulf South Engineering & Testing Inc	2	2				No testing done			
Berkel & company Contractors Inc	6	6				To cold to drill Auger Piles, Crew Stayed on site till 1:00pm waiting for temperature to get above freezing to no avail.  Knocked off @ 1:00pm	F	F	OS
<b>Area C</b> Phoenix Constructors LLC	3	10				Load and haul pile spoils of the job site 2) Excavated PIT piles     area C and D 3) Sweep the streets surrounding the job site.	F	F	OS
Phoenix Constructors LLC	3	8				Stock pile auger pile spoils load and haul off spoils, excavate     and back fill PIT piles 2nd round area C and D	F	F	OS
Gulf South Engineering & Testing Inc	3	8				1) Auger pile drill and flow tests 2)thermal testing 3) 30 PIT tests 2nd round area C and D	F	F	
Area D									
CORE Construction Services, LLC	2	8				dewartered site	F	F	OS
CORE Construction Services, LLC	6	10				Dewatered site from weekend rains, also demucking the sight for the pile driving rig due to equiptment running thru area.	F	F	OS
CORE Construction Services, LLC	6	10				Auger pile elevations and monitoring, Laid out P I T piles approximately 30 in area C/D for excavation on 1/8/2015	F	F	OS
CORE Construction Services, LLC	5	8				Site supervision, Auger pile elevation's. Prep PIT piles @nd round areas C and D.	F	F	OS
Phoenix Constructors LLC	1	8				Removed slopy mud from pile driving area to improve condition's.	F	F	
Berkel & company Contractors Inc	6	2				No work this day due to weekend rain, site conditions to sloppy to work. 2 hour show up time.	F	F	OS
Berkel & company Contractors Inc	4	10				Drilled 17 auger piles in area D started late due to supplier not serving concrete till 10:00 am.	F	F	OS
Berkel & company Contractors Inc	5	10				Drilled 23 Auger piles today area D	F	F	OS
Berkel & company Contractors Inc	6	8				Drilled auger piles area D and E.	F	F	OS

Project:	Sherwood Forest Element	ary Scho	ool			Job:		14-0	02-002
Location:	4801 Maid Marion Drive					Report #:			1
Fair Working	Days To Date:					Date:		01/10	0/2015
Weather Delay	Veather Delays To Date:			Weather Condition:	Partly Cloudy/Cold	Day:		turday	
Is Today Claimed as Weather Day?			N	Precipitation Amount:		Temp:	Low		High
Critical Path W	ork Effected?		N				3	88	50
Phoenix Constru	ctors LLC	1	10		Stockpiled auger pile spoils.		F	F	OS
Berkel & compa	ny Contractors Inc	6	10		Drilled auger cast piles area E		F	F	OS
		80	188						

**Remarks:** 1st load of grout for piles rejected and sent back to Carlo Ditta (by Berkel) for having rocks in the mix, this delayed progress by 1 hr. While reviewing the next truck looking for aggregate, it was noticed that the mix has large quantity of small pea gravel Ditta's Q.C. rep was called out and problem found Ditta's sand supplier had gravel and sand at the plant Q.C. corrected this issue.

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool					Job: Report #:		14-	-02-002 1
Fair Working Days To Date:							Date:		01/1	2/2015
Weather Delays To Date:			Weath	er Conditio	n:	Fog/Rain	Day:		Ν	/londay
Is Today Claimed as Weather Day?		N		itation Amo			Temp:	Lo	w	High
Critical Path Work Effected?		N					•	į	55	65
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q	Sch
CORE Construction Services, LLC	4	6				Office work this day due to rain.		F	Р	
Phoenix Constructors LLC	2	8				Skid steer stock piling auger spoils, excavator assisting moving matt's		F	F	OS
Cordeiro LLC	0									
Gulf South Engineering & Testing Inc	2	8				Auger pile testing and recording				
Gulf South Engineering & Testing Inc	2	10				auger pile testing and recording		F	F	
Gulf South Engineering & Testing Inc	2	1								
Gulf South Engineering & Testing Inc						Auger piles inspecting grout & rebar. Install and test thermal.				
Area A CORE Construction Services, LLC	3	8				Top pile elevations, dewatered site & chipped piles poured approximately 8" to high in pile cap area A		F	F	OS
Cordeiro LLC	4	8				Mobilize form materials and start excavating pile caps Area A		F	F	OS
Cordeiro LLC	6	10				Area A, pile cap Excavation & forming.		F	F	OS
Cordeiro LLC	6	8				Forming pile caps area A / excavate pile caps area A.		F	F	OS
Area D CORE Construction Services, LLC	5	10				Safety, Top pile elevation and de watering the site.		F	F	OS
Phoenix Constructors LLC	2	10				Skid steer- stock piled spoils / Excavator-assisted Berkel moving crane mats around the site.		F	F	OS
Phoenix Constructors LLC	2	8				Skid Steer- stock piling spoils Excavator- assisting Berkel moving crane matt's.		F	F	
Area E										
CORE Construction Services, LLC	6	8				Top pile elevations, pile layout and PIT layout and dewatering site.		F	F	OS
CORE Construction Services, LLC	6	10				Safety, top pile elevation & de watering site.		F	F	OS
CORE Construction Services, LLC	6	8				Top of pile elevation, working with Berkel layout of piles destroyed during pile activities.		Р	F	OS
Phoenix Constructors LLC	2	8				Stock pile, pile spoil materials moved crane matt's with excavator.		Р	F	OS
Phoenix Constructors LLC	2	8				Skid steer- stock plied pile spoils / Excavator- assisted moving matts for the crane.		F	F	
Gulf South Engineering & Testing Inc	2	8				Auger pile testing & reporting.		F	F	
Berkel & company Contractors Inc	6	8				Received 2-loads of matt's set up and drilled 4 pile area E		F	F	OS
Berkel & company Contractors Inc	6	10				Drilled 17 auger piles arae D/E		F	F	OS
Berkel & company Contractors Inc	6	10				Drilled 21 auger piles area D&E		F	F	OS
Berkel & company Contractors Inc	6	7				Drilled 12 piles area E		Р	Р	OS
Berkel & company Contractors Inc	6	8	_			Drilled auger piles area E		F	F	OS
	94	188	_							

**Visitors:** 3 Guys laying out piles from David Marques due to the crans matts moving

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	01/	18/2015
Weather Dela	ays To Date:		Weather Condition:	Cold\Overcast	Day:		Sunday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				48	63

				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	1	8		WIKIS	піз	Mucked out area E for the pile crew.	P	F	-
CORE Construction Services, LLC	4	8				dewater the site.	Р	· F	
CORE Construction Services, LLC	2	8				De watered site.	F	, E	OS
Phoenix Constructors LLC	1	ŭ				Mucked out area E for the pile crew.	P	· F	03
Phoenix Constructors LLC	2	10				Skid steer-stock pile spoils	F	, E	OS
THOURAN CONSTRUCTORS ELEC	_					Excavator- moved crane matt's	·		03
Phoenix Constructors LLC	2	8				Skid steer- stock piled pile spoils.		F	OS
						Excavator- moved crane matt's.			
Phoenix Constructors LLC	2	8				unloading their drain pipe.			
Recovery School District	1	8				Stock piled pile spoils.	F	F	
Gulf South Engineering & Testing Inc	2	10				Auger pile monitring & testing	F	F	
Gulf South Engineering & Testing Inc	2	8				Auger pile monitoring & testing.	F	F	
Gulf South Engineering & Testing Inc	1	8				pile testing	F		
Area A									
Cordeiro LLC	8	10				Excavated and formed pile cap's area A	F	F	OS
Cordeiro LLC	9	8				Excavating & forming pile caps in area A.	F	F	OS
Cordeiro LLC	10	8				Excavated and formed pile caps for area A, Hauled off pile spoils.	F	F	OS
Cordeiro LLC	10	8				Excavating & forming pile caps area A & area C.	F	F	OS
<b>Area C</b> CORE Construction Services, LLC	5	8				Auger pile elevations.	F	F	OS
Phoenix Constructors LLC	2	8				Skid steer- stock pilled pile spoils.	F	F	
						Excavator-moved the matt's for the crane.			
Gulf South Engineering & Testing Inc	2	8				auger pile monitoring and testing.	F		
Berkel & company Contractors Inc	9	8				Drilled 13 auger piles area c	F	F	OS
Area E									
CORE Construction Services, LLC	6	10				Est. Top of pile elevations.	F	F	OS
CORE Construction Services, LLC	6	8				Auger pile elevations	F	F	OS
CORE Construction Services, LLC	6	8				Est. top pile elevations, laid out last 7 slab piles destroyed by Berkel.	F	F	OS
Phoenix Constructors LLC	2	8				Skid steer- stock piled pile spoils.  Excavator- Moving the crane matt's.	F		
Gulf South Engineering & Testing Inc	2	8				Auger pile monitoring and testing.	F		
Berkel & company Contractors Inc	7	10				Drilled 20 auger piles area E	F	F	OS
Berkel & company Contractors Inc	8	8				Drilled 15 auger piles area E	F	F	OS
Berkel & company Contractors Inc	8	8				Drilled 10 auger piles, completed ACC building piles, moving to light poles	F	F	os
Office									
Berkel & company Contractors Inc	8	8				Drove 7 light pole base piles.	F	F	OS
	128	226	_						

Project:	Sherwood Forest Elementary School				Joh	: 1	4-02-002
Location:	4801 Maid Marion Drive				Report	<b>!</b> :	1
Fair Working	Days To Date:				Dat	<b>:</b> 01	/25/2015
Weather Dela	ays To Date:		Weather Condition:	Partly/Cloudy	Da	r.	Sunday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Tem	Low	High
Critical Path \	Work Effected?	N				45	67

Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	1	8				De waterd sight	F	F	
CORE Construction Services, LLC	6					Jobsite safety, De watered site, pile cap layout.			
CORE Construction Services, LLC	6	8				Job site safety, Dewatered site, pile cap layout.	F	F	os
CORE Construction Services, LLC	6	8				Safety and Jobsite supervision, Excavate and clean PIT piles.  Dewater site.	F	F	os
CORE Construction Services, LLC	6	8				Safety & job site supervision.  Excavate & clean PIT piles for testing column lines & inspecting pile caps Area A	F	F	OS
CORE Construction Services, LLC	6	8				Jobsite supervision and safety.	E	F	
Phoenix Constructors LLC	1	8				Stock piled wet pile spoils	F	F	
Phoenix Constructors LLC	2	8				Sweep street's around the job site.	F	F	
Phoenix Constructors LLC	5	8				Stock piling materials & laying out storm drains.	F	F	OS
Phoenix Constructors LLC	6	8				Started storm drain manhole East side	F	F	OS
Phoenix Constructors LLC	6	8				Excavating remaining 3 PIT piles & back filling, Installing manholes for storm drains east side	F	F	OS
Phoenix Constructors LLC	7	8				Laid 8, 8" storm drains (east side0 dozered the site to dress it up, also hauled of spoils left from pile's.	F	F	
Gulf South Engineering & Testing Inc	1	4				finished testing the finale piles.	F		
Gulf South Engineering & Testing Inc	1	8				PIT testing on the last 30 piles	F		
Gulf South Engineering & Testing Inc	1	8				Concrete cylinders pile cap mix test on pile bedding under and above storm drain pipes between manholes.	F	F	OS
Berkel & company Contractors Inc	6	8				Drilled remaining last 3 light pole base's, Started breaking down the crane.	F	F	OS
Berkel & company Contractors Inc	5	8				Breaking down crane and removing drilling equiptment off site.	F		
Berkel & company Contractors Inc	6	8				Demobing the crane	F		
<b>Area A</b> CORE Construction Services, LLC	7	8				Pile cap column lines & concrete monitoring. Chipping high piles clean PIT piles for testing.	F	F	OS
Cordeiro LLC	10	8				Forming Area A	F	F	OS
Cordeiro LLC	10	8				Pile caps area A rebar form work.	F	F	OS
Cordeiro LLC	10	8				Forem pile caps area A, excavate area C	F	F	OS
Cordeiro LLC	10	8				Poured P4 pile caps area A, forming & installing rebar in pile caps.	F	F	OS
Cordeiro LLC	11	8	_			Excavate form & install rebar pile caps in area A. Poured 5 pile caps.	F	F	OS
	136	180							

Remarks: Amanda with Home Land Secutiy Inspector, site visiting for photos of site to show previous building was demolished.

**Visitors:** Clyde with MME inspected pile caps E-4 14.8 D-5 -14, 13.8 E-4, 12- D.5, 12\_E6

Project: Location:	<b>Sherwood Forest Elemen</b> 4801 Maid Marion Drive	ntary Scho	ool					Job: Report #:		14-	02-002 1
Fair Working	Days To Date:							Date:		02/0	4/2015
Weather Del	ays To Date:			Weath	er Condition	n:	Rain	Day:		Wed	nesday
Is Today Clai	med as Weather Day?		N	Precipi	tation Amo	unt:		Temp:	Lo	w	High
Critical Path	Work Effected?		N						4	49	69
		Sub	Sub		2nd Tier	2nd Tier					
Subcontrac	tor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		S	Q	Sch
	ction Services, LLC	4	8				Office Work		F	F	OS
	ction Services, LLC	4	10				Job site safety and supervision.		F	F	OS
CORE Construc	ction Services, LLC	4	8				Jobsite supervision & safety		F	F	OS
Phoenix Constr	ructors LLC	6	8				Installed storm drain inlets & pipe on the south side of site.		F	F	OS
Phoenix Constr	ructors LLC	6	8				Installed storm drain inlets & pipe on the west side of the job site.		F	F	OS
Phoenix Constr	ructors LLC	10	8				Back fill the trenches where the pipe was laid. Laid storm drain pipe 135' & set inlet box #33.		F	F	OS
Phoenix Constr	ructors LLC	8	8				Installed 40' of 18" A-2000, Hauled of spoil dirt, back filled excavations.		F	F	OS
Gulf South Eng	ineering & Testing Inc	1	8				Density test for the storm drain back fill.		F	F	
Gulf South Eng	ineering & Testing Inc	1	8				Density Tests on the storm drain back fill.				
Gulf South Eng	ineering & Testing Inc	1	8				Density testing the back fill installed in the area's they laid pipe		F	F	OS
Gulf South Eng	ineering & Testing Inc	1	8				Density testing.		F	F	OS
Malone All Star	r JV, LLC	1					Reviewing drawings.				
Area A CORE Construc	ction Services, LLC	5	10				Established Column lines, Pile caps area A,B & C		E	F	OS
Area B CORE Construc	tion Services, LLC	5	10				Jobsite Safety & Supervision  Column centerlines & Pre Concrete pour inspections & Pour monitoring.		F	F	OS
Area C											
Cordeiro LLC		10	8				Back filling the pile caps in Area A, Form & Rebar pile caps area C & B.		F	F	OS
Cordeiro LLC		10	10				Poured 8 pile caps in areas A,B & C.		F	F	OS
Cordoine II.C		10	0				Poured 12 pile cap base's incase of rain area C. "30yds"		F	-	O.C
Cordeiro LLC		12	8				Excavate pile caps area C.  Form and Tie rebar area C.		٢	F	OS
Cordeiro LLC		12	8				Excavate, Form and tie Rebar for pile Cap C.		F	F	OS
		101	144	_							

 $\textbf{Remarks:} \ \mathsf{Gary} \ \mathsf{McCain} \ \mathsf{had} \ \mathsf{to} \ \mathsf{go} \ \mathsf{to} \ \mathsf{CMC} \ \mathsf{rebars} \ \mathsf{yard} \ \mathsf{to} \ \mathsf{pick} \ \mathsf{up} \ \mathsf{45} \ \mathsf{\#5} \ \ \mathsf{grade} \ \mathsf{beam} \ \mathsf{dowels}.$ 

Project:	Sherwood Forest Elementary School				Job		14-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	: 0	2/14/2015
Weather Dela	ays To Date:		Weather Condition:	No Work	Day	:	Saturday
Is Today Clain	med as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path V	Work Effected?	N					
			2nd 2nd				'

	Sub	Sub	- 1-	2nd Tier	2nd Tier			_	6-1-
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	·	Sch
CORE Construction Consists II C	4	10				John Color C	-	_	OS
CORE Construction Services, LLC	5	8				Jobsite supervision, Safety & Layout.	r	F	
CORE Construction Services, LLC						Jobsite supervision,Safety & Layout.		F	OS
CORE Construction Services, LLC	5	8				Jobsite safety, supervision & Layout.	F	F	OS
CORE Construction Services, LLC	5	10				Jobsite supervision, Safety & Layout	F	F	OS
CORE Construction Services, LLC	6	8				Jobsite supervision, safety & layout.	F _	F	OS
Bernhard Mechanical Contractors, L.L.C.	3	5				Mobilize tool trailer & bringing to tools to the site.	F	F	
Bernhard Mechanical Contractors, L.L.C.	1	6				Unloading under ground PVC materials for the job site.	F		
Phoenix Constructors LLC	7	8				Back filled pipe trenches on the south side.	F	F	OS
Phoenix Constructors LLC	8	8				Hauled off the spoil material from storm drains.  Installing storm drain inlets 6 & 7 and piping, and hauling out spoiled materials	F	F	os
Phoenix Constructors LLC	7	8				Storm drain inlets & pipeing, sand fill. Haul out spoil materials.	F	F	OS
Phoenix Constructors LLC	7	8				Storm drain boxes & pipe @ North side, and back filled with sand. Haul off spoil materials.	F	F	OS
Phoenix Constructors LLC	7	8				Installed storm drain boxes & inlets on the north side of the job site.	F	F	OS
Cordeiro LLC	12	8				Pile Caps Area B& C, Forming & installing rebar. Excavate caps Area B, Back filling area A.	F	F	OS
Cordeiro LLC	13	8				Poured 12 pile caps Area B & C.	F	F	OS
Gulf South Engineering & Testing Inc	1	8				Concrete and density tests.	F	F	
Gulf South Engineering & Testing Inc	1	8				Density testing back fill around drain pipes	F	F	
Gulf South Engineering & Testing Inc	1	8				Density testing around storm drain pipe.	F	F	
Gulf South Engineering & Testing Inc	1	8				Density testing.	F	F	
Gulf South Engineering & Testing Inc	1	8				Density tests on storm drain fill, also testing the concrete for Cordeiro.	F		
Malone All Star JV, LLC	1	6				Temporary power to subs job trailers	F	F	
Malone All Star JV, LLC	1	6				1 guy hooking up job site trailor	F	F	
Area B Cordeiro LLC	16	8				Form, Install Rebar& Anchor bolts, 12 caps Area B & C, Back filled	F	F	OS
						with sand around caps A & B			
Area C									
Cordeiro LLC	12	10				Poured 44 yds 12 pile caps area C, excavated remaining in area B.	F	F	OS
Cordeiro LLC	11	8	_			Wreck forms & Reset up Area B & C, Excavating Area c & elevator Cap "D", Forming grade beams Area "A".	F	F	OS
	136	189							

Project: Location:	Sherwood Forest Eleme 4801 Maid Marion Drive	-	ool					Job: Report #:		14-	02-002
Fair Working D	Davs To Date:							Date:		02/2	1/2015
Weather Delay				Weath	er Conditio	n·	Overcast	Day:			aturday
-	ed as Weather Day?		N		tation Amo			Temp:	Lo	w	High
Critical Path W	•		N	•						50	75
Subcontracto	r	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q	Sch
CORE Construction	on Services, LLC	3	8				Jobsite supervision, Safety & Layout		F	F	OS
CORE Construction	on Services, LLC	4	10				Jobsite supervision, Safety & Layout.		F	F	OS
CORE Construction	on Services, LLC	5	11				Jobsite superviosn, Safety & Layout.		F	F	OS
CORE Construction	on Services, LLC	4	8				Jobsite supervision, Safety & Layout.		F	F	OS
CORE Construction	on Services, LLC	3	8				Jobsite safety & Supervision.		F	F	OS
Bernhard Mechar	nical Contractors, L.L.C.	2	6				Unload cast Iron pipe & fittings from Southern Supply.		F	F	OS
Phoenix Construc	ctors LLC	5	8				installed storm drain from manhole #34 to existing drain on Robin Hood street.		F	F	OS
Phoenix Construc	ctors LLC	7	9				Installed Inlet #19 and pipe from #26 to #19 & back filled		F	F	OS
Phoenix Construc	ctors LLC	7	11				Storm Drain line tie in, from inlet #19 to existing manhole on Rogin Hood st.		F	F	OS
Gulf South Engine	eering & Testing Inc	1	8				Density test on storm drain pipe bedding & fill materials.		F	F	
Gulf South Engine	eering & Testing Inc	1	9				Storm Drain Density testing.		F	F	
Gulf South Engine	eering & Testing Inc	1	9				Density testing, storm drain fill materials.		E	Ε	OS
Gulf South Engine	eering & Testing Inc	1	8				Storm Drain density tests.		F	F	
Malone All Star J	V, LLC	3	8				Pulled wire for temp services to job trailers.		F	F	
Malone All Star J	V, LLC	1	6				Reviewing Drawings		F	F	OS
<b>Area A</b> Cordeiro LLC		12	8				Form perimeter Grade beams Area "A", wrecked forms around pile cap forms from Fridays pour, Installed and tied rebar perimeter beams Area "A"		F	F	OS
Cordeiro LLC		17	8				Grade Beams area "A" const. forming & Rebar Pile caps Area "D"		F	F	OS

const. Excavating perimeter Caps Area A Grade beams forming & resteel.

Area D pile caps Excavation.

Excavating & Rebar

in lower area's.

Area C grade beams, layout and Excavation.

Grade beams "A" Forming & Tying rebar Pile caps B & C,

Button up Inside Grade beam forms Area A for (Tuesdays Pour)

Haul off spoil materials from the storm drains. Dress up area's

worked , Installing Boxes & pipe spreading existing dirt in Area E

OS

OS

OS

F OS

**Remarks:** Elevator pit Location needed to proceed with P-5 pile cap.

20

20

127

8

8

173

**Visitors:** Kyle Culver-CORE Estimating. Keanon Yong With Jacobs Safety Inspection.

Notes:

Cordeiro LLC

Cordeiro LLC

Cordeiro LLC

Phoenix Constructors LLC

Area E

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/	23/2015
Weather Dela	ys To Date:		Weather Condition:	Overcast/Rain	Day:		Monday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				41	52

				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	5	10		· · · · · · · · · · · · · · · · · · ·		Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	6	9				Jobsite supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	6	7				Submeetings & office work	F	F	
CORE Construction Services, LLC	4	9				Jobsite Safety and Supervision.	F	F	OS
CORE Construction Services, LLC	4	9				Jobsite Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	3	8				Jobsite supervision & safety	F	F	OS
Phoenix Constructors LLC	2	8				Move materials to staging area & dressing up the site	F	F	
Phoenix Constructors LLC	6	8				Fix silt fencing around perimeter of the job site & clean up, also sweeping the street.	F	F	OS
Phoenix Constructors LLC	1	8				Keeping the street cleaning from track out.	F	F	
Phoenix Constructors LLC	1	8				Sweeping the track out , out of the street.	F	F	
Cordeiro LLC	26	8				Pilecaps Area D excavated, Form and install Rebar. Poured 4 Pedestals Area A & C and 1 pile cap in Area B	F	F	OS
Gulf South Engineering & Testing Inc	1	8				Testing concrete and making cylinders.	F	F	
Area A									
Cordeiro LLC	19	8				Excavate pile caps Area D.	F	F	OS
						Continued butting up Grade beam forms Area A.			
Cordeiro LLC	20	9				Install rebar & pre tie pile caps.  Poured perimeter Grade beams Area A. 40yds - see pour notice for location.	F	F	OS
Area C									
Cordeiro LLC	14	7				Area A back fill & prep for grade beams.  Area B excavate Grade beam & set perimeter forms.  Area C excavate grade beams  Area D Form pile caps, Install rebar& Bolts for Mondays pour.	F	F	OS
Area D									
Cordeiro LLC	16	8	_			Digging pile caps Area D, Grade beam wrecked in Area A, Tied rebar pedestals & Excavate caps Area D.	F	F	OS
	134	132							

<b>Location:</b> 4801 Maid Marion Drive							Report #:			1
Fair Working Days To Date:							Date:		03/02	2/2015
Weather Delays To Date:			Weath	er Conditio	٠.	Overcast	Day:			1onday
Is Today Claimed as Weather Day?		N		itation Amo			Temp:	Lov		High
Critical Path Work Effected?		N	-		<b>a</b>		remp.		0	68
Griden Facilities Ericated.				2-4	2-4					
	Sub	Sub		2nd Tier	2nd Tier					
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		S	Q	Sch
CORE Construction Services, LLC	4	9				Job site supervision & Safety		F	F	OS
						Dewater pile caps & set up matts.				
CORE Construction Services, LLC	7	9				Jobsite safety, supervision & layout.		F	F	OS
CORE Construction Services, LLC	3	9				Chip down high piles.  Jobsite Safety & Supervision.		F	F	OS
Phoenix Constructors LLC		8						· F		
	2					SWEP- correct some area's of the fabric from erosion.		•	F	OS
Phoenix Constructors LLC	10	9				Sand fill the Slab on Grade in area "A".  Building the man hole on Robin Hood st, storm drain tie in.		F	F	OS
Phoenix Constructors LLC	4	8				Area "A" Hauling in Sand for slab on grade 2/3 complete.		F	F	OS
Thochix constructors are	7	Ü				Back filling around man hole on Robin Hood.		•		03
Gulf South Engineering & Testing Inc	1	8				Testing the concrete for Lower grade beams in Area "C".		F		
A A										
Area A Phoenix Constructors LLC	4	8				Back fill the slab on Grade Area "A" , hauling in sand for area "B".		F	F	OS
Thousand Constitutions 220	•	Ü				Sweeping the street after the sand trucks leave.		•		05
Phoenix Constructors LLC	9	8				Building Manhole on Robin Hood st. ,Storm Drain tie in.		F	F	OS
						Placing sand in area "A" Slab on Grade.				
Area B										
Cordeiro LLC	24	8				Area "B" forming and installing rebar in the perimeter grade		F	F	OS
						beams.				
						Area "C" Low Grade beams forming and installing rebar.				
Contract to	25					Area "D" excavating the pile caps.		-	_	06
Cordeiro LLC	25	8				Area "A & B" Forming and installing rebar in perimeter grade beam steel.		F	F	OS
						Area "C" Forming and installing rebar in lower grade beam.				
						Area "D" Pile cap excavation and forming.				
Area C										
Cordeiro LLC	27	8				Area B & C form and install rebar.		F	F	OS
						Grade beams area "D".				
						Wreck pile cap forms and back fill area "C".				
Cordeiro LLC	23	8				Poured 37yds (Low) grade beams Area "C".		F	F	OS
						Forming perimeter grade beams in Area "B".				
Malone All Star JV, LLC	2	8				Excavating Pile Caps Area "E".  Start execution's for the Transformer and under ground conduits.		_	F	OS
						Start excavation's for the Transformer pad under ground conduits.		-	•	
Malone All Star JV, LLC	2	8				Prefabing under ground conduits for under the slab area "C"		F	F	OS
Area D										
CORE Construction Services, LLC	7	9				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Consider II.C.	7	9				Chipping the high piles in area "D".		F	F	OS
CORE Construction Services, LLC	,	9				Jobsite supervision, Safety & Layout. Chipping high piles in Area "D".		г	r	US
Cordeiro LLC	23	8	CMC Rebar			Pile Caps area D - pour 16 Pile caps.		F	F	os
	-					Unload rebar truck (Grade beams B&C)				-
						Dewater pile caps.				
Gulf South Engineering & Testing Inc	1	8	_			Concrete testing the concrete for the pile caps Area D		F	F	
	185	158	_							

Job:

14-02-002

## Remarks:

Project:

**Sherwood Forest Elementary School** 

**Inspections:** Clyde Tice inspected the pile caps for area D. Johnathan Cook for Jacobs here for the concrete pour. **Material Delivered:** Rebar For Area B&C grade beams

Project:	Sherwood Forest Elementary School					Job:	14	-02-002
Location:	4801 Maid Marion Drive				Re	eport #:		1
Fair Working	Days To Date:					Date:	03/0	09/2015
Weather Dela	nys To Date:		Weather Condition:	Rain/Cloudy		Day:	1	Monday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:			Temp:	Low	High
Critical Path V	Vork Effected?	Ν					61	72

Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	5	9				Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	5	8				Jobsite safety, Supervision & Layout	F	F	OS
CORE Construction Services, LLC	4	8				Jobsite Supervision & Safety.	F	F	OS
CORE Construction Services, LLC	4	8				Jobsite Supervision, Safety & layout.	F		
CORE Construction Services, LLC	5	8				Rain Out, Worked in Job Trailer.			
CORE Construction Services, LLC	4	8				Dewatered the site, multiple pumps running.	F	F	
Bernhard Mechanical Contractors, L.L.C.	2	4				1st day on the site had some control lines done by CORE. Area "C & 15"	F		
Bernhard Mechanical Contractors, L.L.C.	2	8				Making up pipe hanger's for their under ground.	F	F	
Bernhard Mechanical Contractors, L.L.C.	2	8				Continuing to make under ground Pipe Hangers.	F		
Bernhard Mechanical Contractors, L.L.C.	2	4				Prefab hanger rods & saddles for under ground piping at Area "A" Kitchen.	F		
Phoenix Constructors LLC	5	4				Completed bricking manhole on Robin Hood and backfilled with sand and stone.	F	F	
Phoenix Constructors LLC	4	4				Repairing the storm drains that where having Erosion problems.	F	F	
Phoenix Constructors LLC	6	3				Sand filling Slab on Grade Area "B".  Dresses up the Man Hole on Robin Hood due to Erosion from the Rain.	F		
Phoenix Constructors LLC	1	4				1/2 of day running sand in Area "B" Slab on Grade.	F		
Malone All Star JV, LLC	2	4				Prefab & Reviewed underground for Area "C". Rain out 10:00 am	F		
Area C Cordeiro LLC	23	8				Wrecked Grade beams in Area "C" from Fridays concrete pour.	F	_	OS
Cordeiro LLC	4	8				Continued checking Anchor Bolts & Control lines, The rest of the crew was rained out.	F	F	03
Cordeiro LLC	17	4				Forming and installing Anchor Bolts at Perimeter grade beams Area "B&C". 10:00am Rain Out.	F		OS
<b>Area D</b> Cordeiro LLC	14	8				Checked Anchor Bolts & Control Lines Grade Beams form & Rebar.	F	F	OS
	111	120	_						

Remarks: 11:30 rain started off and on till the end of the day.

Concrete pour Canceled.

Visitors: Johnathan Cook from Jacobs.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	03/	16/2015
Weather Dela	ays To Date:		Weather Condition:	Sunny	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	Ν				64	77

				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	6	9				Jobsite Supervision, Safety & Layout.	F		
CORE Construction Services, LLC	6	9				Jobsite Supervision, Safety & Layout.	F	F	OS
						Control lines for Anchor bolts Area "D".			
CORE Construction Services, LLC	5	9				Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	5	9				Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	5	9				Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	2	8				Jobsite Supervision.	F	F	OS
Phoenix Constructors LLC	4	8				Sand Filled Area "B" Slab on Grade 1/2 the day, Repaired stone on Robin Hood from storm Drain tie in that Eroded from trucks rolling threw it.	F		
Gulf South Engineering & Testing Inc	1	8				Inspecting Concrete for Pile cap pour Area "D".	F		
Gulf South Engineering & Testing Inc	1	8				Inspecting Concrete for the Grade beams Area "C".	F		
Area A									
Bernhard Mechanical Contractors, L.L.C.	2	8				Prefab piping for the Kitchen Area "A" under ground.	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	2	8				Prefab Cafeteria underground Area "A".	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	4	8				Prefab under ground for Area "A" Cafeteria.	F	F	OS
Area B									
Phoenix Constructors LLC	2	8				Sand Filled Slab On Grade Area "B" approximately 2/3 Complete.	F		BS
Phoenix Constructors LLC	1	8				Sand filling Area "A&B" Slab on Grade.	F	F	BS
Phoenix Constructors LLC	1	8				Sand Fill Slab On Grade Area "B"	F	F	BS
Phoenix Constructors LLC	1	8				Sand Filled Slab on Grade Area "B".	F	F	BS
Cordeiro LLC	22	8				Area "D" Rebar and Anchor bolts on the 16 Pile caps scheduled for Tomorrows pour, also Perimeter Grade Beams "A & B" pouring Tomorrow.	F	F	OS
Cordeiro LLC	7	8				Area "B" wrecked Grade beam forms that where poured the day before, Installed and Tied Rebar Area "C".	F	F	OS
Malone All Star JV, LLC	2	8				Prefab piping and installing Ground Rod Sleeves at Grade beam Perimeter's in the forms.	F	F	OS
Area C									
Cordeiro LLC	23	8				Grade Beams Area "B&C".	F	F	OS
Cordeiro LLC	22	8				Pile Caps Area "E"  Grade beam Area "B & C"	F	F	os
						Pile Cap Excavation Area "E"		•	
Cordeiro LLC	22	8				Poured Grade Beams Area "C" @ Line 7 34yds. Poured Elevator walls.	F	F	OS
Malone All Star JV, LLC	2	8				Layout Underground @ Generator pad.	F	F	OS
Malone All Star JV, LLC	2	8				Prefab Chase with 4" conduits in the under ground Area "C"	F	F	OS
Malone All Star JV, LLC	1	8				Prefab 4" Conduits for underground in Area "C"	F	F	OS
Malone All Star JV, LLC	4	8				Installing under ground Conduits to Chase from Transformer pad Area "C".	F	E	OS
Area D									
Cordeiro LLC	23	9				Poured 16 pile caps Area "D" Approximately COL "1to4" "B&E" 7 Grade Beams on Perimeter @ Line B & E.6 line.	F		OS
	178	222	_						

**Remarks:** Clyde Tice with MMI, could not make it to the site today to inspect Pile Caps and Grade beams, Pour inspection was for 10:00am Asked that we take pictures of Rebar and Anchor Bolts installed.

Site Drying out due to dewatering over the weekend, Poured 108yds in Pile caps Area "D" & Grade Beams Area "B".

Project:	Sherwood Forest Elementary School	I			Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	03/1	17/2015
Weather Dela	ays To Date:		Weather Condition:	Sunny	Day:	Т	Tuesday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				62	86

Project: Sherwood Forest Eleme	entary Scho	ol					Job:		14-(	02-002
<b>Location:</b> 4801 Maid Marion Drive	e						Report #:			1
Fair Working Days To Date:							Date:		03/25	5/2015
Weather Delays To Date:			Weath	er Conditio	n:	Sunny	Day:		Wedr	nesday
Is Today Claimed as Weather Day?		N		itation Amo			Temp:	Lo	w	High
Critical Path Work Effected?		N	•						57	77
				2nd	2nd					
	Sub	Sub		Tier	Tier					
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		S	Q	Sch
CORE Construction Services, LLC	5	10				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	2	3				Job shut down at 10:00 am because of the Rain.		F	F	
CORE Construction Services, LLC	5	10				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	2	8				Job site Supervision.		F	F	OS
Area A										
Bernhard Mechanical Contractors, L.L.C.	4	8				Started layout and digging inside the Fire pump Room grade		F	F	OS
	-					beams to install the under ground piping.		_		0.5
Bernhard Mechanical Contractors, L.L.C.	5	8				Installing the under ground sewer pipes in the fire pump room grade beams.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Installing under Ground piping in Area "A" Kitchen.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	3				Continuing to install under Ground piping in Area "A" Kltchen.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	5	10				Area "A" underground rough in.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	5	8				Area "A" underground rough in.		F	F	OS
Malone All Star JV, LLC	5	8				Installing under ground conduits for the Data to out side the		F	F	OS
						Grade beams Area "A".				
Area B										
Phoenix Constructors LLC	1	8				Back Filling Area "A & B" Slab on Grade.		F	F	BS
Phoenix Constructors LLC	1	8				Installing Sand for Slab On Grade Area's "A & B", Back filled		F	F	BS
Phoenix Constructors LLC	4	8				around Catch Basin's that Eroded away from past rains.		F	F	BS
FIIOEIIX COISTIUCTOIS EEC	4	o				Area "A & B" sand fill for Slab on Grade "A" is filled but not to grade & "B" is in progress of "filling".			г	DS
Phoenix Constructors LLC	2	6						F	F	OS
Malone All Star JV, LLC	5	8				Installing under ground conduits in Area "B".		F	F	OS
						Inspection on the temporary pole and the underground.				
Malone All Star JV, LLC	5	3				Installed under Ground conduits, Back filled ditch Area "B"		F		OS
Malone All Star JV, LLC	5	5				Area "B & C" underground telephone conduits.		F	F	OS
Area C										
Cordeiro LLC	21	9				Area "E" Pile cap Reinforcement & Anchor Bolts.  Area "C" Grade beam forming @ Column line 8. to J1 and E.6.		F	F	OS
Malone All Star JV, LLC	4	8				Installing Underground Conduits in Area "C"		F	F	OS
Area D										
Cordeiro LLC	19	8				Area "D" pile caps ,pedestals excavations & forming.		F	F	OS
						Area "C & B" Set and tie Rebar & Set Anchor Bolts.				
Cordeiro LLC	21	10				Area "D & E" pile caps & pedestals , excavations & forming.		F	F	OS
						Area "C & B" forming the Grade beams, Set and Tie the rebar.  "B & C" Setting Anchor Bolts.				
Area E						b a C Setting Anchor Botts.				
CORE Construction Services, LLC	5	9				Jobsite Supervision, Safety & Layout.		F	F	OS
						Chipping high Piles in Area "E"				
CORE Construction Services, LLC	4	10				Jobsite Supervision Safety & Layout.		F	F	OS
Cordeiro LLC	21	10				Chipping High Pile in Area "E"		E	F	OS
CO. GEN O LLC	21	10				Area "D & E" pile caps excavating and forming pile caps.  Area "C & B" forming grade beams, installing and tying rebar.			r	<i>-</i> 3
						Area "B & C" Setting anchor bolt's.				
Cordeiro LLC	21	3				Worked on wrecking forms in Area "C" .		F	F	OS
			_			Forming and Installing rebar in Area "E".				
	189	197								

Project:	Sherwood Forest Elementary Schoo				Job	i ·	14-02	002
Location:	4801 Maid Marion Drive				Report :	•		1
Fair Working	Days To Date:				Date	<b>.</b> 0	3/26/	2015
Weather Dela	nys To Date:		Weather Condition:	Rain Out	Day	:	Thur	rsday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp	Low	,	High
Critical Path \	Vork Effected?	N				61	I	70

Project:	Sherwood Forest Elementary School				Jo	<b>b:</b> 1	14-02-002
Location:	4801 Maid Marion Drive				Report	#:	1
Fair Working	Days To Date:				Da	i <b>e:</b> 03	3/30/2015
Weather Dela	ays To Date:		Weather Condition:	Sunny	D	ıy:	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Ten	<b>p:</b> Low	High
Critical Path \	Work Effected?	N				60	80

				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	5	10				Jobsite, Supervision & layout.	E	F	OS
CORE Construction Services, LLC	4	9				Jobsite Supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	4	8				Jobsite supervision & Safety	F	F	
CORE Construction Services, LLC	5	10				Jobsite Safety & Supervision	F	F	OS
CORE Construction Services, LLC	4	10				Jobsite Supervision & Safety.	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6								
Cordeiro LLC	24								
Gulf South Engineering & Testing Inc	1	8				Testing Concrete for today's pour.	F	F	
Malone All Star JV, LLC	5								
<b>Area A</b> Bernhard Mechanical Contractors, L.L.C.	5	8				Area "A" under ground piping.	F	F	os
Bernhard Mechanical Contractors, L.L.C.	5	8				Under ground plumbing Area "A" in Cafeteria.	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground & Cafeteria Area "A"	F	F	BS
Area B									
Phoenix Constructors LLC	1	8				No sand to work with Today (Lost Day) to S.O.G Area "A,B&C".	F	F	BS
Area C									
Phoenix Constructors LLC	2	8				sand fill completing at Area "B"(rough grade) and Partial Area "C" rough grade.	F	F	BS
Phoenix Constructors LLC	2	8				Sand fill, Slab on Grade Area "B & C". ( Partial)	F	F	BS
Phoenix Constructors LLC	2	8				Back filling Area "C"	F	Р	BS
Cordeiro LLC	24	8				Poured 25 yards grade beams & walls southwest corner of Area "C" perimeter.	F	F	OS
Malone All Star JV, LLC	4	8				Area "B & C" under ground conduits.	F	F	OS
Malone All Star JV, LLC	4	8				Under ground Electrical conduits Area "C" to Transformer Pad.	F	F	OS
Malone All Star JV, LLC	5	8				Underground at the Transformer pad.	F	F	OS
Malone All Star JV, LLC	3	8				Underground Area "C" outside building lines Conduits	F	F	OS
Area D Cordeiro LLC	24	8				Grade beams Area "D" forms & pile caps Area "E" & Rebar	F	F	os
Area E Cordeiro LLC	23	9				Poured 11 pile caps Area "E" forming and prep grade beams & walls Area "C" for tomorrow's pour.	F	F	OS
	168	168	_						

Remarks: Poured 45 yards, pile caps area "E".

Project:	Sherwood Forest Elementary School				J	ob:	14-02	2-002
Location:	4801 Maid Marion Drive				Repor	t #:		1
Fair Working	Days To Date:				D	ate: (	04/07/	2015
Weather Dela	ays To Date:		Weather Condition:	Sunny	Γ	ay:	Tue	esday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Te	<b>np:</b> Low	v	High
Critical Path \	Work Effected?	N				7	1	84

Employee Work Accomplished

Employee						Work Accomplished			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	s	Q	Sch
CORE Construction Services, LLC	4	10				Jobsite Safety, Supervision & Layout.	E	F	OS
CORE Construction Services, LLC	5	10				Jobsite supervision, Safety & Layout.	F	F	OS
CORE Construction Services, LLC	6	10				Jobsite Supervision, Safety & Layout	F	F	OS
CORE Construction Services, LLC	6	10				Jobsite Supervision, Safety & Layout	F	F	OS
CORE Construction Services, LLC	1	7				Jobsite Supervision.	F	F	OS
Gulf South Engineering & Testing Inc						Testing concrete for the Grade Beams.			
Gulf South Engineering & Testing Inc	1	8				Testing Concrete			
Gulf South Engineering & Testing Inc	1	8				Concrete testing for concrete pour pile caps Area "E"	F	F	
Area A									
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "A"	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground plumbing in Area "A"	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Area "A" underground rough in	F	F	BS
Bernhard Mechanical Contractors, L.L.C.	6	8				Rough in underground Area "A"	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Continuing underground rough in Area "A"	F	F	BS
Area B									
Phoenix Constructors LLC	1	7				Behind schedule with S.O.G back fill - Presently working Area "B"	F	Р	BS
A41 A116 11416	2	•				1 man no crew today.	_		0.5
Malone All Star JV, LLC	2	8				Underground Conduits to courtyard Area "B"	F	F	OS
Area C	2	0					-	_	D.C.
Phoenix Constructors LLC	2	8				Sand fill S.O.G Area B&C	F	F	BS
Phoenix Constructors LLC	3	8				Fill S.O.G. Area "C" (SAND)	F	F	BS
Phoenix Constructors LLC	6	8				Back fill S.O.G. Area "C"	F	P _	BS
Malone All Star JV, LLC	5	8				Underground Area "C"	F	E	OS
Malone All Star JV, LLC	2	8				Underground rough in Area "C".	F	F	OS
Malone All Star JV, LLC	1	8				Underground @ Courtyard.	r	E	OS
Area D CORE Construction Services, LLC	5	10				Jobsite supervision , Safety & Layout	F	F	OS
CORE COnstruction Services, LEC	3	10				Sweep the street's & cut the grass around the job site.	'	F	03
Cordeiro LLC	24	8				Poured 35yds- Grade beams Area "D" Col.7 & B to E. also forming	F	F	OS
						Pile caps Area "E"			
Cordeiro LLC	19	8				Pile caps Area "E" & Grade beams Area "D"	F	F	OS
Cordeiro LLC	8	7				Layout grade beams Area "D&E" wrecked PILE CAP FORM Area "E"	F	F	OS
Area E									
Cordeiro LLC	20	9				Poured 3 pile caps 30yds pump truck broke down.	F	F	OS
Cordeiro LLC	22	8				Poured 50yds Pile caps Area "E" (Appx 9 Pile Caps poured.	F	F	OS
Cordeiro LLC	19	8				Wreck & Backfill pile caps Area "E" & Grade beams Area "D"	F	F	OS
			_			Rebar & Formwork			
	193	224							

**Remarks:** Held Prepatoy Meeting for the slab on grade.

Inspections: S&WB still waiting for the underground inspection Area "A" delaying backfill & S.O.G. "A" progress.

Notes: Pushed structural steel start date back 1 week till 4-23-15 due to S.O.G. Area "A" delays.

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool					Job: Report #:		14-	02-002 1
Fair Working Days To Date:							Date:		04/1	3/2015
Weather Delays To Date:			Weath	er Condition	n:	Rain	Day:		Ν	/londay
Is Today Claimed as Weather Day?		N	Precip	itation Amo	unt:		Temp:	Lo	w	High
Critical Path Work Effected?		N	1				•		70	73
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q	Sch
CORE Construction Services, LLC	4	8				Jobsite Supervision, Safety & Layout		F	F	OS
CORE Construction Services, LLC	4	8				Jobsite supervision & safety.		F	Е	OS
CORE Construction Services, LLC	7	10				Jobsite Supervision & Safety  De watering site		F	F	
CORE Construction Services, LLC	5	10				Jobsite Supervision & Safety		F	F	OS
CORE Construction Services, LLC	7	10				Jobsite Safety & Supervision Repair Anchor Bolts in Area "A"		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	4				11:00 am rain out		F	F	
Phoenix Constructors LLC	4	4				11:00 am rain out		F	F	
Phoenix Constructors LLC	3	8				No sand available sand pit and site to wet erosion control @ drains.		F	F	
Cordeiro LLC	18	2				9:00 am rain out		F	F	OS
Malone All Star JV, LLC	1	2				Rain out		F	F	OS
Malone All Star JV, LLC	1	4				11:00 am rain out		F	F	
<b>Area A</b> CORE Construction Services, LLC	3	8				Rain out 9:00 am -continued repairing the anchor bolts damaged by Phoenix in Area "A".		F	F	os
Bernhard Mechanical Contractors, L.L.C.	5	4				Rough in underground Area "C" rain out at 10:30am		F	F	BS
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "A"		F	F	BS
Bernhard Mechanical Contractors, L.L.C.	6	8				underground Area "A"		F	F	OS
Phoenix Constructors LLC	4	8				Sand fill Area "C"		F	F	
Cordeiro LLC	19	8				Final Grade Area "A"		F	F	OS
Malone All Star JV, LLC	1	8				Lightning protection		F	F	OS
Malone All Star JV, LLC	1	8				Lightning protection conduits.		F	F	
Area B Cordeiro LLC	9	2				Fine Grade Area "B" rain out @ 9:00 am		F	F	
Malone All Star JV, LLC	1	8				Lightning protection		F	F	OS
Area C										
Phoenix Constructors LLC	6	4				Rough grade Area "C" & sand fill 10:30am rain out.		F	F	BS
Phoenix Constructors LLC	3	8				Sand fill Area "C"		F	F	BS
<b>Area D</b> Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D"		F	F	OS
Cordeiro LLC	12	8				Poured grade beams in Area "D"		F	F	OS
Cordeiro LLC	4	8				Dewater Area "D&E" clean bolts in Area "A"		F	F	
	146	175	_							

**Remarks:** Discovered damaged anchor bolts , repairing the anchor bolts damaged by Phoenix.

Site conditions bad from this weeks rain also because of the equiptment traveling threw the mud.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	04/	20/2015
Weather Dela	ys To Date:		Weather Condition:	Partly/ Cloudy	Day:		Monday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				66	80
			2nd 2nd			•	

	Cul	Cul		2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	q	Sch
CORE Construction Services, LLC	7	10				Jobsite safety & Supervision De watering	F	F	OS
CORE Construction Services, LLC	5	10				Jobsite Supervision & Safety	F	F	OS
CORE Construction Services, LLC	7	10				Jobsite Supervision & Safety.  De watering.	F	F	OS
CORE Construction Services, LLC	7	10				Jobsite supervision, Safety & layout.  De watering the site.	F	F	OS
CORE Construction Services, LLC	4	10				Jobsite supervision, Safety & Layout	F	F	OS
CORE Construction Services, LLC	2	6				Jobsite supervision & Safety.	F	F	OS
Malone All Star JV, LLC	1	8				Temporary Power	F	F	
Malone All Star JV, LLC	1	8				Temporary Power.	F	F	
Malone All Star JV, LLC	1	8				Temporary Poles.			
Area A CORE Construction Services, LLC	3	6				Repairing damaged anchor bolts Area "A" by Phoenix APPX. 20 total- 7 remaining today 6hrs each person.	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Area "A" Underground	F	F	
Cordeiro LLC	21	8				Area "A" fine grade slab area. Area "D&E" grade beams.	F	F	
Cordeiro LLC	21	8				Area "A" fine grade slab Area "A" . Area "E" grade beam perimeter. Poured 30yds Grade Beam "D"	F	F	
Cordeiro LLC	22	8				Area "A" Fine grade.  Area "E" grade beam @ perimeter & ramps form work.	F	F	
Cordeiro LLC	13	6				Vapor barrier Area "A" fabricate angel iron slab supports per SKS-8 extra work.	F	F	
Malone All Star JV, LLC	1	8				Underground Area "A"	F	F	
Area B									
Bernhard Mechanical Contractors, L.L.C.	5	8				Area "B&C" underground plumbing.			
Bernhard Mechanical Contractors, L.L.C.	5	8				Underground plumbing Area "B"	F	F	
Bernhard Mechanical Contractors, L.L.C.	5	6				Plumbing underground Area "B"	F	F	
<b>Area C</b> Bernhard Mechanical Contractors, L.L.C.	5	8				Area "C" under ground plumbing.	F	F	
Bernhard Mechanical Contractors, L.L.C.	5	8				Area "C" underground.	F	F	
Phoenix Constructors LLC	5	8				Area "C" Sandfill	F	F	
Cordeiro LLC	19	8				Area "C" fine grade	F	F	
						Area "D&E" grade beams.			
Area D	_						_		
Phoenix Constructors LLC	5	8				Sand fill Area "D"	F	F	
Phoenix Constructors LLC	5	8				Area "D" sand fill.	_		
Phoenix Constructors LLC	5	8				Putting sand in Area "D"	F _	F	
Phoenix Constructors LLC	5	8				Area "D" Sand fill to rough grade (On going).	F	F	
Phoenix Constructors LLC	5	6				S.O.G fill area "D".  Install sand and rocks for trucks to be able to get to the courtyard.	F	F	
Cordeiro LLC	21	8				Area "D&E"- Grade beams Area "A" fine grade.			
Malone All Star JV, LLC	1	6				Conduits @ grade beams area "D"	F	F	
Area F									

Project:	Sherwood Forest Elementa	ary Scho	ol			Job:	14	1-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	04/	23/2015
Weather Dela	ys To Date:			Weather Condition:	Cloudy/Rain	Day:	Т	Thursday
Is Today Clain	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				69	84
Gulf South Engir	neering & Testing Inc	1	8		Testing grade beam pour.			
Malone All Star	JV, LLC	1	8		Grounding conduits Area "E" grade beams.		F F	:
		220	254	•				

Remarks: Orderd angel iron for SKS-8.

 $Canceled\ concrete\ due\ to\ site\ conditions\ \&\ afternoon\ rain\ fore\ cast.\ Reset\ up\ for\ Monday\ 4-27-15.$ 

Location: 4801 Maid Marion Driv							Report #:			1
							Date:		ns /n	2/2015
Fair Working Days To Date:			<b>347</b>			Sunny				
Weather Delays To Date:		N		er Conditio		Sumy	Day:			aturday
Is Today Claimed as Weather Day?  Critical Path Work Effected?		N	Пссір	itation Amo	unc.		Temp:	Lov	v 4	High 82
Critical Path Work Effected?		- 14							7	- 02
	Sub	Sub		2nd Tier	2nd Tier					
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		S	Q	Sch
CORE Construction Services, LLC	7	9				Jobsite supervision & Safety.		F	F	OS
CORE Construction Services, LLC	6	12				De watering the site.  Jobsite Safety & Supervision.		F	F	OS
CORE Construction Services, LLC	6	12				Jobsite supervision & Safety.		F	F	OS
CORE Construction Services, LLC	4	12				Jobsite supervision & Safety.		F	F	OS
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	2	10				Jobsite Supervision, Safety & Layout.		F	F	OS
Phoenix Constructors LLC						Not on site				
Malone All Star JV, LLC										
Area A										
Bernhard Mechanical Contractors, L.L.C.	6	8				Setting Drains in Area A.		F	F	
Cordeiro LLC	19	4				Sand Grade and vapor barrier, Fabricating angels for SKS-8.		F	F	
Cordeiro LLC	19	8				Area "A" slab prep.		F	F	
						Vapor barrier installed.				
						Angel supports for the pedestals.  Starting the slab matts.				
Cordeiro LLC	23	10				Slab Rebar Area "A".		F	F	
						Pour grade beams Area "E".				
Cordeiro LLC	23	11				Rebar slab Area A.		F	F	
Cordeiro LLC	21	10				Pile cap grade beams Area D Slab "A" Rebar.		F	F	
Cordeiro LLC	16	10				Set & Tie Rebar in Area "A".		F	· F	
Malone All Star JV, LLC	1	4				lighning protection in Area "A"		F	' F	
Malone All Star JV, LLC	6	8				Lightning Protection.		F	' F	
Malone All Star JV, LLC	2	8				Lightning Protection.		F	· F	
Malone All Star JV, LLC	2	8				Slab "A" Rough In.		F	, E	
·	_	Ü				Siab A Rough III.		·	'	
<b>Area B</b> Bernhard Mechanical Contractors, L.L.C.	6	4				Underground Area "B"		F	F	
Bernhard Mechanical Contractors, L.L.C.	1	8				Underground Area"B".		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				- Underground Area "B"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Rough In for Slab "B"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Finishing The Under Ground Roughin In Area "A" Started to		F	F	
						Backfill, Also Continuing Under Ground in Area "C".				
Area C										
Phoenix Constructors LLC	4	8				Sandfilling For Slab "C" rough Grade.		F	Р	
Area D						6 15" 1 "0"		-	_	
Phoenix Constructors LLC	4	4				Sand fill in Area "D".		F	P	
Phoenix Constructors LLC	5	8				Site work & back fill Area "D".		F	F	
Phoenix Constructors LLC	5	8				Site work and back fill Area D.		F	F	
Area E	1	0				testing consists for the grade bases as a first				
Gulf South Engineering & Testing Inc	1	8	_			testing concrete for the grade beam pours Area E				
	207	216								

Job:

14-02-002

Remarks:

Project:

**Sherwood Forest Elementary School** 

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol					Job: Report #:		14-0	02-002
Fair Working Days To Date:							Date:		05/03	3/2015
Weather Delays To Date:				er Conditio	n:	No Work	Day:		S	Sunday
Is Today Claimed as Weather Day?		N	i iccipi	tation Amo	unt:		Temp:	Lo	W	High
Critical Path Work Effected?		N								
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q	Sch
				***************************************		•				
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	os
CORE Construction Services, LLC	4	14				Job Site Safety & Supervision.		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	12				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	14				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.										
Bernhard Mechanical Contractors, L.L.C.										
Cordeiro LLC										
Cordeiro LLC										
Malone All Star JV, LLC										
Malone All Star JV, LLC										
Area A										
Cordeiro LLC	26	14				Pour Area "A" S.O.G. vapor Barrier ARea "B".		F	F	
Area B										
Cordeiro LLC	22	10				Vapor Barrier & Rebar For Slab on Grade Area "B"		F	F	
Cordeiro LLC	24	11				Area "B" place and tie rebar		F	F	
Cordeiro LLC	26	14				Poured the Slab in Area "B"		F	F	
Malone All Star JV, LLC	5	8				Lightning Protection Area "A,B & C"		F	F	
Malone All Star JV, LLC	2	8				Rough in conduits in Area "B"		F	F	
Malone All Star JV, LLC	2	8				Area "B" -Slab floor boxes.		F	F	
Area C										
Bernhard Mechanical Contractors, L.L.C.	6	8				Plumbing Underground Area "C"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "C"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground in Area "C"		F	F	
Malone All Star JV, LLC	2	8				Underground Area "C & D"		F	F	
Malone All Star JV, LLC	2	8				Underground in Area "C"		F	F	
Area D										
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D", and slab drains Area "B"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D"		F	F	
Phoenix Constructors LLC	2	8				Sand Fill to Grade Area "D"		F	Р	
Phoenix Constructors LLC	5	8				Sand fill Area "D"		F	F	
Phoenix Constructors LLC	4	8				Sand Filling to Rough Grade Area "D"		F	Р	
Area E Phoenix Constructors LLC	4	8						F	Р	
Phoenix Constructors LLC	4	8				Rough grade sand fill Area "E"		F	Р	
Cordeiro LLC	23	10				Pump & Place Concrete Area "E" grade beams. Set and Tie rebar in Area "B"		F	F	
	204	241	_			Second the repair in rated of				

Project:	Sherwood Forest Elementary School				Job	: 1	14-02-0	002
Location:	4801 Maid Marion Drive				Report #	<b>}</b> •		1
Fair Working	Days To Date:				Date	<b>:</b> 05	5/06/20	015
Weather Dela	ays To Date:		Weather Condition:	Partly/ Cloudy	Day	r. W	/ednes	day
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp	Low	Н	ligh
Critical Path \	Work Effected?	N				68		84

**Inspections:** GSE testing the concrete for grade beams in Area "E"

Project: Sherwood Forest Elem: Location: 4801 Maid Marion Drive Fair Working Days To Date:	=	ool					Job: Report #: Date:			02-002 1 0/2015
Weather Delays To Date:			Weath	er Conditio	n:	No Work	Day:		9	Sunday
Is Today Claimed as Weather Day?		Ν		tation Amo			Temp:	Lo	w	High
Critical Path Work Effected?		Ν	1				•			3
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		S	Q	Sch
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	10				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	12				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	15				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	1	6				Jobsite Supervision.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.		Ü				Jobske Supervision.		•		00
Bernhard Mechanical Contractors, L.L.C.										
Phoenix Constructors LLC										
Cordeiro LLC										
Malone All Star JV, LLC										
Malone All Star JV, LLC	2	8				Site rough in.		F	F	
Malone All Star JV, LLC	-	Ü				Site rough in.		·	'	
Area A  Quality Iron Fabricators Inc.	6	10				Set up Crane and unloaded steel for Area "A"		F	F	
Quality Iron Fabricators Inc.	6	10				Hanging Iron Area "A"		· F	, E	
Quality Iron Fabricators Inc.	6	8				Hanging Iron Area "A&B"		F	· F	
•	Ü	ŭ				Hanging Hon Alea Alea		•		
Area B  Quality Iron Fabricators Inc.	6	8				Hanging Iron in Area "B"		F	F	
Quality Iron Fabricators Inc.	10	10				Hanging Iron Area "A&B"		F	F	
Malone All Star JV, LLC	2	8				Rough in Site.		F	F	
	_								•	
Area C Cordeiro LLC	23	9				Vapor Barrier Area "C" / Rebar placement in Area "C"		F	F	
Cordeiro LLC	23	11				Placing and tying Steel Area "C"		F	F	
Cordeiro LLC	22	14				Poured Gym slab Area "C" 1st floor 360yds.		F	F	
Cordeiro LLC	18	11				Slab "C" wreck forms (Slab)		F	F	
						Area "E" wrecked forms (Grade beams)				
Malone All Star JV, LLC	3	8				Slab rough in Area "C"		F	F	
Area D										
Bernhard Mechanical Contractors, L.L.C.	6	8				Area "D" plumbing underground rough in.		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "D"		F	F	
Cordeiro LLC	5	6				Started fine Grading Area "D"		F	F	
Malone All Star JV, LLC	2	8				Underground rough in Area "D"		F	F	
Malone All Star JV, LLC	2	8				Site Underground		F	F	
Area E										
Bernhard Mechanical Contractors, L.L.C.	6	8				Underground Area "E"		F	F	
Phoenix Constructors LLC	4	8				Back filling Area "E"		F	F	
Phoenix Constructors LLC	4	8				Sand Fill Area "E"		F	F	

Project:	Sherwood Forest Elementa	ry Sch	ool			Job:	14	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	05/1	12/2015
Weather Dela	ys To Date:			Weather Condition:	Sunny	Day:	1	Tuesday
Is Today Clair	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				75	87
Cordeiro LLC		20	9		Poured perimeter Grade Beams Area "E"		F F	
		215	266					

Remarks: G B White Rebar delivery Area "D"

Inspections: GSE testing concrete for grade beam pour Area "E'

Project: Sherwood Forest Elem	=	ol					Job:		14-0	02-002
<b>Location:</b> 4801 Maid Marion Driv	e						Report #:			1
Fair Working Days To Date:							Date:	(	05/1	7/2015
Weather Delays To Date:				er Conditior		No Work	Day:		S	Sunday
Is Today Claimed as Weather Day?		N	i iccipi	itation Amo	unt:		Temp:	Lov	V	High
Critical Path Work Effected?		N								
	Sub	Sub		2nd	2nd					
Subcontractor	Wrkrs	Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished		s	Q	Sch
				***************************************		·				
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.										
Bernhard Mechanical Contractors, L.L.C.	5	8				Cleaned up lay down yard , preparing for next phase of the project.		F	F	
Bernhard Mechanical Contractors, L.L.C.						Over seeing the pour.				
Cordeiro LLC										
Cordeiro LLC						Pouring Area D and putting down the vapor barrier in Area E				
Quality Iron Fabricators Inc.										
Malone All Star JV, LLC										
Malone All Star JV, LLC										
Area A  Quality Iron Fabricators Inc.	10	10				Hanning Iron Aven "A OrD"		F	F	
•	9	10				Hanging Iron Area "A&B"		, E		
Quality Iron Fabricators Inc.						Hanging Iron in Area "A&B"		F	F	
Quality Iron Fabricators Inc.	9	10				Hanging Iron Area A&B		г	F	
<b>Area B</b> Quality Iron Fabricators Inc.	9	10				Hanging Iron Area "A&B"		F	F	
Quality Iron Fabricators Inc.	9	10				Hanging Iron in Area "A&B"		F	F	
Area D										
Cordeiro LLC	24	10				Final grade, installing vapor barrier and starting to install rebar.		F	F	
Cordeiro LLC	22	10				Finsihing Vapor Barrier and Rebar		F	F	
Cordeiro LLC	24	10				Placing and tying rebar area "D"		F	F	
Cordeiro LLC	24	10				Finishing up Area D for Pour. Grading Area E		F	F	
Malone All Star JV, LLC	5	8				Underground Area "D"		F	F	
Malone All Star JV, LLC	5	8				Finishing up underground in Area "D"		F	F	
Area E										
Bernhard Mechanical Contractors, L.L.C.	5	8				Finish plumbing rough in Area "E"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Plumbing underground Area "E"		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				Finishing underground & backfill in Area "E"		F	F	
Bernhard Mechanical Contractors, L.L.C.	5	8				Finishing back fill in Area E & Cleaning up work Area.		F	F	
Cordeiro LLC	19	8				Remove forms from Grade beams Area "E" Fine grading Area "D"		F	F	
Malone All Star JV, LLC	5	8				Underground in Area "E"		F	F	
Malone All Star JV, LLC	5	8				Underground in Area "E"		F	F	
Malone All Star JV, LLC	5	8				Finishing up underground in Area E		F	F	
	241	231	_							

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	05/	/22/2015
Weather Dela	ays To Date:		Weather Condition:	Overcast	Day:		Friday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Work Effected?	N				68	82

**Inspections:** GSE testing the flatness of the slab.

Project: Sherwood Forest Elem	=	ol					Job:		14-02	
<b>Location:</b> 4801 Maid Marion Driv	е						Report #:			1
Fair Working Days To Date:							Date:	0	5/24/2	2015
Weather Delays To Date:				er Conditio	n:	No Work	Day:		Sui	nday
Is Today Claimed as Weather Day?		Ν	l Precip	itation Amo	unt:		Temp:	Low	, 1	High
Critical Path Work Effected?		Ν	l							
	Ch	Cul		2nd	2nd					
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished		s	Q S	sch
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	os
CORE Construction Services, LLC	1	8				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	6	10				Jobsite Supervision, Safety & Layout & de watering site.		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC	4					Jobsite Supervision, Safety & Layout.		F	F	OS
CORE Construction Services, LLC						Jobsite Supervision, Safety & Layout.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.										
Bernhard Mechanical Contractors, L.L.C.	5	8				Preparing for above ground Plumbing.		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8				preparing for the above ground plumbing.		F	F	
Bernhard Mechanical Contractors, L.L.C.										
Cordeiro LLC										
Cordeiro LLC										
Cordeiro LLC						Rain out				
Cordeiro LLC										
Quality Iron Fabricators Inc.										
Quality Iron Fabricators Inc.										
Malone All Star JV, LLC										
Malone All Star JV, LLC						Rain out				
Malone All Star JV, LLC										
Area A										
Bernhard Mechanical Contractors, L.L.C.	3					Installing sink stands in Area A		F	F	
Quality Iron Fabricators Inc.	10					Hanging Steel Area C, also Detailing Area A&B		F	F	
Area C										
Quality Iron Fabricators Inc.	8	7				Installing Iron in Area C		F	F	
Quality Iron Fabricators Inc.	9	10				Hanging Iron in Area A,B&C		F	F	
Quality Iron Fabricators Inc.	9	10				Hanging steel in Area C, welding in Area A&B		F	F	
Quality Iron Fabricators Inc.	10	10				Hanging Iron in Area C Detailing in Area A&B		F	F	
Area D										
Bernhard Mechanical Contractors, L.L.C.	4	8				Installing Clean outs in Area D		F	F	
Bernhard Mechanical Contractors, L.L.C.	5	8				Installing Clean Outs		F	F	
Malone All Star JV, LLC	4	8				Temporary panel in Area D/ Entergy hooked up temporary power poles		F	F	
Area E Cordeiro LLC	23	10				Placing and tying rebar in area E, Also fixing vapor Barrier in Area		F	F	
						E.				
Cordeiro LLC	22	10				Area E place and tie rebar.		F	F	
Cordeiro LLC	22					Placing and tying rebar in Area E, also working on exterior pile caps.		F	F	
Malone All Star JV, LLC	5	8				Pre fabbing conduit for next slab pour.		F	F	
Malone All Star JV, LLC	2	8				Area E rough in.		F	F	
Malone All Star JV, LLC	4					Rough in Area E.		F	F	

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	05/	29/2015
Weather Dela	nys To Date:		Weather Condition:	Partly/ Cloudy	Day:		Friday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				73	81

Subcontracte	or	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q Sch	
Critical Path V	Vork Effected?		N						7	1 88	
Is Today Clain	ned as Weather Day?		N	Preci	pitation Amou	unt:		Temp:	Low	v High	
Weather Dela	Weather Delays To Date:			Weat	Weather Condition: Overcast			Day:	Day: Monday		
Fair Working	Days To Date:							Date:	(	06/01/2015	
Location:	4801 Maid Marion Drive							Report #:		1	
Project:	Sherwood Forest Element	tary Scho	ol					Job:		14-02-002	

4	12	Jobsite Supervision, Safety & Layout.	F	F	OS
5	11	Jobsite, Safety & de watering.	F	F	OS
5	15	Jobsite, Safety & Supervision.	F	F	OS
6	11	Jobsite, Safety & Supervision.	F	F	OS
		Cleaning up the site.			
6	11	Jobsite, Safety & Supervision.	F	F	OS
		handrails & Clean up.			
5	9	Jobsite, Safety & Supervision.	F	F	OS
	5 5 6	<ul> <li>5 11</li> <li>5 15</li> <li>6 11</li> <li>6 11</li> </ul>	5 11 Jobsite, Safety & de watering. 5 15 Jobsite, Safety & Supervision. 6 11 Jobsite, Safety & Supervision. Cleaning up the site. 6 11 Jobsite, Safety & Supervision. handrails & Clean up.	5 11 Jobsite, Safety & de watering. F 5 15 Jobsite, Safety & Supervision. F 6 11 Jobsite, Safety & Supervision. F Cleaning up the site. 6 11 Jobsite, Safety & Supervision. F handrails & Clean up.	5       11       Jobsite, Safety & de watering.       F       F         5       15       Jobsite, Safety & Supervision.       F       F         6       11       Jobsite, Safety & Supervision.       F       F         6       11       Jobsite, Safety & Supervision.       F       F         6       11       Jobsite, Safety & Supervision.       F       F         handrails & Clean up.       F       F

Bernhard Mechanical Contractors, L.L.C.

Phoenix Constructors LLC

Cordeiro LLC

Quality Iron Fabricators Inc.

Quality Iron Fabricators Inc.

Allied Construction, LLC

Gulf South Engineering & Testing Inc

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:		14-02-002
Fair Working Days To Date:					Date:	0	6/02/2015
Weather Delays To Date:			Weather Condition:	Sunny	Day:		Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	, High
Critical Path Work Effected?		N			-	72	2 89
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Malone All Star JV, LLC							
Area A							
Bernhard Mechanical Contractors, L.L.C.	6	8		Preparing for above ground plumbing Area A		F	F
Bernhard Mechanical Contractors, L.L.C.	5	8		Preparing for the above ground plumbing in Area A.		F	F
Bernhard Mechanical Contractors, L.L.C.	4	8		Laying out materials in Area A		F	F
Bernhard Mechanical Contractors, L.L.C.	16	8		Putting the chair carriers together for Area A.		F	F
Area B							
Cordeiro LLC	15	9		Installing forms for the mock up.		F	F
Cordeiro LLC	14	9		Forming the pile caps in Area B & wrecking forms in Area E.  Installing Rebar in the pile cap's in Area B & pouring the concrete		F	F
				in the pile caps in Area B.			•
Cordeiro LLC	4	8		Removing forms from the pile caps in Area B		F	F
Gulf South Engineering & Testing Inc	1	8		Testing the concrete in Area B's pile cap pour.		F	F
Area C							
Quality Iron Fabricators Inc.	9	10		Hanging Structural Steel in Area C.		F	F
Quality Iron Fabricators Inc.	9	10		Detailing in Area A&B.  Racking the steel structure in Area C.		F	F
quality inon rubineations into		.0		Decking the roof in Area B.			'
Quality Iron Fabricators Inc.	9	10		Plumbing the Structural steel in Area C and detailing in Area's		F	F
Malana All Star IV LLC	4	8		A&B.		F	F
Malone All Star JV, LLC	4	0		Installing temporary power in Area C.		г	r
Area D Malone All Star JV, LLC	4	8		Repaired Temporary Electrical entering the building in Area D		F	F
Malone All Star JV, LLC	4	8		Repairing and pulling new wire fir the temporary in Area D.		F	
	•			nepaining and poining new time in the temporary invited 2.		•	•
Area E  Bernhard Mechanical Contractors, L.L.C.	5	8		Overseeing the floor drains in Area E slab pour.		F	F
Cordeiro LLC	22	9		Installing Rebar in Area E & finishing edge forms in area E.		F	F
				Forming pile caps in Area A&B.			
Cordeiro LLC	25	10		Pouring the slab in Area E		F	F
Quality Iron Fabricators Inc.	10	10		Hanging column's & beam's in Area C. Detailing in Area A&B.		F	F
Malone All Star JV, LLC	4	8		Installing temporary power in Area E.		F	F
Malone All Star JV, LLC	4	8		Temporary power in Area E		F	F
	205	242					

Subcontractor		Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q Sch	
Critical Path	Work Effected?		Ν	I					77	7 90	
Is Today Clair	s Today Claimed as Weather Day?		N Precipitation Amount:			unt:		Temp:	Low	, High	
Weather Del	Veather Delays To Date:			Weath	Weather Condition: Sunny			Day:	<b>r</b> : Monday		
Fair Working	Days To Date:							Date:	0	06/08/2015	
Location:	4801 Maid Marion Drive							Report #:		1	
Project:	Sherwood Forest Elemen	tary Scho	ool					Job:		14-02-002	

CORE Construction Services, LLC	6	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	7	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	5	9	Jobsite, Safety & Supervision.	F	F	OS
Phoenix Constructors LLC				F		
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Phoenix Constructors LLC	3	8	Repairing the silt fence around the job site.	F	F	
Quality Iron Fabricators Inc.						
Allied Construction, LLC						
Allied Construction, LLC						
Allied Construction, LLC						
Allied Construction, LLC						
Allied Construction, LLC						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Malone All Star JV, LLC	4	8	Prefab and installing the 40' Connex box.	F	F	
Malone All Star JV, LLC	2	8	Reviewing the prints for the overhead power.	F	F	

Project: Sherwood Forest Eleme	-	ol			Job:		14-02-002	
<b>Location:</b> 4801 Maid Marion Drive	2				Report #:		1	
Fair Working Days To Date:					Date:		06/08/2015	
Weather Delays To Date:			Weather Condition:	Sunny	Day:		1 6/08/2015 Monday High	
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov	w High	
Critical Path Work Effected?		N			•	7	-	
Area A								
Bernhard Mechanical Contractors, L.L.C.	4	8		Installing Carriers and Chairs in Area A		F	F	
Bernhard Mechanical Contractors, L.L.C.	3	8		Laying out in the building in Area A&B to start installing temporary power.		F	F	
Bernhard Mechanical Contractors, L.L.C.	5	8		Started installing stack's and chairs in Area A		F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing drain lines & stacks in Area A.		F	F	
Cordeiro LLC	17	8		Grouting the column's in Area A.		F	F	
				Excavating for the ramps and Forming them up.				
Malone All Star JV, LLC	4	8		Prefab box's for temporary panels in Area A&B.		F	F	
Malone All Star JV, LLC	4	8		Temporary Panels in Area A&B.		F	F	
Malone All Star JV, LLC	3	8		Installing Temporary panels in Area A.		F	F	
Area B								
Cordeiro LLC	14	8		Back filling the pile cap's in Area B, grouting the columns in Area A&B.		F	F	
Cordeiro LLC	18	8		Back filling Around the pile cap's in Area B. Grouting Column's in Area A&B		F	F	
Cordeiro LLC	14	8		Forming the ramps in Area B,D&E		F	F	
Quality Iron Fabricators Inc.	7	10		Welding the roof deck in Area A&B. Hanging Structural Steel, Area C		F	F	
Quality Iron Fabricators Inc.	9	10		Welding roof deck in Area A&B.		F	F	
				Hanging Structural Steel in Area C.				
Area C								
Bernhard Mechanical Contractors, L.L.C.	3	8		Installing temporary water line's.		F	F	
Quality Iron Fabricators Inc.	9	10		Plumbing the Structural Steel in Area C.		F	F	
				Installing the roof decking in Area's A&B				
Quality Iron Fabricators Inc.	10	10		Detailing the Structural Steel in Area A&B.		F	F	
				Hanging the Structural Steel in area C.				
Area E Cordeiro LLC	17	8		Forming the ramps in Area R.D. & F.		F	F	
Cordeno LLC	17	U		Forming the ramps in Area B,D & E.  Grouting the column's in Area B		'	F	
	184	221						
	10-7							

Subcontract	or	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q S	Sch
Critical Path \	Work Effected?		Ν	l					78	}	90
Is Today Clair	s Today Claimed as Weather Day?			Precipitation Amount:				Temp:	Low	, ,	High
Weather Dela	Veather Delays To Date:				Weather Condition: Overcast			Day:		Mo	nday
Fair Working	Days To Date:							Date:	0	6/15/	2015
Location:	4801 Maid Marion Drive							Report #:			1
Project:	Sherwood Forest Elemen	tary Scho	ool					Job:		14-02	2-002

CO	RE Construction Services, LLC	6	11	Jobsite, Safety & Supervision.	F	F	OS
CO	RE Construction Services, LLC	7	11	Jobsite, Safety & Supervision.	F	F	OS
CO	RE Construction Services, LLC	6	11	Jobsite, Safety & Supervision.	F	F	OS
CO	RE Construction Services, LLC	7	14	Jobsite, Safety & Supervision.	F	F	OS
CO	RE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
Ph	oenix Constructors LLC						
Pho	oenix Constructors LLC						
Ph	oenix Constructors LLC						
Ph	oenix Constructors LLC						
Ph	oenix Constructors LLC						
Alli	ed Construction, LLC						
Gu	lf South Engineering & Testing Inc						
Gu	If South Engineering & Testing Inc						
Gu	lf South Engineering & Testing Inc						
Gu	If South Engineering & Testing Inc						
Ar	ea A						
Bei	rnhard Mechanical Contractors, L.L.C.	6	8	Hanging the vents and prefabing pipe in Area A	F	F	
Bei	rnhard Mechanical Contractors, L.L.C.	5	8	Working in Area A installing vents.	F	F	
Bei	rnhard Mechanical Contractors, L.L.C.	5	8	Continued to run vents in Area A	F	F	
Bei	rnhard Mechanical Contractors, L.L.C.	5	8	Running Vent stacks in Area A	F	F	
Bei	rnhard Mechanical Contractors, L.L.C.	5	8	Waiting on walls to be laid out, installing vent stacks in Area A.	F	F	
Alli	ed Construction, LLC	3	8	Mobilizing in Area A	F	F	
Alli	ed Construction, LLC	8	9	Installing CMU wall in Area A.	F	F	

Project: Sherwood Forest Elem	entary Scho	ol			Job:		14-02-002
<b>Location:</b> 4801 Maid Marion Driv	re e				Report #:		1
Fair Working Days To Date:					Date:		06/18/2015
Weather Delays To Date:			Weather Condition:	Partly/Cloudy	Day:		Thursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov	w High
Critical Path Work Effected?		N				7	'8 89
Allied Construction, LLC	8	10		Installing CMU blocks in Area A.		F	F
Allied Construction, LLC	13	10		Installing CMU blocks in Area A& B.		F	F
Malone All Star JV, LLC	3	8		Temporary electrical panels in Area A		F	F
Malone All Star JV, LLC	3	8		Temporary lightning in Area A & B		F	F
Malone All Star JV, LLC	4	8		Installed conduits in CMU walls.		F	F
Malone All Star JV, LLC	4	8		Overhead conduits in Area A		F	F
Area B							
Cordeiro LLC	12	9		Forming the Stage in Area B.		F	F
				Grouting the column block outs.			
Gulf South Engineering & Testing Inc	1	8		Testing the Welds in Area A & B.		F	F
Malone All Star JV, LLC	4	8		Installing Temporary lighting in Area B.		F	F
Area C							
Cordeiro LLC	13	9		Forming the Canopy in Area C, grouting the column block outs and forming the stage.		F	F
Cordeiro LLC	14	10		Installing forms for the canopy, Forming the stage in Area B.		F	F
Cordeiro LLC	12	14		Pouring the stage, and forming the canopy in Area C		F	F
Cordeiro LLC	12	9		Forming Grade beams in Area C. Grouting column block outs in Area C.		F	F
Quality Iron Fabricators Inc.	10	10		Detailing the Structural Steel in Area B & C.		F	F
Quality Iron Fabricators Inc.	9	10		Installing the roof frames, installing roof angels on the mezzanine and detailing Structural steel.		F	F
Area D							
Quality Iron Fabricators Inc.	9	10		Installing Columns and Beams in Area D, Detailing in Area's A $\&$ B.		F	F
Quality Iron Fabricators Inc.	10	10		Structural Steel in Area D, Detailing in Area C.		F	F
Quality Iron Fabricators Inc.	9	10		Detailing in Area B $\&$ C , Installing column's and beam in Area D.		F	F
	218	284					

Subcontract	or	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q Sch	1
Critical Path \	Work Effected?		Ν	l					77	' (	93
Is Today Clair	s Today Claimed as Weather Day?		Ν	l Precip	itation Amo	unt:		Temp:	Low	Hig	зh
Weather Dela	/eather Delays To Date:				Weather Condition: Overcast			Day:		Monda	ay
Fair Working	Days To Date:							Date:	0	6/22/20	15
Location:	4801 Maid Marion Drive							Report #:			1
Project:	Sherwood Forest Elemen	tary Scho	ol					Job:		14-02-00	ე2

CORE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC	5	11	Jobsite, Safety & Supervision.	F	F	OS
CORE Construction Services, LLC		8	Jobsite, Safety & Supervision.	F	F	OS
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Area A						
Bernhard Mechanical Contractors, L.L.C.	5	8	Rerouting vent stack's in Area A over the bathroom.	F	F	
Bernhard Mechanical Contractors, L.L.C.	6	8	Running Hangers for Domestic water lines and installing Vent	F	F	
		2	Stacks.	_		
Bernhard Mechanical Contractors, L.L.C.	6	8	Installing pipe hangers in Area A. Moving pipe in Area B.	F	F	
Bernhard Mechanical Contractors, L.L.C.		8	Running Domestic and Chill water Hangers in Area A.	F	F	
Malone All Star JV, LLC	4	8	Overhead conduits in Area A.	F	F	
Malone All Star JV, LLC	4	8	Overhead Conduits Area A, and installing CMU block Conduits.	F	F	
Area B						
Allied Construction, LLC	13	10	Installing CMU block in Area's A & B	F	F	
Malone All Star JV, LLC	4	8	Installing conduits in Area A, B & masonry wall's.	F	F	
Area C						
Cordeiro LLC	12	9	Forming grade beams in Area C.	F	F	
Cordeiro LLC	13	9	Grade beams and ramps in Area C.	F	F	
Cordeiro LLC	13	10	Area C grade beam and ramps.	F	F	

Project: Sherwood Forest Location: 4801 Maid Marior	-	ol			Job: Report #:		14-0	2-002
Fair Working Days To Date:					Date:	1	06/26	· 5/2015
Weather Delays To Date:			Weather Condition:	Cloudy/Rain	Day:			Friday
Is Today Claimed as Weather Day	y?	Ν	Precipitation Amount:		Temp:	Lov	N	High
Critical Path Work Effected?		N				7	73	89
Cordeiro LLC		6		Reinstalling pipes for the transformer pad, pipes where installed in the wrong place.		F	F	
Quality Iron Fabricators Inc.	10	10		Hanging Structural Steel in Area D, roof decking in Area C and detailing.		F	F	
Allied Construction, LLC	13	10		Installing CMU block's in Area A B & C		F	F	
Allied Construction, LLC	18	10		Installing CMU block's in Area A, B & C.		F	F	
Allied Construction, LLC		6		Pouring CMU block wall's in Area C.		F	F	
Malone All Star JV, LLC		7		Installing conduit's in Area A & C & CMU block wall's.		F	F	
Area D								
Quality Iron Fabricators Inc.	10	10		Hanging Structural Steel in Area D, and detailing in Area C.		F	F	
Quality Iron Fabricators Inc.	10	10		Installing Structural steel in Area D, detailing in Area C.		F	F	
Quality Iron Fabricators Inc.		6		Hanging Structural Steel in Area D, detailing in Area C.		F	F	
	156	210						

Project: Sherwood Forest Elem Location: 4801 Maid Marion Driv		ool					Job: Report #:		14-0	02-002
Fair Working Days To Date:							Date:		07/01	1/2015
Weather Delays To Date:				er Conditio	n:	Sunny	Day:		Wedn	nesday
Is Today Claimed as Weather Day?		N	· · · · · · ·	itation Amo	unt:		Temp:	Lo		High
Critical Path Work Effected?		N						7	73	91
				2nd	2nd					
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished		s	Q	Sch
				WING	- 1115	•				
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	os
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC										
Bernhard Mechanical Contractors, L.L.C.	5	8				Installing the above ground plumbing in Area B.		F	F	
Bernhard Mechanical Contractors, L.L.C.										
Morris Drywall Systems Inc										
Morris Drywall Systems Inc										
Morris Drywall Systems Inc										
Phoenix Constructors LLC										
Phoenix Constructors LLC										
Phoenix Constructors LLC										
Cordeiro LLC								F	F	
Cordeiro LLC										
Quality Iron Fabricators Inc.	11	10				Detailing in Area D, also hanging columns and beams in Area D & E.		F	F	
Quality Iron Fabricators Inc.						L.				
Allied Construction, LLC										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Malone All Star JV, LLC										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Area A Allied Construction, LLC	13	10				Installing Blocking in Area's A & B		F	F	
Malone All Star JV, LLC	4	8				Installing Electrical home runs in walls in ceilings		F	F	
Malone All Star JV, LLC	4	8				Installing Electrical home runs in walls in ceilings Area A.		F	F	
<b>Area B</b> Bernhard Mechanical Contractors, L.L.C.	6	8				Installing the above ground plumbing in Area B.		F	F	
Area C										
Cordeiro LLC	11	9				Removing Forms at Canopy grade beams.		F	F	
All'ad Carrier of LUC	_	46				Grouting the columns in Area D		_	_	
Allied Construction, LLC	8	10				Installing CMU Blocking in Area's C		F	F	
Area D		40				15.00		_	-	
Quality Iron Fabricators Inc.		10	_			Installing columns and Detailing in Area D.		F	F	
	72	103								

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	07/	/02/2015
Weather Dela	ys To Date:		Weather Condition:	Overcast	Day:	Т	Thursday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				75	91

Project: Sherwood Forest Elem Location: 4801 Maid Marion Driv	_	ool					Job: Report #:		14-	-02-00 <i>2</i>
Fair Working Days To Date:							Date:		07/0	06/201
Weather Delays To Date:			Weath	er Conditio	n:	Partly/Cloudy	Day:		N	Иonday
Is Today Claimed as Weather Day?		N		itation Amo			Temp:	Lo	w	High
Critical Path Work Effected?		N					•		73	91
				2nd	2nd					
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished		s	Q	Sch
				WINIS	1113					
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	6	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	7	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	7	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite, Supervision & Safety		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	8				Installing vents and Waste stacks in Area C, Finishing up the floor drains in Area B.		F	F	
Morris Drywall Systems Inc	1	10				Laying out for the walls in Area B		F	F	
Phoenix Constructors LLC										
Phoenix Constructors LLC	2	8				Transferring the Mound of soil on side of Area E to a new location.				
Phoenix Constructors LLC	2	8				Transferring the soil stock pile from Area E to a new location.				
Cordeiro LLC								F	F	
Cordeiro LLC	7	10				Installing the rebar for the Canopy and Transformer pad.		F	F	
Quality Iron Fabricators Inc.	11	10				Detailing in Area D, also hanging columns and beams in Area D.		F	F	
Allied Construction, LLC		10				Installing the CMU Blocking in Area C, also pouring the cell's of CMU blocks as well.		F	F	
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc	4	0				Land Control of the C		-	_	
Malone All Star JV, LLC	4	8				Installing conduits for the transformer pad.		F	F	
Atlas-Edco Inc Atlas-Edco Inc										
Atlas-Edco Inc Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc Atlas-Edco Inc										
<b>Area A</b> Morris Drywall Systems Inc	1	10				Laying out walls in Area A.		F	F	
Morris Drywall Systems Inc		10				Laying out the walls in Area A.		F	F	
Morris Drywall Systems Inc	4	10				Installing Metal I studs and Hanging Gypsum board in Area A		F	F	
Morris Drywall Systems Inc		10				Installing Metal studs and Hanging Gypsum board in Area A		F	F	

Installing Blocking in Area A fire pump room.

Allied Construction, LLC

12 10

Project: Sherwood Forest Eleme	-	ol			Job:		14-02-002
<b>Location:</b> 4801 Maid Marion Drive	9				Report #:		1
Fair Working Days To Date:					Date:	(	07/06/2015
Weather Delays To Date:			Weather Condition:	Partly/Cloudy	Day:		Monday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov	v High
Critical Path Work Effected?		N				7	3 91
Malone All Star JV, LLC	4	8		Installing Electrical home runs in walls in ceilings Area A		F	F
Area B							
Bernhard Mechanical Contractors, L.L.C.	5	8		Installing Domestic water lines and vent stacks in Area B		F	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in Area B		F	F
Allied Construction, LLC	15	10		Installing Blocking in Area B & C		F	F
Area C							
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in Area C		F	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks.		F	F
Cordeiro LLC	12	10		Installing Rebar for the Transformer pad.		F	F
Cordeiro LLC	8	10		Installing the wire mesh on the mezzanine deck, also Pouring the transformer pad.		F	F
Cordeiro LLC	9	10		Installing the wire mesh on the Mezzanine deck.		F	F
Allied Construction, LLC	12	10		Installing CMU Blocking in Area C		F	F
Allied Construction, LLC	9	10		Installing CMU Blocking in Area C		F	F
Malone All Star JV, LLC	4	8		Installing conduits in the electrical pad Area C		F	F
Malone All Star JV, LLC	3	8		Installing electrical conduit for the transformer pad.		F	F
Malone All Star JV, LLC	4	8		Installing temporary power in Area C		F	F
Area D							
Quality Iron Fabricators Inc.	14	10		Detailing in Area D, also hanging columns and beams in Area D.		F	F
Quality Iron Fabricators Inc.	14	10		Detailing in Area D, also hanging columns and beams in Area D.		F	F
Quality Iron Fabricators Inc.	13	10		Detailing in Area D, also hanging columns and beams in Area D		F	F
Quality Iron Fabricators Inc.	12	10		Detailing in Area D, also hanging columns and beams in Area D.  Installing Some decking on the second floor of area D.		F	F
Area E							
Phoenix Constructors LLC	2	8		Moving the pile of mud from on side of Area E		F	F
Phoenix Constructors LLC	2	8		Relocating the dirt pile on side of Area E to a new location.			
	239	357					

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive Fair Working Days To Date: Weather Delays To Date: Is Today Claimed as Weather Day?		<b>pol</b>	i	ner Condition itation Amo		Sunny	Job: Report #: Date: Day: Temp:	Lo	07/1 M	02-002 1 3/2015 1onday High
Critical Path Work Effected?		N	l					7	78	95
				2nd	2nd					
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished		S	0	Sch
<u>Substitution</u>	Wikis		2.10 110	Wrkrs	Hrs	TOTAL PROGRAMME				
CORE Construction Services, LLC	4	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	4	11				Jobsite, Supervision & Safety		F	·	OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	3	9				Jobsite, Supervision & Safety		F	F	OS
Bernhard Mechanical Contractors, L.L.C.										
Morris Drywall Systems Inc										
Phoenix Constructors LLC	2	8				Transferring the dirt pile on side of area E to a new location.				
Phoenix Constructors LLC										
Phoenix Constructors LLC	3	8				Fixing the swppp Around the job site.				
Phoenix Constructors LLC	3	8				Installing drain pipe at the ramps in the rear of the gym.				
Phoenix Constructors LLC										
Cordeiro LLC										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Malone All Star JV, LLC										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas Edga Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Area A Morris Drywall Systems Inc	8	10				Installing Metal studs and Hanging Gypsum board in Area A		F	F	
Morris Drywall Systems Inc	ŭ	10						F	F	
Drywan Systems Inc		10				Installing the exterior metal stud in Area A		1.	F	

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14	4-02-002 1
Fair Working Days To Date:					Date:	07,	/16/2015
Weather Delays To Date:			Weather Condition:	Sunny	Day:	-	Thursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				88	96
Morris Drywall Systems Inc	8	10		Installing Metal studs and Hanging Gypsum board on the exterior		F I	F
Morris Drywall Systems Inc	8	10		in the loading dock Area A Installing Metal studs and Hanging Gypsum board on the exterior Area A&B		F į	F
Allied Construction, LLC	12	10		Installing CMU Blocking in Area's A&C also pouring the CMU cells with concrete.		F I	F
Malone All Star JV, LLC	3	8		Installing Electrical home runs in walls in ceilings in Area A, also installing conduits in CMU walls in Area C.		F I	F
Malone All Star JV, LLC	4	8		Installing Electrical home runs in stud walls Area A, also installing conduits in the CMU walls Area C		F I	F
Malone All Star JV, LLC	5	8		Installing Electrical home runs in walls in Area A		F (	F
Area B							
Morris Drywall Systems Inc	8	10		Installing Metasl studs and Hanging Gypsum board on the exteriors of Area A & B		F	F
Allied Construction, LLC	11	10		Installing CMU blocking in Area's B & C		F I	F
<b>Area C</b> Bernhard Mechanical Contractors, LL.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in area C		F	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in  Area C		F I	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in  Area C		F	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in Area C		F	F
Bernhard Mechanical Contractors, L.L.C.	6	8		Installing Carriers, Domestic water lines & Sewer vent stacks in Area C		F I	F
Phoenix Constructors LLC		8		Installing pipe in the rear of the GYM"S ramps.			
Cordeiro LLC	10	10		Pouring Concrete ramps in Area C		F	F
Cordeiro LLC	9	10		Pouring the walls for the ramps in the rear of Area C		F	F
Cordeiro LLC	11	10		Pouring the beams for the ramp at the electrical pad		F (	F
Cordeiro LLC	9	10		Removing forms and Grading Around the electrical pad		F	F
Cordeiro LLC	9	10		Grading Around the Transformer pad, also forming and installing rebar at the pad.		F	F
Allied Construction, LLC	12	10		Installing CMU Blocking for the bathrooms in Area C		F (	F
Allied Construction, LLC	17	10		Installing CMU Blocking in Area C also pouring the cells in the CMU blocking.		F	F
Allied Construction, LLC	15	10		Installing CMU Blocking Around the stage wall in the GYM		F I	F
Allied Construction, LLC	6	8		Pouring concrete in Cells of the CMU blocking also clean up.		F (	F
Malone All Star JV, LLC	4	8		Repairing the temporary conduits in Area C		F I	F
Malone All Star JV, LLC	4	8		Installing conduit in the CMU walls in Area C		F	F
Area D	10	10		Detailing in Area D. ales harrier arthurs and the control of		г .	-
Quality Iron Fabricators Inc.	13	10		Detailing in Area D, also hanging columns and beams in Area D		r 1	r -
Quality Iron Fabricators Inc.	12	10		Detailing and decking 2nd floor of Area D		r 1	r -
Quality Iron Fabricators Inc.	11	10		Detailing in Area D, also hanging columns and beams in Area D.		F	t -
Quality Iron Fabricators Inc.	11	10		Detailing in Area D, also hanging columns and beams in Area D		F	-
Quality Iron Fabricators Inc.	12	10		Detailing in Area D, also hanging columns and beams in Area D		F 1	-
Quality Iron Fabricators Inc.	7	8		Detailing in Area D.		F	F
	302	390					

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive Fair Working Days To Date:		ool					Job: Report #: Date:			02-002 1 0/2015
Weather Delays To Date:			Weath	er Conditio	n:	Sunny	Day:		M	1onday
Is Today Claimed as Weather Day?		Ν	Precip	itation Amo	unt:		Temp:	Lov	v	High
Critical Path Work Effected?		Ν	I					7	7	91
				2nd	2nd					
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished		s	Q	Sch
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	, E	OS
CORE Construction Services, LLC	6	11				Jobsite, Supervision & Safety		F	F	OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety		F	· F	OS
CORE Construction Services, LLC										
Bernhard Mechanical Contractors, L.L.C.										
Morris Drywall Systems Inc										
Phoenix Constructors LLC	4	8				Installing the down spouts in the court yard.				
Phoenix Constructors LLC						, ,				
Phoenix Constructors LLC										
Cordeiro LLC										
Quality Iron Fabricators Inc.										
River City Fire Protection										
Allied Construction, LLC										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
CFI Insulation Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Gulf South Engineering & Testing Inc										
Malone All Star JV, LLC										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
Atlas-Edco Inc										
<b>Area A</b> Bernhard Mechanical Contractors, L.L.C.	7	8				Installing Carriers, Domestic water lines & Sewer vent stacks Area  A&C also making roof penetrations		F	F	
Bernhard Mechanical Contractors, L.L.C.	7	8				Installing Carriers, Domestic water lines & Sewer vent stacks in		F	F	

Area A also roof penetrations

Part	Project: Sherwood Forest Elemental Location: 4801 Maid Marion Drive	=	ol			Job: Report #:	14	4-02-002 1
Probaby Claritation & Westler Day's   Probaby Information & Probaby Claritation Amounts   Prob	Fair Working Days To Date:					Date:	07,	/24/2015
Contained Park Whork Effected   11	Weather Delays To Date:			Weather Condition:	Sunny	Day:		Friday
Grideria LLC 11 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the Control 1 Forming the control camps in Avea AMR Formation Control 1 Forming the Control 1 Form	Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Alled Construction LLC	Critical Path Work Effected?		N				77	96
Malion All Sart M. LC	Cordeiro LLC	11			Forming the exterior ramps in Area A&B		FF	
Malone All Start M, LLC    So   S   Recommendation   Reco	Allied Construction, LLC	9	10		Preping to install finish brick around area A		F F	Ţ.
Conduction in Aman CAUNU block wasters   Conduction in Aman CAUNU block wast	Allied Construction, LLC	9	10		Installing the exterior Finish brick in area A		F	F
Mallore All Star IV, LLC 7 8 8 Installing Description home runs in walls Area A 8 7 8 Mallore All Star IV, LLC 8 8 8 Installing Description home runs in walls in Area A 8 7 8 Mallore All Star IV, LLC 8 8 8 Installing Demissic water lines & Sewer vent Stacks in area C 8 8 8 Installing Demissic water lines & Sewer vent Stacks in area C 8 8 8 Installing Demissic water lines & Sewer vent Stacks in area C 8 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 8 8 Installing Demissic water lines & Sewer vent Stacks in Area C 8 9 10 10 10 10 10 10 10 10 10 10 10 10 10	Malone All Star JV, LLC	6	8				FF	=
Malone All Satr M, LLC 7 8 8 Installing Electrical hore runs in valls in Area A 8 8  Area C 8  Benhard Mechanical Contractors, LLC 6 8 8 Installing Domestic water lines & Sever vent stacks in area C 7 F 6 6 8 Installing Domestic water lines & Sever vent stacks in Area C 7 F 7 F 7 F 7 F 8 F 8 F 8 F 9 F 9 F 9 F 9 F 9 F 9 F 9	Malone All Star JV, LLC	5	8		Installing Electrical home runs in walls Area A		F F	F
Area B Makeur Al Starr IV, LC	Malone All Star JV, LLC	7	8		Installing Electrical home runs in walls Area A		F F	F
Area C  Fig. 8  Fig. 8	Malone All Star JV, LLC	7	8		Installing Electrical home runs in walls in Area A		F F	F
Bernhard Michanical Contractors, LLC. 6 8 8 Installing Domestic water lines & Sewer vent stacks in area C F 8 7 8 8 8 8 8 8 8 8 8 9 8 9 8 9 8 9 9 9 9		6	8		Installing Electrical home runs in walls in Area B		F	F
Bernhard Michanical Contractors, LLC. 6 8 8 Installing Domestic water lines & Sewer vent stacks in Avea C F F F F Sembard Michanical Contractors, LLC. 6 8 8 Installing Domestic water lines & Sewer vent stacks F F F F F F F F F F F F F F F F F F F		6	0		Latelline Demonities about on the Common state of the Common Comm			_
Bernhard Mechanical Contractors, LLC. 6 8 8 Installing Domestic water lines & Sewer vent stacks. 7 F F F F F F F F F F F F F F F F F F F					-			-
Morris Drywell Systems Inc  8	•				, and the second			-
Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board on the exterior of A & C  Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board exterior Area  C  Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board exterior Area  C  Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board exterior Area  C  Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board on the exterior Area  C  Morris Drywall Systems Inc  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Metal studs and Hanging Gypsum board on the exterior  Installing Gypsum board on the exterior  Installing Avoid the electrical pad.  Installing Own Dile in the electrical pad.  Installing Own Electrical pad.  Installing Own Electrical pad.  Installing Own Electrical pad.  Installing Own Installing the CMU blocks in the  Installing Own Installing the CMU blocks in the coll blocks.  Installing Own Installing Own Installing the CMU blocks in the coll blocks.  Installing Own					-			-
Morris Drywall Systems Inc    10   10   10   10   10   10   10   1	Morris Drywaii Systems inc	0	10		5 5 7.		' '	-
Morris Drywall Systems Inc    10   Installing exterior metal framing in area B and sheeting the exterior of Area C   Morris Drywall Systems Inc   12   10   Installing Metal studs and Hanging Gypsum board on the exterior of the exterior of Area C   Morris Drywall Systems Inc   12   10   Installing Metal studs and Hanging Gypsum board on the exterior of the exterior of the gym.   Cordeiro LLC   10   10   10   Forming the electrical pad.   F   F     Cordeiro LLC   10   10   Installing rebar in the electrical pad.   F   F     Cordeiro LLC   11   8   Pump place and finish the concrete for the electrical pad.   F   F     Allied Construction, LLC   8   10   Installing CMU Blocking in Area C and filling the cells with concrete or oncrete.   Allied Construction, LLC   7   10   Prepping For air barrier, also completing the CMU blocks in the GYM     Allied Construction, LLC   6   10   Finishing up filling the concrete in the cells of the CMU Blocks.   F   F     Area D     Phoenix Constructors LLC   5   8   Installing down spout in the court yard     Phoenix Constructors LLC   5   8   Installing down spout in the court yard     Phoenix Constructors LLC   5   8   Installing down spout in the court yard     Phoenix Constructors LLC   5   8   Installing down spout in the court yard     Quality Iron Fabricators Inc.   10   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   11   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   15   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   15   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   15   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   15   10   Detailing in Area D, also hanging columns and beams in Area D & F   F     Quality Iron Fabricators Inc.   15   10   Detailing in Are	Morris Drywall Systems Inc	10	10				F	F
Morris Drywall Systems Inc  12 10 10 Installing Metal studs and Hanging Gypsum board on the exterior of the gym.  Cordeiro LLC  10 10 10 Forming the electrical pad. Forming Around the electri	Morris Drywall Systems Inc	10	10				F	F
Cordeiro LLC  10 10 10 Forming Around the electrical pad. F F F Cordeiro LLC 10 10 10 Installing rebar in the electrical pad. F F F F Cordeiro LLC Cordeiro LLC 11 8 10 Installing CMU Blocking in Area C and filling the cells with concrete. Allied Construction, LLC R Allied Construction, LLC 7 10 10 Repring For air barrier, also completing the CMU blocks in the GYM Allied Construction, LLC F F F F F F F F F F F F F F F F F F	Morris Drywall Systems Inc		10				F	F
Cordeiro LLC  10 10 10 10 10 10 10 10 10 10 10 10 10	Morris Drywall Systems Inc	12	10				F	Ξ
Cordeiro LLC  10 10 10 10 10stalling rebar in the electrical pad Area. F F F Cordeiro LLC  11 8 10 Installing CMU Blocking in Area C and filling the cells with concrete for the electrical pad. F F F F F F F F F F F F F F F F F F F	Cordeiro LLC	10	10		Forming the electrical pad.		F F	=
Cordeiro LLC  11 8  Pump place and finish the concrete for the electrical pad.  F F F F Allied Construction, LLC  Allied Construction, LLC  7 10  Prepping For air barrier, also completing the CMU blocks in the GYM  Allied Construction, LLC  6 10  Finishing up filling the concrete in the cells of the CMU Blocks.  F F F F F F F F F F F F F F F F F F F	Cordeiro LLC	10	10		Forming Around the electrical pad.		F F	F
Allied Construction, LLC  8 10 Installing CMU Blocking in Area C and filling the cells with concrete.  Allied Construction, LLC  7 10 Prepping For air barrier, also completing the CMU blocks in the GYM  Allied Construction, LLC  6 10 Finishing up filling the concrete in the cells of the CMU Blocks.  F F F F F F F F F F F F F F F F F F F	Cordeiro LLC	10	10		Installing rebar in the electrical pad Area.		F F	F
Concrete.  Allied Construction, LLC  7 10  Prepping For air barrier, also completing the CMU blocks in the GYM  Allied Construction, LLC  6 10  Finishing up filling the concrete in the cells of the CMU Blocks.  F F F F F F F F F F F F F F F F F F F	Cordeiro LLC	11	8		Pump place and finish the concrete for the electrical pad.		F F	F
Area D Phoenix Constructors LLC 5 8 Installing down spout in the court yard Phoenix Constructors LLC 5 8 Installing down spout in the court yard Phoenix Constructors LLC 5 8 Installing down spout in the court yard Phoenix Constructors LLC 5 8 Installing down spout in the court yard Phoenix Constructors LLC 5 8 Installing down spout in the court yard Phoenix Constructors LLC 5 8 Installing down spouts in the court yard Phoenix Constructors LLC 5 8 Installing down spouts in the court yard. Phoenix Constructors LLC 5 8 Installing down spouts in the court yard. Phoenix Constructors LLC 5 9 Installing down spouts in the court yard. Phoenix Constructors LLC 5 9 Installing down spouts in the court yard. Phoenix Constructors LLC 5 Installing down spouts in the court yard. Phoenix Constructors LLC 5 Installing down spouts in the court yard. Phoenix Constructors LLC Installing down spouts in the court yard. Phoenix Constructors LLC Installing down spouts in the court yard. Phoenix Constructors LLC Installing down spout in the court yard. Phoenix Constructors LLC Installing down spout in the court yard. Phoenix Constructors LLC Installing down spout in the court yard. Phoenix Constructors LLC Installing down spout in the court yard. Phoenix Constructors LLC Installing down spout in the court yard. Phoenix Constructors LLC Installing in Area D, also hanging columns and beams in Area D, also hanging columns and beams in Area D & F F F F F F F F F F F F F F F F F F	Allied Construction, LLC	8	10				F	F
Area D Phoenix Constructors LLC S 8 Installing down spout in the court yard Phoenix Constructors LLC Installing the down spout in the court yard Phoenix Constructors LLC Installing down spouts in the court yard Installing down spout in the court yard Insta	Allied Construction, LLC	7	10				F	F
Phoenix Constructors LLC  Phoenix Constructors Int.  Phoenix	Allied Construction, LLC	6	10		Finishing up filling the concrete in the cells of the CMU Blocks.		F	=
Phoenix Constructors LLC  Phoenix Constructors LLC  S  8  Installing the down spout in the court yard  F  F  F  Quality Iron Fabricators Inc.  10  10  10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  11  10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  11  10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  11  10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  15  10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  Detailing in Area D, also hanging columns and beams in Area D & F  E.								
Phoenix Constructors LLC  5 8 Installing down spouts in the court yard.  F F Quality Iron Fabricators Inc.  10 10 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  11 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  11 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.								
Quality Iron Fabricators Inc.  10 10  Detailing in Area D, also hanging columns and beams in Area D, also hanging columns and beams in Area D & F F F F F F F F F F F F F F F F F F							_	
Aguality Iron Fabricators Inc.  9 10  Detailing in Area D, also hanging columns and beams in Area D & F F F  E.  Quality Iron Fabricators Inc.  11 10  Detailing in Area D, also hanging columns and beams in Area D & F F F  E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F F F  E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F F F  E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F F F  E.					, ,		F 1	=
Quality Iron Fabricators Inc.  9 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  11 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.	Quality Iron Fabricators Inc.	10	10				F	=
Quality Iron Fabricators Inc.  11 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F E.	Quality Iron Fabricators Inc.	9	10		Detailing in Area D, also hanging columns and beams in Area D &		F	Ē.
Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  Quality Iron Fabricators Inc.  15 10  Detailing in Area D, also hanging columns and beams in Area D & F  E.  E.	Quality Iron Fabricators Inc.	11	10		Detailing in Area D, also hanging columns and beams in Area D $\&$		F	F
Quality Iron Fabricators Inc. 15 10 Detailing in Area D, also hanging columns and beams in Area D & F F  E.	Quality Iron Fabricators Inc.	15	10		Detailing in Area D, also hanging columns and beams in Area D $\&$		F	F
<del></del>	Quality Iron Fabricators Inc.	15	10		Detailing in Area D, also hanging columns and beams in Area D $\&$		F	=
		299	354					

Project:	Sherwood Forest Elemen	tary Scho	ol					Job:		14-02-002
Location:	4801 Maid Marion Drive							Report #:		1
Fair Working	Days To Date:							Date:	C	07/26/2015
Weather Dela	ys To Date:			Weath	er Condition	ı:		Day:		Sunday
Is Today Clain	ned as Weather Day?		Ν	Precipi	itation Amou	ınt:		Temp:	Low	v High
Critical Path V	Vork Effected?		Ν	I						
Subcontracto	or	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished		s	Q Sch

	Cul	Cul		2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
						·		
CORE Construction Services, LLC		11				Jobsite, Supervision & Safety	F	F OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety	F	F OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety	F	F OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety	F	F OS
CORE Construction Services, LLC	5	11				Jobsite, Supervision & Safety	F	F OS
Bernhard Mechanical Contractors, L.L.C.		8				Installing Carriers, Domestic water lines & Sewer vent stacks.	F	F
Morris Drywall Systems Inc		10				Installing Metasl studs and Hanging Gypsum board	F	F
Phoenix Constructors LLC		10						
Phoenix Constructors LLC								
Phoenix Constructors LLC	5	10				Installed a Drain box in the court yard and saw cut the street on Maid Marion	F	F
Phoenix Constructors LLC	7	10				Breaking up the concrete on MaidMarion.	F	F
Cordeiro LLC							F	F
Quality Iron Fabricators Inc.						Detailing in Area D, also hanging columns and beams in Area D & E.	F	F
River City Fire Protection								
Allied Construction, LLC						Installing Blocking in Area's	F	F
CFI Insulation Inc								
CFI Insulation Inc								
CFI Insulation Inc								
CFI Insulation Inc								
CFI Insulation Inc								
Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc								
Malone All Star JV, LLC		8				Installing Electrical home runs in walls in ceilings	F	F
Atlas-Edco Inc		10						
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
<b>Area A</b> Bernhard Mechanical Contractors, L.L.C.	8	8				Installing domestic water line in Area A also installing gas lines in	F	F
Bernhard Mechanical Contractors, L.L.C.	6	8				Area A Installing Domestic water lines & Sewer vent stacks and gas lines	F	F
Cordeiro LLC	10	10				in Area A Installing rebar in the exterior ramps of area A & B.	F	F
River City Fire Protection		10				Installing pipe hangers in Area A & B	F	F
River City Fire Protection	7	10				Installing sprinkler pipe in Area A, B & C	•	'
River City Fire Protection	7	10				Installing Sprinkler pipe in Area A, B & C		
Allied Construction, LLC	13	10				Installing Exterior brick in area A & B	F	F
	.5						•	

Project: Sherwood Forest Eleme 4801 Maid Marion Drive	-	ol			Job:		14-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:		07/30/2015
Weather Delays To Date:			Weather Condition:	Sunny	Day:		Thursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov	w High
Critical Path Work Effected?		N				7	'8 96
Allied Construction, LLC	6	10		Installing the exterior finished brick around Area A & B		F	F
Malone All Star JV, LLC	6	8		Installing Electrical home runs in walls in Area A & B		F	F
Malone All Star JV, LLC	6	8		Installing Electrical home runs in walls in Area A&B		F	F
Area B							
Cordeiro LLC	9	10		Installing rebar in the exterior ramps of Area A & B		F	F
Malone All Star JV, LLC	6	8		Installing Electrical home runs in walls in Area A $\&$ B		F	F
Malone All Star JV, LLC	6	8		Installing Electrical home runs in walls in Area A & B		F	F
Area C							
Bernhard Mechanical Contractors, L.L.C.	8	8		Installing Carriers, Domestic water lines & Sewer vent stacks in area C		F	F
Bernhard Mechanical Contractors, L.L.C.	8	8		Installing Domestic water lines & Sewer vent stacks, also installing gas lines in Area A		F	F
Morris Drywall Systems Inc	14	10		Installing Metasl studs and Hanging Gypsum board on the Exterior of the Gym		F	F
Morris Drywall Systems Inc	16	10		Installing Metal studs and Hanging Gypsum board on the exterior of Area C, also laying out the walls on the mezzanine		F	F
Morris Drywall Systems Inc	17	10		Framed the North wall of the Gym exterior also framing the south side of the Gym Area		F	F
Morris Drywall Systems Inc	14	10		Installing Metal studs and Hanging Gypsum board on the exterior of Area C		F	F
Cordeiro LLC	7	10		Form exterior ramps out side the North side of the GYM		F	F
Cordeiro LLC	7	8		Forming the exterior ramps out side the north side of the gym		F	F
Allied Construction, LLC	14	10		Installing CMU blocks in the bathrooms of Area C		F	F
Allied Construction, LLC	8	10		Installing CMU Blocking in the bathrooms of Area C		F	F
Area D							
Phoenix Constructors LLC	5	10		Tying in down spouts in the court yard.		F	F
Quality Iron Fabricators Inc.	14	10		Detailing in Area D, also hanging columns and beams in Area D & E.		F	F
Quality Iron Fabricators Inc.	14	10		Detailing in Area D, also hanging columns and beams in Area D & E.		F	F
Quality Iron Fabricators Inc.	13	10		Detailing in Area D, also hanging columns and beams in Area D & E.		F	F
Quality Iron Fabricators Inc.	14	10		Detailing in Area D, also hanging columns and beams in Area D & E.		F	F
	295	383					

Project:	Sherwood Forest Elementary School					Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Re	port #:		1
Fair Working	Days To Date:					Date:	08/0	03/2015
Weather Dela	nys To Date:		Weather Condition:	Sunny		Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:			Temp:	Low	High
Critical Path V	Vork Effected?	N					74	90

**Work Accomplished** 

Tanner Broughton			
George Caillouet			Coordinating ROof Blocking
Alisha White			
Gary McCaan			Coordinating SIte and Enclosure SUbs
Dennis Dobson			Safety.
Tanner Broughton			
George Caillouet			Coordinating ROof Blocking
Alisha White			
Gary McCaan			Coordinating SIte and Enclosure SUbs
Dennis Dobson			Safety.
Tanner Broughton			
George Caillouet			Coordinating ROof Blocking
Alisha White			
Gary McCaan			Coordinating SIte and Enclosure SUbs
Dennis Dobson			Safety.
Tanner Broughton			
George Caillouet			Coordinating ROof Blocking
Alisha White			
Gary McCaan			Coordinating SIte and Enclosure SUbs
Dennis Dobson			Safety.
Tanner Broughton			
	C.L. C.L	2nd 2nd	
Subcontractor	Sub Sub Wrkrs Hrs 2nd Tier	Tier Tier	Work Accomplished S Q Sch
		Tier Tier	Work Accomplished S Q Sch
Subcontractor  1st Floor Morris Drywall Systems Inc		Tier Tier	Work Accomplished S Q Sch  Installing Exterior Walls at C
1st Floor	Wrkrs Hrs 2nd Tier	Tier Tier	
<b>1st Floor</b> Morris Drywall Systems Inc	Wrkrs Hrs 2nd Tier	Tier Tier	Installing Exterior Walls at C
<b>1st Floor</b> Morris Drywall Systems Inc Morris Drywall Systems Inc	Wrkrs Hrs 2nd Tier  20 20	Tier Tier	Installing Exterior Walls at C Installing Exterior Walls at C
1st Floor Morris Drywall Systems Inc Morris Drywall Systems Inc Morris Drywall Systems Inc	Wrkrs         Hrs         2nd Tier           20         20           20         20           20         20	Tier Tier	Installing Exterior Walls at C Installing Exterior Walls at C Installing Exterior Walls at C
1st Floor Morris Drywall Systems Inc Morris Drywall Systems Inc Morris Drywall Systems Inc Morris Drywall Systems Inc	Wrkrs Hrs 2nd Tier  20 20 20 20 20	Tier Tier	Installing Exterior Walls at C
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 20 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 15 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B Installing Brick at A and B Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 15 15 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B Installing Brick at A and B Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 15 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B Installing Brick at A and B Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC	20 20 20 20 15 15 15 15 15 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 15 15 15	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Cordeiro LLC	Wrkrs Hrs 2nd Tier  20 20 20 20 20 15 15 15 15 20	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Cordeiro LLC Cordeiro LLC	20 20 20 20 15 15 15 15 20 20 20 20 20 20 20 20 20 20 20 20 20	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Cordeiro LLC Cordeiro LLC Cordeiro LLC Cordeiro LLC Cordeiro LLC	20 20 20 20 15 15 15 15 20 20 20 20 20 20 20 20 20 20 20 20 20	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B
1st Floor Morris Drywall Systems Inc Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Cordeiro LLC Cordeiro LLC Cordeiro LLC	20 20 20 20 15 15 15 15 20 20 20 20 20 20 20 20 20 20 20 20 20	Tier Tier	Installing Exterior Walls at C Installing Brick at A and B

**Employee** 

Project:	Sherwood Forest Elementa	ry School				Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:							08/0	04/2015
Weather Dela	ays To Date:			Weather Condition:	Sunny	Day:	Т	uesday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N				74	90
Quality Iron Fal	bricators Inc.	20			Installing Steel at E			
Quality Iron Fal	bricators Inc.	20			Installing Steel at E			
Quality Iron Fal	bricators Inc.	20			Installing Steel at E			
Caf								
New Orleans G	lass Company, Inc.	3			Mobilizing at A			
New Orleans G	lass Company, Inc.	3			Mobilizing at A			
New Orleans G	lass Company, Inc.	3			Mobilizing at A			
New Orleans G	lass Company, Inc.	3			Mobilizing at A			
CFI Insulation In	nc	5			Waterproofing at A-C			
CFI Insulation In	nc	5			Waterproofing at A-C			
CFI Insulation In	nc	5			Waterproofing at A-C			
CFI Insulation In	nc	5			Waterproofing at A-C			
CFI Insulation In	nc	5			Waterproofing at A-C			
		372						

**Notes:** Held Safety Meeting at 7am.

Sub Meeting at 9am.

CORE PM meeting at 1pm.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	08/	10/2015
Weather Dela	ays To Date:		Weather Condition:	Partly Cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				77	93

Employee						Work Accomplished		
Tanner Broughton								
George Caillouet								
Dave Cortez								
Alisha White								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Dave Cortez								
Alisha White								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Dave Cortez								
Alisha White								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
George Caillouet						Working on Roof Blocking		
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished	s	Q Sch
Subcontractor	WIKIS	піз	ZIIG HEI	Wrkrs	Hrs	Work Accomplished	F	
CORE Construction Services, LLC	3	24				Roof Blocking	F	
Phoenix Constructors LLC	3					Working at Courtyard	F	
Phoenix Constructors LLC	4					Working at Courtyard	F	
Phoenix Constructors LLC	4					Working at Courtyard	F	
Phoenix Constructors LLC	4					Working at Courtyard	F	
Phoenix Constructors LLC	4					Working at Courtyard	F	
Rufino`s Painting & Construction Inc.	3	24				Painting Gym Decking		

8 Allied Construction, LLC 64 Installing Block walls at D 2nd FLoor Cordeiro LLC Poured Area D, 2nd Floor Cordeiro LLC 6 Poured Area D, 2nd Floor Cordeiro LLC 6 Poured Area D, 2nd Floor Cordeiro LLC 6 Poured Area D, 2nd Floor

Project: Sherwood Forest Elements Location: 4801 Maid Marion Drive	· <del>-</del>				Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	08/1	4/2015
Weather Delays To Date:			Weather Condition:	Partly Cloudy	Day:		Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	•			75	93
Cordeiro LLC	6			Poured Area D, 2nd Floor		F	
Area A							
New Orleans Glass Company, Inc.				Installing Windows at A.		F	
New Orleans Glass Company, Inc.	2			Installing Windows at A.		F	
New Orleans Glass Company, Inc.	2			Installing Windows at A.		F	
New Orleans Glass Company, Inc.	2			Installing Windows at A.		F	
New Orleans Glass Company, Inc.	2			Installing Windows at A.		F	
Roofing Solutions LLC				Installing Roof at A.		E	
Roofing Solutions LLC	3			Installing Roof at A.		E	
Roofing Solutions LLC	3			Installing Roof at A.		E	
Roofing Solutions LLC	3			Installing Roof at A.		E	
Roofing Solutions LLC	3			Installing Roof at A.		E	
Allied Construction, LLC				Brick @ Area A and B.		F	
Allied Construction, LLC	11			Brick @ Area A and B.		F	
Allied Construction, LLC	11			Brick @ Area A and B.		F	
Allied Construction, LLC	11			Brick @ Area A and B.		F	
Allied Construction, LLC	11			Brick @ Area A and B.		F	
Area B CFI Insulation Inc				Installing waterproofing at B.		F	
CFI Insulation Inc	2			Installing waterproofing at B.		F	
CFI Insulation Inc	2			Installing waterproofing at B.		F	
CFI Insulation Inc	2			Installing waterproofing at B.		F	
CFI Insulation Inc	2			Installing waterproofing at B.		F	
Area C							
Morris Drywall Systems Inc				Installing exterior framing at N Gym Wall, Mezzanine North Wall.		F	
Morris Drywall Systems Inc	11			Installing exterior framing at N Gym Wall, Mezzanine North Wall.		F	
Morris Drywall Systems Inc	11			Installing exterior framing at N Gym Wall, Mezzanine North Wall.		F	
Morris Drywall Systems Inc	11			Installing exterior framing at N Gym Wall, Mezzanine North Wall.		F	
Morris Drywall Systems Inc	11			Installing exterior framing at N Gym Wall, Mezzanine North Wall.		F	
<b>Area D</b> Dillon Bros. Concrete, LLC				Supplied Concrete for pour.		F	
Dillon Bros. Concrete, LLC	2			Supplied Concrete for pour.		F	
Dillon Bros. Concrete, LLC	2			Supplied Concrete for pour.		F	
Dillon Bros. Concrete, LLC	2			Supplied Concrete for pour.		F	
Dillon Bros. Concrete, LLC	2			Supplied Concrete for pour.		F	
Area E Quality Iron Fabricators Inc.				Installing Steel at E.		F	
Quality Iron Fabricators Inc.	12			Installing Steel at E.		F	
Quality Iron Fabricators Inc.	12			Installing Steel at E.		F	
Quality Iron Fabricators Inc.	12			Installing Steel at E.		F	
Quality Iron Fabricators Inc.	12			Installing Steel at E.		F	
				<b>3</b>			
<b>Gym</b> Rufino's Painting & Construction Inc.	3			Painting Steel in Gym		F	
Rufino's Painting & Construction Inc.	3			Painting Steel in Gym		F	
Rufino's Painting & Construction Inc.	3			Painting Steel in Gym		F	
Rufino's Painting & Construction Inc.	3			Painting Steel in Gym		F	

Project:	Sherwood Forest Elementary S	chool			Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	08/	14/2015
Weather Dela	ys To Date:		Weather Condition:	Partly Cloudy	Day:		Friday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				75	93
	23	8 112					

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	08/	17/2015
Weather Dela	ays To Date:		Weather Condition:	Rainy	Day:	,	Monday
Is Today Clair	ned as Weather Day?	Υ	Precipitation Amount: 2"		Temp:	Low	High
Critical Path \	Work Effected?	Υ				79	86

Employee						Work Accomplished		
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
Gary McCaan								
Tanner Broughton								
George Caillouet								
Alisha White								
Eugene Naquin								
				2nd	2nd			
Subcontractor	Sub	Sub	2nd Tion	Tier	Tier	Work Assemblished	S	Q Sch
	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		Q SGI
Phoenix Constructors LLC						Installing Drainage at Courtyard		
Phoenix Constructors LLC						Installing Drainage at Courtyard		
Phoenix Constructors LLC  Phoenix Constructors LLC						Installing Drainage at Courtyard  Installing Drainage at Courtyard		
Phoenix Constructors LLC						Installing Drainage at Courtyard		
1st Floor								
Allied Construction, LLC						Installing Interior walls at D.		
Allied Construction, LLC						Installing Interior walls at D.		
Allied Construction, LLC						Installing Interior walls at D.		
Allied Construction, LLC						Installing Interior walls at D.		
Allied Construction, LLC						Installing Interior walls at D.		
Area C								
Roofing Solutions LLC						Delayed Due To Rain.		

Delayed Due To Rain.

Roofing Solutions LLC

Project: Sherwood Forest Elementary School Location: 4801 Maid Marion Drive	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:				Date:	08/1	19/2015
Weather Delays To Date:		Weather Condition:	Rainy	Day:	Wed	dnesday
Is Today Claimed as Weather Day?	Υ	Precipitation Amount: 2"		Temp:	Low	High
Critical Path Work Effected?	Υ				79	86
Roofing Solutions LLC			Delayed Due To Rain.			
Roofing Solutions LLC			Delayed Due To Rain.			
Roofing Solutions LLC			Delayed Due To Rain.			
Area D						
Bernhard Mechanical Contractors, L.L.C.			Installing Duct at D, Rough In at C			
Bernhard Mechanical Contractors, L.L.C.			Installing Duct at D, Rough In at C			
Bernhard Mechanical Contractors, L.L.C.			Installing Duct at D, Rough In at C			
Bernhard Mechanical Contractors, L.L.C.			Installing Duct at D, Rough In at C			
Bernhard Mechanical Contractors, L.L.C.			Installing Duct at D, Rough In at C			
Morris Drywall Systems Inc			Installing Framing at D			
Morris Drywall Systems Inc			Installing Framing at D			
Morris Drywall Systems Inc			Installing Framing at D			
Morris Drywall Systems Inc			Installing Framing at D			
Morris Drywall Systems Inc			Installing Framing at D			
Cordeiro LLC			Prepping for Slab pour			
Cordeiro LLC			Poured Area D Second FLoor			
Cordeiro LLC			Delayed due to Rain.			
Cordeiro LLC			Delayed due to Rain.			
Area E						
Quality Iron Fabricators Inc.			Installing Steel at E			
Quality Iron Fabricators Inc.			Installing Steel at E			
Quality Iron Fabricators Inc.			Installing Steel at E			
Quality Iron Fabricators Inc.			Installing Steel at E			
Quality Iron Fabricators Inc.			Installing Steel at E			
Caf						
New Orleans Glass Company, Inc.			Installing Windows at A and B.			
New Orleans Glass Company, Inc.			Installing Windows at A and B.			
New Orleans Glass Company, Inc.			Installing Windows at A and B.			
New Orleans Glass Company, Inc.			Installing Windows at A and B.			
New Orleans Glass Company, Inc.			Installing Windows at A and B.			
<b>Gym</b> CFI Insulation Inc			Installing Waterproofing at C.			
CFI Insulation Inc			Installing Waterproofing at C.			
CFI Insulation Inc			Installing Waterproofing at C.			
CFI Insulation Inc			Installing Waterproofing at C.			
CFI Insulation Inc			Installing Waterproofing at C.			
Malone All Star JV, LLC			Installing Rough in at Gym			
Malone All Star JV, LLC			Installing Rough in at Gym			
Malone All Star JV, LLC			Installing Rough in at Gym			
Malone All Star JV, LLC			Installing Rough in at Gym			
			y y y			

Installing Rough in at Gym

Remarks:

Malone All Star JV, LLC

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	08/7	24/2015
Weather Dela	nys To Date:		Weather Condition:	Sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Vork Effected?	N				75	90

Childal Patri Work Effected:		13 30
Employee	Work Accomplished	
Tanner Broughton		
George Caillouet		
Alisha White		
Marybeth Leonard		
Eugene Naquin		
Tanner Broughton		
George Caillouet		
Alisha White		
Marybeth Leonard		
Eugene Naquin		
Tanner Broughton		
George Caillouet		
Alisha White		
Marybeth Leonard		
Eugene Naquin		
Tanner Broughton		
George Caillouet		
Alisha White		
Marybeth Leonard		
Eugene Naquin		
Tanner Broughton		
George Caillouet		
Alisha White		
Marybeth Leonard		
Eugene Naquin		
George Caillouet		
	2nd 2nd	

Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
Morris Drywall Systems Inc	12	96				Installing Framing, Exterior at D, Interior at C, D.		
Morris Drywall Systems Inc	12	96				Installing Framing, Exterior at D, Interior at C, D.		
Morris Drywall Systems Inc	12	96				Installing Framing, Exterior at D, Interior at C, D.		
Morris Drywall Systems Inc	12	96				Installing Framing, Exterior at D, Interior at C, D.		
Morris Drywall Systems Inc	12	96				Installing Framing, Exterior at D, Interior at C, D.		
Phoenix Constructors LLC	4	32				Installing Haul Road		
Phoenix Constructors LLC	4	32				Installing Haul Road		
Phoenix Constructors LLC	4	32				Installing Haul Road		
Phoenix Constructors LLC	4	32				Installing Haul Road		
Phoenix Constructors LLC	4	32				Installing Haul Road		
RUSH MASONRY INC						Installing Brick at C		
RUSH MASONRY INC						Installing Brick at C		

Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ry Scho	ool			Job: Report #:		14-	·02-002 1
Fair Working Days To Date:					Date:		08/2	26/2015
Weather Delays To Date:			Weather Condition:	Sunny	Day:		Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	w	High
Critical Path Work Effected?		N				7	75	88
RUSH MASONRY INC				Installing Brick at C				
RUSH MASONRY INC				Installing Brick at C				
RUSH MASONRY INC				Installing Brick at C				
RUSH MASONRY INC	12	96		Laying Brick at C				
Area C								
Quality Iron Fabricators Inc.	11	88		Installing Steel at C. Decking Roof at D.		F	Ε	OS
Quality Iron Fabricators Inc.	11	88		Installing Steel at C. Decking Roof at D.		F	Ε	OS
Quality Iron Fabricators Inc.	11	88		Installing Steel at C. Decking Roof at D.		F	Е	OS
Quality Iron Fabricators Inc.	11	88		Installing Steel at C. Decking Roof at D.		F	Е	OS
Quality Iron Fabricators Inc.	11	88		Installing Steel at C. Decking Roof at D.		F	Ε	OS
Area D								
Cordeiro LLC	12	96		Pouring ramps and Stairs				
Cordeiro LLC	12	96		Pouring ramps and Stairs				
Cordeiro LLC	12	96		Pouring ramps and Stairs				
Cordeiro LLC	12	96		Pouring ramps and Stairs				
Cordeiro LLC	12	96		Pouring ramps and Stairs				
Caf	4	22		Leady III and English and A. C.				
New Orleans Glass Company, Inc.	4	32 32		Installing Frames at A.C.				
New Orleans Glass Company, Inc.		32		Installing Frames at A-C				
New Orleans Glass Company, Inc.	4	32		Installing Frames at A.C.				
New Orleans Glass Company, Inc.	4	32		Installing Frames at A.C.				
New Orleans Glass Company, Inc.	4	32		Installing Frames at A-C				
<b>Gym</b> Bernhard Mechanical Contractors, L.L.C.	11	88		Installing Rough in at A-C, duct at D.		Е	Е	OS
Bernhard Mechanical Contractors, L.L.C.	11	88		Installing Rough in at A-C, duct at D.		E	E	OS
Bernhard Mechanical Contractors, L.L.C.	11	88		Installing Rough in at A-C, duct at D.		E	E	OS
Bernhard Mechanical Contractors, L.L.C.	11	88		Installing Rough in at A-C, duct at D.		Е	E	OS
Bernhard Mechanical Contractors, L.L.C.	11	88		Installing Rough in at A-C, duct at D.		Е	E	OS
CFI Insulation Inc	6	48		Installing Waterproofing at C			_	
CFI Insulation Inc	6	48		Installing Waterproofing at C				
CFI Insulation Inc	6	48		Installing Waterproofing at C				
CFI Insulation Inc	6	48		Installing Waterproofing at C				
CFI Insulation Inc	6	48		Installing Waterproofing at C				
Malone All Star JV, LLC	8	64		Rough In at A-C, setting equipment.				
Malone All Star JV, LLC	8	64		Rough In at A-C, setting equipment.				
Malone All Star JV, LLC	8	64		Rough In at A-C, setting equipment.				
Malone All Star JV, LLC	8	64		Rough In at A-C, setting equipment.				
Malone All Star JV, LLC	8	64		Rough In at A-C, setting equipment.				
	352	2816						

Project:	Sherwood Forest Elementary School					lob:	14-	02-002
Location:	4801 Maid Marion Drive				Repo	rt #:		1
Fair Working	Days To Date:				ι	ate:	08/3	1/2015
Weather Dela	nys To Date:		Weather Condition:	Partly Cloudy		Day:	M	/londay
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Te	emp:	Low	High
Critical Path \	Vork Effected?	N					78	88

Is Today Claimed as Weather Day?		N	Precipi	tation Amo	unt:		Temp:	Low	High
Critical Path Work Effected?		N					•	78	
Employee						Work Accomplished			
George Caillouet									
Marybeth Leonard									
Tanner Broughton									
Alisha White									
Eugene Naquin									
George Caillouet									
Marybeth Leonard									
Tanner Broughton									
Alisha White									
Eugene Naquin									
George Caillouet									
Marybeth Leonard									
Tanner Broughton									
Alisha White									
Eugene Naquin									
George Caillouet									
Marybeth Leonard									
Tanner Broughton									
Alisha White									
Eugene Naquin									
George Caillouet									
Marybeth Leonard									
Tanner Broughton									
Alisha White									
Eugene Naquin									
	Sub	Sub		2nd Tier	2nd Tier				
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		S	Q Sch
Bernhard Mechanical Contractors, L.L.C.	10	80				Installing Equipment at Mezzanine			
Bernhard Mechanical Contractors, L.L.C.	10	80				Installing Equipment at Mezzanine			
Bernhard Mechanical Contractors, L.L.C.	10	80				Installing Equipment at Mezzanine			
Bernhard Mechanical Contractors, L.L.C.	10	80				Installing Equipment at Mezzanine			
Bernhard Mechanical Contractors, L.L.C.	10	80				Installing Equipment at Mezzanine			
New Orleans Glass Company, Inc.	3	24				Installing Frames at C			
New Orleans Glass Company, Inc.	3	24				Installing Frames at C			
New Orleans Glass Company, Inc.	3	24				Installing Frames at C			
New Orleans Glass Company, Inc.	3	24				Installing Frames at C			
New Orleans Glass Company, Inc.	3	24				Installing Frames at C			
Phoenix Constructors LLC	5	40				Grading Courtyard			
Phoenix Constructors LLC	5	40				Grading Courtyard, cleaned backside of B and D.			

Grading Courtyard, cleaned backside of B and D.

Phoenix Constructors LLC

5

40

Project: Sherwood Forest Elemental Location: 4801 Maid Marion Drive	ry Scho	ol			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	09/0	03/2015
Weather Delays To Date:			Weather Condition:	Afternoon Showers	Day:	TI	hursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				75	86
Phoenix Constructors LLC	5	40		Grading Courtyard, cleaned backside of B and D.			
Phoenix Constructors LLC	5	40		Grading Courtyard, cleaned backside of B and D.			
Cordeiro LLC	15	120		Pouring Ramps at D			
Cordeiro LLC	15	120		Pouring Ramps at D			
Cordeiro LLC	15	120		Pouring Ramps at D			
Cordeiro LLC	15	120		Pouring Ramps at D			
Cordeiro LLC	15	120		Pouring Ramps at D			
Rufino`s Painting & Construction Inc.	3	24		Painting MEP Pipes at Gym.			
Rufino's Painting & Construction Inc.	3	24		Painting MEP Pipes at Gym.			
Rufino's Painting & Construction Inc.	3	24		Painting MEP Pipes at Gym.			
Rufino's Painting & Construction Inc.	3	24		Installing Block Filler at Gym			
Quality Iron Fabricators Inc.	11	88		Decking At D Roof, E deck.			
Quality Iron Fabricators Inc.	11	88		Decking At D Roof, E deck.			
Quality Iron Fabricators Inc.	11	88		Decking At D Roof, E deck.			
Quality Iron Fabricators Inc.	11	88		Decking At D Roof, E deck.			
Quality Iron Fabricators Inc.	11	88		Decking At D Roof, E deck.			
Roofing Solutions LLC	18	144		Installing Roof at Low roofs of C			
Roofing Solutions LLC	18	144		Installing Roof at Low roofs of C			
Roofing Solutions LLC	18	144		Installing Roof at Low roofs of C			
Roofing Solutions LLC	18	144		Installing Roof at Low roofs of C			
Roofing Solutions LLC	18	144		Installing Roof at Low roofs of C			
RUSH MASONRY INC	11	88		Installing Interior Walls at D			
RUSH MASONRY INC	11	88		Installing Interior Walls at D			
RUSH MASONRY INC	11	88		Installing Interior Walls at D			
RUSH MASONRY INC	11	88		Installing Interior Walls at D			
RUSH MASONRY INC	11	88		Installing Interior Walls at D			
CFI Insulation Inc	3	24		Installing Waterproofing at C			
CFI Insulation Inc	3	24		Installing Waterproofing at C			
CFI Insulation Inc	3	24		Installing Waterproofing at C			
CFI Insulation Inc	3	24		Installing Waterproofing at C			
CFI Insulation Inc	3	24		Installing Waterproofing at C			
Malone All Star JV, LLC	8	64		Installing Gear at Mezzanine			
Malone All Star JV, LLC	8	64		Installing Gear at Mezzanine			
Malone All Star JV, LLC	8	64		Installing Gear at Mezzanine			
Malone All Star JV, LLC	8	64		Installing Gear at Mezzanine			
Malone All Star JV, LLC	8	64		Installing Gear at Mezzanine			
	432	3456					

Material Delivered: Duct Work for D3 was delivered today.

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	09/	08/2015
Weather Dela	ays To Date:		Weather Condition:	Cloudy/Afternoon Rain	Day:		Tuesday
Is Today Clair	med as Weather Day?	N	Precipitation Amount: 1"		Temp:	Low	High
Critical Path \	Work Effected?	Ν				78	89

Empleyee						Mayle Accomplished			
Employee						Work Accomplished			
Tanner Broughton									
Alisha White									
George Caillouet									
Marybeth Leonard									
Eugene Naquin									
Tanner Broughton									
Alisha White									
George Caillouet									
Marybeth Leonard									
Eugene Naquin									
Tanner Broughton									
Alisha White									
George Caillouet									
Marybeth Leonard									
Eugene Naquin									
Tanner Broughton									
Alisha White									
George Caillouet									
Marybeth Leonard									
Eugene Naquin									
Lugerie Maquiri									
Tanner Broughton				2nd	2nd				
Tanner Broughton	Sub	Sub	2nd Tier	Tier	Tier	Work Accomplished	5	0	Sch
Tanner Broughton  Subcontractor	Wrkrs	Hrs	2nd Tier			Work Accomplished	S	Q	Sch
Tanner Broughton  Subcontractor  Cordeiro LLC	Wrkrs 10	<b>Hrs</b> 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab			
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC	10 10	<b>Hrs</b> 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab  Rough in at C	E	E	OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Malone All Star JV, LLC	10 10 10	80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C	E E	E	OS OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Malone All Star JV, LLC	10 10 10 10	80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab  Rough in at C  Rough in at C  Rough in at C	E E	E E	OS OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC	10 10 10	80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C	E E	E	OS OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC	10 10 10 10	80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C	E E	E E	OS OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC	10 10 10 10 10	80 80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab  Rough in at C  Rough in at C  Rough in at C	E E E	E E E	OS OS OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC  Roofing Solutions LLC	10 10 10 10 10 10	80 80 80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C	E E E	E E E	os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC  Roofing Solutions LLC	10 10 10 10 10 10 10 10	80 80 80 80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C	E E E P	E E E	os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC  Roofing Solutions LLC  ROOFING SOLUTIONS LLC  RUSH MASONRY INC	10 10 10 10 10 10 10 10 10 10 10	80 80 80 80 80 80 80	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing white top at C	E E E P P	E E E E	os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC  Roofing Solutions LLC  ROOFING Solutions LLC  RUSH MASONRY INC  Allied Construction, LLC	10 10 10 10 10 10 10 10 10 11 11	80 80 80 80 80 80 80 80 112	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing brick at East Elevation	E E E P P	E E E E F	os os os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Malone All Star JV, LLC	10 10 10 10 10 10 10 10 10 10 10 10 10	80 80 80 80 80 80 80 80 112	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing white top at C Installing brick at East Elevation Installing Brick Veneer at C	E E E P P P F	E E E E F E	os os os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC	10 10 10 10 10 10 10 10 10 10 10 10 10 1	80 80 80 80 80 80 80 80 112 128	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing white top at C Installing brick at East Elevation Installing Brick Veneer at C	E E E P P P F F	E E E E E E	os os os os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Area C  Roofing Solutions LLC  Roofing Solutions LLC  ROOFing Solutions LLC  RUSH MASONRY INC  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC	10 10 10 10 10 10 10 10 10 10 10 10 10 1	80 80 80 80 80 80 80 80 112 128	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing white top at C Installing brick at East Elevation Installing Brick Veneer at C	E E E P P P F F	E E E E E E	os os os os os os os
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Roofing Solutions LLC  Roofing Solutions LLC  Roofing Solutions LLC  RUSH MASONRY INC  Allied Construction, LLC	10 10 10 10 10 10 10 10 10 10 16 16 16	80 80 80 80 80 80 80 80 112 128 128	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing white top at C Installing brick at East Elevation Installing Brick Veneer at C Installing Brick Veneer at C Installing Brick Veneer at C	E E E P P P F F	E E E E E E	OS
Subcontractor  Cordeiro LLC  Malone All Star JV, LLC  Area C  Roofing Solutions LLC  Roofing Solutions LLC  Roofing Solutions LLC  RUSH MASONRY INC  Allied Construction, LLC  Area D  Bernhard Mechanical Contractors, L.L.C.	10 10 10 10 10 10 10 10 10 10 10 10 10 1	80 80 80 80 80 80 80 80 112 128 128 128	2nd Tier	Tier	Tier	Prepping 3rd floor slab Rough in at C Rough in at C Rough in at C Rough in at C Installing white top at C Installing white top at C Installing brick at East Elevation Installing Brick Veneer at C	E E E F F F	E E E E E F	OS OS OS OS OS OS OS

Project: Sherwood Forest El	_	ol			Job:		14-	02-002
<b>Location:</b> 4801 Maid Marion I	Drive				Report #:			1
Fair Working Days To Date:					Date:		09/0	9/2015
Weather Delays To Date:			Weather Condition:	Cloudy/Afternoon Rain	Day:		Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount: 1"		Temp:	Lo		High
Critical Path Work Effected?		N					78	89
Morris Drywall Systems Inc	17	136	Fr	aming in D		F	Е	OS
Morris Drywall Systems Inc	17	136	Fr	aming in D		F	E	OS
Morris Drywall Systems Inc	11	88	In	stalling Exterior Walls at D		F	F	OS
CFI Insulation Inc	1	8	FI	ashing at WIndows		F	Ε	OS
CFI Insulation Inc	1	8	Fla	ashing at WIndows		F	E	OS
CFI Insulation Inc	1	8	FI	ashing at WIndows		F	Е	OS
Area E								
Cordeiro LLC	30	240	Po	oured 2nd Floor E		F	F	OS
Cordeiro LLC	8	64	Fc	rming at Courtyard		F	F	OS
Cordeiro LLC	8	64	Pr	epping Slab at 2nd Floor		F	F	OS
Quality Iron Fabricators Inc.	12	96	Fii	nishing Deck at E		F	Ε	OS
Quality Iron Fabricators Inc.	12	96	Fir	nishing Deck at E		F	E	OS
Quality Iron Fabricators Inc.	12	96	Fii	nishing Deck at E		F	Е	OS
LayDown								
New Orleans Glass Company, Inc.	2	16	Re	Organizing materials		F	E	OS
New Orleans Glass Company, Inc.	2	16	Re	Organizing materials		F	E	OS
New Orleans Glass Company, Inc.	2	16	Re	Organizing materials		F	Ε	OS
Site								
Phoenix Constructors LLC	4	32	In	stalling Water Line		F	F	BS
Phoenix Constructors LLC	4	32	In	stalling Water Line		F	F	BS
Phoenix Constructors LLC	4	32	In	stalling Water Line		F	F	BS
	337	2696						

Project:	Sherwood Forest Elementary School				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	09/1	14/2015
Weather Dela	ys To Date:		Weather Condition:	Sunny	Day:	N	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				71	86

Employee						Work Accomplished		
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck								
Marybeth Leonard								
Alisha White								
George Caillouet						oversee crews; graded south of transformer pad		
Tanner Broughton								
Ellen Heck								
Marybeth Leonard								
Eugene Naquin								
Alisha White						stopped by site to drop off items		
George Caillouet								
Tanner Broughton						went to visit architect in Baton Rouge		
Ellen Heck						(6:45- 7:30)		
Marybeth Leonard								
Eugene Naquin								
George Caillouet						went to LSU in afternoon		
Tanner Broughton						went to LSU		
Ellen Heck								
Marybeth Leonard								
Eugene Naquin								
George Caillouet						run crews		
Tanner Broughton						had meeting at Jacob's office @ 8:00; met with architect and roofer for 10:30		
Ellen Heck						oversee site operations		
Marybeth Leonard						·		
Eugene Naquin								
Ellen Heck						(6:45-6:00) oversee site operations; set up office; worked on 3rd floor layout		
						with Jose		
	Sub	Sub		2nd Tier	2nd			
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Tier Hrs	Work Accomplished	S	Q Sch
	9	90				Premier Const install decking on E roof, installing trim angle on	F	F
						high roof and installing 6x4 support angles under 2nd floor area E		
	9	90				Premier - finished installing decking on roof of E;installing trim angle @ same; installing support angles underneath 2nd floor;	F	F
						installing galv angles lentels @ col line M		
	2	16				Rufino's- began blockfilling in gym (lower section)	F	F
	1	8				ISS- insulate water lines in kitchen	F	F
	3	35				LSL - 2 carpenters- install wood blocking at windows; 1 laborer- weed eat(6:30-5:30)	F	F
	2	23				Holi Services - 2 laborers (6:30-5:30) clean-up; fix gates, misc.	F	F

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	I			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:					Date:		09/18	8/2015
Weather Delays To Date:			Weather Condition:	mainly sunny	Day:			Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	w	High
Critical Path Work Effected?		N	·		•		74	87
	9	81		Premier - finished installing decking on roof of E;installing trim angle @ same; set lentels @ col line M 2nd & 3rd floors; welding stair platforms on bldg D; workin at main stairs		F	F	
	2	16		Rufino's- blockfilling in gym (lower section)		F	F	
	1	8		ISS- insulate water lines in kitchen		F	F	
	3	35		LSL - 2 carpenters- install wood blocking at windows; 1 laborer- weed eat(6:30-5:30)		F	F	
	2	23		Holi Services - 2 laborers (6:30-5:30) clean-up; fix gates, misc.		F	F	
						F	F	
						F	F	
						F	F	
	2	16		LSL - 2 carpenters- install wood blocking at windows and roof blocking at low roof of D		F	F	
	2	18		Holi Services - 2 laborers (7:00-3:30 & 5:30) clean-up; fix gates, misc.		F	F	
Bernhard Mechanical Contractors, L.L.C.						F	F	OS
Morris Drywall Systems Inc	15	150		clean-up, frame parapets on roof between B & D;		F	F	OS
Morris Drywall Systems Inc	18	180		clean-up, frame parapets on roof between B & D; installing interior framing on E1, D2, C2 and sheathing on south side of E; received drywall		F	F	OS
Morris Drywall Systems Inc	18	180		clean-up, frame parapets on roof between B & D; installing interior framing on E1, D2, C2 and sheathing on south side of E; received drywall		F	F	OS
Morris Drywall Systems Inc	10	76		clean-up;frame exterior walls of D3		F	F	OS
New Orleans Glass Company, Inc.	3	24		Install sill pans in courtyard		F	F	OS
New Orleans Glass Company, Inc.	3	24		installing frames in courtyard @ area D		F	F	OS
New Orleans Glass Company, Inc.	6	48		installing frames in courtyard @ area D		F	F	OS
New Orleans Glass Company, Inc.						F	F	OS
Phoenix Constructors LLC						Р	F	OS
Cordeiro LLC						F	F	OS
Roofing Solutions LLC	4	32		install insulation bd on C2; flash the walls on small section of lower A roof		F	F	
Roofing Solutions LLC	4	32		flash walls and install membrane on small section of lower A roof		F	F	
Roofing Solutions LLC	5	40		install white cap on low roof of A		F	F	
Roofing Solutions LLC						F	F	
Allied Construction, LLC	2	10		clean brick at north side of courtyard			F	OS
CFI Insulation Inc	2	16				F	F	OS
Malone All Star JV, LLC						F	E	OS
Atlas-Edco Inc	9	72		put together duct; install hangers				
Atlas-Edco Inc	8	64		lay out hangers on D3; install duct in C, D2 & D3		F	F	
Atlas-Edco Inc	9	72		lay out hangers on D3; install duct in C, D2 & D3		F	F	
Atlas-Edco Inc	8	64		lay out hangers on D3; install duct in C, D2 & D3		F	F	
Atlas-Edco Inc						F	F	
Area A Roofing Solutions LLC	4	32		reworked insulation at scupper on roof of area A				
<b>Area C</b> Allied Construction, LLC	11	88		Installing Brick at East Elevation of C		F	F	OS

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	=	ol			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:					Date:	(	)9/15	5/2015
Weather Delays To Date:			Weather Condition:	Sunny	Day:		Tu	uesday
Is Today Claimed as Weather Day? Critical Path Work Effected?		N N	Precipitation Amount:		Temp:	Lov 7		High 86
Allied Construction, LLC	13	130		install brick at lobby at area B; brick at west wall of area C; bricked				
7. II. C.	.5	150		entrance @ C&D work on exterior brick of area D; did some clean-up				
Allied Construction, LLC	13	130		Installing Brick at South Elevation of C, topping out wall in lobby; clean-up		F	F	OS
Allied Construction, LLC	10	100		Installing brick on west side of bldg D; clean-up		F	F	OS
Allied Construction, LLC	10	80		Installing brick on west side of bldg D & north side of courtyard; clean-up		F	F	OS
Malone All Star JV, LLC	10	80		Rough In at C		F	Е	OS
Malone All Star JV, LLC	11	88		set switch gear outside; overhead in area B and in gym; roughed in walls on 2nd floor area D				
Malone All Star JV, LLC	12	96		Rough-in overhead in B1 & D2; rough-in walls on D1 & D2		F	E	OS
Malone All Star JV, LLC	15	120		Rough-in overhead in B1 & D2; rough-in walls on D1 & D2		F	E	OS
Malone All Star JV, LLC	14	112		Rough-in overhead in B1 ; rough-in walls on D1 & D2		F	E	OS
Area D	9	90		Premiere Construction- install roof decking on area D				
Bernhard Mechanical Contractors, L.L.C.	22	176		Duct Work at D, Rough In at D		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	13	130		welding pipe in mechanical rooms in area C; working on plbg on 2nd floor restrooms; install copper on 1st floor area D				
Bernhard Mechanical Contractors, L.L.C.	12	96		Rough-in copper at D, installing chilled water lines on 2nd floor of C		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	11	88		Rough-in sanitary at D1& D2, installing chilled water lines on 2nd floor of C; install copper pipe in D		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	12	88		Rough-in sanitary at D1& D2, installing chilled water lines on 2nd floor of C; install copper pipe in D		F	F	OS
Morris Drywall Systems Inc	13	130		installing exterior framing on 2nd floor area D; sheath south side of area D				
Cordeiro LLC	11	88		Poured Ramps at D		F	F	OS
Cordeiro LLC	12	104		poured the 3rd floor of area E				
Cordeiro LLC	10	80		clean up site		F	F	os
Cordeiro LLC	10	80		clean up site; poured 3 columns on west side of D and south curb on E2		F	F	OS
Cordeiro LLC	10	80		clean up site; poured 3 columns on west side of D and south curb on E2		F	F	OS
CFI Insulation Inc	3	30		Waterproofing at D		F	F	OS
CFI Insulation Inc	4	20		installed waterproofing around windows in courtyard; did not see after lunch				
CFI Insulation Inc	3	17		Waterproofing at D courtyard; picked up materials on north side of bldg		F	F	OS
CFI Insulation Inc	3	18		(9:00-3:30)installing wall flashing @ north wall of courtyard; waterproofing around windows on south side of D2 & E2		F	F	OS
CFI Insulation Inc	3	22		(7:00-4:30waterproofing around windows on south side of D2 $\&$ E2		F	F	OS
Site								
Phoenix Constructors LLC	6	60		Finishing Waterline at NW		F	F	OS
Phoenix Constructors LLC	3	24		worked on water line into street on Maid Marion side				
Phoenix Constructors LLC	5	50		Install water line across Maid Marion St.		Р	F	OS
Phoenix Constructors LLC	4	40		Began building manhole on Maid Marion for water valve;		Р	F	OS
Phoenix Constructors LLC	4	40		Began building manhole on Maid Marion for water valve;		Р	F	OS
	477	4149						

Project:	Sherwood Forest Elementary School				Joi	¢.	14-02	2-002
Location:	4801 Maid Marion Drive				Report	<b>#</b> :		1
Fair Working	Days To Date:				Dat	<b>e:</b> 0	)9/18/	/2015
Weather Dela	ays To Date:		Weather Condition:	mainly sunny	Da	y:	F	riday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Tem	<b>p:</b> Low	,	High
Critical Path \	Work Effected?	N				74	4	87

**Communication with Subcontractors:** Ellen and Jose discussed schedule and Jose agreed that Morris Drywall would have a crew here tomorrow to work on the 3rd floor exterior walls to help get the high roof ready to possibly start on Wednesday.

Material Delivered: NO Glass- truck load of glass and a truck of frames

CMC- 1 load of wire mesh

Rush- 1 truck load of brick

**Visitors:** Glenn Tegre with GraceHebert, Lionel Washington with Hewitt/Washington & Assoc., Bob Edwards & Jean Parro with Roofing Solutions all came to the site to meet with Turner & myself to discuss expansion joint areas. We discussed and walked the site from 10:30 till about 1:20.

 $\label{eq:Deanwith Morris Drywall came to the site this afternoon and introduced himself to Ellen. \\$ 

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	09/	21/2015
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				72	84

Employee						Work Accomplished		
George Caillouet								
Ellen Heck						(6:35-6:00) oversee site operations; Bim meeting; held sub-meeting		
Marybeth Leonard								
Eugene Naquin								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:50) oversee site operations; attended OAC meeting		
Marybeth Leonard								
Eugene Naquin								
George Caillouet						attended meeting @ LSU in afternoon		
Tanner Broughton						attended meeting @ LSU in afternoon		
Ellen Heck						(6:35-6:30) oversee site operations		
Marybeth Leonard								
Eugene Naquin								
George Caillouet								
Tanner Broughton						attended meeting @ Habbens and LSU		
Ellen Heck						(6:35-6:45) oversee site operations		
Marybeth Leonard								
Eugene Naquin								
George Caillouet								
Ellen Heck						(6:35-5:45) oversee site operations		
Marybeth Leonard						,		
George Caillouet								
<b>3</b>				2nd	2nd			
	Sub	Sub		Tier	Tier		_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
							F	F
	3	30				LSL - 2 carpenters- install wood blocking at windows and roof	F	F
	1	10				blocking at low roof of D; 1 laborer- clean-up  Holi Services - 1 laborers (7:00-5:30) clean-up; fix gates, misc.	F	F
	3	30				LSL - 2 carpenters- install roof blocking at high roof of D; 1	F	F
						laborer- clean-up		
	1	10				Holi Services - 1 laborers (7:00-5:30) clean-up; move mats, misc.	F	F
	1	8				Rufino's - tape & float @ mechanical mezzanine		
	3	30				LSL - 2 carpenters- install roof blocking at high roof of D; 1	F	F
	1	10				laborer- clean-up Holi Services - 1 laborers (7:00-5:30) clean-up; move mats, misc.	F	F
	1	8				Rufino's - tape & float @ mechanical mezzanine		
	3	30				LSL - 2 carpenters- install roof blocking at high roof of D; 1	F	F
						laborer- clean-up		

Project: Sherwood Forest Elemer	ntary School			Job:		14-0	02-002
<b>Location:</b> 4801 Maid Marion Drive				Report #:			1
Fair Working Days To Date:				Date:		09/2	5/2015
Weather Delays To Date:		Weather Condition:	partly cloudy	Day:			Friday
Is Today Claimed as Weather Day?	Ī	N Precipitation Amount:		Temp:	Lo	w	High
Critical Path Work Effected?	ľ	N .		•	-	73	85
	3 30		LSL - 2 carpenters- install roof blocking at high roof of D; 1		F	F	
			laborer- clean-up				
	1 10		Holi Services - 1 laborers (7:00-5:30) clean-up; move mats, misc.		F	F	
	1 8		Rufino's - tape @ kitchen & cafeteria				
	1 8		LSL - 1 laborer- clean-up		F	F	
	1 3		Holi Services - 1 laborers (7:00-10:00) clean-up		F	F	
CORE Construction Services, LLC	1 10		carpenter- clean-up; move materials		F	F	
CORE Construction Services, LLC	1 1		carpenter- sent home for 3 days for not wearing proper fall		F	F	
CORE Construction Services, LLC			protection		F	· F	
CORE Construction Services, LLC					F	· -	
CORE Construction Services, LLC					F	Г	
CORE Construction Services, LLC	1 7		install blocking		· F	F	
Bernhard Mechanical Contractors, L.L.C.	13 104				, E	F	os
Bernhard Mechanical Contractors, L.L.C.	13 104		continue water line & overhead sanitary in area D1 and wall sanitary in D2; continue running chilled water piping in C2 continue water line & overhead sanitary in area D1 & D2; wall		F	F	OS
			sanitary in D2; continue running chilled & hot water piping in C2		•	•	O5
Bernhard Mechanical Contractors, L.L.C.	1 8		ISS - insulate 2" pipe in walls in area A		F	F	
Bernhard Mechanical Contractors, L.L.C.	14 112		continue water line & overhead sanitary in area D1 & D2; wall		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1 8		sanitary in D2; continue running chilled & hot water piping in C2 ISS- install insulation on piping in area A in walls		F	F	
Bernhard Mechanical Contractors, L.L.C.	12 96		continue water line & overhead sanitary in area D1 & D2; wall		F	· F	OS
berniara Weerlanear Contractors, E.E.C.	12 30		sanitary in D2; continue running chilled & hot water piping in C2			'	OS
Bernhard Mechanical Contractors, L.L.C.	1 8		ISS- install insulation on piping in area A in walls		F	F	
Bernhard Mechanical Contractors, L.L.C.	14 112		continue water line & overhead sanitary in area D1 & D2; wall sanitary in D2; continue running chilled & hot water piping in C2		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1 8		ISS- install insulation on piping in area A in walls		F	F	
Bernhard Mechanical Contractors, L.L.C.					F	F	OS
Bernhard Mechanical Contractors, L.L.C.					F	F	
Morris Drywall Systems Inc	15 76		frame exterior walls of D3 & E3		F	F	OS
Morris Drywall Systems Inc	10 76		frame exterior walls of D3 & E3; sheath at low roof of D		F	F	OS
Morris Drywall Systems Inc	10 76		frame exterior walls of D3 & E3; sheath at low roof of D		F	F	OS
Morris Drywall Systems Inc	10 76		frame exterior walls of D3 & E3; sheath at low roof of D		F	F	OS
Morris Drywall Systems Inc	20 162		frame exterior walls of D3 & E3; sheath at low roof of D		F	F	OS
Morris Drywall Systems Inc	20 160		frame exterior walls of D3 & E3; sheath at courtyard; layout; frame in scuppers; rock in mechanical room C2; finish framing in area C		F	F	os
New Orleans Glass Company, Inc.	6 48		install glass on west elevation of area B; install frames @ areas E1 & E2; unload glass truck		F	F	OS
New Orleans Glass Company, Inc.	7 56		install glass on west elevation of area B; install frames @ areas E1; unload glass truck		F	F	OS
New Orleans Glass Company, Inc.	8 64		install glass on north elevation @ gym in area C and west elevation of area B; install frames @ areas E1;		F	F	OS
New Orleans Glass Company, Inc.	7 56		install glass on north elevation @ gym in area C and west elevation of area B; install frames @ areas E; caulk and install vinyl at west elevation of area B; moved frames to D2 for west elevation		F	F	OS
New Orleans Glass Company, Inc.	6 48		set sills and frames @ D & E		F	F	OS
New Orleans Glass Company, Inc.					F	F	OS

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:					Date:		09/2	1/2015
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:		Μ	1onday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	W	High
Critical Path Work Effected?		Ν					72	84
Phoenix Constructors LLC	7	56		finished ductile iron water pipe to property line and got ready for pressure test; graded site on north and west side of property so it would drain where access roads are needed.		Р	F	OS
Phoenix Constructors LLC	4	32		work on water and sewer line @ NW corner of bldg.		Р	F	OS
Phoenix Constructors LLC	5	40		work on water and sewer line @ NW corner of bldg.		Р	F	OS
Phoenix Constructors LLC	9	72		work on water and sewer line @ NW corner of bldg.; hauled off dirt		Р	F	OS
Phoenix Constructors LLC	10	90		work on water and sewer line @ NW corner of bldg.; hauled off dirt		Р	F	OS
Phoenix Constructors LLC						Р	F	OS
Cordeiro LLC	4	32		poured curb on north side of E2; began digging for grease trap		F	F	OS
Cordeiro LLC	8	64		wrecked curb on E2; laid out grease trap		F	F	OS
Cordeiro LLC						F	F	OS
Cordeiro LLC						F	F	OS
Cordeiro LLC						F	F	OS
Cordeiro LLC						F	F	OS
Quality Iron Fabricators Inc.	9	90		Premier - continue working on 2nd & 3rd floor beams @ main stairs; install elevator rails; completed high roof decking; welding x-brace tubes on bldg E3		F	F	
Quality Iron Fabricators Inc.	9	90		Premier - continue working on 2nd & 3rd floor beams @ main stairs; install elevator rails; completed high roof decking; welding x-brace tubes on bldg E3		F	F	
Quality Iron Fabricators Inc.	9	90		Premier - install elevator rails; welding kickers on D2 & E2		F	F	
Quality Iron Fabricators Inc.	10	100		Premier - completed elevator rails/hoist beam and decking above; welding kickers on D2 & E2		F	F	
Quality Iron Fabricators Inc.	10	100		Premier - completed elevator rails/hoist beam and decking above; welding kickers on D2 & E2		F	F	
Quality Iron Fabricators Inc.						F	F	
Roofing Solutions LLC	8	64		install top coat on low C roof		F	F	
Roofing Solutions LLC	8	64		install top coat on area A		F	F	
Roofing Solutions LLC	8	64		received materials for low roof of D and began installing insulation bd @ same		F	F	
Roofing Solutions LLC	8	64		drying in low roof of D		F	F	
Roofing Solutions LLC	8	64		drying in low roof of D		F	F	
Roofing Solutions LLC						F	F	
Multivista Construction Documentation	1	1		came and took progress photos			_	06
Allied Construction, LLC  Allied Construction, LLC	11	110		lay brick on west side of D1; lay brick on north side of courtyard west end; washed north elevation			F	OS OS
Allied Construction, LLC	13	104		lay brick on west side of D1; lay brick on north side of courtyard west end; washed north elevation lay brick on west side of D1; lay brick on north side of courtyard			F	OS
, and constitution, and	.5			west end; washed north elevation; installed scaffolding on north wall of courtyard			•	00
Allied Construction, LLC	11	88		washed brick on west side of D1; lay brick on north side of courtyard west end			F	OS
Allied Construction, LLC	16	128		washed brick on west side of D1; lay brick on north side of courtyard west end			F	OS
Allied Construction, LLC	6	48		set up scaffolds on west side of bldg; clean-up			F	OS
CFI Insulation Inc	4	32		install waterproofing @ window on north and south side of E windows		F	F	os
CFI Insulation Inc	3	20		applying barrier coat on south elevation of D1 & E1		F	F	OS
CFI Insulation Inc	2	5		waterproof around west windows @ D2		F	F	OS

Project:	Sherwood Forest Elementa	ary Scho	ool			Job:		14-	02-002	
Location:	4801 Maid Marion Drive					Report #:			1	
Fair Working	g Days To Date:					Date:		09/2	4/2015	
Weather De	elays To Date:			Weather Condition:	partly cloudy	Day:		Th	nursday	
Is Today Cla	imed as Weather Day?		N	Precipitation Amount:		Temp:		w	High	
Critical Path	Work Effected?		N					74	85	
CFI Insulation	Inc						F	F	OS	
CFI Insulation	Inc	2	11		water proofed windows on west side of D and south side of courtyard		F	F	OS	
CFI Insulation	Inc						F	F	OS	
Malone All Sta	ar JV, LLC	13	104		rough-in overhead in gym & area B; rough-in walls on D1 & D2		F	Е	OS	
Malone All Sta	ar JV, LLC	12	96		rough-in overhead in gym & area B; rough-in walls in D2; install temp lights @ D1		F	E	OS	
Malone All Sta	ar JV, LLC	13	104		rough-in overhead in gym & area B; rough-in walls in D2; install temp lights @ D1		F	E	OS	
Malone All Sta	ar JV, LLC	13	104		rough-in overhead in gym & area B; rough-in walls in D2; install temp lights @ D1 $$		F	E	OS	
Malone All Sta	ar JV, LLC	2	16		Bonded - work on lightning protection on roofs					
Malone All Sta	ar JV, LLC	10	80		rough-in overhead in gym & area B; rough-in walls in D2; install temp lights @ D1		F	E	OS	
Malone All Sta	ar JV, LLC						F	E	OS	
Atlas-Edco Inc	=	9	72		continue layout hangers on D2 & E2; bang duct together		F	F		
Atlas-Edco Inc	=	6	48		continue layout hangers on D2 & E2; bang duct together		F	F		
Atlas-Edco Inc	:	8	64		continue layout hangers on D2 & E2; bang duct together		F	F		
Atlas-Edco Inc	<u>:</u>	8	64		continue layout; bang duct together; sea; duct in cafeteria		F	F		
Atlas-Edco Inc	=	7	56		continue layout; bang duct together; sea; duct in cafeteria		F	F		
Atlas-Edco Inc	=						F	F		
		530	4330							

Project:	Sherwood Forest Elementary School				Je	ob:	14-02	2-002
Location:	4801 Maid Marion Drive				Repor	t #:		1
Fair Working	Days To Date:				Da	ate:	09/28/	/2015
Weather Dela	ays To Date:		Weather Condition:	mostly cloudy	D	ay:	Mc	onday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Ter	<b>mp:</b> Lov	N	High
Critical Path \	Work Effected?	N				7	74	80

Employee						Work Accomplished		
George Caillouet						work on field issues and oversee core crew		
Tanner Broughton								
Ellen Heck						(6:20-6:00) oversee site operations		
Marybeth Leonard						(		
Eugene Naquin								
Alisha White								
George Caillouet						take care of issues in the field and oversee Core workers		
Tanner Broughton								
Ellen Heck						(6:30-6:20) oversee site operations; attend OAC meeting		
Marybeth Leonard								
Eugene Naquin								
Alisha White								
George Caillouet						work @ LSU		
Tanner Broughton						work @ LSU		
Ellen Heck						(6:30-6:00) oversee site operations; held meeting on the expansion joint in the bldg and roof conditions at the low roof of D @ parapet walls.		
Marybeth Leonard								
Eugene Naquin								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-6:30) oversee site operations		
Marybeth Leonard								
Eugene Naquin								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:15) oversee site operations		
Marybeth Leonard								
Eugene Naquin								
Tanner Broughton								
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier	2nd Tier	Work Accomplished	s	Q Sch
Subcontractor			Ziiu iiei	Wrkrs	Hrs			
	3	30				LSL - 2 carpenters- install wall blocking at area B & C; 1 laborer- clean-up/dewater	F	F
	1	10				Holi Services - 1 laborers (7:00-5:30) clean-up; unload shoring	F	F
	3	30				LSL - 2 carpenters- install wall blocking at area B & C; 1 laborer-	F	F
						clean-up/dewater	F	F
	7	56				Rufino's -tape/floated and primed walls in C2	•	

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ol			Job: Report #:		14-02	2-002 1
Fair Working Days To Date:					Date:	C	)9/29;	/2015
Weather Delays To Date:			Weather Condition:	mostly cloudy/showers	Day:		Tue	esday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	v	High
Critical Path Work Effected?		N			-	72	2	86
	3	30		LSL - 2 carpenters- install wall blocking at area B & C; assisted in cutting roof deck @ high D & E; 1 laborer- clean-up/dewater		F	F	
	1	10		Holi - 1 laborer - clean-up; chip piles		F	F	
	7	56		Rufino's -tape/floated and primed walls in C2				
	3	30		LSL - 2 carpenters- install wall blocking at area B & C; assisted in		F	F	
				cutting roof deck @ high D & E; 1 laborer- clean-up/dewater				
	1	10		Holi - 1 laborer - clean-up; chip piles		F	F	
	4	32		Rufino's -tape/floated and primed walls in C2				
	3	26		LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater		F	F	
	2	17		Holi - 2 laborer - clean-up		F	F	
	4	32		Rufino's -tape/floated and primed walls in C2; tape/float in A & B				
	2	16		LSL - 2 carpenters- finished installing protection bd on mechanical roof on C and install temp. protection to windows @ west window in B and worked on roof blocking on east end of E; Holi - 2 laborers- moved material and clean-up				
CORE Construction Services, LLC	1	10		1 carpenter - install window blocking		F	F	
CORE Construction Services, LLC	1	10		1 carpenter - install window blocking		F	F	
CORE Construction Services, LLC	1	5		1 carpenter - install window blocking, roof hatches on D & E		F	F	
CORE Construction Services, LLC	1	5		1 carpenter - install window blocking, roof hatches on D & E		F	F	
CORE Construction Services, LLC	1	8		1 carpenter - install wall & roof blocking		F	F	
CORE Construction Services, LLC	1	8		1 carpenter- roof & wall blocking				
Bernhard Mechanical Contractors, L.L.C.	12	120		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D		F	F	OS
Bernhard Mechanical Contractors, L.L.C.				ISS		F	F	
Bernhard Mechanical Contractors, L.L.C.	12	120		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; brought curbs on high roof of D & E and began assembling curbs; install exhaust fans on A,B & C		F	F	OS
Bernhard Mechanical Contractors, L.L.C.				ISS		F	F	
Bernhard Mechanical Contractors, L.L.C.	13	130		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; brought curbs on high roof of D & E and began assembling curbs; install exhaust fans on A,B & C		F	F	OS
Bernhard Mechanical Contractors, L.L.C.				ISS		F	F	
Bernhard Mechanical Contractors, L.L.C.	14	112		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; brought curbs on high roof of D & E and began assembling curbs; install exhaust fans on A,B & C		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area C		F	F	
Bernhard Mechanical Contractors, L.L.C.	10	112		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; finished curbs on high roof of D & E and finished installing vents through high roof of D & E.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area D1 & D2		F	F	
Morris Drywall Systems Inc	18	180		sheath exterior walls of D3 & E3; layout; rock in mechanical room C2; install drywall in C		F	F	OS
Morris Drywall Systems Inc	19	190		sheath exterior walls of D3 & E3; layout; install drywall in B & C		F	F	OS

Project: Sherwood Forest Elemeration: 4801 Maid Marion Drive	=	ool			Job: Report #:		14-	02-002 1
Fair Working Days To Date:					Date:		09/3	0/2015
Weather Delays To Date:			Weather Condition:	mostly cloudy	Day:		Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo		High
Critical Path Work Effected?		N					71	85
Morris Drywall Systems Inc	21	210		sheath exterior walls of D3 & E3; top out drywall in B & C; frame stair @ E; frame at interior walls of D2; finish parapet wall between B & D		F	F	OS
Morris Drywall Systems Inc	21	210		sheath exterior walls of D3 & E3; top out drywall in B & C; frame stair @ E; frame at interior walls of D2; finish parapet wall between B & D		F	F	OS
Morris Drywall Systems Inc	18	148		sheath exterior walls of D3 & E3; top out drywall in A, B & C; raise parapet @ east end of E; frame at interior walls of D2 & E2; frame furdowns in B		F	F	OS
Morris Drywall Systems Inc	7	56		frame furdowns in cafeteria, sheath south side of D $\&\text{E}$				
New Orleans Glass Company, Inc.	5	80		install glass @ north side of courtyard; set misc frames @ D & E		F	F	OS
New Orleans Glass Company, Inc.	4	32		install glass @ north side of courtyard; set misc frames @ D & E		F	F	os
New Orleans Glass Company, Inc.	4	32		install glass @ north side of courtyard; set misc frames @ D & E		F	F	OS
New Orleans Glass Company, Inc.	3	24		install frames in E and prep frames for glass		F	F	OS
New Orleans Glass Company, Inc.	7	56		install frames in E and prep frames for glass		F	F	OS
Phoenix Constructors LLC	10	80		Set backflow preventer; grade street; work on drainage in north parking lot		Р	F	OS
Phoenix Constructors LLC	10	80		work on drainage in north parking lot		Р	F	OS
Phoenix Constructors LLC	6	48		work on drainage in north parking lot; help set shoring in hole		Р	F	OS
Phoenix Constructors LLC	6	48		work on drainage in north parking lot; help set shoring in hole		Р	F	OS
Phoenix Constructors LLC	6	48		haul of spoils and grade @ north parking lot		Р	F	OS
Phoenix Constructors LLC	2	10		grade/dress up west side of bldg and worked on gradingn north parking lot and laid out inlets				
Cordeiro LLC						F	F	OS
Cordeiro LLC	8	64		poured stairs in E; dug grease trap pile cap		F	F	OS
Cordeiro LLC	6	60		dug grease trap pile cap and installed shoring; put together forms for pile cap and tied rebar cage		F	F	OS
Cordeiro LLC	6	66		dried up bottom of grease trap pile cap and installed form; cut piles		F	F	OS
		66		finished forming pile cap and poured cap		·	F	OS
Quality Iron Fabricators Inc.	10	100		Premier- worked on fix at stairs in D; removed tube support on D3 west side that was in a window; unloaded material; began working on lintel fix on 3rd floor; worked on layout for fire rated door		F	F	
Quality Iron Fabricators Inc.	9	90		Premier- worked on fix at stairs in D; removed tube support on D3 west side that was in a window; working on lintel fix on 3rd floor;		F	F	
Quality Iron Fabricators Inc.	10	100		Premier- working on lintel fix on 3rd floor; install header supports for operable wall and accordian fire doors in corridor of D2 & D3		F	F	
Quality Iron Fabricators Inc.	10	100		Premier- working on lintel fix on 3rd floor; finished header supports for operable wall and accordian fire doors in corridor of D2 & D3		F	F	
Quality Iron Fabricators Inc.						F	F	
Roofing Solutions LLC						F	F	
Roofing Solutions LLC	6	30		began loading and blacking in north low roof of D		F	F	
Roofing Solutions LLC						F	F	
Roofing Solutions LLC	8	64		finished drying in north low roof of D and load high roof of D		F	F	
Roofing Solutions LLC	6	18		finished loading high roof of D and then left		F	F	
Roofing Solutions LLC	12	96		began roofing high roof of D at NW corner to main stairs				
Allied Construction, LLC	11	88		install brick at upper portion of B west elevation; build scaffold @ courtyard west side			F	OS
Allied Construction, LLC	13	112		install brick at upper portion of B west elevation; install CMU @ D3 RR's; install brick @ west wall of courtyard			F	OS

Project: Sherwood Forest Elementar	ry Scho	ool			Job:	1	4-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	09	/30/2015
Weather Delays To Date:			Weather Condition:	mostly cloudy	Day:	W	ednesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				71	85
Allied Construction, LLC	17	136		install brick at upper portion of B west elevation; install CMU @			F OS
				D3 RR's; install brick @ west wall of courtyard			
Allied Construction, LLC	12	96		install brick at upper portion of B west elevation; install CMU @			F OS
				D3 RR's; install brick @ west wall of courtyard & began south wall of courtyard			
Allied Construction, LLC	16	128		install brick at upper portion of B west elevation; install CMU @			F OS
				D3 RR's; install brick @ west wall of courtyard & began south wall			
				of courtyard			
Allied Construction, LLC							
Allied Construction, LLC	8	64		brick on west side of courtyard; cut brick at main entry of B;			
CELL Latin La	2	16		graded and prepped for scaffold		-	- 06
CFI Insulation Inc	2	16		waterproof windows @ D & E		-	F OS
CFI Insulation Inc	2	22		waterproof windows @ D & E; sprayed west wall of courtyard @ 1st floor@ D1 in courtyard		F	F OS
CFI Insulation Inc	2	22		waterproof windows @ D & E; sprayed south wall of courtyard		F	F OS
CFI Insulation Inc						F	F OS
CFI Insulation Inc	2	16		waterproof windows in courtyard on south & west sides		F	F OS
CFI Insulation Inc	2	16		continue waterproofing windows			
Malone All Star JV, LLC	10	80		Overhead in B, C2 & D2		F	E OS
Malone All Star JV, LLC	14	112		Overhead in B, C2 & D2		F	E OS
Malone All Star JV, LLC	16	128		Overhead in B, C2 & D2		F	E OS
Malone All Star JV, LLC	13	104		Overhead in B, C2 & D2		F	E OS
Malone All Star JV, LLC	13	104		Overhead in C1, D2 & E1		F	E OS
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct on D2		F	F
				& D3; seal duct in A & B			
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct on D2		F	F
Atlas-Edco Inc	10	80		& D3; seal duct in A & B layout hangers on E2 & D3; beat duct together; hang duct on D3		F	F
Atlas-Edco Inc	7	56		layout hangers on E2 & D3; beat duct together; hang duct on D3		F	F
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct on D3		F	F
•	579	5063					

**Communication with Subcontractors:** Spoke with Kevin and Jose regarding demising wall at special ed room on 1st floor in section E. We came to the conclusion that we would move the 6" wall from being centered on column line to being 2" off centered to encase the conduits. This would shrink special ed by 2" in width.

**Inspections:** Gulf South was here for the concrete pour to make cylinders

**Material Delivered:** Dillon Bros. - 16 cyds of concrete for pile cap **Visitors:** John LaPort & Chad stopped by the site this morning.

Glenn Tregre stopped by to pick up a terrazzo sample @ 4:30.

Project:	Sherwood Forest Elementary School				Job:	1.	4-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	: 10	)/05/2015
Weather Dela	nys To Date:		Weather Condition:	partly sunny	Day	:	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path \	Vork Effected?	N				68	79

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:35) oversee site operations		
Marybeth Leonard								
Eugene Naquin								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-3:30) oversee site operations; attend OAC meeting		
Marybeth Leonard								
Eugene Naquin								
George Caillouet								
Ellen Heck						(6:30-5:50) oversee site operations		
Eugene Naquin						(6:00-10:00)		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-7:00) oversee site operations		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:35-3:40) oversee site operations; set off set for control pt for parking lot		
Marybeth Leonard								
George Caillouet								
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub	2nd Tier	Tier	Tier	Work Accomplished	s	Q Sch
Subcontractor	Wrkrs	Hrs	2nd Tier			Work Accomplished  LSL - 2 carpenters- install roof blocking at high D.8 E and install	S	Q Sch
Subcontractor			2nd Tier	Tier	Tier	Work Accomplished  LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-	<b>S</b>	Q Sch
Subcontractor	Wrkrs 3	<b>Hrs</b> 18	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater	F	F
Subcontractor	<b>Wrkrs</b> 3	<b>Hrs</b> 18	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater  Holi - 2 laborer - clean-up		
Subcontractor	Wrkrs 3	<b>Hrs</b> 18	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater	F	F
Subcontractor	Wrkrs           3           2           4	18 16 32	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B	F	F
Subcontractor	<b>Wrkrs</b> 3	<b>Hrs</b> 18	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-	F	F
Subcontractor	Wrkrs           3           2           4	18 16 32	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B	F	F
Subcontractor	Wrkrs  3  2 4  3	18 16 32 18	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater	F	F F
Subcontractor	Wrkrs  3  2 4  3 2	18 16 32 18 16	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up	F	F F
Subcontractor	Wrkrs  3  2 4  3 2	18 16 32 18 16	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/float in B in cafeteria and in electrical rooms  LSL - 2 carpenters- install window & blocking at D & E; clean-up;	F	F F
Subcontractor	Wrkrs  3  2 4  3  2 4  3 3	18 16 32 18 16 32 20	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/float in B in cafeteria and in electrical rooms  LSL - 2 carpenters- install window & blocking at D & E; clean-up; cover windows	F F F	F F F
Subcontractor	Wrkrs  3  2 4  3  2 4	18 16 32 18 16 32	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater  Holi - 2 laborer - clean-up  Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater  Holi - 2 laborer - clean-up  Rufino's -tape/float in B in cafeteria and in electrical rooms  LSL - 2 carpenters- install window & blocking at D & E; clean-up; cover windows  Holi - 2 laborer - clean-up; dewater	F F F	F F F
Subcontractor	Wrkrs           3           2           4           3           2           4           3           2           4           3           2	18 16 32 18 16 32 20 20	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/float in B in cafeteria and in electrical rooms  LSL - 2 carpenters- install window & blocking at D & E; clean-up; cover windows	F F F	F F F
Subcontractor	Wrkrs           3           2           4           3           2           4           3           2           4           3           2	18 16 32 18 16 32 20 20	2nd Tier	Tier	Tier	LSL - 2 carpenters- install roof blocking at high D & E, and install protection bds on mechanical roof of C; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/floated and primed walls in C2; tape/float in A & B  LSL - 2 carpenters- install window blocking on D & E; 1 laborer-clean-up/dewater Holi - 2 laborer - clean-up Rufino's -tape/float in B in cafeteria and in electrical rooms  LSL - 2 carpenters- install window & blocking at D & E; clean-up; cover windows Holi - 2 laborer - clean-up; dewater Rufino's -tape/float in cafeteria and kitchen; paint electrical rooms	F F F	F F F

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ol			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:					Date:		10/08	8/2015
Weather Delays To Date:			Weather Condition:	mostly clear	Day:		Th	ursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	W	High
Critical Path Work Effected?		N					69	84
	4	32		Rufino's -tape/float in cafeteria and kitchen; paint electrical rooms on 2nd floor; sand and begin priming in cafeteria				
	2	16		LSL - 2 carpenters- install window & wall blocking at D & E; clean-up; cover windows		F	F	
	2	16		Holi - 2 laborer - clean-up; dewater		F	F	
	1	8		Holi - 1 Jahorer - clean-un; dewater		F	F	
	,	0		Holi - 1 laborer - clean-up; dewater		,	r	
CORE Construction Services, LLC	2	19		2 carpentesr - install wall blocking; hand rails @ ramps; temp in at louver in A		F	F	
CORE Construction Services, LLC	2	19		2 carpentesr - check/install temp fire extinguishers, work on safety items; misc blocking		F	F	
CORE Construction Services, LLC	2	19				F	F	
CORE Construction Services, LLC	2	19				F	F	
CORE Construction Services, LLC	2	16		Bennie- re-establish control point; Ray- misc., work on safety items, check dimensions concerning lintel issues		F	F	
CORE Construction Services, LLC	1	8		Ray- misc., dress up site		F	F	
Bernhard Mechanical Contractors, L.L.C.	12	96		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; finished curbs on high roof of D & E and finished installing vents through high roof of D & E.		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area D1 & D2		F	F	
Bernhard Mechanical Contractors, L.L.C.	13	104		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area D1 & D2		F	F	
Bernhard Mechanical Contractors, L.L.C.	13	104		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area D1 & D2		-	F	0.0
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	18	186		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2		F	F	OS
		128		ISS- insulate pipes in area D1 & D2		· F		os
Bernhard Mechanical Contractors, L.L.C.	16	120		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; worked on piping in grease trap		r	F	US
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS- insulate pipes in area D1 & D2		F	F	
Bernhard Mechanical Contractors, L.L.C.						F	F	OS
Bernhard Mechanical Contractors, L.L.C.						F	F	
Morris Drywall Systems Inc	18	180		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E		F	F	OS
Morris Drywall Systems Inc	20	200		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E		F	F	OS
Morris Drywall Systems Inc	23	230		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E; begin framing upper walls at D stairs; install insulation in area A		F	F	OS

Project: Sherwood Forest Elementa 4801 Maid Marion Drive	ary Scho	ool			Job:		14-0	02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:			1
Fair Working Days To Date:					Date:			8/2015
Weather Delays To Date:		N	Weather Condition:	mostly clear	Day:			ursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	w 59	High 84
Critical Path Work Effected?								
Morris Drywall Systems Inc	21	210		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E; framing upper walls at D stairs; install insulation in area A; install plywood sheathing at roof @ D stairs		F	F	OS
Morris Drywall Systems Inc	22	176		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E; shenthing upper walls at D stairs; install insulation in area C; clean-up of roof		F	F	OS
Morris Drywall Systems Inc	14	112		sheath exterior walls of D3 & E3; top out drywall in A, B & C; shenthing upper walls at D stairs; install insulation in area C; clean-up of roof		F	F	OS
New Orleans Glass Company, Inc.	7	56		install frames in E and prep frames for glass		F	F	OS
New Orleans Glass Company, Inc.	7	56		install frames in E and prep frames for glass		F	F	OS
New Orleans Glass Company, Inc.	7	56		install large glass on south elevation of courtyard		F	F	OS
New Orleans Glass Company, Inc.	7	56		finished installing glass on south elevation of courtyard		F	F	OS
New Orleans Glass Company, Inc.	7	56		install glass on south side of E		F	F	OS
New Orleans Glass Company, Inc.						F	F	OS
Phoenix Constructors LLC	6	48		haul of spoils and grade @ north parking lot		Р	F	OS
Phoenix Constructors LLC	5	40		haul of spoils and grade @ north parking lot; work on errosion control		Р	F	OS
Phoenix Constructors LLC	5	40		haul of spoils and grade @ north parking lot; cut north parking lot getting ready for proof roll		P	F	OS
Phoenix Constructors LLC	2	20		proof rolled the west end of the north parking lot; cut out muck and installed rock at car pool drop off		Р	F	OS
Phoenix Constructors LLC	2	20		finished rough grading under canopy at car pool drop off and ran storm line in north parking lot at west end		Р	F	os
Phoenix Constructors LLC	6	72		ran storm line in north parking lot center line		Р	F	OS
Cordeiro LLC	3	9		wrecked pile cap forms and dewatered		F	F	OS
Cordeiro LLC						F	F	OS
Cordeiro LLC	2	2		supposedly cut mesh for stairs in D		F	F	OS
Cordeiro LLC	6	69		supposedly cut mesh for stairs in D		F	F	OS
Cordeiro LLC	3	15		helped remove shore box from grease trap hole; wreck forms @ housekeeping pads that were poured yesterday		F	F	OS
Cordeiro LLC						F	F	OS
Quality Iron Fabricators Inc.	10	100		Premier - began working on grating and hand rails @ chiller roof; welded clips on at windows in cafeteria but unable to install lintels because they were used else where; misc welding @ stairs for lintels and handrails in D		F	F	
Quality Iron Fabricators Inc.	8	80		Premier - working on grating and hand rails @ chiller roof; install missing tubes for stairs in D and worked on lintels on A		F	F	
Quality Iron Fabricators Inc.	8	80		Premier - working on grating and hand rails @ chiller roof; worked on lintels on A		F	F	
Quality Iron Fabricators Inc.	5	50		Premier - working on grating and hand rails @ chiller roof; worked on lintels on A; added support to lintel west of stair D		F	F	
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.						F	F	
Roofing Solutions LLC	4	18		ran roofing up parapet walls on north side of high D		F	F	
Roofing Solutions LLC	6	48		ran roofing up parapet walls on north side of high D		F	F	
Roofing Solutions LLC	5	40		ran roofing on north half of E		F	F	
Roofing Solutions LLC	5	40		ran roofing on north half of E and began south half on east end of E		F	F	

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:		14-0	02-002
Fair Working Days To Date:					Date:		10/09	9/2015
Weather Delays To Date:			Weather Condition:	mostly clear	Day:			Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:	,	Temp:	Lo		High
Critical Path Work Effected?		N			remp.		58	85
Roofing Solutions LLC	5	40		ran roofing on north half of E and began south half on east end		F	F	
Roofing Solutions LLC	7	56		of E ran roofing on south half of E		F	F	
Allied Construction, LLC	16	128		install CMU @ D3 RR's; install brick @ west wall of courtyard &		•	, E	OS
Allied Collstituction, LLC	10	120		began south wall of courtyard			г	03
Allied Construction, LLC	13	104		finished brick @ west wall of courtyard & worked on south wall			F	os
Allied Construction, LLC	13	104		of courtyard worked on south wall of courtyard; topped out RR walls on D3;			F	OS
				clean-up			•	
Allied Construction, LLC	10	80		worked on south wall of courtyard;clean-up			F	OS
Allied Construction, LLC	23	184		worked on south wall of courtyard;clean-up; grout cells in CMU @ kitchen			F	OS
Allied Construction, LLC	14	112		worked on south wall of courtyard & south wall of E;clean-up;			F	OS
				grout cells in CMU @ kitchen				
CFI Insulation Inc	2	16		waterproof windows in courtyard on south & west sides		F	F	OS
CFI Insulation Inc	2	16		waterproof windows in courtyard on south & west sides		F	F	OS
CFI Insulation Inc	2	21		waterproof south wall of courtyard and also north half of the west wall of area E		F	F	OS
CFI Insulation Inc	2	2		came and loaded up sprayer and then left		F	F	OS
CFI Insulation Inc	2	16		waterproofed at windows on south side of D & E		F	F	OS
CFI Insulation Inc	3	24		waterproofed at windows on south side of D & E and sealed jts on west side of D		F	F	OS
Malone All Star JV, LLC	13	104		Overhead in C1, D2 & E1		F	Ε	OS
Malone All Star JV, LLC	15	120		Overhead in C1, D2; walls in E1; install gear		F	Е	OS
Malone All Star JV, LLC	16	128		Overhead in C1, D2; walls in E1; install gear		F	Е	OS
Malone All Star JV, LLC	12	96		Overhead in C1, D2; walls in E1; install gear		F	Е	OS
Malone All Star JV, LLC	15	120		Overhead in C1, D2; walls in E1; install gear in C2		F	Е	OS
Malone All Star JV, LLC						F	Ε	OS
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct on D3		F	F	
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct in D		F	F	
Atlas-Edco Inc	11	88		layout hangers on E2 & D3; beat duct together; hang duct in D &		F	F	
Atlas-Edco Inc	11	88		E; hang duct in C layout hangers on E2 & D3; beat duct together; hang duct in D & E; hang duct in C		F	F	
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct in D & E; hang duct in C		F	F	
Atlas-Edco Inc				<del>-</del>		F	F	
	612	5156						

Project:	Sherwood Forest Elementary School				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	10/1	12/2015
Weather Dela	ys To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				69	84

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:40) oversee site operations; held sub & safety meeting; worked on issues		
Marybeth Leonard						153065		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:00) oversee site operations; held safety orientation; attended OAC meeting; worked on issues		
Marybeth Leonard						meeting, notice on osaes		
George Caillouet								
Tanner Broughton						went to Habbins		
Ellen Heck						(6:35-6:00)went to Habbins this morning until about 9:00am to meet Terri; oversee site operations; worked on issues		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-5:45) oversee site operations; worked on issues		
Marybeth Leonard								
Tanner Broughton								
Ellen Heck						(6:35-4:30) oversee site operations; tried to order sidewalk and paving material but ran into issues		
Marybeth Leonard								
Tanner Broughton								
	Ch	Ch		2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
	2	16		*******		LSL - 2 carpenters- install wall blocking at gym; clean-up; move	F	F
						protection bd from mechanical roof on C over by low roof of D		·
	2	16				Holi - 2 laborer - clean-up	F	F
	2	20					-	
	2	20				Holi - 2 laborer - clean-up	F	F
	2	18				Holi - 2 laborer - clean-up	F	F
	2	18				Holi - 2 laborer - clean-up	F	F
	1	2				Firestop International- foreman came and walked the job		-
	2	18				Holi - 2 laborer - clean-up	F	F
	3	24				Firestop International- began installing firestopping on 2nd floor in mechanical/electrical rooms		

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	וטנ			Job: Report #:		14-	02-002 1
Fair Working Days To Date:					Date:		10/1	2/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:		M	1onday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	W	High
Critical Path Work Effected?		Ν				6	59	84
CORE Construction Services, LLC	2	16		Ray- misc., work on safety items, clean-up; help move protection bd		F	F	
CORE Construction Services, LLC	1	10		Ray- misc., install roof protection on low roofs of D; raise roof hatch @ D; install window blocking		F	F	
CORE Construction Services, LLC	1	10		Ray- misc. blocking; checked all safety items		F	F	
CORE Construction Services, LLC	1	10		Ray- misc. blocking; checked all safety items		F	F	
CORE Construction Services, LLC	1	5		Ray- redid toe bds at duct shafts		F	F	
Bernhard Mechanical Contractors, L.L.C.	16	148		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; worked on piping in grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.						F	F	
Bernhard Mechanical Contractors, L.L.C.	17	138		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; worked on piping in grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS - insulate water lines in D1 RR's			F	0.5
Bernhard Mechanical Contractors, L.L.C.	17	138		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; worked on piping in grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS - insulate water lines in D1 RR's		F	F	
Bernhard Mechanical Contractors, L.L.C.	16	138		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; worked on piping in grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	1	8		ISS - insulate water lines in D2 RR's		F	F	
Bernhard Mechanical Contractors, L.L.C.	17	136		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; installed risers on manhole tops on grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	2	16		ISS - insulate water lines and began insulating ducts		F	F	
Morris Drywall Systems Inc	20	200		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ E; shenthing upper walls at D stairs; install insulation in area C; finish sheathing from low D roof/high D roof clockwise all the way to SE corner of area E		F	F	OS
Morris Drywall Systems Inc	21	219		sheath exterior walls of D3 & E3; top out drywall in A, B & C; frame at interior walls of D2 & E2; frame furdowns in B; work on framing stairs @ D; shenthing upper walls at D stairs; install insulation in area C; finish sheathing from SE corner of bldg to stair @ D		F	F	OS
Morris Drywall Systems Inc	18	219		sheath exterior walls of stair D; top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; work on framing stairs @ D; shenthing upper walls at D stairs; install insulation in area C; finish sheathing from SW corner of bldg to stair @ D		F	F	OS
Morris Drywall Systems Inc	19	190		sheath exterior walls of stair D; top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C; finish sheathing		F	F	OS
Morris Drywall Systems Inc	20	160		top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C		F	F	OS
Morris Drywall Systems Inc	5	25		Worked in Gym, hanging drywall.				
New Orleans Glass Company, Inc.	6	48		install glass and frames on south side of E & D; installed small frames and glass at west side of courtyard		F	F	OS
New Orleans Glass Company, Inc.	8	64		install glass and frames on south side of E & D; installed glass at west side of courtyard; installed glass on west side of D		F	F	OS
New Orleans Glass Company, Inc.	6	48		install frames & glass on south side of E2&3; installed glass on D2; weld clips on steel for curtainwall at main stairs		F	F	OS

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:				Date:		10/15	5/2015
Weather Delays To Date:		Weather Condition:	mainly sunny	Day:		Thu	ursday
Is Today Claimed as Weather Day?	N	Precipitation Amount:		Temp:	Lo	w	High
Critical Path Work Effected?	N	·				57	85
New Orleans Glass Company, Inc.	6 48		install frames & glass on south side of E2&3; weld clips on steel for curtainwall at main stairs; install large glass on south wall of courtyard on west end		F	F	OS
New Orleans Glass Company, Inc.	6 48		install frames & glass on south side of E2&3; weld clips on steel for curtainwall at main stairs; install large glass on south wall of courtyard on west end		F	F	OS
Phoenix Constructors LLC	2 20		finished rough grading under canopy at car pool drop off and ran storm line in north parking lot at west end		Р	F	OS
Phoenix Constructors LLC	6 48		continue to cut dirt to grade at north parking lot; worked on installing 8" storm line to bldg north of gym; pressurized water line and kept test on for over 2 hours		Р	F	OS
Phoenix Constructors LLC	6 48		continue to cut dirt to grade at north parking lot; re- pressurized water line and kept test on for over 2 hours		Р	F	OS
Phoenix Constructors LLC	6 48		continue to cut dirt to grade at north parking lot		Р	F	OS
Phoenix Constructors LLC	6 48		continue to cut dirt to grade at north parking lot; proof rolled next section of north parking lot		Р	F	OS
Cordeiro LLC	2 6		moved forms		F	F	OS
Cordeiro LLC					F	F	OS
Cordeiro LLC					F	F	OS
Cordeiro LLC	2 6		unloaded WWF and light std rebar		F	F	OS
Cordeiro LLC					F	F	OS
Rufino's Painting & Construction Inc.	2 16		tape and float electrical room on D1		F	F	
Rufino`s Painting & Construction Inc.	2 16		tape and float electrical rooms		F	F	
Rufino's Painting & Construction Inc.	7 56		tape and float in mechanical room on 1st floor & gym; painted sides of stair stringers and beams @ main stairs		F	F	
Rufino's Painting & Construction Inc.	5 56		tape and float in electricall room on 2nd floor & gym; sanding & priming walls in cafeteria & kitchen		F	F	
Quality Iron Fabricators Inc.	5 50		Premier - finish installing 2nd lintel angle under original brick lintel and began stitch welding it; worked on 4x6 lintel at the SW corner of D; straightened lintel above 20' window at the west side of D1; extended lintel around corner at column lines 4/B		F	F	
Quality Iron Fabricators Inc.	5 50		Premier - straightened lintel above 20' window at the west side of D1; extended lintel around corner at column lines 4/B; modified base plates at overhead doors; finished stitch welding dbl angle lintel		F	F	
Quality Iron Fabricators Inc.	5 40		Premier - modified base plates at overhead doors; finished stitch welding dbl angle lintel; misc.		F	F	
Quality Iron Fabricators Inc.	5 30		Premier - misc., waited on lintels & ladder extension that did not show up; picked up and removed most of their stuff		F	F	
Quality Iron Fabricators Inc.					F	F	
Roofing Solutions LLC	5 40		finished blacking in south half on E and began on D		F	F	
Roofing Solutions LLC	5 40		finished blacking in south half on E and began on D		F	F	
Roofing Solutions LLC	7 56		blacking in south half of high D		F	F	
Roofing Solutions LLC	5 40		began white capping south side of D		F	F	
Roofing Solutions LLC	5 40		flash walls with base & white cap on high D		F	F	
Allied Construction, LLC	14 112		worked on south wall of courtyard;clean-up; grout cells in CMU			F	OS
Allied Construction, LLC	15 120		@ kitchen; began brick on south & east side of E; cleaned brick @ east of C worked on south wall of courtyard; clean-up; grout cells in CMU @ kitchen; cont. brick on south & east side of E; cleaned brick; install brick on north wall in courtyard where left out previously			F	OS

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	ool			Job:		14-0	02-002
					Report #:			1
Fair Working Days To Date:					Date:			1/2015
Weather Delays To Date:		N	Weather Condition:	mainly sunny	Day:	,	Wedn	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lov		High
Critical Path Work Effected?		N				6	4	83
Allied Construction, LLC	13	104		worked on south wall of courtyard;clean-up; grout cells in CMU @ kitchen;cont.brick above window lintel at west side of D1; cleaned brick; install brick on north wall in courtyard where left out previously			F	OS
Allied Construction, LLC	18	144		worked on east wall of area E; install brick on north wall in courtyard where left out previously; remove scaffolding from courtyard; install additional protection bd on low roof of D			F	OS
Allied Construction, LLC	17	136		worked on east wall of area E; clean-up D2&3			F	OS
Allied Construction, LLC	10	80		continue laying brick on east end of area E; continued scaffold erection on south wall of courtyard at west end.				
CFI Insulation Inc	2	16		waterproofed at windows on south side of D & E; misc waterproofing in courtyard; installed expansion jt and finished waterproofing at column line 8/B		F	F	OS
CFI Insulation Inc	2	16		waterproofed at windows on south side of D & E; installed expansion jt and finished waterproofing at column line 8/B		F	F	OS
CFI Insulation Inc	2	16		waterproofed at walls at low roofs of D and part of south wall		F	F	OS
CFI Insulation Inc	2	8		waterproofed at windows on south side of D & E		F	F	OS
CFI Insulation Inc						F	F	OS
Malone All Star JV, LLC	16	128		Overhead in C1, D2; walls in E1; install gear in C2		F	Е	OS
Malone All Star JV, LLC	14	104		Overhead in C1, D2; walls in E1; install gear in C2		F	Е	OS
Malone All Star JV, LLC	16	128		Overhead in C1, D2; walls in E1; install gear in C2		F	Ε	OS
Malone All Star JV, LLC	18	144		Overhead in C1, D2; walls in E1; install gear in C2		F	Ε	OS
Malone All Star JV, LLC	2	8		Bonded - marked out roof for lightning protection pads on areas A, B $\&$ C				
Malone All Star JV, LLC	16	128		Overhead in C1, D2; walls in E1 & E2; install gear in C2 & E2		F	Е	OS
Malone All Star JV, LLC								
Atlas-Edco Inc	10	80		layout hangers on E2 & D3; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
Atlas-Edco Inc	9	72		layout hangers on E2 & D3; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
Atlas-Edco Inc	9	72		layout hangers on E2 & D3; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
Atlas-Edco Inc	9	72		layout hangers on E2 & D3; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
Atlas-Edco Inc	8	64		layout hangers; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
	560	4696						

**Remarks:** I tried to order material today for the sidewalks and paving. I kept hitting walls; multiple contradictions between specs, plans and FRTP's. No one in to give clarification on how to proceed. I ended up placing a partial order to get us going.

All Star had someone come in and certify their crew in the use of pneumatic guns (ramsets) this afternoon

**Verbal or Written Instruction from Architect or Engineer:** Unable to get clarification on spacing of expansion jts. in paving & sidewalks. Melisa stated the the FRTP's stated that sidewalks should be 5" and not 4" as shown on drawings. She also stated that control joints need to be

keyways and not sawcutting per the FTRP's.

**Inspections:** Proof rolled the next section of north parking lot paving. It past. Tanner and Ellen along with Jonathan, Chris & Jude witnessed the 2nd proof roll.

Visitors: Jonathan with Jacobs/CSRS to witness proof roll

Chris & Jude w/ Gulf South to witness proof roll

Project:	Sherwood Forest Elementary School					Job:	14	-02-002
Location:	4801 Maid Marion Drive				1	Report #:		1
Fair Working	Days To Date:					Date:	10/	19/2015
Weather Dela	ays To Date:		Weather Condition:	sunny		Day:	1	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:			Temp:	Low	High
Critical Path \	Work Effected?	N					64	72

Employee						Work Accomplished		
Tanner Broughton								
Ellen Heck						(6:25-6:00) oversee site operations; worked on sidewalk issues		
Marybeth Leonard								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-3:30) oversee site operations; went to City Park for picture; went to McD		
						42 for 4:00pm and worked there till 6:45.		
Marybeth Leonard								
Chad Goubert								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:00) oversee site operations; met with Mike with Kone		
Marybeth Leonard								
Chad Goubert								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:15) oversee site operations		
Marybeth Leonard								
Chad Goubert								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-4:45) oversee site operations		
Marybeth Leonard								
Chad Goubert								
	Sub	Sub		2nd	2nd			
Subcontractor	Wrkrs	Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	S	Q Sch
	2	16				Holi - 2 laborer - help with cutting deck in roof/ clean-up	F	F
	1	1				Eagle Eye - termite sprayed at north sidewalk		
		_					_	
CORE Construction Services, LLC	1	8				Ray-worked on cutting holes in roof deck at high roof	F	F -
CORE Construction Services, LLC	1	8				Ray-worked on cutting holes in roof deck at high roof	F	F -
CORE Construction Services, LLC	1	8				Ray- install wall blocking	F	F

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	=			Job: Report #:		14-0	02-002 1
Fair Working Days To Date:				Date:		10/22	2/2015
Weather Delays To Date:		Weather Condition:	partly cloudy	Day:		Thu	ursday
Is Today Claimed as Weather Day?	N	<b>Precipitation Amount:</b> 0		Temp:	Lov	N	High
Critical Path Work Effected?	N				6	59	80
CORE Construction Services, LLC	1 8		Ray- install wall blocking; install door frame C112 @ loading dock		F	F	
CORE Construction Services, LLC	1 8		Ray-replumbedl door frame C112 @ loading dock;		F	F	
CORE Construction Services, LLC	1 8		Ray- graded west side of site; swept street		F	F	
Bernhard Mechanical Contractors, L.L.C.	14 112		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; installed risers on manhole tops on grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	2 16		ISS - insulate water lines and began insulating ducts		F	F	
Bernhard Mechanical Contractors, L.L.C.	14 112		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D; continue sewer & water on D2; installed risers on manhole tops on grease trap		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	11 88		Atlas - layout hangers; beat duct together; hang duct in D $\&$ E all floors; hang duct in C		F	F	
Bernhard Mechanical Contractors, L.L.C.	2 16		ISS - insulate water lines and began insulating ducts		F	F	
Bernhard Mechanical Contractors, L.L.C.	16 112		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D2; ran nyron pipe in A & B		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	11 88		Atlas - layout hangers; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
Bernhard Mechanical Contractors, L.L.C.	5 40		ISS - insulate water lines and insulating ducts in D1		F	F	
Bernhard Mechanical Contractors, L.L.C.	16 154		work on chilled & hot water piping in mezzanine of C, work on sanitary & sewer in D2; ran nyron pipe in A & B; covered all outside air unit curbs for the 2nd time on high roof of D & E		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	10 80		Atlas -install fire dampers in D & E; hang duct in E		F	F	
Bernhard Mechanical Contractors, L.L.C.	5 40		ISS - insulate water lines and insulating ducts in D1		F	F	
Bernhard Mechanical Contractors, L.L.C.	16 128		work on sanitary & sewer in D3; ran nyron pipe in A, B & C; covered all outside air unit curbs for the 2nd time on high roof of D & E; lay out remaining house keeping pads		F	F	OS
Bernhard Mechanical Contractors, L.L.C.	10 80		Atlas -install fire dampers in D & E; hang duct in E		F	F	
Bernhard Mechanical Contractors, L.L.C.	4 32		ISS - insulate water lines and insulating ducts in D1 & 2		F	F	
Bernhard Mechanical Contractors, L.L.C.					F	F	OS
Bernhard Mechanical Contractors, L.L.C.					F	F	
Bernhard Mechanical Contractors, L.L.C.					F	F	
Holi Services Inc	2 16		Holi - 2 laborer - help with cutting deck in roof/ clean-up		F	F	
Holi Services Inc	2 16		Holi - 2 laborer -clean-up		F	F	
Holi Services Inc	2 16		Holi - 2 laborer -clean-up		F	F	
Holi Services Inc	2 13		Holi - 2 laborer -clean-up		F	F	
Holi Services Inc	24 240				F	F	0.5
Morris Drywall Systems Inc	21 210 21 210		top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C		F F	F	OS OS
Morris Drywall Systems Inc	21 210		top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C		Г	F	US
Morris Drywall Systems Inc	20 200		top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C		F	F	OS
Morris Drywall Systems Inc	20 180		top out drywall in A, B & C; frame at interior walls of D3 & E3; frame furdowns in B; install insulation in area C		F	F	OS
Morris Drywall Systems Inc	19 172		top out drywall in A, B & C; began framing elevator shaft on 1 and stairwells in D & E on 1st floor; frame furdowns in B; install insulation in area C		F	F	OS
Morris Drywall Systems Inc	15 120		top out drywall in A, B & C; framing elevator shaft on 3 and stainwells in D & E on 1st & 3rd floors; frame furdowns in B; finished rocking in gym		F	F	OS

Project:	Sherwood Forest Elemen	tary Schoo	ol			Job:		14-0	02-002
Location:	4801 Maid Marion Drive					Report #:			1
Fair Working	Days To Date:					Date:		10/19	9/2015
Weather Del	ays To Date:			Weather Condition:	sunny	Day:		М	londay
Is Today Clai	med as Weather Day?		N	Precipitation Amount:		Temp:	Lov	v	High
Critical Path	Work Effected?		N				6	4	72
New Orleans G	lass Company, Inc.	8	64		install frames & glass on south side of E2&3; weld clips on steel for curtainwall at main stairs; install large glass on south wall of courtyard on west end		F	F	OS
New Orleans G	lass Company, Inc.	7	64		install frames & glass on south side of E2&3; weld clips on steel for curtainwall at main stairs; install large glass on south wall of courtyard on west end		F	F	OS
New Orleans G	lass Company, Inc.	7	64		install frames & glass on south side of E2&3		F	F	OS
New Orleans G	lass Company, Inc.	6	56		install frames & glass on south side of E2&3; install frames at elev $$\sf CW3$$		F	F	OS
New Orleans G	lass Company, Inc.	7	56		installed glass at curtain wall @ main stairs; installed glass on west side of D1; cleaned up		F	F	OS
New Orleans G	lass Company, Inc.						F	F	OS
Phoenix Constr	uctors LLC	6	48		continue to cut dirt to grade at north parking lot; proof rolled next section of north parking lot		Р	F	OS
Phoenix Constr	uctors LLC	6	48		continue to cut dirt to grade at north parking lot; proof rolled next section of north parking lot		Р	F	OS
Phoenix Constr	uctors LLC	6	48		continue to cut dirt to grade at north parking lot; began running sanitary lines on west side of building		Р	F	OS
Phoenix Constr	uctors LLC	6	48		continue to cut dirt to grade at north parking lot; began running sanitary lines on west side of building		Р	F	OS
Phoenix Constr	uctors LLC	4	26		running sanitary lines on west side of building; did 3rd proof roll test on north parking lot and passed; hauled off dirt on west side of bldg		Р	F	OS
Phoenix Constr	uctors LLC	2	10		installed filter fabric and sand at east central section of north parking lot		Р	F	OS
Cordeiro LLC		2	10		start getting ready to begin forming sidewalk at north side of gym		F	F	OS
Cordeiro LLC		2	10		installing light pole bases & prep sidewalk.		F	F	OS
Cordeiro LLC		2	10		installing light pole bases & prep sidewalk.		F	F	OS
Cordeiro LLC		4	32		finished prepping sidewalk & light pole bases for tomorrow's pour		F	F	OS
Cordeiro LLC		10	84		poured sidewalk on north side of gym and 3 light standards		F	F	OS
Cordeiro LLC							F	F	OS
Rufino`s Paintir	ng & Construction Inc.	5	56		tape and float in electricall room on 2nd floor & gym; sanding & priming walls in cafeteria & kitchen		F	F	
Rufino`s Paintir	ng & Construction Inc.	5	56		tape and float in electricall room on 2nd floor & gym; sanding & priming walls in cafeteria & kitchen		F	F	
	ng & Construction Inc.	4	32		tape and float in mechanical room @ kitchen; sanding in gym		F	F	
Rufino`s Paintir	ng & Construction Inc.	5	40		tape and float in mechanical room @ kitchen;tape/float @ gym		F	F	
Rufino`s Paintir	ng & Construction Inc.	4	32		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Paintir	ng & Construction Inc.						F	F	
Quality Iron Fal	oricators Inc.						F	F	
Quality Iron Fal	oricators Inc.						F	F	
Quality Iron Fal	oricators Inc.	3	24		Premier- installed 3 lintels in cafeteria above windows & installed ladder extensions		F	F	
Quality Iron Fal	oricators Inc.						F	F	
Quality Iron Fal	oricators Inc.						F	F	
Quality Iron Fal	oricators Inc.						F	F	
Roofing Solution	ons LLC	5	40		flash walls with base & white cap on high D		F	F	
Roofing Solution	ons LLC	5	40		flash walls with base & white cap on high D		F	F	
Roofing Solution	ons LLC	5	40		flash walls with base & white cap on high D & E		F	F	
Roofing Solution	ons LLC	5	40		flash walls with base & white cap on high D & E		F	F	

Project:	Sherwood Forest Element	ary Scho	ol			Job:		14-	02-002
Location:	4801 Maid Marion Drive					Report #:			1
Fair Working I	Days To Date:					Date:		10/2	3/2015
Weather Delay				Weather Condition:	partly sunny	Day:			Friday
	ed as Weather Day?		N	Precipitation Amount: 0		Temp:	Lo	w	High
Critical Path W	/ork Effected?		N			•	(	69	82
Roofing Solution	is LLC	3	20		work on mock-up wall install; 1 guy came and installed scuppers on C this afternoon		F	F	
Roofing Solution	s LLC	5	10		came and picked up propane tanks		F	F	
Allied Constructi	on, LLC	13	112		worked on east & souths walls of area E; clean-up			F	OS
Allied Constructi	on, LLC	16	112		worked on east & souths walls of area E; clean-up			F	OS
Allied Constructi	on, LLC	16	112		worked on east & souths walls of area E; clean-up			F	OS
Allied Construction	on, LLC	15	120		completed brick @ stairwell @ E and worked on south wall of E; clean-up			F	OS
Allied Construction	on, LLC	16	128		worked on south wall of E; cleaned brick in courtyard; took down scaffolding in front of west main entrance			F	OS
Allied Construction	on, LLC	4	16		droped off brick; distributed block into bldg; cleaned brick in courtyard			F	OS
CFI Insulation Inc	=						F	F	OS
CFI Insulation Inc	3						F	F	OS
CFI Insulation Inc	=						F	F	OS
CFI Insulation Inc	2						F	F	OS
CFI Insulation Inc	3	1	9		sprayed south wall on D		F	F	OS
CFI Insulation Inc	2						F	F	OS
Malone All Star J	V, LLC	16	128		Overhead in C1, D2; walls in E1 & E2; install gear in C2 & E2		F	Ε	OS
Malone All Star J	V, LLC								
Malone All Star J	V, LLC	16	128		Overhead in C1, D2; walls in E1 & E2; install gear in C2 & E2		F	Ε	OS
Malone All Star J	V, LLC	16	128		Overhead in D2; walls in E1 & E2; install gear in E2		F	Ε	OS
Malone All Star J	V, LLC	16	128		Overhead in D2; walls in E1 & E2; install gear in E2		F	F	OS
Malone All Star J	V, LLC	15	120		Overhead in D2; walls in E1 & E2; install gear in E2 & E2		F	F	OS
Malone All Star J	V, LLC						F	F	OS
Atlas-Edco Inc		11	88		layout hangers; beat duct together; hang duct in D & E all floors; hang duct in C		F	F	
		579	4753						

Remarks: Sub meeting held as usual on Mondays.

**Verbal or Written Instruction from Architect or Engineer:** spoke with Shishir with MMI. Expansion jts. in sidewalks are to be 70'-80' apart. He approved us pouring curb monolithic with sidewalks where sidewalks abut paving. Curbs will be poured monolithic with paving at other locations. Handicap ramp at north side is to be centered between canopy columns and ramp and wings are to be 5' each.

**Communication with Subcontractors:** Spoke with Pam with Beverly and confirmed to send sand out for Phoenix to this job only and have it be billed to Core. Phoenix will be backcharged for this.

Material Delivered: Morris had a truck come and pick up unneeded studs this afternoon.

Beverly delivered 15 loads of sand to Phoenix today for north parking lot.

Project:	Sherwood Forest Elementary School			Job:	14	-02-002
Location:	4801 Maid Marion Drive			Report #:		1
Fair Working	Days To Date:			Date:	10/2	26/2015
Weather Del	ays To Date:	Weather Condition:	rain (excessive rain over weeke	Day:	1	Monday
Is Today Clair	med as Weather Day?	Precipitation Amount: 7" in	n last 2 days	Temp:	Low	High
Critical Path	Work Effected?				69	76

Employee						Work Accomplished		
Alisha White								
George Caillouet								
Ellen Heck						(6:35-5:45) oversee site operations; gave the safety meeting this morning; worked on 3 week look ahead and held sub meeting		
Marybeth Leonard						<del>-</del>		
Chad Goubert								
Alisha White								
George Caillouet								
Ellen Heck						(6:35-6:15) oversee site operations		
Marybeth Leonard								
Chad Goubert								
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:50) oversee site operations		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Ellen Heck						(6:35-5:40) oversee site operations		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35- 6:30) oversee site operations		
Marybeth Leonard								
Chad Goubert								
Ellen Heck						(6:45-3:30) oversee site operations		
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
	2	16		WIKIS	шэ	Firestop International- install firestopping		
	2	16				Firestop International - install firestopping between floors; wall		
						caulking		
CORE Construction Services, LLC	1	8				Ray- dewater building	F	F
CORE Construction Services, LLC							F	F
CORE Construction Services, LLC							F	F
CORE Construction Services, LLC						Ray- install wall blocking in stairwell @ E & D	F	F
CORE Construction Services, LLC	1	8				Ray- stayed on dozer dressing up road and dragging trucks to get unloaded	F	F
CORE Construction Services, LLC	1	8				Ray - grade off road and around site before it rained; install temp handrails @ elevator openings		

Project: Sherwood Forest Element 4801 Maid Marion Drive	ntary Scho	ool	Job Report		14-	-02-002 1
Fair Working Days To Date:			Dat	<b>:</b> :	10/2	26/2015
Weather Delays To Date:			Weather Condition: rain (excessive rain over weeke Da	r:	N	∕Ionday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount: 7" in last 2 days Tem	): I	_ow	High
Critical Path Work Effected?		Υ			69	76
Bernhard Mechanical Contractors, L.L.C.	14	120	work on sanitary & sewer in D3; ran nyron pipe in A, B & C;continue running in wall and overhead copper pipe in D	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	10	80	Atlas -install duct in A & E	F	F	
Bernhard Mechanical Contractors, L.L.C.	4	32	ISS - insulate water lines and insulating ducts in D1 & 2	F	F	
Bernhard Mechanical Contractors, L.L.C.	17	136	work on sanitary & sewer in D3; ran nyron pipe in A, B & C;continue running in wall and overhead copper pipe in D	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	7	56	Atlas -install duct in E3; sealing jts on D2; installing duct on E2	F	F	
Bernhard Mechanical Contractors, L.L.C.	4	32	ISS - insulating ducts in D1 & 2	F	F	
Bernhard Mechanical Contractors, L.L.C.	14	136	work on sanitary & sewer in D3; ran nyron pipe in A, B & C;continue running in wall and overhead copper pipe in D	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	45	Atlas -install duct in E3; sealing jts on D2; installing duct on E2	F	F	
Bernhard Mechanical Contractors, L.L.C.	4	32	ISS - insulating ducts in D1 & 2	F	F	
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	16 6	132 45	work on sanitary & sewer in D3; ran nyron pipe in A, B & C;continue running in wall and overhead copper pipe in D Atlas -install duct in E3; sealing jts on D2; installing duct on E2;	F	F	OS
			install duct in C			
Bernhard Mechanical Contractors, L.L.C.	4	32	ISS - insulating ducts in D1 & 2	F	F	
Bernhard Mechanical Contractors, L.L.C.	15	137	work on sanitary & sewer in D3; ran nyron pipe in A, B & C;continue running in wall and overhead copper pipe in D; set chillers & AHU's	F	F	OS
Bernhard Mechanical Contractors, L.L.C.	6	45	Atlas -install duct in E3; sealing jts on D2; installing duct on E2; install duct in C	F	F	
Bernhard Mechanical Contractors, L.L.C.	2	16	ISS - insulating ducts in D1 & 2	F	F	
Bernhard Mechanical Contractors, L.L.C.	7	77	American Machine Movers- set chillers & AHU's			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Holi Services Inc	2	31	Holi - 4 laborer - dewater	F	F	
Holi Services Inc	2	16	Holi - 4 laborer - dewater	F	F	
Holi Services Inc	2	16	Holi - 4 laborer - dewater/clean-up/move materials	F	F	
Holi Services Inc	2	16	Holi - 2 laborer - dewater/clean-up/cut lintel angles/ help with blocking	F	F	
Holi Services Inc	2	18	Holi - 2 laborer - clean-up	F	F	
Holi Services Inc						
Morris Drywall Systems Inc	21	210	top out drywall in A, B & C; finish framing elevator shafts; framing stairwells in D & E on 3rd floor; frame furdowns in B; install insulation in area C	F	F	OS
Morris Drywall Systems Inc	22	220	top out drywall in A, B & C; finish framing elevator shafts; framing stairwells in D & E on 3rd floor; frame furdowns in B; install insulation in area C	F	F	OS
Morris Drywall Systems Inc	23	230	top out drywall in A, B & C; framing stainwells in D & E on 2nd floor; frame furdowns in B & began rocking	F	F	os
Morris Drywall Systems Inc	23	230	top out drywall in A, B & C; framing stairwells in D & E on 2nd floor; frame furdowns in B & began rocking	F	F	OS
Morris Drywall Systems Inc	23	184	top out drywall in A, B & C; framing stairwells in D & E on 2nd floor; frame furdowns in B & began rocking	F	F	OS
Morris Drywall Systems Inc	21	168	Continue rocking in A, B & C			
New Orleans Glass Company, Inc.				F	F	OS
New Orleans Glass Company, Inc.	7	56	installing rubber in windows on south side of courtyard and install pressure bar at main stair curtainwall; installing rubber @ west side of B	F	F	OS

Project: Sherwood Forest Elemer Location: 4801 Maid Marion Drive	itary Scho	ol			Job: Report #:		02-002	
Fair Working Days To Date:					Date:		10/2	8/2015
Weather Delays To Date:			Weather Condition:	mostly sunny	Day:		Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Lo	w	High
Critical Path Work Effected?		N				(	68	79
New Orleans Glass Company, Inc.	8	64		caulk exterior of windows; install vinyl ext. @ areas D & E 1st & 2nd floor		F	F	OS
New Orleans Glass Company, Inc.	6	48		caulk exterior of windows; install vinyl ext. @ areas D & E 3rd & 2nd floor		F	F	OS
New Orleans Glass Company, Inc.	6	48		caulk & install vinyl @ courtyard windows		F	F	OS
New Orleans Glass Company, Inc.								
Phoenix Constructors LLC	4	26		running sanitary lines on west side of building; did 3rd proof roll test on north parking lot and passed; hauled off dirt on west side of bldg		Р	F	OS
Phoenix Constructors LLC	5	40		running sanitary lines on west side of building; attempted to get densities on sand at north parking lot but failed due to it being too wet; worked on water line-still can't get it to hold pressure		Р	F	OS
Phoenix Constructors LLC	5	40		running storm lines on west side of building		Р	F	OS
Phoenix Constructors LLC	5	40		running storm lines on west side of building; bladed off roads		Р	F	OS
Phoenix Constructors LLC	5	40		running storm lines on west side of building		Р	F	OS
Phoenix Constructors LLC								
Cordeiro LLC	5	20		wrecked forms @ sidewalk @ north side of gym and formed housekeeping pads (3 ea)		F	F	OS
Cordeiro LLC		20				F	F	OS
Cordeiro LLC		20				F	F	OS
Cordeiro LLC		20				F	F	OS
Cordeiro LLC		20				F	F	OS
Cordeiro LLC	1	4		drill for dowels for cmu at chase walls @ 1st & 2nd floor RR's in D				
Rufino`s Painting & Construction Inc.	4	32		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Painting & Construction Inc.	6	48		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Painting & Construction Inc.	3	24		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Painting & Construction Inc.	4	32		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Painting & Construction Inc.	7	56		fire tape @ kitchen;tape/float @ gym		F	F	
Rufino`s Painting & Construction Inc.								
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.						F	F	
Quality Iron Fabricators Inc.								
River City Fire Protection	9	32		began distributing pipe in D & E				
River City Fire Protection	7	70		distributing pipe in D & E; began hanging pipe in D				
River City Fire Protection	7	70		hanging pipe in D & E 1st floor; began stocking 3rd floor				
River City Fire Protection	7	56		hanging pipe in D & E 3rd floor; stocking 3rd floor				
River City Fire Protection	7	56		hanging pipe in D & E 3rd floor; stocking 3rd floor				
River City Fire Protection						_		
Roofing Solutions LLC	-	40				F	F	
Roofing Solutions LLC	5	40		fix scuppers at west side of B where it was causing leaks		f -	F	
Roofing Solutions LLC	11	88		white cap @ D & E including flashings		+	F	
Roofing Solutions LLC	6	48		white cap @ D & E including flashings; remove materials from high roof of D&E		F	F	
Roofing Solutions LLC						F	F	
Roofing Solutions LLC								

Project:	Sherwood Forest Elementa	ary Scho	ool			Job:		14-	02-002
Location:	4801 Maid Marion Drive					Report #:			1
Fair Working	Days To Date:					Date:		10/2	6/2015
Weather De	lays To Date:			Weather Condition:	rain (excessive rain over weeke	Day:		M	londay
Is Today Clai	med as Weather Day?		Υ	Precipitation Amount: 7" in	last 2 days	Temp:	Lov	N	High
Critical Path	Work Effected?		Υ				6	9	76
Allied Constru	ction, LLC							F	OS
Allied Constru	ction, LLC							F	OS
Allied Constru	ction, LLC	16	128		brick south side of D & E			F	OS
Allied Constru	ction, LLC	13	104		brick south side of D & E; washing brick			F	OS
Allied Constru	ction, LLC	13	104		brick south side of D & E; washing brick			F	OS
Allied Constru	ction, LLC	9	36		Brick @ south side of D & E; install starter courses of brick @ low D roofs; set up scaffolding				
CFI Insulation	nc						F	F	OS
CFI Insulation	nc						F	F	OS
CFI Insulation	nc						F	F	OS
CFI Insulation	nc						F	F	OS
CFI Insulation	nc						F	F	OS
CFI Insulation	nc								
Malone All Sta	r JV, LLC	14	112		Overhead in D2; walls in E1 & E2; install gear in C2 & E2		F	F	OS
Malone All Sta	r JV, LLC	14	112		Overhead in D2; walls in E1 & E2; install gear in C2 & E2		F	F	OS
Malone All Sta	r JV, LLC	14	112		Overhead in D2; walls in E1 & E2; install gear in C2 & E2		F	F	OS
Malone All Sta	r JV, LLC	14	112		Overhead in D2; walls in E1 & E2; install gear in C2 & E2		F	F	OS
Malone All Sta	r JV, LLC	18	144		Overhead in D2; walls in E1 & E2; install gear in C2 & E2		F	F	OS
Malone All Sta	r JV, LLC								
		551	4669						

**Remarks:** Hector with Heritage Tile came to the site @ noon to pick up 20 bags of mortar mix to bring to Habbins.

It began raining at 10:53am today and stopped about 12:30pm. Began raining again @ 1:00. Rained off and on all afternoon.

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/	/01/2015
Weather Dela	ays To Date:		Weather Condition:	mainly sunny	Day:		Sunday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				61	69

Employee						Work Accomplished			
Alisha White						·			
George Caillouet									
Ellen Heck						(6:35-4:40) oversee site operations			
Marybeth Leonard						attended safety meeting @ main office this morning			
George Caillouet						attended safety meeting & main office this morning			
Tanner Broughton									
Ellen Heck									
Marybeth Leonard									
Chad Goubert									
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:30-6:50pm) oversee site operations; deal with McD 42 A/C issues			
Marybeth Leonard						. , , ,			
Chad Goubert									
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:30-7:00) oversee site operations			
Marybeth Leonard									
Chad Goubert									
Tanner Broughton						Habbins, LSU and then here			
Ellen Heck						(6:30-5:50) oversee site operations			
Marybeth Leonard						Habbins then here			
Chad Goubert									
Ellen Heck						(6:30-8:00 & 12:00-4:30) oversee site operations, give safety orientations;			
						(8:00-12:00) went to McD42 to meet concerning playground ooz and A/C issues			
Marybeth Leonard						- EMERGENCY MANDATORY MEETING			
Chad Goubert									
Ellen Heck						(6:30-8:00 & 12:00-4:30) oversee site operations, give safety orientations;			
						(8:00-12:00) went to McD42 to meet concerning playground ooz and A/C issues			
						- EMERGENCY MANDATORY MEETING			
Marybeth Leonard									
Chad Goubert				n4	٠١				
	Sub	Sub		2nd Tier	2nd Tier				
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q	Sch
CORE Construction Services, LLC	1	8				Ray-install j-hooks to hang extension cords on 2nd & 3rd floors			
CORE Construction Services, LLC	1	8				Ray- cut lintel @ cafeteria window			
CORE Construction Services, LLC	1	10				Ray- cut lintel @ cafeteria window			
CORE Construction Services, LLC	1	10				Ray, Manuel, Carlos & Juan- install temp doors in storefront			

openings

Project: Sherwood Forest Eleme 4801 Maid Marion Drive	=				Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	11/0	05/2015
Weather Delays To Date:			Weather Condition:	cloudy & humid	Day:	Т	hursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				73	82
CORE Construction Services, LLC	4	32		Ray, Manuel, Carlos & Juan- install temp doors in storefront openings; finish cutting lintels @ cafeteria windows; waterproof elevator pit			
CORE Construction Services, LLC	4	32		Ray, Manuel, Carlos & Juan- install temp doors; wood temp louver openings; waterproof elevator pit; backdrag site; sweep street			
CORE Construction Services, LLC	1	8		Ray- waterproof at main entry; grade site; help clean gym			
Bernhard Mechanical Contractors, L.L.C.	17	148		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water			
Bernhard Mechanical Contractors, L.L.C.	6	45		for pumps; got wall inspection on D1 & D3 RR  Atlas - installing ducts and sealing ducts in C & E			
Bernhard Mechanical Contractors, L.L.C.	9	72		ISS - continue insulating ducts in D & E and pipe insulation in			
Definition Westuried Contractors, E.E.C.	ý	,,		cafeteria; insulated duct risers on 3rd floor; insulating duct in east section of C			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	15	128		coring holes in area D2 & E2; running nyron pipe in C1; continueing to work on installing chiller lines; continue sanitary & water line installation on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	6	48		Atlas - installing ducts and sealing ducts in D & E; beg			
Bernhard Mechanical Contractors, L.L.C.	2	16		ISS - continue insulating ducts in D & E			
Bernhard Mechanical Contractors, L.L.C.	3	18		bolted and caulked AHU's together on roof			
Bernhard Mechanical Contractors, L.L.C.	15	128		coring holes in area D2 & E2; running nyron pipe in C1; continueing to work on installing chiller lines; continue sanitary & water line installation on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	7	53		Atlas - installing ducts and sealing ducts in D & E; finish installing kitchen hood			
Bernhard Mechanical Contractors, L.L.C.	2	16		ISS - continue insulating ducts in D & E			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	17	148		coring holes in area D2 & E2; running nyron pipe in C1; continueing to work on installing chiller lines; continue sanitary & water line installation on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	5	40		Atlas - installing ducts and sealing ducts in D & E; finish installing kitchen hood			
Bernhard Mechanical Contractors, L.L.C.	4	32		ISS - continue insulating ducts in D & E			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	17	146		coring holes in area D2 & E2; continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	5	40		Atlas - installing ducts and sealing ducts in D & E; finish installing kitchen hood			
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - continue insulating ducts in D & E and in cafeteria & kitchen			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	15	120		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D; continue welding headers for chilled & hot water for pumps; move materials out of gym			
Bernhard Mechanical Contractors, L.L.C.	6	44		Atlas - installing ducts and sealing ducts in D & E; finish installing kitchen hood			
Bernhard Mechanical Contractors, L.L.C.	4	32		ISS - continue insulating ducts in D & E and in cafeteria & kitchen			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							

Project: Sherwood Forest Element 4801 Maid Marion Drive Fair Working Days To Date: Weather Delays To Date: Is Today Claimed as Weather Day?	ntary scho	N	Weather Condition: Precipitation Amount:	partly cloudy	Job: Report #:  Date:  Day:  Temp:	11/0	-02-002 1 07/2015 aturday High
Critical Path Work Effected?		N				71	81
Bernhard Mechanical Contractors, L.L.C.	4	32		ISS - continue insulating ducts in D & E and in cafeteria & kitchen			
Kone Inc	2	20		working on elevator -rope elevator and set floor stops			
Kone Inc	2	10		unloaded elevator and then left because they did not have their tools			
Kone Inc							
Holi Services Inc	2	16		Mike and Eddie dewatered bldg.			
Holi Services Inc	2	16		dewater			
Holi Services Inc	2	20		2 laborers - dewater; unload materials			
Holi Services Inc	2	20		2 laborers - dewater; unload materials			
Holi Services Inc	2	18		2 laborers - dewater; unload materials; clean elevator pit			
Holi Services Inc	1	8		1 laborers - cleaned gym			
Holi Services Inc	1	8		1 laborers - cleaned gym			
Morris Drywall Systems Inc Morris Drywall Systems Inc	25 24	225		1st side S/R @ E1 & D1; framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3; cut scupper holes larger on bldg E & D  Continue to top out walls in A & C; 1st side S/R @ E1 & D1;			
Morris Drywall Systems Inc	23	107		began framing furdowns @ D1  Continue to top out walls in A & C; 1st side S/R @ E1 &			
Morris Drywall Systems Inc	22	196		D1;framing furdowns @ D1  Continue to top out walls in A & C; 1st side S/R @ E1 &			
Morris Drywall Systems Inc	23	207		D1;framing furdowns @ D1  Continue to top out walls in A & C; 1st side S/R @ E1 &  D1;framing furdowns @ D1			
Morris Drywall Systems Inc	20	160		1st side S/R @ E1 & D1;framing furdowns @ D1			
Morris Drywall Systems Inc	2	10		move materials to 3rd floor			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	5	40		install vinyl and caulk; began installation of interior curtainwall at main entrance			
New Orleans Glass Company, Inc.	5	40		install vinyl and caulk; installation of interior curtainwall at main entrance			
New Orleans Glass Company, Inc.	5	40		install vinyl and caulk; install glass at stairwell @ D & Eentrance			
New Orleans Glass Company, Inc.	4	32		install vinyl and caulk; install misc. glass in area E 2nd & 3rd floor			
New Orleans Glass Company, Inc.	5	40		install glass area E1			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC							
Phoenix Constructors LLC	1	4		worked on water line			
Phoenix Constructors LLC	1	4		worked on water line			
Phoenix Constructors LLC	1	4		worked on water line and finally got it to pass; worked in courtyard; helped grade north parking lot			
Phoenix Constructors LLC	5	46		worked on catch basins on west side of project by road; backfilled at water line			
Phoenix Constructors LLC	5	40		worked on catch basins on west side of project by road; backdragged temp road			
Phoenix Constructors LLC	5	40		worked on catch basins on west side of project by road; backdragged temp road			
Cordeiro LLC	4	32		Prep for paving pour			
Cordeiro LLC	5	40		pour 3 house keeping pads on D3; worked on light standards; began forming for paving at north parking lot.			
Cordeiro LLC	5	50		continue forming and finish grading north parking lot just north of gym			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	11/0	4/2015
Weather Delays To Date:			Weather Condition:	mostly sunny	Day:	Wed	lnesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				67	77
Cordeiro LLC	5	50		continue forming and finish grading north parking lot just north			
				of gym			
Cordeiro LLC	9	117		regraded north parking lot just north of gym & poured it			
Cordeiro LLC	5	40		sawcut control joints in paving; cleaned up; wreck light standard forms			
Cordeiro LLC	5	40		began prepping for 2nd paving pour			
Rufino's Painting & Construction Inc.	9	72		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino's Painting & Construction Inc.	9	72		tape/float in kitchen; sand in gym			
Rufino's Painting & Construction Inc.	10	80		tape/float in kitchen; sand in gym			
Rufino's Painting & Construction Inc.	9	72		tape/float in kitchen; sand in gym			
Rufino`s Painting & Construction Inc.	9	72		tape/float in kitchen; sand in gym			
Rufino`s Painting & Construction Inc.	11	88		tape/float in kitchen; paint in gym			
Rufino`s Painting & Construction Inc.	2	16		paint in gym			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection	2	16		install sprinkler lines on 2nd floor			
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	6	48		install scuppers and began installing termination bars			
Roofing Solutions LLC	6	48		install scuppers and began installing termination bars			
Roofing Solutions LLC	6	48		install scuppers and began installing termination bars & receivers			
Roofing Solutions LLC							
Roofing Solutions LLC							
Alack Refrigeration Company							
Allied Construction, LLC	9	72		SW corner of D2 & 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	11	88		continue bricking on south side of D & E; laid cmu chase walls @			
				RR's in D1 & D2			
Allied Construction, LLC	12	100		continue bricking on south side of D & E; laid cmu chase walls @			
Allied Construction, LLC	10	80		RR's in D1 & D2 continue bricking on south side of D2 &3; laid cmu chase walls @ RR's in D2			
Allied Construction, LLC	6	48		complete exterior brick @ D3; start brick above eyebrows @ E			
Allied Construction, LLC	9	54		complete exterior brick @ D3; start brick above eyebrows @ E;			
Allied Construction, LLC				breakdown scaffolding			
CFI Insulation Inc							
CFI Insulation Inc							

Project:	Sherwood Forest Element 4801 Maid Marion Drive	tary Scho	ool			Job:	14-	02-002
Location:	4001 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	11/0	3/2015
Weather Dela	ays To Date:			Weather Condition:	partly sunny	Day:	7	uesday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N				65	76
CFI Insulation In	nc	2	16		waterproof SW corner of area D and misc windows			
CFI Insulation In	nc	2	16		waterproof SW corner of area D and misc windows			
CFI Insulation In	nc							
CFI Insulation In	nc							
CFI Insulation In	nc							
Ellison Builders								
Ellison Builders		3	11		began hanging HM exterior doors			
Ellison Builders								
Ellison Builders								
Ellison Builders		3	18		Install HM doors on mezzanine and exterior HM doors			
Ellison Builders		3	18		Install HM doors on mezzanine and exterior HM doors			
Ellison Builders								
Malone All Star	JV, LLC	17	136		overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 &			
					central plant, mech room A1, ceilings in C1, install temp lights			
Malone All Star		17	136		pull main feeders; overhead @ E2, rough-in walls in E1,E2 & D2			
Malone All Star		18	144		pull main feeders; overhead @ E2, rough-in walls in E1,E2 & D2			
Malone All Star	JV, LLC	18	144		pull main feeders; overhead @ E2, rough-in walls in E1,E2 & D2; run conduit for pole lights			
Malone All Star	JV, LLC	17	136		pull main feeders; overhead @ E2, rough-in walls in E1,E2 & D2			
Malone All Star	JV, LLC	21	136		pull main feeders; overhead @ E2 & D1, rough-in walls in E1 &			
					,clean gym			
Malone All Star	JV, LLC							
		669	5295					

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/	09/2015
Weather Del	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	Υ	Precipitation Amount: 0 -	site extremely muddy	Temp:	Low	High
Critical Path	Work Effected?	N				58	74

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-6:00) oversee site operations; dealt with getting fire extinguishers		
						recharged and/or replaced; met with architect and MMI concerning site grades		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-6:15) oversee site operations; walk site with Nick & Glen; attend OAC meeting		
Marybeth Leonard						ccg		
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operations		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operations		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Ellen Heck						(6:30-3:45) oversee site operations		
George Caillouet								
Ellen Heck						(6:30-3:40) oversee site operations		
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
	3	12		.71703		Hahn Enterprises- unloaded gym equipment		
	3	24				Hahn Enterprises- install basketball goals and divider curtain		
	3	27				Hahn Enterprises- finished installing basketball goals; worked on		
						divider curtain; install wall pads		
	1	1				termite treated around dumpster pad and loading dock area		
	2	16				Firestop International - fire caulk bathroom header wall @ D1 and floor penetrations		
	3	12				Hahn Enterprises- finished installing divider curtain and touch-up		
						paint		
CORE Construction Services, LLC	1	10				Ray- misc safety; backdrag site; sweep street		
						• •		

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	11/	10/2015
Weather Delays To Date:			Weather Condition:	partly sunny	Day:	-	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				62	74
CORE Construction Services, LLC	1	10		Ray- misc safety; backdrag site			
CORE Construction Services, LLC	1	10		Ray- misc safety; backdrag site			
CORE Construction Services, LLC	1	8		Ray- misc safety; backdrag site			
CORE Construction Services, LLC	1	8		Ray- block in and install doors at main entrance of B; install door			
				to pump room; backdrag site			
CORE Construction Services, LLC	1	8		Ray- backdrag site; run lull for clean-up			
Bernhard Mechanical Contractors, L.L.C.	16	160		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D; continue welding headers for chilled & hot water for pumps; move materials out of gym			
Bernhard Mechanical Contractors, L.L.C.	6	44		Atlas - installing ducts and sealing ducts in D & E 3rd floor; hook duct to units on roof			
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - continue insulating ducts in D & E and in cafeteria & kitchen			
Bernhard Mechanical Contractors, L.L.C.	16	160		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	7	53		Atlas - installing ducts and sealing ducts in D & E 3rd floor; hook duct to units on roof			
Bernhard Mechanical Contractors, L.L.C.	4	32		ISS - continue insulating ducts in D $\&$ E and in cafeteria $\&$ kitchen			
Bernhard Mechanical Contractors, L.L.C.	16	139		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	6	44		Atlas - installing ducts and sealing ducts in C $\&$ E; hook duct to units on roof			
Bernhard Mechanical Contractors, L.L.C.	4	32		ISS - continue insulating ducts in D $\&$ E and in cafeteria $\&$ kitchen			
Bernhard Mechanical Contractors, L.L.C.	2	8		Synergy - Bob was here trying to rough-in on 2nd & 3rd floors			
Bernhard Mechanical Contractors, L.L.C.	16	138		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	6	44		Atlas - installing ducts and sealing ducts in C $\&$ E; hook duct to units on roof			
Bernhard Mechanical Contractors, L.L.C.	9	67		ISS - continue insulating ducts in D & E and pipe insulation in cafeteria; insulated duct risers on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	1	4		Synergy - Bob was here trying to rough-in on 2nd & 3rd floors			
Bernhard Mechanical Contractors, L.L.C.	15	120		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	6	44		Atlas - installing ducts and sealing ducts in C & E; hook duct to units on roof			
Bernhard Mechanical Contractors, L.L.C.	7	56		ISS - continue insulating ducts in D & E and pipe insulation in cafeteria; insulated duct risers on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.	1	8		roughing in for controls			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	7	46		ISS - continue insulating ducts in D & E and pipe insulation in kitchen; insulated duct risers on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.				Synergy -			
Kone Inc	2	20		install cables and weld clips for rails			
Kone Inc	2	20		install cables and weld clips for rails			

Project: Sherwood Forest Element 4801 Maid Marion Drive	icary SCNC	וטנ			Job: Report #:	14-	02-002 1
Fair Working Days To Date:					Date:	11/1	0/2015
Weather Delays To Date:			Weather Condition:	partly sunny	Day:	T	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				62	74
Kone Inc	2	20		began installing clips			
Kone Inc							
Kone Inc	2	20		Installed platform and back & sidewalls in			
Kone Inc	2	20		working on elevator			
Kone Inc	2	16		working on elevator - stacking rails			
Holi Services Inc	7	8		dewatered; clean-up			
Holi Services Inc	6	48		dewatered; clean-up			
Holi Services Inc	6	48		dewatered; clean-up			
Holi Services Inc	2	16		dewatered; clean-up			
Holi Services Inc	2	16		dewatered; clean-up			
Holi Services Inc	2	16		clean-up; sweep street			
Morris Drywall Systems Inc	34	340		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up			
Morris Drywall Systems Inc	34	340		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up			
Morris Drywall Systems Inc	34	294		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls			
Maria Barrall Carrana las	24	260		on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3			
Morris Drywall Systems Inc	31	260		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3			
Morris Drywall Systems Inc	31	260		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls			
				on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3			
Morris Drywall Systems Inc	23	184		clean-up; framing on 2nd & 3rd floors; s/r of furdowns in B			
New Orleans Glass Company, Inc.	4	32		install main storefront on west side			
New Orleans Glass Company, Inc.	4	32		install main storefront on west side and set interior glass at main entrance of B			
New Orleans Glass Company, Inc.	4	32		set interior glass at main entrance of B; and built center			
				storefront section from vestibule to cafeteria			
New Orleans Glass Company, Inc.	4	32		set exterior glass at main entrance of B			
New Orleans Glass Company, Inc.	4	32		set exterior glass at main entrance of B; caulk windows adjacent			
New Orleans Glass Company, Inc.				to brick; tape window head and jambs adjacent to metal panels			
Phoenix Constructors LLC	5	40		backdragged temp road; sawcut in courtyard for missing storm			
	,	.0		drain line @ SW corner			
Phoenix Constructors LLC	5	40		added and helped grade for 2nd pour			
Phoenix Constructors LLC	5	40		added and helped grade for 2nd pour			
Phoenix Constructors LLC	5	40		finished installing and backfilling storm line to SW corner of court			
				yard and then began running 8" line to catch basin in court yard			
Phoenix Constructors LLC	5	40		relocated catch basin at east end of courtyard that was installed			
Phoenix Constructors LLC	5	40		at incorrect spot run storm line in court yard; grade for 3rd pour of north parking			
	,	.0		lot; haul of dirt on west side of bldg			
Cordeiro LLC	9	72		began forming and prepping for pour at loading dock and			
				adjacent area			
Cordeiro LLC	5	40		forming and prepping for pour at loading dock and adjacent			
Cordeiro LLC	5	50		area; set/poured in bollards forming and prepping for pour at loading dock and adjacent			
	,			area; set/poured in bollards			
Cordeiro LLC	10	90		poured 2nd section of north paving by loading dock and poured			
	_			some curb at north parking lot			
Cordeiro LLC	5	40		wrecked forms from 2nd paving pour and began prepping for 3rd			
Cordeiro LLC				paving pour at north parking lot			
Rufino`s Painting & Construction Inc.	11	88		tape/float/sand in area C minus gym; paint in gym			
•				,			

Project: Sherwood Forest Elemen Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	11/1	0/2015
Weather Delays To Date:			Weather Condition:	partly sunny	Day:	Т	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	·		•	62	74
Rufino`s Painting & Construction Inc.	12	96		tape/float/sand in area C minus gym; paint in gym; tape & float			
5				in D1 & E1			
Rufino's Painting & Construction Inc.	11	88		tape & float in D1 & E1			
Rufino's Painting & Construction Inc.	8	64		tape & float in D1 & E1; paint in gym and in back rooms of area			
Rufino's Painting & Construction Inc.	8	64		A tape & float in D1 & E1; paint in gym and in back rooms of area			
D. Cooks Defection On Consequently allow				A			
Rufino's Painting & Construction Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Alack Refrigeration Company	5	30		unloaded cooler/freezer and set floor panels			
Alack Refrigeration Company	4	32		Put together cooler/freezer			
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC	9	54		complete exterior brick @ D3; start brick above eyebrows @ E; breakdown scaffolding			
Allied Construction, LLC	9	54		exterior brick @ D3 west of stairwell; wash brick at east end of E			
Allied Construction, LLC	9	54		exterior brick @ D3 west of stairwel; install block above windows			
All'ad Carata al'ar II C	10	00		in cafeteria; finish bricking around doorway by kitchen			
Allied Construction, LLC	10	80		exterior brick @ D3 west of stairwel; install block above windows in cafeteria			
Allied Construction, LLC	6	48		lay brick @ SW corner of area B1; finish installing block above windows in cafeteria			
Allied Construction, LLC	7	50		clean-up; setting up scaffolding @ SW corner of D and bricking			
CFI Insulation Inc				same			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Ellison Builders							

Project:	Sherwood Forest Element	ary Scho	ool			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	11/1	0/2015
Weather Dela	ays To Date:			Weather Condition:	partly sunny	Day:	Т	uesday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Work Effected?		Ν				62	74
Ellison Builders								
Ellison Builders								
Ellison Builders								
Ellison Builders								
Ellison Builders								
Malone All Star	JV, LLC	19	152		overhead @ E2, rough-in walls in E1 &E2 ,elec rooms C2 & E2;			
					pull feeders			
Malone All Star	JV, LLC	19	152		overhead @ E2, rough-in walls in E1 &E2 ,elec rooms C2 & E2;			
					pull feeders			
Malone All Star	JV, LLC	19	152		overhead @ E2, rough-in walls in D1,E2 &E3 ,elec rooms C2 & E2;			
					pull feeders			
Malone All Star	JV, LLC	13	104		overhead @ E2, rough-in walls in D1,E2 &E3 ,elec rooms C2 & E2			
Malone All Star	JV, LLC	2	8		Bonded Lightning- install ground rods			
Malone All Star	JV, LLC	15	117		overhead @ E2, rough-in walls in D1,E2 &E3 ,elec rooms C2 & E2			
Malone All Star	JV, LLC							
		675	5509					

Project:	Sherwood Forest Elementary Schoo	l			Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/	16/2015
Weather Dela	ys To Date:		Weather Condition:	mostly cloudy	Day:	!	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Vork Effected?	Ν				70	76

Employee				Work Accomplished
George Caillouet				
Tanner Broughton				
Ellen Heck				(6:35-5:30) oversee site operations
Chad Goubert				
Alisha White				
George Caillouet				
Ellen Heck				(6:35-7:00) oversee site operations; attend quarterly safety meeting @ office
Marybeth Leonard				
Chad Goubert				
Alisha White				
George Caillouet				
Ellen Heck				(6:35-6:00) oversee site operations
Marybeth Leonard				
Chad Goubert				
Alisha White				
George Caillouet				
Ellen Heck				(6:35-4:40) oversee site operations
Marybeth Leonard				attended safety meeting @ main office this morning
Alisha White				
George Caillouet				
Tanner Broughton				
Ellen Heck				(6:35-4:10) oversee site operations
Marybeth Leonard				
Ellen Heck				(6:45-2:30) oversee site operations
		2nd	2nd	
Subcontractor	Sub Sub Wrkrs Hrs	Tier Wrkrs	Tier Hrs	Work Accomplished S Q Sch

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	- <del></del>			Job: Report #:		-02-00 <i>2</i>
Fair Working Days To Date:					Date:	11/	17/201
Weather Delays To Date:			Weather Condition:	windy and cloudy	Day:	-	Tuesday
ls Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				66	79
CORE Construction Services, LLC	1	10		Ray- installed door @ 3rd floor window in D, installed door on electrical room on D2; boarded in dbl ext doors at corridor to kitchen; installed blocking in stair D			
CORE Construction Services, LLC	1	3		Ray-install j-hooks to hang extension cords			
CORE Construction Services, LLC	1	8		Ray-install j-hooks to hang extension cords on 2nd & 3rd floors			
CORE Construction Services, LLC	1	8		Ray - install blocking at stair D and began blocking at main stair			
CORE Construction Services, LLC	1	8		Ray -clear areas for concrete pump; work on expansion jt. and			
Bernhard Mechanical Contractors, L.L.C.	17	148		wall blocking continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water for pumps			
Bernhard Mechanical Contractors, L.L.C.	6	45		Atlas - installing ducts and sealing ducts in C & E			
Bernhard Mechanical Contractors, L.L.C.	8	64		ISS - continue insulating ducts in D & E and pipe insulation in cafeteria; insulated duct risers on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.				Synergy -			
Bernhard Mechanical Contractors, L.L.C.	17	148		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water			
	_			for pumps; got wall inspection on D1 & D3 RR			
Bernhard Mechanical Contractors, L.L.C.	5	39		Atlas - installing ducts and sealing ducts in C & E			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS - continue insulating ducts in D & E and pipe insulation in cafeteria; insulated duct risers on 3rd floor; insulating duct in east section of C			
Bernhard Mechanical Contractors, L.L.C.	1	5		Synergy - roughed in for controls in C			
Bernhard Mechanical Contractors, L.L.C.	15	1,132		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water			
Bernhard Mechanical Contractors, L.L.C.	6	45		for pumps; installing valve packs for VAV's in B & C			
Bernhard Mechanical Contractors, L.L.C.	8	64		Atlas - installing ducts and sealing ducts in C.  ISS - continue insulating ducts in D & E and pipe insulation in			
permand Mechanical Contractors, E.E.C.	Ü	04		cafeteria; insulated duct risers on 3rd floor; insulating duct in east section of C			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	17	148		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue welding headers for chilled & hot water for pumps; got wall inspection on D1 & D3 RR			
Bernhard Mechanical Contractors, L.L.C.	6	45		Atlas - installing ducts and sealing ducts in C & E			
Bernhard Mechanical Contractors, L.L.C.	9	72		ISS - continue insulating ducts in D & E and pipe insulation in cafeteria; insulated duct risers on 3rd floor; insulating duct in east section of C			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	19	152		continueing to work on installing chiller & hot water lines in A & C; continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue installing VAV valve packs; started piping in domestic water booster pump.			
Bernhard Mechanical Contractors, L.L.C.	4	32		Atlas - installing ducts and sealing ducts in C			
Bernhard Mechanical Contractors, L.L.C.				ISS - not here today; had safety meeting at office			
Bernhard Mechanical Contractors, L.L.C.	1	8		Synergy - installing raceways across hard ceilings			
Bernhard Mechanical Contractors, L.L.C.	7	56		sanitary & water in E1; work in pump room; set dumpster drain and floor trench in kitchen $ \label{eq:control} % \begin{center} cente$			
Bernhard Mechanical Contractors, L.L.C.							

Project: Sherwood Forest Element 4801 Maid Marion Drive	icary SCNC	וטנ			Job: Report #:	14	-02-00 <i>2</i>
Fair Working Days To Date:					Date:	11/2	21/201
Weather Delays To Date:			Weather Condition:	cloudy/rain	Day:	S	aturday
ls Today Claimed as Weather Day?		Υ	Precipitation Amount: 1/4"		Temp:	Low	High
Critical Path Work Effected?		N				46	67
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Kone Inc	2	20		working on elevator			
Kone Inc	2	16		working on elevator			
Kone Inc	2	20		working on elevator - wire machine and controller			
Kone Inc	2	20		working on elevator -rope elevator and set floor stops			
Kone Inc	2	16		working on elevator - build door frames			
Kone Inc	2	14		working on elevator - install doors; clean-up			
Holi Services Inc	2	16		Mike worked with Ray; Eddie did clean-up, handled dumpster pulls, swept street			
Holi Services Inc	2	16		Mike worked with Ray and swept stairs; Eddie did clean-up, handled dumpster pulls, swept street			
Holi Services Inc	2	20		Mike and Eddie dewatered bldg.			
Holi Services Inc	2	16		Mike and Eddie dewatered bldg.			
Holi Services Inc	2	16		Mike and Eddie clean-up			
Holi Services Inc							
Morris Drywall Systems Inc	30	279		1st side S/R @ E1 & D1; framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3			
Morris Drywall Systems Inc	33	306		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3;			
Morris Drywall Systems Inc	27	243		cut scupper holes larger on bldg E & D  1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stainwell in E2 & E3; framing stainwell in D3;			
Morris Drywall Systems Inc	25	225		cut scupper holes larger on bldg E & D  1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3; cut scupper holes larger on bldg E & D			
Morris Drywall Systems Inc	30	240		1st side S/R @ E1 & D1; framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3; cut scupper holes larger on bldg E & D			
Morris Drywall Systems Inc	18	90		1st side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls on 2nd floor and rock stainwell in E2 & E3; framing stainwell in D3; cut scupper holes larger on bldg E & D			
New Orleans Glass Company, Inc.	3	24		caulk windows adjacent to brick; tape window head and jambs adjacent to metal panels			
New Orleans Glass Company, Inc.	3	24		caulk windows adjacent to brick; tape window head and jambs adjacent to metal panels; install pressure bar at main entrance of B			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	5	45		finished grading for 3rd paving pour; hauled off dirt on west side of property			
Phoenix Constructors LLC	5	45		finished grading for 3rd paving pour; hauled off dirt on west side of property			
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Phoenix Constructors LLC	5	30		haul dirt out of courtyard and work on storm line along Maid Marion			
Cordeiro LLC	5	40		prepping for 3rd paving pour at north parking lot			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	11/1	7/2015
Weather Delays To Date:			Weather Condition:	windy and cloudy	Day:	1	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				66	79
Cordeiro LLC	5	40		prepping for 3rd paving pour at north parking lot			
Cordeiro LLC							
Cordeiro LLC	4	32		Prep for paving pour			
Cordeiro LLC	4	32		Prep curbs			
Cordeiro LLC							
Rufino's Painting & Construction Inc.	9	72		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino's Painting & Construction Inc.	10	80		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino`s Painting & Construction Inc.	10	80		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino`s Painting & Construction Inc.	9	72		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino`s Painting & Construction Inc.	10	80		tape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino's Painting & Construction Inc.				· · · · · · · · · · · · · · · · · · ·			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection	2	20		installing sprinkler pipe on 2			
River City Fire Protection	2	16		install sprinkler lines on 2nd floor			
River City Fire Protection	2	16		install sprinkler lines on 2nd floor			
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC	4	38		dry-in and install scuppers on D & E			
Roofing Solutions LLC				,			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC	6	48		SW corner of D2 & 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	9	72		SW corner of D2 & 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	9	72		SW corner of D2 & 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	9	72		SW corner of D2 & 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	7	56		SW corner of D 3 exterior brick; layout block on D3 RR's			
Allied Construction, LLC	4	26		build scaffold @ eyebrow in courtyard			
CFI Insulation Inc		-		conyara			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
C							

<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	11/	20/2015
Weather Delays To Date:			Weather Condition:	mainly sunny	Day:		Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	60	69
CFI Insulation Inc							
CFI Insulation Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	15	120		overhead @ E2, rough-in walls inE2 &E3 ,elec rooms E2 &			
				central plant			
Malone All Star JV, LLC	16	128		overhead @ E2, rough-in walls inE2 &E3 ,elec rooms E2, C2 &			
				central plant			
Malone All Star JV, LLC	16	128		overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 &			
Mala a All Cras IV LLC	17	126		central plant, mech room A1, ceilings in C1, install temp lights			
Malone All Star JV, LLC	17	136		overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 &			
Malone All Star JV, LLC	15	116		central plant, mech room A1, ceilings in C1, install temp lights			
IVIDIONIC AN STOLE JV, LLC	13	110		overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 & central plant, mech room A1, ceilings in C1, install temp lights			
Malone All Star JV, LLC				central plant, meet room A1, cenings in C1, histain temp lights			
	563	5628					

Job:

14-02-002

Remarks: Began raining about noon

**Material Delivered:** 

Notes:

Project:

**Sherwood Forest Elementary School** 

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/3	23/2015
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:		Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				48	59

Employee						Work Accomplished
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:15-8:45) oversee site operations; held sub meeting
Marybeth Leonard						(0.15 0.45) oversee site operations, field sub-freeting
Chad Goubert						
George Caillouet						
Tanner Broughton						
Ellen Heck						(45.62)
Ellen Heck						(6:15-6:30) oversee site operations; attended OAC meeting and walked with  Nick
Marybeth Leonard						
Chad Goubert						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:15-3:00) oversee site operation
Marybeth Leonard						
				2nd	2nd	
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished S Q Sch
	7	28				came and installed the exterior rolling door and interior rolling grille Entergy - installed power pole and wire
	7	21				Entergy - installed transformer and energized pole
CORE Construction Services, LLC	, 1	8				Ray - hang ropes to support extension cords off floors; move
						mats to get access to 2nd floor
CORE Construction Services, LLC	1	8				Ray - install blocking at main stair; work on expansion jt. covers;
CORE Construction Services, LLC						dismantled temp wall from corridor in C to courtyard
Bernhard Mechanical Contractors, L.L.C.	18	158				continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof; poured back concrete at dumpster drain and floor trench in kitchen.
Bernhard Mechanical Contractors, L.L.C.	7	56				Atlas - installing ducts and sealing ducts in C & E1
Bernhard Mechanical Contractors, L.L.C.	6	48				ISS - insulate pipes and duct in area E1
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	17	146				continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof; poured back concrete at dumpster drain and floor trench in kitchen.
Bernhard Mechanical Contractors, L.L.C.	5	40				Atlas - installing ducts in gym & kitchen
Bernhard Mechanical Contractors, L.L.C.	12	96				ISS - insulate pipes and duct in area C1, D1, E1 & B1

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	iidaiy SCNC	, Ji			Job: Report #:		-02-00
Fair Working Days To Date:					Date:		25/201
Weather Delays To Date:		N	Weather Condition:	partly cloudy with rain in the m	Day:	Wed	Inesda
Is Today Claimed as Weather Day?		N	Precipitation Amount: some		Temp:	Low	Hig -
Critical Path Work Effected?		N				63	7
Bernhard Mechanical Contractors, L.L.C.	17	119	fl	ontinue sanitary & water line installation on 2nd floor & 3rd oors of D & E; continue piping in domestic water booster pump; vorking on lines to chillers on roof;			
Bernhard Mechanical Contractors, L.L.C.	10	50		tlas - installing fabric duct in gym & installing duct on E2			
Bernhard Mechanical Contractors, L.L.C.	9	63	15	SS - insulate pipes and duct in area C1, D1, E1 & A1			
Bernhard Mechanical Contractors, L.L.C.							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	2	16	N	flike and Eddie clean-up; mark holes in floors; flag for Ray			
Holi Services Inc	2	16		flike and Eddie clean-up; unload trucks			
Holi Services Inc	2	15		like and Eddie - fix fence & gates; clean-up			
Morris Drywall Systems Inc	30	240		Ist side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls in 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3;			
Morris Drywall Systems Inc	29	261	c	ut scupper holes larger on bldg E & D Ist side S/R @ E1 & D1;framing on E3; 2 did clean-up; shaft walls n 2nd floor and rock stairwell in E2 & E3; framing stairwell in D3;			
Morris Drywall Systems Inc	28	140	fı	ut scupper holes larger on bldg E & D raming in D, rock in stairs, elevator shaft enclosures, shafts on nd floor, frame in gym			
New Orleans Glass Company, Inc.	3	24	ir	nstall glass at main entry of B; set storefront between vestibule nd cafeteria in area B			
New Orleans Glass Company, Inc.	2	16	ir	nstall storefront at corridor C to courtyard; install glass in B			
New Orleans Glass Company, Inc.	2	16	c	aulk, install pressure bar @ face elev of CW1, move glass			
Phoenix Constructors LLC	5	45		nstall storm line along Maid Marion; haul dirt out of courtyard nd finished cutting paving for 4th pour			
Phoenix Constructors LLC	5	45	ir	nstall storm line along Maid Marion			
Phoenix Constructors LLC	5	40	ir	nstall storm line along Maid Marion			
Cordeiro LLC	8	116	P	our paving at west end of north parking lot			
Cordeiro LLC	4	32	W	reck paving forms @ pour 4; pour curbs			
Cordeiro LLC	4	28	С	hip concrete protruding walls in kitchen for quarry to be installed			
Rufino's Painting & Construction Inc.	12	96	t	ape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino's Painting & Construction Inc.	10	80	t	ape & float in D1 & E1; paint in gym and in back rooms of area c			
Rufino's Painting & Construction Inc.	9	72	t	ape & float in D1 & E1			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC	6	48	b	uild scaffold @ low D roof; lay brick @ eyebrow in courtyard			
Allied Construction, LLC	8	56	:	lay brick @ eyebrow in courtyard; lay cmu on D3			

Project: Sherwood Forest Elementar	ry Scho	ool		Job:	14-	-02-002
<b>Location:</b> 4801 Maid Marion Drive				Report #:		1
Fair Working Days To Date:				Date:	11/2	25/2015
Weather Delays To Date:			<b>Weather Condition:</b> partly cloudy with rain in the m	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount: some	Temp:	Low	High
Critical Path Work Effected?		Ν			63	70
Allied Construction, LLC	8	56	lay brick @ eyebrow in courtyard; lay cmu on D3			
CFI Insulation Inc						
CFI Insulation Inc	2	10	installed peal & stick and waterproofed directly above	ve .		
			termination bar on areas A, B & C			
CFI Insulation Inc						
Gulf South Engineering & Testing Inc	1	8	technician was here to take cylinders and slump the	concrete		
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Ellison Builders						
Ellison Builders						
Ellison Builders						
Malone All Star JV, LLC	19	152	overhead @ E2, rough-in walls inE2 &E1 ,elec rooms	s E2, C2 &		
			central plant			
Malone All Star JV, LLC	19	152	overhead @ E2, rough-in walls inE2 &E1 ,elec rooms	s E2, C2 &		
			central plant; ran branch circuits in kitchen			
Malone All Star JV, LLC	18	126	overhead @ E2, rough-in walls inE2 &E1 ,elec rooms	s E2, C2 &		
			central plant; ran branch circuits in kitchen			
	362	2761				

**Remarks:** Entergy's crew came and installed transformer.

**Visitors:** Kenan Young came by this morning and walked the job with me. The walk went well.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	11/	30/2015
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount: som	ne	Temp:	Low	High
Critical Path	Work Effected?	Ν				63	70

						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-5:40) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-5:40) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-5:40) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-4:50) oversee site operation		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-3:40) oversee site operation		
Marybeth Leonard								
Chad Goubert								
				2nd	2nd			
	Sub	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Scl

Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	s	Q :	Sch_
	1	8				Fire Stop International - floor penetration on 2nd & 3rd floor			
CORE Construction Services, LLC	1	10				Ray- install expansion joint			
CORE Construction Services, LLC	1	8				Ray- install expansion joint; temp doors			
	1	8				Ray- install expansion joint; help temp in at eyebrows			

Project: Sherwood Forest Elemer Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	12/0	3/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:	Th	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	45	60
CORE Construction Services, LLC	1	8		Ray- install expansion joint; remove temp barricade and then reinstall temp door @ exterior entrance of main stairs			
CORE Construction Services, LLC	1	9		Ray-removed broken matts from dirt pile; misc blocking			
CORE Construction Services, LLC	1	8		Ray- installed blocking in restroom ceilings; roof blocking at eyebrow in courtyard			
Bernhard Mechanical Contractors, L.L.C.	16	140		continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof;			
Bernhard Mechanical Contractors, L.L.C.	5	38		Atlas - installing fabric duct in gym & installing duct on E2			
Bernhard Mechanical Contractors, L.L.C.	7	56		ISS - insulate pipes and duct in area D1, E1 & A1			
Bernhard Mechanical Contractors, L.L.C.				,			
Bernhard Mechanical Contractors, L.L.C.	16	140		continue sanitary & water line installation on 2nd floor & 3rd			
berniad Mechanica Contractors, E.E.C.	10	140		floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof; cont. working in pump room; set exhaust fans on roofs			
Bernhard Mechanical Contractors, L.L.C.	5	38		Atlas - installing fabric duct in gym & installing duct on E2			
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - insulate pipes and duct in area D1, E1 & A1			
Bernhard Mechanical Contractors, L.L.C.	1	8		Synergy - install stub ups on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.	14	114		continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump;			
Bernhard Mechanical Contractors, L.L.C.	4	30		working on lines to chillers on roof  Atlas - installing duct in C at stage			
Bernhard Mechanical Contractors, L.L.C.	3	30		ISS - insulate duct in area D3, E3			
Bernhard Mechanical Contractors, L.L.C.				iss institute decementation by Es			
Bernhard Mechanical Contractors, L.L.C.	15	130		continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof			
Bernhard Mechanical Contractors, L.L.C.	4	30		Atlas - installing duct at stage and on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	8	80		ISS - insulate duct in area 1st floor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	18	144		continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof			
Bernhard Mechanical Contractors, L.L.C.	4	32		Atlas- install duct			
Bernhard Mechanical Contractors, L.L.C.	8	64		ISS - insulate duct in area 1st floor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	8	53		continue sanitary & water line installation on 2nd floor & 3rd floors of D & E; continue piping in domestic water booster pump; working on lines to chillers on roof			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	5	33		ISS - insulate duct & pipes on 1st floor			
Bernhard Mechanical Contractors, L.L.C.							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	2	20		Mike and Eddie - mike worked with Ray; Eddite did clean-up			
				·			

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	12/0	2/2015
Weather Delays To Date:			Weather Condition:	overcast with some drizzle	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount: some		Temp:	Low	High
Critical Path Work Effected?		N			•	49	63
Holi Services Inc	2	18		Mike and Eddie -dewater bldg			
Holi Services Inc	2	16		Mike and Eddie -dewater bldg			
Holi Services Inc	1	9		Mike worked with Ray; clean-up			
Holi Services Inc	1	8		Mike worked with Ray			
Morris Drywall Systems Inc	25	225		rocking iin D1, rock in stairs, shafts on 2nd floor			
Morris Drywall Systems Inc	25	225		rocking iin D1, rock in stairs, shafts on 2nd floor			
Morris Drywall Systems Inc	28	252		rocking iin D1, rock in stairs, shafts on 2nd floor			
Morris Drywall Systems Inc	29	264		rocking iin D1, rock on 2nd floor			
Morris Drywall Systems Inc	29	232		rocking iin D1, rock on 2nd floor			
Morris Drywall Systems Inc	29	232		rocking on D1, rock on 2nd floor			
New Orleans Glass Company, Inc.	3	24		install frame at east end of corridor in C			
New Orleans Glass Company, Inc.	3	24		caulk south & west walls; work on Iull			
New Orleans Glass Company, Inc.	4	32		install vinyl @ caulk at D & E			
New Orleans Glass Company, Inc.	3	24		install curtainwall system @ exit of main stairway			
New Orleans Glass Company, Inc.	3	24		install glass @ elev C220 & S209; install vinyl & caulk in courtyard			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	5	45		install storm line along Maid Marion; tied in water line			
Phoenix Constructors LLC	5	45		install storm line along Maid Marion; tied in water line; grade @ parking lot			
Phoenix Constructors LLC	5	45		install storm line along Maid Marion; tied in water line			
Phoenix Constructors LLC	5	48		prepped pour backs in street at utility cuts; prepped approach @ west end of north parking lot; haul off spoils on Maid Marion side			
Phoenix Constructors LLC	5	48		prepped pour backs in street at utility cuts; prepped approach @ west end of north parking lot; haul off spoils on Maid Marion side			
Phoenix Constructors LLC	5	20		prepped courtyard			
Cordeiro LLC							
Cordeiro LLC	5	45		form 4th section of paving on north side			
Cordeiro LLC	4	38		prep/pour curbs @ west end of north parking lot; pour sidewalk patch at courtyard; prep paving pour @ north parking lot 5th section			
Cordeiro LLC	4	42		finished prepping for 5th pour of north parking lot; prepped approach at west side of north parking lot			
Cordeiro LLC	8	72		finished prepping for 5th pour of north parking lot; prepped approach at west side of north parking lot			
Cordeiro LLC	4	32		wrecked forms and began prepping in courtyard			
Rufino's Painting & Construction Inc.	11	88		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino's Painting & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino's Painting & Construction Inc.	10	80		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino's Painting & Construction Inc.	11	88		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino's Painting & Construction Inc.	11	88		tape/float/prime in D1 & E1			
Rufino`s Painting & Construction Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							

River City Fire Protection

Project: Sherwood Forest Elemer Location: 4801 Maid Marion Drive	ntary Scho	ool		Job: Report #:	14-02-002 1
Fair Working Days To Date:				Date:	12/01/2015
Weather Delays To Date:			Weather Condition: cloudy/light rain	Day:	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount: some	Temp:	Low High
Critical Path Work Effected?		N			59 75
River City Fire Protection					
River City Fire Protection					
River City Fire Protection					
River City Fire Protection					
River City Fire Protection					
Roofing Solutions LLC	6	56	install thru wall flashing at low to high D		
Roofing Solutions LLC	6	56	install thru wall flashing at low to high D		
Roofing Solutions LLC	1	1	orientation		
Roofing Solutions LLC	4	32	solder thru wall flashing @ high to low roof of D; install scupp	ers	
Roofing Solutions LLC	12	96	install scuppers, torch in scuppers; working on edge of roof a	nd	
Roofing Solutions LLC	4	32	installing expansion jt between B&D install hat channels on area C by chiller roof		
Alack Refrigeration Company			install late channels of died c by chiller root		
Alack Refrigeration Company	2	4	replaced damage cooler panel		
Alack Refrigeration Company	3	6	adjusted cooler door		
Alack Refrigeration Company			•		
Alack Refrigeration Company					
Alack Refrigeration Company					
Allied Construction, LLC	8	64	lay brick @ eyebrow in courtyard		
Allied Construction, LLC	8	64	lay brick @ eyebrow in courtyard		
Allied Construction, LLC	8	76	dismantle and set up scaffolding & lay brick @ north eyebrov	r; lay	
			cmu @ D3; clean-up		
Allied Construction, LLC	8	76	finished laying brick @ north eyebrow; lay cmu @ D3; clean-u	p	
Allied Construction, LLC	8	64	finished laying brick @ north eyebrow;		
Allied Construction, LLC	6	48	lay brick at low roof of D; dismantle and then set up scaffold south side eyebrow	on	
CFI Insulation Inc					
CFI Insulation Inc					
CFI Insulation Inc					
CFI Insulation Inc					
CFI Insulation Inc					
CFI Insulation Inc					
Gulf South Engineering & Testing Inc					
Gulf South Engineering & Testing Inc					
Gulf South Engineering & Testing Inc					
Gulf South Engineering & Testing Inc					
Gulf South Engineering & Testing Inc	1	8	took cylinders and slumps on concrete; took densities on bac at water tie-in across Maid Marion	cfill	
Gulf South Engineering & Testing Inc					
Ellison Builders					
Ellison Builders					
Ellison Builders					
Ellison Builders					
Ellison Builders					

Ellison Builders

Project:	Sherwood Forest Element	ary Sch	ool		Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	g Days To Date:				Date:	11/3	30/2015
Weather Del	lays To Date:			Weather Condition: partly cloudy	Day:	N	Monday
Is Today Clai	imed as Weather Day?		N	Precipitation Amount: some	Temp:	Low	High
Critical Path	Work Effected?		N			63	70
Malone All Sta	r JV, LLC	22	209	overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 &			
				central plant; installed conduits and pulled feeders to			
				transformer; installed underground conduit from power pole to			
				transformer pad; pull branch wires in kitchen			
Malone All Sta	r JV, LLC	19	181	overhead @ E2, rough-in walls inE2 &E1 ,elec rooms E2, C2 &			
				central plant; installed conduits and pulled feeders to			
				transformer; installed underground conduit from power pole to			
	N/ 11 C	_	26	transformer pad; pull branch wires in kitchen			
Malone All Sta	r JV, LLC	5	26	installing rack in C2 and began installing CAT 6 cabling			
Malone All Sta	r JV, LLC	23	230	overhead @ E2, rough-in walls inE2 &E1 , pull branch wires in			
				cafeteria; work on site lighting			
Malone All Sta	r JV, LLC	3	24	pulling cat 5 cable in cafeteria and in areas A, B & C			
Malone All Sta	r JV, LLC	17	170	overhead @ E2, rough-in walls in E2 & E1, pull branch wires in			
				cafeteria; work on site lighting			
Malone All Sta	r JV, LLC	3	24	pulling cat 5 cable in cafeteria and in areas A, B & C			
Malone All Sta	r JV, LLC	19	152	run branch circuits; work on D2 & E2			
Malone All Sta	r JV, LLC	3	24	run data wiring in A, B & C			
Malone All Sta	r JV, LLC						
Malone All Sta	r JV, LLC						
Heritage Floor	ing Inc.	3	30	installed vapor barrier & mesh and began putting down grade			
				pads			
Heritage Floor	ing Inc.	3	30	install mud bed pads throughout kitchen area			
Heritage Floor	ing Inc.	3	24	install mud bed in kitchen office and dishwash room			
Heritage Floor	ing Inc.	3	24	install mud be bed in kitchen area			
		664	5644				

Project:	Sherwood Forest Elementary School	ol			Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/0	07/2015
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				51	66

Employee						Work Accomplished
George Caillouet						went to LSU in afternoon
Tanner Broughton						went to LSU mid morning
Ellen Heck						(6:35-5:35) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:35-5:45) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(6:35-5:30) oversee site operation
Marybeth Leonard						
Chad Goubert						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:35-5:10) oversee site operation; attended finishing meeting; went to
						Christmas party after work @ 5:40- 7:30.
Marybeth Leonard						
Chad Goubert						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:35-4:50) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(6:35-3:40) oversee site operation
	Sub	Sub		2nd Tier	2nd Tier	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished S Q Sch
	2	16				Firestop International - fire seal floor penetrations on 3rd floor
CORE Construction Services, LLC	1	10				Ray- finish installing wood blocking at roof of courtyard eyebrow;
CORE Construction Services, LLC	1	10				installed wood blocking @ window on 2nd floor next to stairs in D
CORE Construction Services, LLC	1	10				Ray-reinstalled expansion jt at doorways in lobby corridor  Ray-reinstalled expansion jt at doorways in lobby corridor &
CONE CONSTRUCTION Services, EEC		10				worked on blocking
CORE Construction Services, LLC	1	10				Ray- worked on wall blocking; installed brackets for exterior wall
CORE Construction Services, LLC						ladder from chiller roof to mid C roof
CORE Construction Services, LLC						
Bernhard Mechanical Contractors, L.L.C.	17	150				continue welding on chiller deck; continue working on inwall
	• •					rough-in on 2nd floor; tieing up loose ends in pump room.
Bernhard Mechanical Contractors, L.L.C.	4	30				Atlas - installing duct at stage and on 1st floor
Bernhard Mechanical Contractors, L.L.C.	9	72				ISS - insulate ducton 2nd floor; insulate chilled & hot water on 1st

Bernhard Mechanical Contractors, L.L.C.

Project: Sherwood Forest Element 4801 Maid Marion Drive	ida. y odno				Job: Report #:		-02-00
air Working Days To Date:					Date:	12/	08/201
Weather Delays To Date:			Weather Condition:	sunny	Day:		Tuesda
s Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	Hig
ritical Path Work Effected?		N	·			64	7
ernhard Mechanical Contractors, L.L.C.	17	150		continue welding on chiller deck; continue working on inwall rough-in on 2nd floor and loose ends on 1st & 2nd floors; tieing up loose ends in pump room; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; began working on E3.			
ernhard Mechanical Contractors, L.L.C.	2	15		Atlas - installing duct at stage and on 1st floor			
ernhard Mechanical Contractors, L.L.C.	12	96		ISS - insulate ducton 2nd floor; insulate chilled & hot water on 1st floor; insulate domestic hot & cold on 2nd floor			
ernhard Mechanical Contractors, L.L.C.	1	8		Synergy - wall rough-in on 3rd floor			
ernhard Mechanical Contractors, L.L.C.	17	150		continue welding on chiller deck; continue working on inwall rough-in on 2nd floor and loose ends on 1st & 2nd floors; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; began working on E3.			
ernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc. ductwork			
ernhard Mechanical Contractors, L.L.C.	12	96		ISS - insulate duct on 2nd floor; insulate chilled & hot water on 1st floor; insulate domestic hot & cold on 2nd floor			
ernhard Mechanical Contractors, L.L.C.							
ernhard Mechanical Contractors, L.L.C.	19	158		continue welding on chiller deck; continue working on inwall rough-in on 2nd floor and loose ends on 1st & 2nd floors; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; began working on E3.			
ernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc. ductwork			
ernhard Mechanical Contractors, L.L.C.	9	72		ISS - insulate duct on 2nd floor; insulate chilled & hot water on 1st floor; insulate domestic hot & cold on 2nd floor			
ernhard Mechanical Contractors, L.L.C.	3	24		Synergy - pulling wire on 1st floor A,B,C & D			
ernhard Mechanical Contractors, L.L.C.	17	136		continue welding on chiller deck; continue working on inwall rough-in on 2nd floor; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; working on E3.			
ernhard Mechanical Contractors, L.L.C.	3	23		Atlas - misc. ductwork			
ernhard Mechanical Contractors, L.L.C.	10	80		ISS - insulate duct to gym on 2nd floor; insulate chilled & hot water in mechanical room on 2nd floor; insulate domestic hot & cold on all floors			
ernhard Mechanical Contractors, L.L.C.	3	24		Synergy - pulling wire on 1st floor D & E; terminate @ VAV's			
ernhard Mechanical Contractors, L.L.C.	12	96		continue welding on chiller deck; continue working on inwall rough-in on 3rd floor; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; working on E3; set skillet trough drain			
ernhard Mechanical Contractors, L.L.C.				and the second s			
ernhard Mechanical Contractors, L.L.C.							
ernhard Mechanical Contractors, L.L.C.							
&T Tile & Terrazzo Co. Inc.	2	10		began prepping main corridor in C			
0&T Tile & Terrazzo Co. Inc.	2	10		finished prepping main corridor slab in C to begin installation of crack membrane tomorrow			
&T Tile & Terrazzo Co. Inc.	2	10		did layout and installed divider strips in main corridor of B $\&$ C			
&T Tile & Terrazzo Co. Inc.	3	27		installed 1st terrazzo color in main corridor			
&T Tile & Terrazzo Co. Inc.	3	27		installed 2nd & 3rd terrazzo color in main corridor			
&T Tile & Terrazzo Co. Inc.	2	9		finished installing terrazzo in main corridor			
one Inc							

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive Fair Working Days To Date: Weather Delays To Date: Is Today Claimed as Weather Day? Critical Path Work Effected?	ntary Scho	N N	Weather Condition: Precipitation Amount:	partly cloudy	Job: Report #: Date: Day: Temp:
Kone Inc					
Kone Inc					
Kone Inc					
Kone Inc					
Holi Services Inc	2	16		Mike worked with Ray; Eddie - clean-up; set fire pump; misc.	
Holi Services Inc	2	18		Mike worked with Ray; Eddie - clean-up; misc.	
Holi Services Inc	2	18		Mike worked with Ray; Eddie - clean-up; misc.	
Holi Services Inc Holi Services Inc	2	18		Mike worked with Ray; Eddie & 2 laborers- clean-up/organize south side of property, help remove bds from dirt pile by courtyard  Mike worked with George installing peal & stick at 2 window	
				openings @ 3rd floor on south elevation; Eddie & 2 laborers- clean-up/organize south side of property, help remove bds from dirt pile by courtyard	
Holi Services Inc	2	16		Mike & Eddie continued to clean-up and moved mats; fix fence	
Morris Drywall Systems Inc	29	264		rocking D1 & E1, rock on 2nd floor	
Morris Drywall Systems Inc	29	264		rocking D1 & E1, rock on 2nd floor; working on framing canopy ceiling at car drop off	
Morris Drywall Systems Inc	29	264		rock on 2nd floor; working on framing canopy ceiling at car drop off; build scaffolding in main stairs; clean-up	
Morris Drywall Systems Inc	29	264		rock on 2nd floor; framing wall in main stairs; clean-up	
Morris Drywall Systems Inc	27	216		rock on 2nd floor; rock on 1st floor; frame & install shaft liners on 3rd floor; clean-up	
Morris Drywall Systems Inc	24	192		rock on 2nd floor; rock on 1st floor; frame & install shaft liners on 3rd floor; clean-up	
New Orleans Glass Company, Inc.	4	32		caulk south elevation section E and in courtyard	
New Orleans Glass Company, Inc.	4	32		caulk south elevation section E and in courtyard	
New Orleans Glass Company, Inc.	5	40		install frame and set glass in south elevation SF20	
New Orleans Glass Company, Inc.	5	40		misc vinyl & caulking area E south side	
New Orleans Glass Company, Inc.	5	40		misc vinyl & caulking area E south side; set last 2 window frames on south elevation with glass.	
New Orleans Glass Company, Inc.				<u>-</u>	
Phoenix Constructors LLC	5	40		finished prepping courtyard; installed drain lines to 2 drains by car drop off	
Phoenix Constructors LLC	5	40		finished prepping courtyard; installed drain lines to 2 drains by car drop off	
Phoenix Constructors LLC	7	35		finished prepping courtyard; installed drain lines to 2 drains by car drop off	
Phoenix Constructors LLC	7	56		began cutting west driveway to grade; pick out broken mat bds out of pile of mud by courtyard (roughly3 hrs with 3 guys and a hoe)	
Phoenix Constructors LLC	7	56		cont. to cut west driveway to grade; pick out broken mat bds out of pile of mud by courtyard and hauled off the dirt	
Phoenix Constructors LLC	2	12		continue cutting west driveway to grade	
Cordeiro LLC	4	32		prepping courtyard for pour on Wed.	
Cordeiro LLC	4	32		prepping courtyard for pour on Wed.	
Cordeiro LLC	8	60		poured courtyard sidewalk	
Cordeiro LLC	4	32		wrecked forms @ courtyard sidewalk and popped lines; installed curb forms @ north parking lot	
Cordeiro LLC	4	32		worked on sign base and light stds	

pour curbs at north parking lot

14-02-002

12/09/2015 Wednesday ow High

73

Low 57

30

Cordeiro LLC

Project:	Sherwood Forest Elementa	ry Scho	ol			Job:	14-	02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	12/0	7/2015
Weather Dela	ys To Date:			Weather Condition:	sunny	Day:	N	1onday
Is Today Clain	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				51	66
Rufino`s Painting	g & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino`s Painting	g & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float furdowns in cafeteria			
Rufino`s Painting	g & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float/prime/paint furdowns			
Rufino`s Painting	g & Construction Inc.	9	72		in cafeteria; began taping & floating on 2nd floor tape & float in D1 & E1; prime; tape/float/prime/paint furdowns in cafeteria; taping & floating on 2nd floor			
Rufino`s Painting	g & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float/prime/paint furdowns in cafeteria; taping & floating on 2nd floor			
Rufino`s Painting	g & Construction Inc.							
Quality Iron Fab	ricators Inc.							
Quality Iron Fab	ricators Inc.							
Quality Iron Fab	ricators Inc.							
Quality Iron Fab	ricators Inc.							
Quality Iron Fab	ricators Inc.							
Quality Iron Fab	ricators Inc.							
River City Fire Pr	rotection							
River City Fire Pr	rotection	3	24		install drops and misc. piping on 1st & 2nd floors			
River City Fire Pr	rotection							
River City Fire Pr	rotection							
River City Fire Pr	rotection							
River City Fire Pr	rotection							
Roofing Solution	ns LLC	3	24		install hat channels on east side and north side of area C			
Roofing Solution	ns LLC	4	32		installed hat channels on north side of C and on west side of D			
Roofing Solution	ns LLC	5	32		installed hat channels on north & east side of C;			
Roofing Solution	ns LLC	2	16		finished scuppers on high roof of C			
Roofing Solution	ns LLC	6	48		installed hat channels; take field dimensions for panels; began			
Roofing Solution	ns LLC				installing flashing at north side of C			
Roofing Solution	ns LLC	6	48		installed hat channels; installing flashing at north side of C			
Roofing Solution	ns LLC	4	32		installed roof on courtyard eyebrow			
Roofing Solution	ns LLC	7	56		installed hat channels; installing flashing at north side of A $\&$ C			
Roofing Solution	ns LLC							
Alack Refrigerati	ion Company							
Alack Refrigerati	ion Company							
Alack Refrigerati	ion Company	2	2		deliver 2 pallets of material			
Alack Refrigerati	ion Company							
Alack Refrigerati	ion Company							
Alack Refrigerati	ion Company							
Allied Construct	ion, LLC	8	64		install brick @ low roof of D; build scaffold @ south eyebrow			
Allied Construct		9	72		install brick @ low roof of D; build scaffold @ south eyebrow; clean brick @ south wall & courtyard			
Allied Construct		10	89		install brick @ low roof of D; build scaffold @ south eyebrow; clean brick @ south wall & courtyard			
Allied Construct		10	80		install brick @ low roof of D; build scaffold @ south eyebrow;  pour cmu @ D1 & 2			
Allied Construct		8	64		install brick @ low roof of D; build scaffold @ south eyebrow; pour cmu @ D 2			
Allied Construct	ion, LLC	8	64		finish brick @ low roof of D; begin brick @ south eyebrow			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	ol			Job: Report #:	14-0	02-002 1
Fair Working Days To Date:					Date:	12/07	7/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:	М	onday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				51	66
CFI Insulation Inc							
CFI Insulation Inc	2	18		taped dense glass to bottom of brick angle support @ 3rd floor; waterproofed at 2nd floor window area that had been left out for access; removed excessive peal & stick at windows in cafeteria			
CFI Insulation Inc				access, removed excessive pear at stack at windows in careteria			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	21	168		overhead @ E2 & C2; pull branch circuits in walls on E3			
Malone All Star JV, LLC				DATA -			
Malone All Star JV, LLC	21	168		overhead @ E2; pull branch circuits in walls on E3; work on chillers & central plant branch circuits			
Malone All Star JV, LLC				DATA -			
Malone All Star JV, LLC	20	160		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3; work on chillers & central plant branch circuits			
Malone All Star JV, LLC	1	7		ADS - get aquainted with jobsite			
Malone All Star JV, LLC  Malone All Star JV, LLC	20	160 24		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3; work on chillers & central plant branch circuits; pull feeders ADS - began pulling fire alarm wiring			
Malone All Star JV, LLC	23	104					
Maiorie Air Star JV, LLC	23	104		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3; pulled wires to chillers; teminate @ transformer; overhead on E2; got permanent power inspection			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Heritage Flooring Inc.	4	40		install mud bed pads throughout kitchen area			
Heritage Flooring Inc.	4	38		finished installing mud bed pad throughout kitchen area except for inside cooler/freezer			
Heritage Flooring Inc.	4	38		install quarry tile in kitchen			
Heritage Flooring Inc.	7	66		install quarry tile in kitchen			
Heritage Flooring Inc.	6	42		install quarry tile in kitchen			
Heritage Flooring Inc.							
	746	6016					

 $\textbf{Material Delivered:} \ \mathsf{Dillon \ Bros-} \ \ \mathsf{cyds \ for \ curbs}$ 

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002				
Location:	4801 Maid Marion Drive	4801 Maid Marion Drive Report #:									
Fair Working	Days To Date:				Date:	12/	13/2015				
Weather Delays To Date:			Weather Condition:	mostly cloudy	Day:		Sunday				
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High				
Critical Path \	Work Effected?	N				56	79				

Employee						Work Accomplished		
George Caillouet						Work Accomplished		
Tanner Broughton								
Ellen Heck						(6:35-5:30) oversee site operation		
Marybeth Leonard						(0.33 3.30) Oversee site operation		
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(625 520)		
						(6:35-5:30) oversee site operation		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton						Tanner locked up today		
Ellen Heck						(6:35-4:00) oversee site operation		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-4:45) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-4:00) oversee site operation		
Marybeth Leonard								
Ellen Heck						(6:35-3:40) oversee site operation		
	Sub	Sub		2nd Tier	2nd Tier			
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
	2	16				Firestop International - fire seal floor penetrations on 2nd & 3rd floor		
	2	16				Firestop International - fire seal floor penetrations on 2nd & 3rd		
						floor		
	2	16				Firestop Insternational - seal wall penetrations in area C & A		
CORE Construction Services, LLC								
CORE Construction Services, LLC	1	10				Ray - install blocking in main stairs		
CORE Construction Services, LLC	1	10				Ray - install blocking in main stairs & 1st floor RR ceilings		
CORE Construction Services, LLC	1	10				Ray - install blocking		
CORE Construction Services, LLC	1	10				Ray - install blocking		
CORE Construction Services, LLC	1	10				Ray - install expansion jt @ 2nd floor & misc. blocking		

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Schoo	ol			Job: Report #:	14-	02-002 1
Fair Working Days To Date:					Date:	12/1	9/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:	Sa	aturday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				50	60
CORE Construction Services, LLC	1	5		Ray - install expansion jt @ 2nd floor & misc. blocking			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	18	156		continue working on inwall rough-in on 2nd floor; piping in hot water heater on 2nd floor mezz; continue running chill & heating hot water lines into mech room on 1st floor C bldg.; working on E3.			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - misc. ductwork			
Bernhard Mechanical Contractors, L.L.C.	11	92		ISS - insulate duct to gym on 2nd floor; insulate chilled & hot water in mechanical room on 2nd floor; insulate domestic hot & cold on all floors			
Bernhard Mechanical Contractors, L.L.C.	2	16		Synergy - pulling wire on 1st floor D & E			
Bernhard Mechanical Contractors, L.L.C.	19	164		continue working on inwall rough-in on 2nd floor; piping in hot water heater on 2nd floor mezz; continue running chill & heating			
				hot water lines into mech room on 1st floor C bldg.; working on E3.			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - misc. ductwork			
Bernhard Mechanical Contractors, L.L.C.	12	96		ISS - insulate chill water pump room; insulating supply & return  @ 2nd floor; Insullating at chiller pad			
Bernhard Mechanical Contractors, L.L.C.				5 · · · · · · · · · · · · · · · · · · ·			
Bernhard Mechanical Contractors, L.L.C.	18	164		Cont. running pipe for expandsion tanks & pot fillers on mezz; cont. working on VAV valve packs in E1; cont. running overhead piping on D@ & E3; cont. inwall cast iron on D3; cont. piping units on 1st floor C mezz.			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - cont. hooking up duct in mech room D1			
Bernhard Mechanical Contractors, L.L.C.	12	96		ISS - insulate chill water pump room; insulating supply & return  @ 2nd floor; Insullating domestic water on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	2	16		Synergy - pulling wire in A, B & C			
Bernhard Mechanical Contractors, L.L.C.	14	164		Cont. running pipe for expandsion tanks & pot fillers on mezz; cont. working on VAV valve packs in E1; cont. running overhead piping on D@ & E3; cont. inwall cast iron on D3; cont. piping units on 1st floor C mezz.			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - cont. hooking up duct in mech room D1			
Bernhard Mechanical Contractors, L.L.C.	11	88		ISS - insulate chill water in mech room; insulating supply & return @ 2nd floor; finishing duct wrap on 2nd and moving up to 3rd floor			
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	14	164		Cont running ping for expanding tople 9:+ Ell			
bernnard Mechanical Contractors, L.L.C.	14	104		Cont. running pipe for expandsion tanks & pot fillers on mezz; cont. working on VAV valve packs in E1; cont. running overhead piping on D@ & E3; cont. inwall cast iron on D3; cont. piping units on 1st floor C mezz.			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - cont. hooking up duct in mech room D1			
Bernhard Mechanical Contractors, L.L.C.	11	88		ISS - insulate chill water in mech room; insulating supply & return @ 2nd floor; finishing duct wrap on 2nd and moving up to 3rd floor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	5	80		cont. hook-up of water heater on D3; work on chilled water and domestic water in E3; work on loose ends and begin energizing system			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							

Project: Sherwood Forest Elemental Location: 4801 Maid Marion Drive	a.y Juli				Job: Report #:	14	-02-00
Fair Working Days To Date:					Date:	12/	19/201
Weather Delays To Date:			Weather Condition:	sunny	Day:	S	Saturda
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	•			50	60
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.	1	7		began prepping corridor in D			
D&T Tile & Terrazzo Co. Inc.	3	18		began prepping corridor in D			
D&T Tile & Terrazzo Co. Inc.	3	18		installed divider strips and began pouring terrazzo in D1 corridor & main stair			
D&T Tile & Terrazzo Co. Inc.	3	18		pouring terrazzo in D1 corridor & main stair			
D&T Tile & Terrazzo Co. Inc.	3	18		pouring terrazzo in D1 corridor & main stair			
D&T Tile & Terrazzo Co. Inc.	3	21		pouring terrazzo on D2			
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc							
Holi Services Inc	2	18		Mike & Eddie- dewater bldg.			
Holi Services Inc	2	18		Mike helped Ray & Eddie-clean-up			
Holi Services Inc	2	12		Mike helped Ray & Eddie-clean-up/helped Ray			
Holi Services Inc	2	12		Mike - dewatered & Eddie-clean-up/helped Ray/ fix fence			
Holi Services Inc	2	12		Mike - dewatered/ helped Ray & Eddie-clean-up			
Holi Services Inc	1	8		Eddie - clean-up			
Morris Drywall Systems Inc							
Morris Drywall Systems Inc	28	252		rock on 2nd floor; rock on 1st floor; clean-up			
Morris Drywall Systems Inc	25	225		rock on 2nd floor; rock on 1st floor; clean-up; double check smoke & fire walls			
Morris Drywall Systems Inc	23	117		rock on 2nd floor; rock on 1st floor; clean-up; double check			
Morris Drywall Systems Inc	24	116		smoke & fire walls rock on 2nd floor; rock on 1st floor; clean-up; double check			
Morris Drywall Systems Inc	24	116		smoke & fire walls rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	24	116		rock on 2nd floor; rock on 3rd floor; clean-up			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	3	24		caulk & clean frames			
New Orleans Glass Company, Inc.	4	32		caulk ext sills @ areas B & D; caulk interior sills area E3			
New Orleans Glass Company, Inc.	3	27		caulk ext sills @ areas B & D; caulk interior sills area E3			
New Orleans Glass Company, Inc.	3	21		caulk at cafeteria and misc.			
New Orleans Glass Company, Inc.	3	21		caulk at cafeteria and misc.			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC							
Phoenix Constructors LLC	5	45		cont. to cut west driveway to grade; haul off dirt			
Phoenix Constructors LLC	6	54		cont. to cut west driveway to grade; haul off dirt; proof roll west drive; cut temp power to areas A,B & C			
Phoenix Constructors LLC	6	54		install filter fabric and sand @ west drive			
Phoenix Constructors LLC	6	54		install filter fabric and sand @ west drive			

install filter fabric and sand @ west drive

Phoenix Constructors LLC

6 54

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	12/1	9/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:	S	aturday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				50	60
Phoenix Constructors LLC							
Cordeiro LLC							
Cordeiro LLC	3	9		dewater; wreck/clean curb forms @ north parking lot			
Cordeiro LLC	3	24		dewater; prepped sign base; formed sidewalk to pump room			
Cordeiro LLC	4	26		poured sign base; prepped sidewalk to pump room; began			
				forming west drive			
Cordeiro LLC	3	24		form light pole bases (2 ea) at west drive			
Cordeiro LLC	3	24		form/pour light pole bases (2 ea) at west drive and poured sidewalk to pump room			
Cordeiro LLC	3	24		prepped west drive			
Rufino's Painting & Construction Inc.							
Rufino`s Painting & Construction Inc.	10	80		tape & float in D1 & E1; prime; tape/float/prime/paint furdowns			
				in cafeteria; taping & floating on 2nd floor			
Rufino's Painting & Construction Inc.	12	96		tape & float in D1 & E1; prime; tape/float/prime/paint furdowns			
Rufino's Painting & Construction Inc.	10	80		in cafeteria; taping & floating on 2nd floor tape & float in D1 & E1; prime; tape/float/prime/paint furdowns			
5				in cafeteria; taping & floating on 2nd floor			
Rufino`s Painting & Construction Inc.	11	88		tape & float in D1 & E1; prime; taping & floating on 2nd floor			
Rufino`s Painting & Construction Inc.	10	80		tape & float in D1 & E1; prime; taping & floating on 2nd floor			
Rufino's Painting & Construction Inc.	11	88		spray painting door frames on 3rd floor			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection	3	24		began running pipe on 3rd floor			
River City Fire Protection	3	24		began running pipe on 3rd floor			
River City Fire Protection	3	24		began running pipe on 3rd floor			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	7	65		installed hat channels; installing flashing & began installing panels; receieved and unloaded wall panels			
Roofing Solutions LLC				·			
Roofing Solutions LLC	7	65		installed hat channels; installing flashing & installing panels			
Roofing Solutions LLC							
Roofing Solutions LLC	8	64		installing metal panels of north, south and east elevations of C			
Roofing Solutions LLC							
Roofing Solutions LLC	8	64		installing metal panels of north, south and east elevations of C			
Roofing Solutions LLC							
Roofing Solutions LLC	8	64		installing metal panels of north, south and east elevations of C			
Roofing Solutions LLC							
Reafing Colutions LLC		F.4		Controlling and the state of control and the state of the			

installing metal panels of north, south and east elevations of C

9 54

Roofing Solutions LLC

Project: Sherwood Forest Elements Location: 4801 Maid Marion Drive		ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	12/1	19/2015
Weather Delays To Date:			Weather Condition:	sunny	Day:		aturday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:	,	Temp:	Low	High
Critical Path Work Effected?		N			remp.	50	60
Roofing Solutions LLC							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC	6	48		install brick @ south eyebrow; clean low roof of D; set up			
				remaining scaffold @ eyebrow			
Allied Construction, LLC	10	80		install brick @ south eyebrow; stack and hual equipment off site;			
Allied Construction, LLC	14	112		pour cmu D2 & 3; washed courtyard walls stack and hual equipment off site; cmu D2 & 3; pour @ D2;			
Alled Collstraction, EEC		112		catch up on loose ends; washed courtyard walls			
Allied Construction, LLC	6	48		cmu @ D3; pour @ D2			
Allied Construction, LLC	7	56		install brick @ south eyebrow			
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	2		came for proof roll of west driveway			
Gulf South Engineering & Testing Inc	1	2		came for proof roll of west driveway			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	20	160		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3;			
				pull branch wires in gym			
Malone All Star JV, LLC							
Malone All Star JV, LLC	19	152		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3;			
Malone All Star IV 11 C				pull branch wires in gym			

Malone All Star JV, LLC

Project: Sherwood	Forest Elementary Scho	ool			Job:	14-	-02-002
Location: 4801 Maid	Marion Drive				Report #:		1
Fair Working Days To Date	e:				Date:	12/1	16/2015
Weather Delays To Date:			Weather Condition:	cloudy with rain	Day:	Wed	dnesday
Is Today Claimed as Weatl	her Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected	d?	N				59	74
Malone All Star JV, LLC	144	152		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3; pull branch wires in gym; pull wire for temp power			
Malone All Star JV, LLC							
Malone All Star JV, LLC	20	160		overhead @ E2; work in electrical rooms on C2 & E2; walls on E3; pull branch wires in gym; pull wire for temp power			
Malone All Star JV, LLC							
Malone All Star JV, LLC	20	160		overhead @ E2; walls on E3; pull branch wires in gym; receive lights; work on grounding			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.	6	40		cleaned grout lines and began installing epoxy grout			
Heritage Flooring Inc.	6	42		installing epoxy grout in kitchen			
Heritage Flooring Inc.	6	42		installing epoxy grout in kitchen			
Heritage Flooring Inc.	2	16		installing epoxy grout in kitchen			
Heritage Flooring Inc.	5	40		installing epoxy grout in kitchen			
	828	5511					

**Remarks:** Rush did not show up today as expected.

Brian with Phoenix called in to say they would not be in because his guys were a no show.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/	/21/2015
Weather Dela	ays To Date:		Weather Condition:	cloudy with rain	Day:		Monday
Is Today Clair	med as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				65	72

Employee						Work Accomplished		
George Caillouet								
Ellen Heck						(6:35-5:15) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45-5:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45-5:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:55-10:45) oversee site operation		
				2nd	2nd	(		
	Sub	Sub		Tier	Tier		_	O C=b
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	<u>s</u>	Q Sch
	2	16				Firestop International- caulk wall & floor penetrations, install angles to ducts that require them		
	2	16				Firestop International- caulk wall & floor penetrations, install		
						angles to ducts that require them		
	3	5				Firestop International - seal penetrations in walls		
CORE Construction Services, LLC	1	10				Ray - misc. blocking		
CORE Construction Services, LLC	1	10				Ray - misc. blocking		
CORE Construction Services, LLC	1	10				Ray - misc. blocking		
CORE Construction Services, LLC	1	4				Ray - misc. blocking		
Bernhard Mechanical Contractors, L.L.C.	14	124				cont overhead piping on E3; cored holes on D3 science lab; started retesting domestic water system		
Bernhard Mechanical Contractors, L.L.C.	3	23				Atlas - cont. hooking up duct in mech room D1		
Bernhard Mechanical Contractors, L.L.C.	11	110				ISS - insulate chill water in mech room; insulating supply & return		
						@ 2nd floor; insulating hot water 1st floor		
Bernhard Mechanical Contractors, L.L.C.	3	24				Synergy - teminate VAV boxes; pull wire; pipe in mechanical rooms		
Bernhard Mechanical Contractors, L.L.C.	16	134				cont overhead piping on E3; cored holes on D3 science lab;		
						started retesting domestic water system		
Bernhard Mechanical Contractors, L.L.C.	3	23				Atlas - cont. hooking up duct in mech room D1		
Bernhard Mechanical Contractors, L.L.C.	10	76				ISS - insulate chill water in mech room; insulating supply & return  @ 2nd floor; insulating hot water 1st floor		
Bernhard Mechanical Contractors, L.L.C.	3	24				Synergy - pulling wire on 1st floor; terminate box on 1st floor;		
						piping mechanical rooms		
Bernhard Mechanical Contractors, L.L.C.	12	106				cont overhead piping on E3; cored holes on D3 science lab;		
Bernhard Mechanical Contractors, L.L.C.	3	23				started retesting domestic water system  Atlas - installing louver at gym		
Bernhard Mechanical Contractors, L.L.C.	8	64				ISS - insulate chill water in mech room; insulating supply & return		
						@ 2nd floor; insulating hot water 1st floor		
Bernhard Mechanical Contractors, L.L.C.	3	24				Synergy - running wire and terminating @ VAV boxes		
Bernhard Mechanical Contractors, L.L.C.	11	44				cont overhead piping on E3; cored holes on D3 science lab;		
Bernhard Mechanical Contractors, L.L.C.						started retesting domestic water system		

Project: Sherwood Forest Elemer	ntary Scho	ool			Job:	14-	-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	12/2	24/2015
Weather Delays To Date:			Weather Condition:	cloudy with rain	Day:		nursday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount: 1"		Temp:	Low	High
Critical Path Work Effected?		N			remp.	69	75
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.	3	12		pouring torrazza in D1 corridor 81 main stair			
D&T Tile & Terrazzo Co. Inc.	3	12		pouring terrazzo in D1 corridor & main stair			
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc	2	10					
Holi Services Inc	2	18		Mike - helped Ray & Eddie-clean-up			
Holi Services Inc	2	18		Mike & Eddie - dewater			
Holi Services Inc	2	16		Mike & Eddie - dewater			
Holi Services Inc	2.	446					
Morris Drywall Systems Inc	24	116		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	23	117		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	23	116		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.	3	24		installing pressure bar at front entrance			
New Orleans Glass Company, Inc.	3	12		installing pressure bar at front entrance			
New Orleans Glass Company, Inc.	3	15		installing pressure bar at front entrance and interior caulk			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	6	56		install filter fabric and sand @ west drive			
Phoenix Constructors LLC				rain out			
Phoenix Constructors LLC				rain out			
Phoenix Constructors LLC							
Cordeiro LLC	3	24		form at west drive			
Cordeiro LLC	3	2		rain out			
Cordeiro LLC	3	2		rain out			
Cordeiro LLC							
Rufino's Painting & Construction Inc.	10	80		tape & float in D1 & E1; prime; paint door frames on 1st floor;			
Rufino`s Painting & Construction Inc.	9	72		taping/floating & priming on 2nd floor tape & float in D1 & E1; prime; paint door frames on 1st floor;			
name of among a construction me.	,			taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	8	64		tape & float in D1 & E1; prime; paint door frames on 3rd floor;			
Duffice's Deletion 9: Country ation Inc.				taping/floating & priming on 2nd floor			
Rufino`s Painting & Construction Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							

installing metal panels of north, south and east elevations of  $\ensuremath{\mathsf{C}}$ 

Roofing Solutions LLC

8

64

Project: Location:	Sherwood Forest Elemen 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14-	02-002 1
Fair Working	Days To Date:					Date:	12/2	1/2015
Weather Dela	ys To Date:			Weather Condition:	cloudy with rain	Day:	N	/londay
Is Today Clain	ned as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				65	72
Roofing Solution	ns LLC							
Roofing Solution	ns LLC	8	64		installing metal panels of north, south and east elevations of C			
Roofing Solution	ns LLC							
Roofing Solution	ns LLC	4	32		installing metal flashing and hat channels			
Roofing Solution	ns LLC							
Roofing Solution	ns LLC	2	8		installing hat channels on west side of bldg.			
Roofing Solution	ns LLC							
Alack Refrigerati	on Company							
Alack Refrigerati	on Company							
Alack Refrigerati	on Company							
Alack Refrigerati	on Company							
Allied Constructi	ion, LLC	10	60		finish bricking @ south eyebrow; began bricking below window on 3rd floor and got rained out			
Allied Constructi	ion, LLC	7	31		try to clean remaining exterior wall sections; lay window sills; install loose lintels at west exterior door alcoves of D			
Allied Constructi	ion, LLC	2	16		pour grout in D3 restroooms			
Allied Constructi	ion, LLC	3	3		picking up materials			
CFI Insulation In	c							
CFI Insulation In	c							
CFI Insulation In	С							
CFI Insulation In	c							
Gulf South Engir	neering & Testing Inc							
Gulf South Engir	neering & Testing Inc							
Gulf South Engir	neering & Testing Inc							
_	neering & Testing Inc							
Ellison Builders								
Ellison Builders								
Ellison Builders								
Ellison Builders								
Malone All Star	JV, LLC	19	152		overhead @ E2; walls on E3; pull branch wires in gym; hook up central plant mechanical equipment; work in electrical rooms on C2 & E2			
Malone All Star	IV, LLC	4	32		Data- pulling communication cables and installing j-hooks			
Malone All Star	IV, LLC	19	152		overhead @ E2; walls on E3; pull branch wires in gym; hook up central plant mechanical equipment; work in electrical rooms on C2 & E2; pull feeders to panels in IT rooms @ D1,2 & 3			
Malone All Star	IV, LLC	5	40		Data- pulling communication cables and installing j-hooks			
Malone All Star	JV, LLC	19	131		overhead @ E2; walls on E3; pull branch wires in gym; hook up central plant mechanical equipment; work in electrical rooms on			
Malone All Star .	IV II C	3	24		C2 & E2; pull feeders to panels in IT rooms @ D1,2 & 3  Data- pulling communication cables and installing j-hooks			
Malone All Star.		J	47		Data pulling communication cables and installing j-nooks			
Malone All Star.								
Heritage Floorin		2	18		hegan mudding in cooler/freezer			
Heritage Floorin		5	30		began mudding in cooler/freezer mudding in cooler/freezer; unloaded ceramic tile			
Heritage Floorin		5	30		mudding in cooler/freezer, unloaded ceramic tile mudding in cooler/freezer; hualed off excess mud			
Heritage Floorin	_	3	50		addg iii coolei, iicezei, iidaica oii excess iiida			
age Hooffff	g <del></del>	366	2518					

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12/	24/2015
Weather Dela	ays To Date:		Weather Condition:	cloudy with rain	Day:	Т	hursday
Is Today Clair	ned as Weather Day?	Υ	Precipitation Amount: 1"		Temp:	Low	High
Critical Path \	Work Effected?	N				69	75

**Remarks:** Someone from Phoenix stopped by to pick up barricades.

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	12,	/28/2015
Weather Dela	ays To Date:		Weather Condition:	cloudy with rain	Day:		Monday
Is Today Clair	ned as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				51	67

Employee						Work Accomplished	
George Caillouet							
Tanner Broughton							
Ellen Heck						(6:40-6:20) oversee site operation	
Marybeth Leonard							
George Caillouet							
Tanner Broughton							
Ellen Heck						(6:40-6:00) oversee site operation	
Marybeth Leonard							
George Caillouet							
Ellen Heck						(6:50-5:30) oversee site operation	
Marybeth Leonard						(4.5.5.5) 5.5.5.5.5.6.9	
.,						Kelly (intern)- worked on inventory of hardware	
George Caillouet						telly (intern) worked on inventory or initiativity	
Ellen Heck						(6:32-12:40) oversee site operation	
Marybeth Leonard						(0.52 12.46) oversee site operation	
mary seem zeemara				2nd	2nd		
	Sub	Sub		Tier	Tier		
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished S Q	Sch
	2	16				Firestop International- smoke caulk on 1st floor D & E	
	3	12				Firestop International - caulking at smoke walls on 1st & 2nd floors	
	2	2				Protech - came and took field measurements	
CORE Construction Services, LLC	1	11				Ray - misc. blocking	
CORE Construction Services, LLC	1	13				Ray - unload and take inventory of hardware	
CORE Construction Services, LLC	1	8				Ray - install misc blocking	
CORE Construction Services, LLC	1	4				Ray - install misc blocking; unload doors	
Bernhard Mechanical Contractors, L.L.C.	15	129				cont overhead piping on E3; cored holes on D3 science lab; started retesting domestic water system	
Bernhard Mechanical Contractors, L.L.C.	3	23				Atlas - installing louver at gym	
Bernhard Mechanical Contractors, L.L.C.	11	88				ISS - insulate chill water in mech room; insulating supply & return  @ 2nd floor; insulating hot water 1st floor; insulating supply duct  on 3rd floor	
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	14	124				cont overhead piping on E3; cored holes on D3 science lab; started retesting domestic water system	
Bernhard Mechanical Contractors, L.L.C.	3	23				Atlas - installing louver at gym	
Bernhard Mechanical Contractors, L.L.C.	11	88				ISS - insulate chill water in mech room; insulating supply & return  @ 2nd floor; insulating hot water 1st floor; insulating supply duct  on 3rd floor	
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	14	124				cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3	
Bernhard Mechanical Contractors, L.L.C.	3	23				Atlas - installing louvers	

Project: Sherwood Forest Elemer Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	02-002
Fair Working Days To Date:					Date:	12/3	0/2015
Weather Delays To Date:			Weather Condition:	variable cloudiness and rain	Day:	Wed	nesday
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	58	62
Bernhard Mechanical Contractors, L.L.C.	10	80		ISS - finishing work in kitchen area; hot/ hot water 1st floor corridors; insulate domestic and chill water lines in pump room; insulate duct on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	10	40		clean-up			
Bernhard Mechanical Contractors, L.L.C.	3	16		Atlas - installing louvers in courtyard			
Bernhard Mechanical Contractors, L.L.C.	10	40		ISS - finishing work in kitchen area; hot/ hot water 1st floor corridors; insulate domestic and chill water lines in pump room; insulate duct on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	2	16		Mike & laborer - dewater			
Holi Services Inc	2	56		Mike- help take inventory of hardware; Eddie &4 laborers - clean-up and unload 6 pallets of doors			
Holi Services Inc	2	20		Mike-dewater; Eddie - dewater			
Holi Services Inc	2	8		Mike-dewater; unload doors; clean-up; Eddie - dewater; unload doors; clean-up			
Morris Drywall Systems Inc	25	225		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	27	243		rock on 2nd floor; rock on 3rd floor; clean-up; began rocking locker room ceilings in C1			
Morris Drywall Systems Inc	27	135		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.				ania ana			
Phoenix Constructors LLC	-	40		rain out			
Phoenix Constructors LLC  Phoenix Constructors LLC	5 3	40 6		found catch basins on south side of bldg; began filter fabric repairs @ north parking lot edges			
Phoenix Constructors LLC	J	U		pushed mud around			
Cordeiro LLC				rain out			
Cordeiro LLC				rain out			
Cordeiro LLC							
Cordeiro LLC							
Rufino's Painting & Construction Inc.	12	96		tape & float in D1 & E1; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	11	88		tape & float in D1 & E1; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	14	112		tape & float in D1 & E1; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.							

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool			Job: Report #:	14-02-00
Fair Working Days To Date:					Date:	12/28/201
Weather Delays To Date:			Weather Condition:	cloudy with rain	Day:	Monda
Is Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low Hig
Critical Path Work Effected?		N			-	51 6
Quality Iron Fabricators Inc.						
Quality Iron Fabricators Inc.						
Quality Iron Fabricators Inc.						
Quality Iron Fabricators Inc.						
River City Fire Protection						
River City Fire Protection						
River City Fire Protection						
River City Fire Protection						
Roofing Solutions LLC	5	40		installing metal flashing and hat channels		
Roofing Solutions LLC						
Roofing Solutions LLC	8	80		installing metal flashing and hat channels		
Roofing Solutions LLC						
Roofing Solutions LLC	6	60		installing metal flashing and hat channels		
Roofing Solutions LLC						
Roofing Solutions LLC	6	24		installing metal flashing and hat channels		
Roofing Solutions LLC				3		
Alack Refrigeration Company						
Alack Refrigeration Company						
Alack Refrigeration Company						
Alack Refrigeration Company						
Allied Construction, LLC	2	16		installing cmu chases on D3 restroom; dismantle scaffolding at		
•				south eye brow		
Allied Construction, LLC	5	40		installing cmu chases on D3 restroom; prep equip for pick-up; finished brick on south elevation		
Allied Construction, LLC	5	40		installing cmu chases on D2 restroo		
Allied Construction, LLC	5	20		installing cmu chases on D3 restroom; set up access to D2 to		
				complete south exterior wall		
CFI Insulation Inc						
CFI Insulation Inc						
CFI Insulation Inc						
CFI Insulation Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Ellison Builders	2	2		check out job		
Ellison Builders	2	2		supposedly do hrwr inventory		
Ellison Builders	5	45		Installed hardware on some exterior doors and hung HM doors in		
Ellison Builders	5	20		kitchen area Installed hardware on some exterior doors and hung HM doors in		
Malone All Star JV, LLC	14	131		kitchen area walls on E3; install lights in gym; hook up central plant mechanical equipment; work in electrical rooms on C2 & E2		
Malone All Star JV, LLC	5	39		Data- pulling communication cables and installing j-hooks		
Malone All Star JV, LLC	14	131		walls on E3; install lights in gym; hook up central plant		
Malone All Star JV, LLC	5	50		mechanical equipment; work in electrical rooms on C2 & E2  Data- pulling communication cables and installing j-hooks on 1st  floor		

floor

Project:	Sherwood Forest Element	tary Scho	ool			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:				Date:	12/3	30/2015	
Weather Dela	ays To Date:			Weather Condition:	variable cloudiness and rain	Day:	Wed	Inesday
Is Today Clair	med as Weather Day?		Υ	Precipitation Amount:	ount:			High
Critical Path \	Work Effected?		N				58	62
Malone All Star	JV, LLC	15	143		walls on E3; wire lights in gym; hook up central plant mechanical equipment; install branch lines in pump room; install sleeves for data on 2nd floor through furdowns			
Malone All Star	JV, LLC	5	50		Data- pulling communication cables and installing j-hooks on 1st floor			
Malone All Star	JV, LLC							
Malone All Star	JV, LLC	4	16		Data - pulling cables on 2nd floor			
Heritage Floorir	ng Inc.							
Heritage Floorir	ng Inc.							
Heritage Floorir	ng Inc.							
Heritage Floorir	ng Inc.							
		368	2854					

Material Delivered: Crescent Door & Hardware dropped off 5 pallets of wood doors

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive		Report #:		1		
Fair Working	Days To Date:				Date:	01/	/04/2016
Weather Delays To Date:			Weather Condition:	mainly sunny	Day:		Monday
Is Today Clai	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	Ν				39	57

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton						went to Habbins late morning		
Ellen Heck						(6:35-5:50) oversee site operation		
Marybeth Leonard								
						Kelly (intern) - work with Marybeth		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35-6:00) oversee site operation		
Marybeth Leonard								
						Kelly (intern) - work with Marybeth		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-5:30) oversee site operation		
Marybeth Leonard								
						Kelly (intern) - work with Marybeth; last day		
Alisha White						meeting with George with GWS & Tanner @ 1:30pm		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-4:50) oversee site operation		
Marybeth Leonard								
Chad Goubert						stopped by and did a safety walk this morning		
Alisha White								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-4:00) oversee site operation		
Marybeth Leonard								
Ellen Heck						(5:30 - 9:00) came in for concrete pour		
				2nd	2nd			
Subcontractor	Sub	Sub	2nd Tier	Tier	Tier	Work Assemblished	s	Q Sch
Subcontractor	Wrkrs	Hrs	2nd Her	Wrkrs	Hrs	Work Accomplished		Q Sui
	1	8				Firestop International - floor penetrations on 3rd floor @ science rooms; 1st floor area D & E wall penetrations (smoke seal)		
	2	6				Greenfield Stage Equipment - checking out stage for installing		
						curtain supports		
	2	16				Firestop International - seal penetration on smoke walls in		
						corridors of D1 & E1		

CORE Construction Services, LLC CORE Construction Services, LLC

Project: Sherwood Forest Element 4801 Maid Marion Drive	-			Job: Report #:	14-	·02-002
Fair Working Days To Date:				Date:	01/0	06/2016
Weather Delays To Date:		Weather Condition:	partly cloudy	Day:	Wed	nesday
Is Today Claimed as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?	N				54	60
CORE Construction Services, LLC						
CORE Construction Services, LLC	1 8		Ray - blocking in stage furdown and misc. blocking; installed temp doors on tel/com rooms			
CORE Construction Services, LLC	1 8		Ray - blocking at stage furdown and misc. blocking			
Bernhard Mechanical Contractors, L.L.C.	15 120		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3			
Bernhard Mechanical Contractors, L.L.C.	3 23		Atlas - installing louvers			
Bernhard Mechanical Contractors, L.L.C.	8 64		ISS - finishing work in kitchen area; hot/ hot water 1st floor corridors; insulate domestic and chill water lines in pump room; insulate duct on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.	2 16		Synergy - pull wire on 2nd floor of D & E			
Bernhard Mechanical Contractors, L.L.C.	21 172		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D			
Bernhard Mechanical Contractors, L.L.C.	3 23		Atlas - misc. ductwork			
Bernhard Mechanical Contractors, L.L.C.	10 80		ISS - insulating chill water in A, air handler insulating duct in maintenance room in A; insulating chilled water in pump room; finishing supply duct in E3 wing			
Bernhard Mechanical Contractors, L.L.C.	1 8		Synergy - piping AHU's 4,5 & 7			
Bernhard Mechanical Contractors, L.L.C.	21 172		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D			
Bernhard Mechanical Contractors, L.L.C.	3 23		Atlas - misc. ductwork			
Bernhard Mechanical Contractors, L.L.C.	8 64		ISS - insulating chill water in A, air handler insulating domestic water in maintenance room in A; repairing supply & return ducts on E2			
Bernhard Mechanical Contractors, L.L.C.	1 8		Synergy - piping mechanical rooms			
Bernhard Mechanical Contractors, L.L.C.	22 172		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	11 88		ISS -insulating duct in mech room of area A; insulating H/H/W and domestic water in maint room in A; insulating chilled water lines and air handler in A			
Bernhard Mechanical Contractors, L.L.C.	1 8		Synergy - piping mechanical rooms			
Bernhard Mechanical Contractors, L.L.C.	22 172 x		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D			
Bernhard Mechanical Contractors, L.L.C.	3 23		Atlas - install exhaust duct in restrooms of D1 & D2			
Bernhard Mechanical Contractors, L.L.C.	11 88		ISS -insulating duct in mech room of area A2; insulating H/H/W and domestic water in maint room in A; insulating chilled water lines and air handler in A and chiller pad			
Bernhard Mechanical Contractors, L.L.C.	1 8		Synergy - piping mechanical rooms			
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
Firestop International LLC	1 8		Firestop International- all smoke penetrat5ion on 1st floor on right side of kitchen			
Firestop International LLC						
Kone Inc						

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ol			Job: Report #:	14-	-02-002 1
Location:	•				•		
Fair Working Days To Date:					Date:	01/0	)5/2016
Weather Delays To Date:			Weather Condition:	mainly sunny	Day:	T	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				47	55
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	2	20		Mike-dewater; Eddie - dewater; relocate fence; unload materials			
Holi Services Inc	2	20		Mike - clean-up; Eddie -clean-up			
Holi Services Inc	2	20		Mike & Eddie -clean-up; waterproofing; unload materials			
Holi Services Inc	2	18		Mike & Eddie -clean-up; helped Ray			
Holi Services Inc	2	16		Mike & Eddie -clean-up; dewater & helped Ray			
Morris Drywall Systems Inc	29	232		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	29	232		rock on 2nd floor; rock on 3rd floor; clean-up			
Morris Drywall Systems Inc	27	243		rock on 2nd floor; rock on 3rd floor; clean-up;			
Morris Drywall Systems Inc	27	243		rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid			
				in area C; finish framing restroom ceiling on D3			
Morris Drywall Systems Inc	24	192		rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in area D2 at offices			
New Orleans Glass Company, Inc.				mated 52 of offices			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	3	24		unload & install glass at elev SF-4			
Phoenix Constructors LLC	5	40		dewatered; graded @ west paving; backdragged site to dry			
Phoenix Constructors LLC	8	64		dewatered; graded @ west paving; backdragged site to dry			
Phoenix Constructors LLC	7	67		dug out under canopy; got proof roll under canopy and at north			
Phoenix Constructors LLC	5	40		exit of west drive; installed filter fabric and sand at same locations graded at car drop off			
Phoenix Constructors LLC	5	40		graded at north entry of west drive			
Cordeiro LLC	3	24		Prep/form @ west paving; formed monument base			
Cordeiro LLC	3	24		Prep/form @ west paving			
Cordeiro LLC	3	29		Prep/form @ west paving			
Cordeiro LLC	3	24		Prep/form @ west paving			
Cordeiro LLC	5	40		Prep/form @ west paving			
Rufino`s Painting & Construction Inc.	16	128		tape & float in D1 & E1; prime; taping/floating & priming on 2nd			
				floor; tape/float ceilings in A, B & C			
Rufino`s Painting & Construction Inc.	16	128		tape & float in D1 & E1; prime; taping/floating & priming on 2nd			
Rufino`s Painting & Construction Inc.	14	112		floor; tape/float ceilings in A, B & C tape & float in D1 & E1; prime; taping/floating & priming on 2nd			
<b>.</b>				floor; tape/float ceilings in A, B & C			
Rufino`s Painting & Construction Inc.	14	112		tape & float in D3 & E3; prime; taping/floating & priming on 2nd			
Rufino's Painting & Construction Inc.	15	120		floor tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Enhvisators Inc							

Quality Iron Fabricators Inc.

River City Fire Protection

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ol			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	01/0	5/2016
Weather Delays To Date:			Weather Condition:	mainly sunny	Day:	7	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				47	55
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection	3	21		came to tie-in at the pump room			
Roofing Solutions LLC	4	32		installing metal flashing			
Roofing Solutions LLC							
Roofing Solutions LLC	7	63		installing metal flashing			
Roofing Solutions LLC							
Roofing Solutions LLC	5	40		installing metal flashing			
Roofing Solutions LLC							
Roofing Solutions LLC	3	24		installing metal flashing			
Roofing Solutions LLC							
Roofing Solutions LLC	3	24		installing metal flashing			
Roofing Solutions LLC				5 5			
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company	4	16		set UDS in kitchen			
Alack Refrigeration Company	-	10		Set ODS III ARCHEII			
Alack Refrigeration Company							
Allied Construction, LLC	7	56		complete outgries couth elevation and at west anter deers of D			
Allied Constituction, LEC	,	30		complete exterior south elevation and at west entry doors of D; install brick @ sills			
Allied Construction, LLC	5	40		continue wrap up for completion; stock/pack equipment for			
				removal from site			
Allied Construction, LLC	5	40		continue wrap up for completion; stock/pack equipment for			
Allied Construction, LLC	6	40		removal from site continue wrap up for completion			
Allied Construction, LLC	2	16		install brick sills on south elevation			
CFI Insulation Inc	_	10		ilistali Diick Silis Oli Soutii elevation			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	1		came and took densities at west drive			
Ellison Builders	5	37		Installed hardware on some exterior doors and hung HM doors in			
Ellison Builders	5	37		kitchen area Installed hardware on some exterior doors and hung HM doors in kitchen area			
Ellison Builders	5	40		Installed hardware on some exterior doors and hung HM doors in kitchen area			
Ellison Builders	5	40		Installed hardware on hollow metal doors			
Ellison Builders	4	32		Installed hardware on hollow metal doors			
Malone All Star JV, LLC	19	152		walls on E3; wire lights in gym; work on overhead on E3; run			
				branch wires in E1			
Malono All Star IV LLC	4	22		ADC pulling fire slarm cables and installing i heals on 1st floor			

ADS- pulling fire alarm cables and installing j-hooks on 1st floor

Malone All Star JV, LLC

4 32

Project: She	erwood Forest Elementa	ary Scho	ol			Job:	14	-02-002
Location: 480	01 Maid Marion Drive					Report #:		1
Fair Working Days	s To Date:					Date:	01/0	05/2016
Weather Delays To	o Date:			Weather Condition:	mainly sunny	Day:	-	Tuesday
Is Today Claimed			N	Precipitation Amount:		Temp:	Low	High
Critical Path Work	Effected?		N	•		•	47	55
Malone All Star JV, LL	С	20	190		wire lights in gym; work on overhead on E2; run branch wires in E1; work in gang bath ceilings in E1 & E2; run branch wiring in kitchen & cafeteria			
Malone All Star JV, LL	.C	3	15		ADS- pulling fire alarm cables and installing j-hooks on 1st floor			
Malone All Star JV, LL	C	21	200		work on overhead on E2; run branch wires in kitchen; E1 equipment connections; E2 elect room; C2 elect room; roof at chiller			
Malone All Star JV, LL	С	3	24		ADS- pulling fire alarm, cameras, door sensors and horn cables in A, B & C.			
Malone All Star JV, LL	C	23	184		work on overhead on E2; run branch wires in kitchen, E1 & E2; E1 equipment connections; E3; E2 elect room;gang restrooms in D1, D2 & D3.			
Malone All Star JV, LL	.C	3	24		ADS- pulling fire alarm, cameras, door sensors and horn cables in A, B & C.			
Malone All Star JV, LL	.C	2	16		Data - pulling cable on 2nd floor			
Malone All Star JV, LL	C	23	184		work on overhead on E2, E3 & C1; run branch wires in kitchen, E1 & E2; E1 equipment connections; E3; E2 elect room; work on transformer hook-up			
Malone All Star JV, LL	C	3	24		ADS- pulling fire alarm, cameras, door sensors and horn cables in A, B $\&$ C.			
Malone All Star JV, LL	.C	1	8		Data - cable termination in gym and 2nd floor			
Heritage Flooring Inc		2	19		Misc epoxy grouting in kitchen/cooler/freezer and dry storage			
Heritage Flooring Inc		2	10		Misc epoxy grouting in kitchen/cooler/freezer and dry storage			
Heritage Flooring Inc								
Heritage Flooring Inc								
Heritage Flooring Inc								
		654	5316					

Remarks: Entergy came out about 8:15 to come and turn the power back on to the bldg.

**Inspections:** Gulf South came and took densities at north entrance

**Visitors:** Mickey Ludlum came and walked the job with Tanner & myself to discuss schedule

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	01/	/11/2016
Weather Dela	ays To Date:		Weather Condition:	sunshine; extremely cold (not a	Day:		Monday
Is Today Clair	med as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				34	48

Employee	Work Accomplished	
George Caillouet		
Tanner Broughton		
Ellen Heck	(6:00-5:40) oversee site operation	
Marybeth Leonard		
George Caillouet		
Tanner Broughton		
Ellen Heck	(6:05-5:40) oversee site operation	
Marybeth Leonard		
Tanner Broughton	went to meeting @ main office this afternoon	
Ellen Heck	(6:35-7:35) oversee site operation	
Marybeth Leonard		
Tanner Broughton	went to meeting @ Habbins	
Ellen Heck	(6:30-5:40) oversee site operation	
Marybeth Leonard		
George Caillouet		
Tanner Broughton		
Ellen Heck	(6:30-2:00) oversee site operation	
Marybeth Leonard		
Chad Goubert		
Subcontractor	2nd 2nd Sub Sub Tier Tier Wrkrs Hrs 2nd Tier Wrkrs Hrs Work Accomplished	S Q Sch

CORE Construction Services, LLC	1	10	Ray - blocking at stage furdown and misc. blocking; sweep street
CORE Construction Services, LLC	1	10	x Ray - misc. blocking; sweep street
CORE Construction Services, LLC			
CORE Construction Services, LLC	1	10	Ray - clean north parking lot; helped get trash out of bldg
CORE Construction Services, LLC	1	8	Ray - reinstalled temp fence across north approach of west drive;
CORE Construction Services, LLC	1	8	Ray - build curbs under window wall
Bernhard Mechanical Contractors, L.L.C.	22	176	cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D
Bernhard Mechanical Contractors, L.L.C.	3	23	Atlas - install exhaust duct in restrooms of D1 & D2
Bernhard Mechanical Contractors, L.L.C.	10	80	ISS -insulating duct in mech room of area A-E; insulating H/H/W and domestic water in maint room in A;
Bernhard Mechanical Contractors, L.L.C.	1	8	Synergy - piping mechanical rooms

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	JJ1				Job: Report #:	14	-02-00
Fair Working Days To Date:						Date:	01/	12/201
Weather Delays To Date:				Weather Condition:	mostly sunny	Day:		Tuesda
Is Today Claimed as Weather Day?		N	1	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν	ı				42	57
Bernhard Mechanical Contractors, L.L.C.	21	168	х		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; cont. overhead piping in D3 & E3; piping in units on 2nd floor of D; started up booster pump			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - install kitchen hood exhaust duct			
Bernhard Mechanical Contractors, L.L.C.	11	88	Х		ISS -insulating duct in mech room of area A; insulating chilled water on 1st and 2nd floors			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.	22	176	х		cont overhead piping on E3; testing domestic water system;cont. piping units on mezzanine; flushing systems			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - weldedl kitchen hood exhaust duct			
Bernhard Mechanical Contractors, L.L.C.	8	64	х		ISS - insulating H/H/W on 1st floor; insulating chill water in main mech room			
Bernhard Mechanical Contractors, L.L.C.	1	4	Х		Synergy - piping mech rooms			
Bernhard Mechanical Contractors, L.L.C.	19	152			cont overhead piping on E3; cleaning mechanical rooms and units getting ready to start them up; flushing systems; installing mixing valves and emergency showers in science rooms			
Bernhard Mechanical Contractors, L.L.C.	2	15			Atlas - installed dryer vent and box in kitchen area			
Bernhard Mechanical Contractors, L.L.C.	8	64			ISS - insulating H/H/W on 1st floor; insulating chill water in main mech room			
Bernhard Mechanical Contractors, L.L.C.	1	8			Synergy - pulling wire to AHU's and mounting devices to same			
Bernhard Mechanical Contractors, L.L.C.	20	160			cont overhead piping on E3; cleaning mechanical rooms and units getting ready to start them up; flushing systems; installing mixing valves and emergency showers in science rooms; installing vent piping			
Bernhard Mechanical Contractors, L.L.C.	2	15			Atlas - misc ductwork in area A			
Bernhard Mechanical Contractors, L.L.C.	9	72			ISS - insulating H/H/W on 1st floor; insulating chill water in main mech room; finished installing fire wrap at main kitchen exhaust			
Bernhard Mechanical Contractors, L.L.C.	2	16			Synergy - pulling wire to AHU's and mounting devices to same			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
Firestop International LLC	1	8			all smoke penetratiions on 1st floor and 3rd floor penetrations			
Firestop International LLC	1	8	х		hallway & duct penetrations on 1st floor			
Firestop International LLC								
Firestop International LLC								
Firestop International LLC	2	16			recheck smoke & fire walls on 1st floor and shafts			
Firestop International LLC								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool				Job: Report #:	14-	-02-002 1
Fair Working Days To Date:						Date:	01/1	6/2016
Weather Delays To Date:				Weather Condition:	partly cloudy	Day:	S	aturday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				·	44	63
Kone Inc								
Holi Services Inc	2	16			Mike & Eddie -clean-up; dewater & helped Ray			
Holi Services Inc	2	16	х		Mike & Eddie -clean-up & helped Ray			
Holi Services Inc	2	20	х		Mike & Eddie -clean-up			
Holi Services Inc	2	18			Mike & Eddie -clean-up			
Holi Services Inc	2	16			Mike & Eddie -clean-up, dewater, help with temp fence			
Holi Services Inc								
Morris Drywall Systems Inc	18	252			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in area D2 at offices			
Morris Drywall Systems Inc	17	153			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid			
					wall mold on D1; hang sheetrock ceilings in vestibules @			
Morris Drywall Systems Inc	17	153			lockerrooms and in gym rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid			
monis Brywan systems me	.,	133			wall mold on D1; hang sheetrock ceilings in vestibules @ lockerrooms and in gym			
Morris Drywall Systems Inc	16	144			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid			
					in D1;			
Morris Drywall Systems Inc	16	144			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid			
Morris Drywall Systems Inc	9	12			in D1 & E1 installing rock in main stairwell; rocking room 306			
New Orleans Glass Company, Inc.	-				instanting rock in main stantine, rocking room soo			
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.	1	7			receive glass for hollow metal windows and began installation of			
New Orleans Glass Company, Inc.		,			same			
New Orleans Glass Company, Inc.								
Phoenix Constructors LLC	5	40			busted concrete & prepped at north entry of west drive; install storm line on south side of bldg on east end			
Phoenix Constructors LLC	5	40			busted concrete & prepped at north entry of west drive; install			
	_				storm line on south side of bldg on east end			
Phoenix Constructors LLC	5	40			continue to install stormline along south side of bldg			
Phoenix Constructors LLC	5	50			continue to install stormline along south side of bldg			
Phoenix Constructors LLC	9	72			continue to install stormline along south side of bldg			
Phoenix Constructors LLC	3	15			continue to install stormline along south side of bldg			
Cordeiro LLC	5	40			Prep/form @ west paving along with it's north approach			
Cordeiro LLC	11	99			Pour west paving from under canopy to front steps of B			
Cordeiro LLC	9	81	х		Pour north approach of west drive @ 7:00am (14cyds); pumped north 1/3 of drive between approach and yesterday's pour begining @ 1:30pm (50cyds).			
Cordeiro LLC	5	40			wreck forms at west drive and begin working on forming sidewalk			
Cordeiro LLC	5	40			at same location wreck forms at west drive and working on forming sidewalk at same location			
Cordeiro LLC	5	30			prep sidewalk @ front of bldg			
Rufino's Painting & Construction Inc.	16	128			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino`s Painting & Construction Inc.	17	136	х		tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	12	96	х		tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor $$			

Project: Location:	Sherwood Forest Element 4801 Maid Marion Drive	tary Scho	ol				Job: Report #:	14-	02-002
							•	01 /1	
Fair Working	-					alau du	Date:		4/2016
Weather Dela			N		Weather Condition:	cloudy	Day:		nursday
-	ned as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path W								54	67
Rufino`s Painting	g & Construction Inc.	11	88			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino`s Painting	g & Construction Inc.	12	96			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino`s Painting	& Construction Inc.	8	56			tape & float in restrooms and stairwell; prime & paint ceilings in locker rooms and restrooms on 1st floor; clean/scrape floors			
Quality Iron Fabi	ricators Inc.								
Quality Iron Fabi	ricators Inc.								
Quality Iron Fabi	ricators Inc.								
Quality Iron Fabi	ricators Inc.								
Quality Iron Fabi	ricators Inc.								
Quality Iron Fabi	ricators Inc.								
River City Fire Pr	otection	3	21			working on sprinkler line			
River City Fire Pr	otection	3	24	х		working on sprinkler line			
River City Fire Pr	otection	3	24	х		working on sprinkler line			
River City Fire Pr	otection	3	24			working on sprinkler line			
River City Fire Pr	otection								
River City Fire Pr	otection								
Roofing Solution		8	76			installing metal flashing and began changing out panels on north side of gym			
Roofing Solution		7	67						
Roofing Solution		7	67	х		installing metal flashing and began changing out panels on north side of gym			
Roofing Solution		7	67	v		installing metal flashing and changing out pagels on portheids of			
Roofing Solution			67	х		installing metal flashing and changing out panels on north side of gym			
Roofing Solution		3	21			worked on south eyebrow			
Roofing Solution		7	67			installing metal flashing in courtyard and around area A			
Roofing Solution									
Roofing Solution		10	80			installing metal flashing around bldg.			
Roofing Solution	is LLC	1	5			install goose neck for condensor; install boiler flues through roof; sealed in vent pipes			
Roofing Solution	ns LLC	9	59			installing metal flashing around bldg. and installed metal siding on upper section of north side of A			
Roofing Solution	ns LLC								
Alack Refrigerati	on Company								
Alack Refrigerati	on Company								
Alack Refrigerati	on Company								
Alack Refrigerati	on Company								
Alack Refrigerati	on Company								
Alack Refrigerati	on Company								
Allied Constructi	on, LLC	5	40			install brick sills on south elevation; work on loose ends			
Allied Constructi	on, LLC	5	40	х		install brick sills; work on loose ends			
Allied Constructi	on, LLC	4	32	х		clean-up; work on loose ends			
Allied Constructi	on, LLC	4	32			clean-up; work on loose ends			
Allied Constructi	on, LLC	4	32			clean-up; work on loose ends			
Allied Constructi	on, LLC	5	33			clean-up; work on loose ends; point up in gym & cafeteria			
CFI Insulation Inc	ε								

Project: Sherwood Forest Elemen Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14	4-02-00 <i>2</i>
Fair Worldon Davis To Date:					Date:	01.	/12/2016
Fair Working Days To Date:			Weather Condition:	mostly sunny	Day:		Tuesday
Weather Delays To Date: Is Today Claimed as Weather Day?		Ν		mostly samy	=		
Critical Path Work Effected?		Ν	r recipitation Amount.		Temp:	Low 42	High 57
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc	1	1		came out for concrete pour that was canceled @ 7:20am.			
Gulf South Engineering & Testing Inc	1	6		came out for concrete pour			
Gulf South Engineering & Testing Inc	1	1		came out for concrete pour; took cylinders			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders	5	30		installed hardware on HM doors			
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	21	168		work on overhead on E2 & C1 branch circuits; gym shades, E1 &			
				E2 mech equipment termination; began changing temp power to permanent power			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	22	176	х	work on overhead on E2 & C1 branch circuits - D1 & E1 & gym; installing lights at vestibules to locker rooms and entrances of gym; changing temp power to permanent power			
Malone All Star JV, LLC				g), changing temp poner to permanent pone.			
Malone All Star JV, LLC							
Malone All Star JV, LLC	21	168	x	work on overhead on E2 & E3; branch circuits -E2, E1, kitchen & gym; installing lights at restroom kitchen & coaches offices			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	22	176		work on overhead on E2 & C1; branch circuits -E2, E1, kitchen & gym; installing lights im kitchen, coaches offices & mock-up area			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	18	144		work on overhead on E2 & C1; branch circuits -E2, E1, kitchen & gym; installing lights im kitchen, coaches offices & mock-up area			
Malone All Star JV, LLC	3	24		Bonded - installed lightning protection			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.							

Heritage Flooring Inc.

Project:	Sherwood Forest Elementary S	chool			Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	01/	16/2016
Weather Dela	ys To Date:		Weather Condition:	partly cloudy	Day:	S	aturday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				44	63
	63	5 5184					

Project:	Sherwood Forest Elementary School	ol				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Rep	ort #:		1
Fair Working	Days To Date:					Date:	01/1	18/2016
Weather Dela	ays To Date:		Weather Condition:	sunny		Day:	V	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		7	Гетр:	Low	High
Critical Path \	Work Effected?	N					40	55

Employee			Work Accomplished	
George Caillouet			Work Accomplished	
Tanner Broughton				
Ellen Heck			(6:30-5:15) oversee site operation	
Marybeth Leonard			(olso stris) oreisee site operation	
George Caillouet				
Tanner Broughton				
Ellen Heck			(6:30-5:20) oversee site operation	
Marybeth Leonard			•	
Chad Goubert				
Ellen Heck			(6:30-5:20) oversee site operation	
Marybeth Leonard				
Chad Goubert				
George Caillouet				
Tanner Broughton				
Ellen Heck			(6:42-5:10) oversee site operation	
Marybeth Leonard				
Chad Goubert				
George Caillouet				
Tanner Broughton				
Ellen Heck			(6:45-3:40) oversee site operation	
Marybeth Leonard				
Chad Goubert				
		2nd 2n		
Subcontractor	Sub Sub Wrkrs Hrs 2nd Tier	Tier Tie Wrkrs Hr		S Q Sch

CORE Construction Services, LLC	1	10		Ray - misc blocking and built curbs below window walls in main
				lobby
CORE Construction Services, LLC	1	10		Ray - misc blocking and built curbs below window walls in main
				lobby
CORE Construction Services, LLC	1	10		Ray - cut roof deck @ RTU's on D & E
CORE Construction Services, LLC	1	10		Ray - cut roof deck @ RTU's on D & E
CORE Construction Services, LLC	1	10	х	Ray - cut roof deck @ RTU's on D & E
CORE Construction Services, LLC	1	8		Ray - supervise crews; sweep street; grade site
Bernhard Mechanical Contractors, L.L.C.	23	184		cont overhead piping on E3; cleaning mechanical rooms and units
				getting ready to start them up; flushing systems; installing mixing
				valves and emergency showers in science rooms; installing vent
				piping; raising chilled water lines in cafeteria next to kitchen
Bernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc ductwork in area A

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	01/1	8/2016
Weather Delays To Date:			Weather Condition:	sunny	Day:	N	<b>Monday</b>
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				40	55
Bernhard Mechanical Contractors, L.L.C.	9	72		ISS - insulating H/H/W on 1st floor; insulating chill water lines to			
		•		units			
Bernhard Mechanical Contractors, L.L.C.	1	8		Synergy - pulling wire to AHU's and mounting devices to same			
Bernhard Mechanical Contractors, L.L.C.	21	168		cont overhead piping on E3; flushing systems; installing vent piping; raising chilled water lines in cafeteria next to kitchen			
Bernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc ductwork in area A			
Bernhard Mechanical Contractors, L.L.C.	10	80		ISS - insulating H/H/W in pump room; insulating domestic			
				h/water heaters; insulating supply & return duct in small mech			
Bernhard Mechanical Contractors, L.L.C.	2	16		room in area C; repair insulation as needed			
Bernhard Mechanical Contractors, L.L.C.	21	168		Synergy - pulling wire to AHU's and mounting devices to same			
bermard Mechanical Contractors, E.E.C.	21	100		cont overhead piping on D3; flushing systems; cleaning units in C mech room; final pressure test on chilled water lines; misc repairs;			
				began valve tagging			
Bernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc ductwork in area A			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS - insulating H/H/W in pump room; insulating domestic			
				h/water heaters; insulating supply & return duct in small mech room in area C; repair insulation as needed			
Bernhard Mechanical Contractors, L.L.C.	2	16		Synergy - piping central plant; mounting devices on AHU's			
Bernhard Mechanical Contractors, L.L.C.	20	160		cont overhead piping on D3; flushing systems; cleaning units in C			
				mech room; final pressure test on chilled water lines; misc repairs;			
Perphard Machanical Contractors 11 C	2	15		began valve tagging			
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	6	48		Atlas - misc ductwork in area A			
bermard Mechanical Contractors, E.E.C.	U	40		ISS - insulating H/H/W in pump room; insulating domestic h/water heaters;finishing up air handlers in area A; insulating duct			
				in mech room in kitchen.			
Bernhard Mechanical Contractors, L.L.C.	2	16		Synergy - pulling wire in central plant; mounting devices on			
Bernhard Mechanical Contractors, L.L.C.	18	144 x		AHU's cont overhead piping on D3; flushing systems; cleaning units in C			
				mech room; final pressure test on chilled water lines; misc repairs;			
				began valve tagging			
Bernhard Mechanical Contractors, L.L.C.	2	15		Atlas - misc ductwork in area A			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS - insulating H/H/W in pump room; insulating domestic			
				h/water heaters; insulating supply & return duct in small mech room in area C; repair insulation as needed			
Bernhard Mechanical Contractors, L.L.C.				·			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.	2			grinding terrazzo on 2nd floor			
D&T Tile & Terrazzo Co. Inc.	2	16		grinding terrazzo on 2nd floor			
D&T Tile & Terrazzo Co. Inc.	2	16		grinding east and west locker rooms			
D&T Tile & Terrazzo Co. Inc.	2	16		grinding east and west locker rooms			
D&T Tile & Terrazzo Co. Inc.	2	13		sealing gang RR's in D1 (2nd coat) and boy's C1			
Firestop International LLC	1	8		recheck smoke & fire walls on 1st floor and shafts			
Firestop International LLC							
Firestop International LLC	1	8		fire/smoke caulk on 2nd floor			
Firestop International LLC	2	16		fire/smoke caulk on 1st floor			
Firestop International LLC	2	16 x		fire/smoke caulk on 1st floor			
Firestop International LLC							

	d	٠.							02.622
Project: Location:	Sherwood Forest Elementa 4801 Maid Marion Drive	iry Scho	001				Job:	14	-02-002
Location:	4001 Wald Walloff Drive						Report #:		
Fair Workin	g Days To Date:						Date:		18/2016
	elays To Date:				Weather Condition:	sunny	Day:	ľ	Monday
	imed as Weather Day?		Λ		Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		Ν	l				40	55
Kone Inc									
Kone Inc									
Kone Inc									
Kone Inc									
Kone Inc									
Kone Inc									
Holi Services I	Inc	2	18			Mike & Eddie -clean-up, dewater			
Holi Services I	Inc	2	18			Mike & Eddie -clean-up, dewater			
Holi Services I	nc	2	18			Mike & Eddie -clean-up, assist Ray in cutting roof deck			
Holi Services I	nc	2	18			Mike & Eddie -clean-up, assist Ray in cutting roof deck			
Holi Services I		2	18	х		Mike & Eddie -clean-up, assist Ray in cutting roof deck			
Holi Services I		2	16			Mike & Eddie -clean-up			
Morris Drywal	ll Systems Inc	17	153			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in D1;			
Morris Drywal	ll Systems Inc	15	135			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in D1 & E1; rock @ main stair			
Morris Drywal	ll Systems Inc	17	153	х		rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in D1; install fire & smoke caulk in D1 & E1			
Morris Drywal	ll Systems Inc	15	135			rock on 2nd floor; rock on 3rd floor; clean-up; install ceiling grid in E1; install fire & smoke caulk in D1 & E1			
Morris Drywal	ll Systems Inc	17	136	х		rock on 2nd floor; clean-up; install ceiling grid in E1; install fire & smoke caulk in D1 & E1			
Morris Drywal	Il Systems Inc					SHORE CAUR III DT & ET			
New Orleans	Glass Company, Inc.	4	32			receive glass for hollow metal windows and began installation of same			
New Orleans	Glass Company, Inc.	5	40			install frames in SF 1,2 & 3			
	Glass Company, Inc.	5	40			install frames in SF 3 & 5; caulk interior and exterior frames			
New Orleans	Glass Company, Inc.	3	24			install frames in SF1 & 2			
New Orleans	Glass Company, Inc.	3	24	x		install frames in SF1 & 2			
New Orleans	Glass Company, Inc.								
Phoenix Cons	tructors LLC	6	54			continue to install stormline along south side of bldg			
Phoenix Cons	tructors LLC	6	54			continue to install stormline along south side of bldg			
Phoenix Cons	tructors LLC	6	54			redo storm line at parking spaces @ west drive			
Phoenix Cons	tructors LLC	6	54			redo storm line at parking spaces @ west drive			
Phoenix Cons	tructors LLC	5	40			install 8" turn ups on south side of D & E			
Phoenix Cons	tructors LLC								
Cordeiro LLC		5	40			pour 200' of curb and 1 light std.; prep sidewalk on west side of D			
Cordeiro LLC		5	45			prep sidewalk on west side of D			
Cordeiro LLC		8	64			pour sidewalk on west side of D and handicap ramp; clean-up;			
Cordeiro LLC		5	40			prep sidewalk on west side of B clean-up			
Cordeiro LLC		5	40	х		form for locker curbs (5 hrs); prep sidewalk at west side			
Cordeiro LLC		5	33	^		prep parking area paving @ west drive			
	ing & Construction Inc.	13	104			tape & float in D3 & E3; prime; taping/floating & priming on 2nd			
Rufino`s Paint	ing & Construction Inc.	13	104			floor tape & float in D3 & E3; prime; taping/floating & priming on 2nd			
Dufine's Daint	ing & Construction Inc	10	104			floor			

tape & float in D3 & E3; prime; taping/floating & priming on 2nd

floor

Rufino's Painting & Construction Inc.

13 104

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive Fair Working Days To Date:	=	ool				Job: Report #:  Date:	01/	-02-002 1 21/2016
Weather Delays To Date:		N.		Weather Condition:	cloudy	Day:	Т	hursday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N					46	68
Rufino's Painting & Construction Inc.	13	104			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	16	128	х		tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	7	56	х		tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Quality Iron Fabricators Inc.					· · · · · · · · · · · · · · · · · · ·			
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
River City Fire Protection								
River City Fire Protection	3	24			run sprinkler pipe			
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
Roofing Solutions LLC	10	95			installing metal flashing around bldg. and install panels at north			
g solutions		33			and east side of gym			
Roofing Solutions LLC								
Roofing Solutions LLC	10	95			installing metal flashing around bldg. and install panels at north and east side of gym			
Roofing Solutions LLC								
Roofing Solutions LLC	10	95			installing metal flashing around bldg. and install panels at north and east side of gym			
Roofing Solutions LLC	5	20			roofers came with a delivery of coping and began working on the roof of E			
Roofing Solutions LLC	2	18			installing metal flashing around bldg. and install panels at north			
5 5 5 1 7 115					and east side of gym			
Roofing Solutions LLC	6	54			roofers installed coping on the roof of E			
Roofing Solutions LLC	2	18	Х		installing metal flashing around bldg. and remove some old panels			
Roofing Solutions LLC	5	45			roofers installed coping on the roof of E			
Roofing Solutions LLC					, 3			
Roofing Solutions LLC								
Multivista Construction Documentation	1	1			took exterior photos			
Alack Refrigeration Company								
Alack Refrigeration Company	4	16			set condensor on roof			
Alack Refrigeration Company	•	.5						
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
	5	40			clean up; work on loose ands			
Allied Construction, LLC					clean-up; work on loose ends			
Allied Construction, LLC	5	40			clean-up; work on loose ends; set up scaffold; hauled off materials			
Allied Construction, LLC	6	48			clean-up; work on loose ends; set up scaffold; hauled off materials			
Allied Construction, LLC	4	32			clean-up; work on loose ends; hauled off materials			
Allied Construction, LLC	6	48	Х		clean-up; work on monument signs; install brick window sills			

Project: Location:	Sherwood Forest Elementa 4801 Maid Marion Drive	ry Scho	ol				Job: Report #:	14-	02-002 1
Fair Working	Days To Date:						Date:	01/2	3/2016
Weather Dela	•				Weather Condition:	sunny/windy	Day:	S	aturday
	ned as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path W	Vork Effected?		N		•		•	33	51
Allied Constructi	ion, LLC	3	21			clean-up; work on monument signs; install brick window sills;			
						install brick cap at transformer yard			
CFI Insulation Inc	С								
CFI Insulation Inc	С								
CFI Insulation Inc	С								
CFI Insulation Inc	с								
CFI Insulation Inc	с	2	12			seal in flashing (wind making it hard to install primer)			
CFI Insulation Inc	С	2	4			flash in flashing			
Gulf South Engir	neering & Testing Inc								
Gulf South Engir	neering & Testing Inc								
Gulf South Engir	neering & Testing Inc	1	3			Jude was here to take cylinders during pour			
Gulf South Engir	neering & Testing Inc	2	1			Jude came and took densities at storm line ditch			
Gulf South Engir	neering & Testing Inc								
Gulf South Engir	neering & Testing Inc								
Ellison Builders									
Ellison Builders									
Ellison Builders									
Ellison Builders									
Ellison Builders									
Ellison Builders									
Malone All Star	IV, LLC	19	152			work on overhead on E2 & C1; branch circuits -E2, E1, kitchen & gym; installing lights im kitchen, coaches offices & mock-up area			
Malone All Star	IV, LLC								
Malone All Star	IV, LLC								
Malone All Star	IV, LLC	17	136			work on overhead on E2 & E3; branch circuits -E2 & E3; installing lights in mezanine; mech equipment hook-up			
Malone All Star	IV, LLC								
Malone All Star	IV, LLC								
Malone All Star	IV, LLC	19	152			work on overhead on E2 $\&$ E3; branch circuits -E2 $\&$ E3; installing lights in mezanine; mech equipment hook-up			
Malone All Star	IV, LLC	5	40			Data - pulling cable on 2nd floor			
Malone All Star	IV, LLC	3	24			ADS - pulling wire			
Malone All Star	IV, LLC	20	160			work on overhead on E2 $\&$ E3; branch circuits -E2 $\&$ E3; installing lights in mezanine; mech equipment hook-up			
Malone All Star	IV, LLC	4	32			Data - pulling cable on 2nd floor			
Malone All Star	IV, LLC								
Malone All Star	IV, LLC	19	152	Х		work on overhead on E2 & E3; branch circuits -C1, E2 & E3; mech equipment hook-up			
Malone All Star	IV, LLC	5	40	х		Data - pulling cable on 2nd floor			
Malone All Star	IV, LLC								
Malone All Star	IV, LLC								
Malone All Star	IV, LLC								
Malone All Star	IV, LLC								
Heritage Floorin	g Inc.								
Heritage Flooring	g Inc.	4	32			floating walls in gang restrooms; installing ceramic tile in maint restroom			
Heritage Floorin	g Inc.	3	27			began installing tile in boy's RR in C1			
Heritage Flooring	g Inc.	4	36			installing tile in boy's RR in C1			

Project:	Sherwood Forest Element	ary Scho	ool			Job:	14	1-02-002	
Location:	4801 Maid Marion Drive					Report #:		1	
Fair Working	Days To Date:			Date			: 01/22/2016		
Weather Dela	ys To Date:			Weather Condition:	overcast and windy (rained last	Day:		Friday	
Is Today Clain	ned as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High	
Critical Path V	Vork Effected?		N				35	46	
Heritage Floorin	ig Inc.	4	36		installing tile in boy's RR in C1				
Heritage Floorin	ig Inc.	4	32		installing tile in girl's RR in C1				
		653	5294						

Project:	Sherwood Forest Elementary School	ol			Je	ob:	14-02	-002
Location:	4801 Maid Marion Drive				Repor	t #:		1
Fair Working	Days To Date:				Da	nte: C	)1/25/2	2016
Weather Del	ays To Date:		Weather Condition:	overcast	C	ay:	Moi	nday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Ter	<b>np:</b> Low	v 1	High
Critical Path	Work Effected?	N				5	5	68

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:20-5:30) oversee site operation		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:20-5:00) oversee site operation		
Marybeth Leonard								
Chad Goubert								
George Caillouet								
Ellen Heck						(6:40-5:30) oversee site operation		
Marybeth Leonard								
Tanner Broughton								
Ellen Heck						(6:18-5:15) oversee site operation		
Marybeth Leonard								
Chad Goubert								
Tanner Broughton								
Ellen Heck						(6:20-3:45) oversee site operation		
Marybeth Leonard								
Ellen Heck						(6:20-4:15) oversee site operation		
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished	s	Q Sch
Subcontractor			Ziiu iiei	Wrkrs	Hrs			<b>Q</b> 501
	3	9				Hahn - install score boards		
	3	0				Hahn - install volleyball inserts		
CORE Construction Services, LLC	1	10				Ray - clean street; pull misc measurements		
CORE Construction Services, LLC	1	10				clean street; unload materials; seal exterior penetrations		
CORE Construction Services, LLC	1	10				clean street; build curb on 2nd floor under sidelites at fire door at main stairs		
CORE Construction Services, LLC	1	11				clean street; build curb on 2nd floor under sidelites at fire door at main stairs		
CORE Construction Services, LLC	1	9				clean street;cut concrete for walk-off mats		
CORE Construction Services, LLC	1	8				clean street;cut concrete for walk-off mats		
Bernhard Mechanical Contractors, L.L.C.	18	144				cont overhead piping on D3; flushing systems; cleaning units in C mech room; final pressure test on chilled water lines; misc repairs;		
Bernhard Mechanical Contractors, L.L.C.	2	15				continue working on eye wash/emergency showers on D3  Atlas - install shroud at kitchen hood;		

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	01/	25/2016
Weather Delays To Date:			Weather Condition:	overcast	Day:		Monday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	·		•	55	68
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - patching as needed; finishing supply duct in mech room on A1; insulating chill/ h/hw line in mech room			
Bernhard Mechanical Contractors, L.L.C.	1	8		Synergy - pulling wires to AHU; flexing to devices on units			
Bernhard Mechanical Contractors, L.L.C.	20	160		cont overhead piping on D3; flushing systems; cleaning units in C mech room; final pressure test on chilled water lines; misc repairs; continue working on eye wash/emergency showers on D3			
Bernhard Mechanical Contractors, L.L.C.	2	15		Atlas - installing exhaust on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS -insulating air handler on 1st & 2nd floor and pump room on C2			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	16	128	х	cont overhead piping on 2nd & 3rd floor; flushing systems			
Bernhard Mechanical Contractors, L.L.C.	2	15	х	Atlas - installing louver on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	6	48	х	ISS -insulating air handler on 1st & 2nd floor and repairing insulation on h/hw all over			
Bernhard Mechanical Contractors, L.L.C.			х	Synergy - terminating devices and panles for AHU's; pulling wire to AHU's			
Bernhard Mechanical Contractors, L.L.C.	17	136		cont overhead piping on 2nd & 3rd floor; flushing systems; work on unit in stairway E			
Bernhard Mechanical Contractors, L.L.C.	2	16		Atlas - install grilles in room 306			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS - insulating h/h/w & chill water in mech rooms; repaired domestic water in RR's in E			
Bernhard Mechanical Contractors, L.L.C.	3	24		Synergy - pulling wire on 2nd floor; terminating panels /devices and AHU's			
Bernhard Mechanical Contractors, L.L.C.	19	153		cont overhead piping on 2nd & 3rd floor; flushing systems; work on unit in stairway E; hooking up fixtures in kitchen			
Bernhard Mechanical Contractors, L.L.C.	3	24		Atlas - install grilles in main stair			
Bernhard Mechanical Contractors, L.L.C.	6	48		ISS -Insulating fresh air on 2nd floor; insulating grill's in mock up room; insulating h/h/w and chill water on air handlers			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.	2	16		install epoxy finish in restrooms in D1 & D2			
D&T Tile & Terrazzo Co. Inc.	2	16		install epoxy finish in restrooms in D2 & began prepping @ D3			
D&T Tile & Terrazzo Co. Inc.	2	17		installing epoxy flooring in gang restrooms on C1, D2 & D3			
D&T Tile & Terrazzo Co. Inc.	2	17		installing epoxy flooring in gang restrooms on C1, D2 & D3			
D&T Tile & Terrazzo Co. Inc.	2	17		installing epoxy flooring in gang restrooms on C1, D2 & D3 and began in locker rooms			
D&T Tile & Terrazzo Co. Inc.	2	10		installing epoxy flooring in locker rooms			
Firestop International LLC	2	16		fire/smoke caulk on 2nd floor			
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC	2	16		fire sealing floor penetrations on 3rd floor west end; fire/smoke seal at 1st floor			
Firestop International LLC							
Kone Inc							
Kone Inc							
Kone Inc							

Project: Sherwood Forest Elementa	ary Scho	ool			Job:	14	-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:		28/2016
Weather Delays To Date:		NI	Weather Condition:	plenty of sun	Day:	Т	hursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				42	56
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	2	18		Mike & Eddie -clean-up			
Holi Services Inc	2	18		Mike & Eddie -clean-up			
Holi Services Inc	2	18		Mike & Eddie -clean-up/dewater			
Holi Services Inc	2	18		Mike & Eddie -clean-up; install protection paper in gang restrroms in D1 and men's in C1			
Holi Services Inc	2	17		Mike & Eddie -clean-up;chip for walk off mats in gym and vestibule to kitchen			
Holi Services Inc	1	8		Mike -clean-up;chip for walk off mats in gym and vestibule to kitchen			
Morris Drywall Systems Inc	17	153		rock on 2nd floor; clean-up; install ceiling grid in E1			
Morris Drywall Systems Inc	16	144		rock on 2nd floor; clean-up; install ceiling grid in kitchen & mock-up room on 3rd floor			
Morris Drywall Systems Inc	16	144 x		rock on 2nd floor; clean-up; install ceiling grid in kitchen			
Morris Drywall Systems Inc	17	153		rock on 2nd floor; clean-up; install ceiling grid in kitchen and cafeteria			
Morris Drywall Systems Inc	17	136		rock on 2nd floor; clean-up; install ceiling grid in kitchen and cafeteria			
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.	2	16		caulk ext. frames on south elevation; install fire frames @ 1st floor at main stairs			
New Orleans Glass Company, Inc.	2	16		caulk ext. frames on south elevation			
New Orleans Glass Company, Inc.	4	32		hauled fire doors to locations needed; installed fire door & lites @ 1st floor by main stair			
New Orleans Glass Company, Inc.	4	32		finished installing fire door & lites @ 1st floor by main stair; work on some exterior caulking			
New Orleans Glass Company, Inc.	3	24		install fire door & lites on 2nd floor			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	5	40		install 8" turn ups on south side of D & E; grading island @ north paving			
Phoenix Constructors LLC	5	40		install 8" turn ups on south side of D & E; dewater/move muck			
Phoenix Constructors LLC	5	40					
Phoenix Constructors LLC	5	40		rotated vavle stem at main backflow preventer; demo asphalt between drives on Maid Marion; install sand at sidewalk @ main entrance			
Phoenix Constructors LLC	5	40		demo asphalt and grade along Maid Marion			
Phoenix Constructors LLC	1	3		worked dirt on south and east side to help dry it up			
Cordeiro LLC	5	40					
Cordeiro LLC							
Cordeiro LLC	5	37 x		poured remainder of locker bases and prepped/poured strap beam for canopy @ main entrance			
Cordeiro LLC	4	32		wrecked forms in locker rooms & @ strap beam; prep/pour canopy pedestals @ main entry; set 1 bollard; prep sidewalk in front of main entrance steps			
Cordeiro LLC	5	40		finished prepping sidewalk @ main entry; bust concrete for grade beam tie-in at west canopy north end			
Cordeiro LLC				••			
Rufino's Painting & Construction Inc.	12	96		tape & float in D3 & E3; prime; taping/floating & priming on 2nd			

floor

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive Fair Working Days To Date:	=	JUI				Job: Report #:  Date:		-02-002 1 26/2016
Weather Delays To Date:				Weather Condition:	cloudy with showers/rain starte	Day:		Tuesday
Is Today Claimed as Weather Day?		N	1	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν	1			•	46	69
Rufino`s Painting & Construction Inc.	13	104			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	13	104	х		tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	13	104			tape & float in D3 & E3; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	13	104			tape & float in RR's in E1; prime; taping/floating & priming on 2nd floor			
Rufino's Painting & Construction Inc.	4	32			painting underneath sides of main stairs and E stairs			
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
Roofing Solutions LLC	2	18			received/loaded new/old panels			
Roofing Solutions LLC								
Roofing Solutions LLC	6	48			Install wall panels on north side of gym; received/unloaded remainder of wall panels			
Roofing Solutions LLC								
Roofing Solutions LLC	7	67	x		Install wall panels on north side of gym			
Roofing Solutions LLC	7	63	x		Install coping & counter flashing on bldg E			
Roofing Solutions LLC	11	104			Install wall panels on north side of gym &			
Roofing Solutions LLC	7	67			Install coping & counter flashing on bldg C			
Roofing Solutions LLC	12	96			Install wall panels on north side of gym & band in courtyard beginning on west end moving south			
Roofing Solutions LLC	7	56			Install coping & counter flashing on bldg A & B			
Roofing Solutions LLC	12	96			Install wall panels on north side of gym & band in courtyard and on east end of area E			
Roofing Solutions LLC	7	53			Install coping & counter flashing on bldg A & B			
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Pofrigoration Company								

Alack Refrigeration Company

Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ry Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	01/2	25/2016
Weather Delays To Date:			Weather Condition:	overcast	Day:	N	Monday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	-		•	55	68
Allied Construction, LLC	5	40		clean-up; work on monument signs; install brick window sills			
Allied Construction, LLC	5	13		set up to work on monument signs & cap at transormer yard; pulled off because I wouldn't stop what others were doing to let them have use of our equipment			
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC	4	28		worked on monument sign			
CFI Insulation Inc	2	18		seal in flashing			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	19	152		work on overhead on E2 & E3; branch circuits -C1, E2 & E3; install lights in locker rooms			
Malone All Star JV, LLC	4	32		Data - pulling cable on 2nd floor			
Malone All Star JV, LLC							
Malone All Star JV, LLC	19	152		work on overhead on E1, E2 & E3; branch circuits -C1, E2 & E3; install lights in locker rooms & mezzanine; mechanical equipment E3 roof			
Malone All Star JV, LLC	4	32		Data - pulling cable on 2nd floor			
Malone All Star JV, LLC	3	24		ADS - pull wire in gym			
Malone All Star JV, LLC	19	152 x		work on overhead on E2 $\&$ E3; branch circuits -kitchen, E2 $\&$ E3; install lights in mezzanine $\&$ E306			
Malone All Star JV, LLC	4	32 x		Data - pulling cable on 2nd floor			
Malone All Star JV, LLC	5	40 x		ADS - pull wire in gym			
Malone All Star JV, LLC	18	144		work on overhead on E2 & E3; branch circuits -kitchen, E2 & E3; install lights in mezzanine & E306			
Malone All Star JV, LLC							
Malone All Star JV, LLC	3	24		ADS - pull wire			
Malone All Star JV, LLC	19	153		work on overhead on E2 & E3; install lights in mezzanine & kitchen; work on branch circuits in kitchen & E1			
Malone All Star JV, LLC							
Malone All Star JV, LLC	3	24		ADS - pull wire			
Malone All Star JV, LLC							

Project:	Sherwood Forest Element 4801 Maid Marion Drive	tary Scho	ool			Job:	14-	-02-002
Location:	4001 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	01/3	80/2016
Weather Dela	Weather Delays To Date:			Weather Condition:	mostly sunny	Day:	Sa	aturday
Is Today Claimed as Weather Day?			N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				58	70
Malone All Star	JV, LLC							
Malone All Star	JV, LLC							
Heritage Floorin	g Inc.	4	36		installing tile in boy's RR in C1			
Heritage Floorin	g Inc.	4	36		installing tile in admin rr on D2; install CT RR D140			
Heritage Floorin	g Inc.	4	36		installing tile in RR's D123 & D140			
Heritage Floorin	g Inc.	4	36		installing tile in RR's D123 & D140			
Heritage Floorin	g Inc.	4	36		installing tile in RR's D236, D136			
Heritage Floorin	g Inc.	2	14		installing tile in RR's D236, D136			
		620	5030					

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/	/01/2016
Weather Dela	ays To Date:		Weather Condition:	plenty of sun	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				64	75

Employee						Work Accomplished		
Tanner Broughton								
Ellen Heck						(6:10-5:45) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:30-3:45) oversee site operation		
Marybeth Leonard								
George Caillouet						went to LSU in afternoon		
Tanner Broughton						went to LSU for afternoon		
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard								
	Sub	Sub		2nd Tier	2nd Tier			
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
	4	24				Joffrey - install shades in gym		
	4	32				Joffrey - work on shades in gym		
CORE Construction Services, LLC	1	10	x			cut/ chip concrete for walk-off mats		
CORE Construction Services, LLC	1	10	^			Ray - work on installing roof ladders, misc.		
CORE Construction Services, LLC	1	10				,		
CORE Construction Services, LLC	1	10				Ray - cover floors; install roof ladders		
CORE Construction Services, LLC	1	8	х			Ray - cover floors; install roof ladders		
CORE Construction Services, LLC	1	8	х			Ray - clean parking lots		
Bernhard Mechanical Contractors, L.L.C.	17	136	x			cont overhead piping on 2nd & 3rd floor; flushing systems; hooking up fixtures in kitchen		
Bernhard Mechanical Contractors, L.L.C.	3	24				Atlas - hook up duct to louver in D240		
Bernhard Mechanical Contractors, L.L.C.	6	48				ISS -Insulating fresh air on 2nd floor; insulating h/h/w and chill water on air handlers		
Bernhard Mechanical Contractors, L.L.C.								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool				Job: Report #:	14-	-02-002 1
Fair Working Days To Date:						Date:	02/0	2/2016
Weather Delays To Date:				Weather Condition:	windy and cloudy/rain @ night	Day:	Т	uesday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N		-		•	57	74
Bernhard Mechanical Contractors, L.L.C.	17	136			cont overhead piping on 2nd & 3rd floor; flushing systems; hooking up fixtures in kitchen			
Bernhard Mechanical Contractors, L.L.C.	2	16			Atlas - hook up duct to louver in D240			
Bernhard Mechanical Contractors, L.L.C.	10	76			ISS -Insulating chill water on 2nd floor; insulating h/h/w and domestic water in hallway of 2nd floor; insulating chilled water & h/h/w on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.	19	153	х		cont overhead piping on 2nd & 3rd floor; flushing systems; hooking up fixtures in kitchen			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - work on boiler flues			
Bernhard Mechanical Contractors, L.L.C.	10	76	х		ISS -Insulating chill water on 2nd floor; insulating h/h/w and domestic water in hallway of 2nd floor; insulating chilled water & h/h/w on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.	17	136			cont overhead piping on 2nd & 3rd floor; added chemicals to system			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - work on boiler flues			
Bernhard Mechanical Contractors, L.L.C.	4	32			ISS -Insulating in hallways on 2nd and 3rd floor			
Bernhard Mechanical Contractors, L.L.C.		440						
Bernhard Mechanical Contractors, L.L.C.	14 3	112 23	х		cont overhead piping on 2nd & 3rd floor; added chemicals to system			
Bernhard Mechanical Contractors, L.L.C.	9	72	V		Atlas - work on boiler flues			
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	1	8	х		ISS -Insulating chilled water h/h/w on E3; insulating h/h/w and domestic cold & hot on E2  Synergy - work in elec/telcom room on D2			
Bernhard Mechanical Contractors, L.L.C.		ŭ			Synergy Work in electroleon room on D2			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.			х					
Bernhard Mechanical Contractors, L.L.C.								
D&T Tile & Terrazzo Co. Inc.	2	17	х		grinding terrazzo in corridor of area C			
D&T Tile & Terrazzo Co. Inc.	2	17	^		grinding terrazzo in corridor of area C & B; install epoxy base in			
D&T Tile & Terrazzo Co. Inc.	2	17			lockerrooms grinding terrazzo in corridor of area C & B; install epoxy base in			
D&T Tile & Terrazzo Co. Inc.	2	12			lockerrooms installing sealer in locker rooms and adj restrooms			
D&T Tile & Terrazzo Co. Inc.	3	24			grinding terrazzo in B			
D&T Tile & Terrazzo Co. Inc.	3	24			grouting terrazzo in B			
Firestop International LLC	2	16	x		fire sealing floor penetrations on 3rd floor west end; fire/smoke seal at 2nd floor			
Firestop International LLC	2	16			fire/smoke caulk on 2			
Firestop International LLC	2	16	х		fire/smoke caulk on 2			
Firestop International LLC								
Firestop International LLC								
Firestop International LLC								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ol				Job: Report #:	14-	-02-002 1
Fair Working Days To Date:						Date:	02/0	01/2016
Weather Delays To Date:				Weather Condition:	plenty of sun	Day:	N	Monday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				•	64	75
Holi Services Inc	1	10	х		Mike - chip for walk off mats			
Holi Services Inc	2	18			Eddie - chip for walk off mats; Mike-help Ray			
Holi Services Inc	2	18	х		Eddie - chip for walk off mats; Mike- dewater; both unloaded			
					trucks			
Holi Services Inc	2	18			Eddie - chip for walk off mats; Mike- dewater; helped Ray			
Holi Services Inc Holi Services Inc	2	16	X		Eddie - chip for walk off mats; Mike- dewater; helped Ray			
Morris Drywall Systems Inc	2 16	16 144	X		Eddie - sweep 3rd floor; Mike- helped Ray rock on 2nd floor; clean-up; install ceiling grid in cafeteria and			
Mons Drywaii Systems Inc	10	144	х		installed border tile in kitchen			
Morris Drywall Systems Inc	17	153			rock on 2nd floor; clean-up; install ceiling grid in cafeteria and installed border tile in kitchen			
Morris Drywall Systems Inc	17	153			rock on 2nd floor; clean-up; install ceiling grid in cafeteria and			
Morris Drywall Systems Inc	16	144			installed border tile in kitchen rock on 2nd floor; clean-up; install ceiling grid in cafeteria and			
World Drywaii Systems inc	10	144			installed border tile in kitchen			
Morris Drywall Systems Inc	17	136	х		rock on 2nd floor; clean-up; rock 3rd; ceiling grid in D1; sheetrock in elevator equipment room			
Morris Drywall Systems Inc	17	136	х		clean-up; rock 3rd; ceiling grid in D1; sheetrock in elevator equipment room; move sheetrock out of gym			
New Orleans Glass Company, Inc.	3	24	х		install fire door & lites on 2nd floor; unload fire glass and caulk			
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.	2	16	Х		Install mock-up metal panel between windows; caulk			
New Orleans Glass Company, Inc.	2	16			caulk exterior frames in courtyard			
New Orleans Glass Company, Inc.	2	16	Х		caulk exterior frames in courtyard			
New Orleans Glass Company, Inc.			Х					
Phoenix Constructors LLC	5	40			finish locating all catch basins and reinstalling filter fabric in them; grade between west and north paving areas			
Phoenix Constructors LLC								
Phoenix Constructors LLC								
Phoenix Constructors LLC								
Phoenix Constructors LLC  Phoenix Constructors LLC								
Cordeiro LLC	5	48	х		finished prepping grade beam extension at west canopy north			
cordeno esc	3	40	^		end; poured beam extension and sidewalk at main entry of area B			
Cordeiro LLC	5	18			prep pedestals at the west end of the north canopy; wreck forms at same and backfill			
Cordeiro LLC	4	32			pour pedestals at north canopy at west end; began			
Cordeiro LLC	5	40			chipping/rubbing walls at loading dock form/prep sidewalk at east end of north canopy; rub walls in			
Cordeiro LLC	5	40	x		loading dock pour sidewalk at east end of north canopy; rub walls in loading dock; pour back in gym			
Cordeiro LLC					· · · · · · · · · · · · · · · · · · ·			
Rufino's Painting & Construction Inc.	12	96	x		tape & float in RR's in E1; prime; taping/floating & priming on 2nd & 3rd floors			
Rufino`s Painting & Construction Inc.	12	96			prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.	12	96	х		prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.	11	88			prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.	11	88	х		prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.			х					
Peachtree Protective Covers	2	2			came to check out job			

Project: Sherwood Forest Elemen	tary Scho	ool				Job:	14	-02-002
<b>Location:</b> 4801 Maid Marion Drive						Report #:		1
Fair Working Days To Date:						Date:	02/	02/2016
Weather Delays To Date:				Weather Condition:	windy and cloudy/rain @ night	Day:		Tuesday
Is Today Claimed as Weather Day?		N	1	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	1				57	74
Peachtree Protective Covers	2	18			install bolts for beams at north canopy			
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
River City Fire Protection								
Roofing Solutions LLC	12	96			Install wall panels on north side of gym & band in courtyard			
					beginning on west end moving south			
Roofing Solutions LLC	7	56	Х		Install coping & counter flashing on bldg A & B			
Roofing Solutions LLC	8	72			Install wall panels on north side of gym & band in courtyard beginning on west end moving south; installing panels on south elevation east end			
Roofing Solutions LLC								
Roofing Solutions LLC	8	72	х		Install wall panels in courtyard and on south elevation			
Roofing Solutions LLC								
Roofing Solutions LLC	9	81			finished wall panels in courtyard and had 3 crew working on south elevation			
Roofing Solutions LLC	7	56			Roofing sheetmetal - install splice plates on coping on A & B			
Roofing Solutions LLC	9	72	x		working on south & west elevations with panels			
Roofing Solutions LLC								
Roofing Solutions LLC	9	72	х		complete south $$ elevation $$ continue working on west elevation $$ with panels $$			
Roofing Solutions LLC								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								
Alack Refrigeration Company								

Alack Refrigeration Company
Allied Construction, LLC

N N N N N N N N N N N N N N N N N N N	Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool				Job: Report #:	14-	-02-002 1
Martin Condition:   Weather Condition:   Windy and Cloudly/rish @ ringht	Fair Working Days To Date:						Date:	02/0	02/2016
Products of the West Products   1					Weather Condition:	windy and cloudy/rain @ night	Day:	Т	Tuesday
Alline Consultation ILC  Alline Consultation ILC  Alline Consultation ILC  All of Consultation ILC  Chi readdoon Inc  Chi readdoon  Chi readdoon  Chi read			N	I				Low	High
Allind Construction, LLC	Critical Path Work Effected?		N	I	-		•	57	74
Allied Construction, LLC 9 16 19 72 install cap on transformer well (route). Allied Construction, LLC 9 72 install cap or transformer well (route). Allied Construction LLC 9 72 IN Installation Inc CHI Installation Installation Inc CHI Insta	Allied Construction, LLC								
Allies Construction, LLC 9 7 72 install or part dumpster pact not wasks in actinome.  Allies Construction In C.  Cil Insulation in C	Allied Construction, LLC	3	21			install cap on transformer wall (west)			
Allied Construction LCC Of Invalation Inc Of Inv	Allied Construction, LLC	2	16			install cap on transformer wall (south)			
CFI Inoutation Insc CFI In	Allied Construction, LLC	9	72			install cap at dumpster pad; rub walls in restrooms			
CFI Insolation for CFI Insolatio	Allied Construction, LLC	9	72			install monument sign brick; rub restrooms on D2, D3			
CFI Insulation Inc CFI Insulation CFI In	CFI Insulation Inc								
CFI Involution in c CFI In	CFI Insulation Inc								
CFI Invasidation Inc CFI Invasidation Inc CGI Invasidation Inc CGI South Engineering & Testing Inc CGI South Engineering CGI South Engineering C	CFI Insulation Inc								
Call South Engineering & Testing Inc Gulf South Engineering A Ext Gulf South En	CFI Insulation Inc								
Culf South Engineering & Testing Inc Culf South Engineering A Esting Inc Culf South Engineering A E	CFI Insulation Inc								
Guil South Engineering & Testing Inc Guil South Full Cut Malone All Star IV, LLC  Malone All St	CFI Insulation Inc								
Gulf South Engineering & Testing Inc Gulf South Engineering Inc Gulf South Engineering & Testing Inc Gulf South Engineering Inc Gulf South Engineering & Testing Inc Gulf South Engineering Gulf	Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc Gulf South Engineering & Testing Inc Gulf South Engineering & Testing Inc Glifson Builders Elison Builders How All Star JY, LLC  22 176 x  work on overhead on £2 & £1; install lights in mezzanine & kirchen; work on branch circuits in kirchen & £1; jackhammered the south run of concrete for the floor box in the gym Malone All Star JY, LLC	Gulf South Engineering & Testing Inc								
Gulf South Engineering & Testing Inc  Ellison Builders  Malone All Star JV, LLC  Malone All Star JV,	Gulf South Engineering & Testing Inc								
Gillson Builders  Elison Builders  Malone All Star /V, LLC  22 176 x  ADS - pull wire  work on overhead on E2 & E3; install lights in mezzanine & istrhen & E1, jackhammered the south run of concrete for the floor box in the gym  work on overhead on E2 & E3; install lights in mezzanine & istrhen & E1, jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star /V, LLC  Malone All Star /V, LLC  40 48 x  ADS - pull wire  Malone All Star /V, LLC  Malone All Star /V, LLC  41 92 x  Malone All Star /V, LLC  Malone All Star /V, LLC  42 48 x  ADS - pull wire  Malone All Star /V, LLC  Malone All Star /V, LLC  ADS - pull wire  Malone All Star /V, LLC  ADS - pull wire  Malone All Star /V, LLC  Malone All Star /V, LLC  ADS - pull wire in orth run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star /V, LLC  ADS - pull wire in orth run of concrete for the floor box in the gym and worked on installing conduit  Malone All Star /V, LLC  ADS - pull wire in gym for speakers  Malone All Star /V, LLC  Malone All St	Gulf South Engineering & Testing Inc								
Ellison Builders  Malone All Star JV, LLC  22 176 x  work on overhead on £2 & £3; install lights in mezzanine & kitchen & £1 jachahmmened the south run of concrete for the floor box in the gym  Malone All Star JV, LLC  23 176 x  ADS - pull wire  work on overhead on £2 & £3; install lights in mezzanine & kitchen & £1 jachahmmened the south run of concrete for the floor box in the gym  Malone All Star JV, LLC  24 176 x  Malone All Star JV, LLC  ADS - pull wire  work on overhead on installing conduit in south run; set lights in place in D1 & £1  lights in place in D1 & £1  work on overhead on installing conduit in south run; set lights in mezzanine & kitchen jachammened the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & £1  Malone All Star JV, LLC  ADS - pull wire  Malone All Star JV, LLC  ADS - pull wire  work on overhead on £2, work on lights in kitchen & £1; finished jachammening the north run of concrete for the floor box in the gym and worked on installing conduit  Malone All Star JV, LLC  ADS - pull wire in gym for speakers  Malone All Star JV, LLC  Malone All Star JV, LLC  ADS - pull wire in gym for speakers  work on overhead on £2; work on lights in kitchen, cafeteria & £1; work on oles in kitchen  Work on overhead on £2; work on lights in kitchen, cafeteria & £1; work on oles in kitchen  Work on overhead on £2; work on lights in kitchen, cafeteria & £1; work on oles in kitchen	Gulf South Engineering & Testing Inc								
Elison Builders  Malone All Star JY, LLC  Malone All Star J	Gulf South Engineering & Testing Inc								
Ellison Builders  Ellison Buil	Ellison Builders								
Ellison Builders  Ellison Builders  Ellison Builders  Ellison Builders  Malone All Star JV, LLC	Ellison Builders								
Ellison Builders  Ellison Builders  Ellison Builders  Malone All Star IV, LLC  Malone All Star I	Ellison Builders								
Ellison Buliders  Malone All Star JV, LLC  Mal	Ellison Builders								
Malone All Star JV, LLC  Malone All Star JV, L	Ellison Builders								
Malone All Star JV, LLC  Malone All Star JV, L	Ellison Builders								
Malone All Star JV, LLC  Malone All Star JV, L	Malone All Star JV, LLC	22	176	х		work on overhead on E2 & E3; install lights in mezzanine &			
Malone All Star JV, LLC						-			
Malone All Star JV, LLC	Mala a All Cras N/ LLC					the south run of concrete for the floor box in the gym			
Malone All Star JV, LLC  22 176 work on overhead on E2 & E3; install lights in mezzanine & kitchen; jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC		2	24			ADC III :			
kitchen; jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC									
in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC	Maione Ali Star JV, LLC	22	176						
Malone All Star JV, LLC									
Malone All Star JV, LLC  ADS - pull wire  work on overhead on £2 & £3; install lights in mezzanine & kitchen; jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & £1  Malone All Star JV, LLC  Malone All Star JV, LLC  6 48 x  ADS - pull wire  work on overhead on £2; work on lights in kitchen & £1; finished jackhammering the north run of concrete for the floor box in the gym and worked on installing conduit  Malone All Star JV, LLC						lights in place in D1 & E1			
Malone All Star JV, LLC  24 192 x  work on overhead on E2 & E3; install lights in mezzanine & kitchen; jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC  Malone All Star JV, LLC  21 164 x  Malone All Star JV, LLC	Malone All Star JV, LLC								
kitchen; jackhammered the north run of concrete for the floor box in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC	Malone All Star JV, LLC	6	48			ADS - pull wire			
in the gym and worked on installing conduit in south run; set lights in place in D1 & E1  Malone All Star JV, LLC  Malone All Star JV, LLC  ADS - pull wire  work on overhead on E2; work on lights in kitchen & E1; finished jackhammering the north run of concrete for the floor box in the gym and worked on installing conduit  Malone All Star JV, LLC	Malone All Star JV, LLC	24	192	Х					
Malone All Star JV, LLC									
Malone All Star JV, LLC									
Malone All Star JV, LLC	Malone All Star JV, LLC								
jackhammering the north run of concrete for the floor box in the gym and worked on installing conduit  Malone All Star JV, LLC  Malone All Star JV, LLC  7 56  ADS - pull wire in gym for speakers  Work on overhead on E2; work on lights in kitchen, cafeteria & E1; work on elec in kitchen  Malone All Star JV, LLC	Malone All Star JV, LLC	6	48	х		ADS - pull wire			
gym and worked on installing conduit  Malone All Star JV, LLC  Malone All Star JV, LLC  7 56  ADS - pull wire in gym for speakers  work on overhead on E2; work on lights in kitchen, cafeteria & E1; work on elec in kitchen  Malone All Star JV, LLC	Malone All Star JV, LLC	21	164			work on overhead on E2; work on lights in kitchen & E1; finished			
Malone All Star JV, LLC  Malone All Star JV, LLC  7 56  ADS - pull wire in gym for speakers  work on overhead on E2; work on lights in kitchen, cafeteria & E1; work on elec in kitchen  Malone All Star JV, LLC									
Malone All Star JV, LLC 7 56 ADS - pull wire in gym for speakers work on overhead on E2; work on lights in kitchen, cafeteria & E1; work on elec in kitchen E1; work on elec in kitchen	Malone All Star IV II C					gym and worked on installing conduit			
Malone All Star JV, LLC  22 176 x work on overhead on E2; work on lights in kitchen, cafeteria & E1; work on elec in kitchen  Malone All Star JV, LLC		7	56			ADS - null wire in gym for speakers			
E1; work on elec in kitchen  Malone All Star JV, LLC				v					
Malone All Star JV, LLC	majorie Ali Star 77, LLC	22	170	۸					
Malone All Star JV, LLC 4 32 ADS - pull wire in D1 & E1	Malone All Star JV, LLC								
	Malone All Star JV, LLC	4	32			ADS - pull wire in D1 & E1			

Project: Sherwood Forest Elementa	ary Scho	ool				Job:	14	-02-002
<b>Location:</b> 4801 Maid Marion Drive						Report #:		1
Fair Working Days To Date:						Date:	02/0	06/2016
Weather Delays To Date:				Weather Condition:	sunny	Day:	S	aturday
Is Today Claimed as Weather Day?		Ν	l	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν	I				42	57
Malone All Star JV, LLC								
Malone All Star JV, LLC								
Malone All Star JV, LLC								
Heritage Flooring Inc.	2	16	х		demoing accent tile in girl's gang RR in C			
Heritage Flooring Inc.	1	8			demoing accent tile in girl's gang RR in C			
Heritage Flooring Inc.	1	8			demoing accent tile in girl's gang RR in C			
Heritage Flooring Inc.	1	8			demoing accent tile in girl's gang RR in C			
Heritage Flooring Inc.	6	48			demoing accent tile in girl's gang RR in C; installing tile on wall at			
					dryer vent; 2nd crew showed up and began working in north			
					locker room			
Heritage Flooring Inc.	6	48			demoing accent tile in girl's gang RR in C; installing tile on wall at			
					dryer vent; 2nd crew showed up and began working in north			
			_		locker room			
	629	5085						

**Remarks:** Owner gave permission to remove mock up wall.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/	08/2016
Weather Dela	ays To Date:		Weather Condition:	sunny & windy	Day:		Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				38	56

Employee				Work Accomplished		
George Caillouet						
Ellen Heck				(6:50-4:30) oversee site operation		
George Caillouet						
Tanner Broughton						
Ellen Heck				(6:30-5:45) oversee site operation		
Marybeth Leonard						
Chad Goubert				stopped by and did an orientation and then walked the job with me		
George Caillouet						
Tanner Broughton				had to report for jury duty in the afternoon and had a meeting @ LSU		
Ellen Heck				(6:35-5:45) oversee site operation		
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck				(6:30-4:20) oversee site operation		
Marybeth Leonard						
Tanner Broughton						
Subcontractor	Sub Sub Wrkrs Hrs	2nd Tier	2nd Tier Hrs	Work Accomplished	s	Q Sch

CORE Construction Services, LLC	1	9		Ray - clean up and dirt work
CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
Bernhard Mechanical Contractors, L.L.C.	12	96		cont overhead piping on 2nd & 3rd floor; install edf in cafeteria
Bernhard Mechanical Contractors, L.L.C.				
Bernhard Mechanical Contractors, L.L.C.				
Bernhard Mechanical Contractors, L.L.C.				
Bernhard Mechanical Contractors, L.L.C.	20	160		cont overhead piping on 2nd & 3rd floor; added chemicals to
				system
Bernhard Mechanical Contractors, L.L.C.				
Bernhard Mechanical Contractors, L.L.C.	10	80		ISS - insulating air handlers in stairway's on 3rd floor; insulating
				h/h/w on 2nd floor E2; insulating domestic hot/cold in science
				lab; 2nd floor finishing duct wrap; insulating gym air handler
Bernhard Mechanical Contractors, L.L.C.				
Bernhard Mechanical Contractors, L.L.C.	19	156	х	cont overhead piping on 2nd & 3rd floor; moved container
Bernhard Mechanical Contractors, L.L.C.				

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Schoo	ol				Job: Report #:		-02-002 1
Fair Working Days To Date:						Date:	02/1	11/2016
Weather Delays To Date:				Weather Condition:	sunny	Day:	•	hursday
Is Today Claimed as Weather Day?		N		Precipitation Amount:	,	Temp:	Low	High
Critical Path Work Effected?		N				remp.	54	73
Bernhard Mechanical Contractors, L.L.C.	11	88	х		ISS -insulating h/h/w vav's on E2 and E3; finishing and repairing			
bermara Weenamear Contractors, E.E.C.	• • •	00	^		chill water on chiller pad; insulating fan coil's in stairwells			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.	15	120			cont overhead piping on 2nd & 3rd floor; added chemicals to piping			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - misc duct work			
Bernhard Mechanical Contractors, L.L.C.	7	56			ISS -insulating h/h/w and chilled water on E3; repairing chill water on chiller pad; insulating domestic water and h/h/w in science labs			
Bernhard Mechanical Contractors, L.L.C.	1	8			Synergy - starting AHU's 4, 5 &7			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.	3	24			grinding/grouting terrazzo in B & C			
D&T Tile & Terrazzo Co. Inc.	3	24	х		grinding/grouting terrazzo in B & C			
D&T Tile & Terrazzo Co. Inc.	3	24			grinding terrazzo in D			
D&T Tile & Terrazzo Co. Inc.	3	24			grinding terrazzo in D			
Firestop International LLC								
Firestop International LLC								
Firestop International LLC								
Firestop International LLC	2	16			sealing penetrations on 2nd floor smoke walls			
Firestop International LLC								
Kone Inc								
Kone Inc	2	16			worked on elevator			
Kone Inc	2	16	Х		wire & pipe hoistway			
Kone Inc	2	16			wire & pipe hoistway			
Kone Inc								
Holi Services Inc	1	9			Eddie - clean-up interior & exterior			
Holi Services Inc	6	60			Eddie/ Mike & 4 laborers - removed and reinstalled temp fence; began relocating doors			
Holi Services Inc	6	48	Х		Eddie/ Mike & 4 laborers - moved doors out of gym			
Holi Services Inc	2	16			Eddie/ Mike - clean-up			
Holi Services Inc								
Morris Drywall Systems Inc	16	144			clean-up; rock 3rd			
Morris Drywall Systems Inc  Morris Drywall Systems Inc	16 17	144	x		clean-up; rock 3rd; ceiling grid in D1; sheetrock in elevator equipment room clean-up; rock 3rd			
Morris Drywall Systems Inc	17	156	x		clean-up; rock 3rd			
Morris Drywall Systems Inc	17	130	^		стеап-ир, тоск эти			
New Orleans Glass Company, Inc.	3	24			install angles and panels on south aloyation between windows			
New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.	5	40			install angles and panels on south elevation between windows install angles and panels between windows on south elevation			
New Orleans Glass Company, Inc.	5	40			install angles and panels between windows on south elevation			
New Orleans Glass Company, Inc.	5	40			install angles and panels between windows on south elevation &			
New Orleans Glass Company, Inc.	J	70			in courtyard			
Phaseis Castrusters II.C.								

Phoenix Constructors LLC

Project: Sherwood Forest Elen Location: 4801 Maid Marion Dri	=	ol				Job: Report #:	14-	02-002 1
Fair Working Days To Date:						Date:	02/1	0/2016
Weather Delays To Date:				Weather Condition:	sunny	Day:	Wed	nesday
Is Today Claimed as Weather Day?		Ν	I	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν	I			•	44	56
Phoenix Constructors LLC	5	45			misc dirtwork			
Phoenix Constructors LLC	5	28	x		grade dirt; install water meter			
Phoenix Constructors LLC	4	24			grade dirt; erosion control			
Phoenix Constructors LLC	2	10			fueled/maintenanced mequipment			
Cordeiro LLC	5	40			prep sidewalk at east end of area E; continue to rub columns and walls @ car drop off			
Cordeiro LLC	5	40			prep city sidewalk on west elevation from north property line to 2nd approach			
Cordeiro LLC	7	49	х		pour city sidewalk on west elevation from north property line to 2nd approach and sidewalk at east end of area E			
Cordeiro LLC	5	40			rub columns; wreck forms @ sidewalks			
Cordeiro LLC								
Rufino's Painting & Construction Inc.								
Rufino`s Painting & Construction Inc.	11	88			prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.	12	96	х		prime; taping/floating & priming on 2nd & 3rd floors			
Rufino's Painting & Construction Inc.	12	96			prime; taping/floating & priming on 2nd & 3rd floors			
Rufino`s Painting & Construction Inc.								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
River City Fire Protection	4	30			install heads in areas A, B, C, D1&2, E1			
River City Fire Protection	3	30			hanging pipe at car drop off; installing heads on 1st floor			
River City Fire Protection	3	18			hanging pipe at car drop off; installing heads on 1st floor			
River City Fire Protection								
River City Fire Protection								
Roofing Solutions LLC	7	63			finished south elevation & work on west elevations with panels			
Roofing Solutions LLC								
Roofing Solutions LLC	7	67			working on west elevations with panels			
Roofing Solutions LLC								
Roofing Solutions LLC	7	67			working on west elevations with panels			
Roofing Solutions LLC								
Roofing Solutions LLC	7	67	x		working on west elevations with panels			
Roofing Solutions LLC	5	5			Sheet metal guys brought out material and began installing coping on high C			
Roofing Solutions LLC	7	67			working on west elevations with panels			
Roofing Solutions LLC								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation	1	2			Nick came by and took pictures			
Multivista Construction Documentation								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:		2-002 1
Fair Working Days To Date:					Date:	02/13/	
Weather Delays To Date:		N	Weather Condition:	mainly sunny	Day:	Satı	urday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:		High
Critical Path Work Effected?		N				45	58
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company	2	4		checking out site for cooler/freezer refrigeration			
Alack Refrigeration Company	3	18	Х	run pipe for cooler/freezer			
Alack Refrigeration Company	2	10		ran refrigeration lines for cooler/freezer			
Alack Refrigeration Company							
Allied Construction, LLC	7	56		complete monument sign; rub interior rr walls; haul off material			
Allied Construction, LLC	5	44		rub walls in restrooms; misc brickwork; install insulation bd on A; clean-up			
Allied Construction, LLC	4	32		rub walls in restrooms; misc brickwork; install insulation bd on A; clean-up			
Allied Construction, LLC	4	32	х	misc brickwork; clean-up			
Allied Construction, LLC	4	32		misc brickwork; clean-up			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders	3	24		Install doors and hardware in areas A & C			
Ellison Builders	3	24		Install doors and hardware in areas A & C			
Ellison Builders							
Malone All Star JV, LLC	19	95		work on overhead on E3; work on lights in kitchen, cafeteria & E1; work on elec in kitchen			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	18	144		work on overhead on E2; branch circuits in B1, E2 & E3; work on lights in cafeteria and classrooms on 1st floor			
Malone All Star JV, LLC							
Malone All Star JV, LLC	4	32		ADS - pull wire in D1 & E1			
Malone All Star JV, LLC	19	156	х	branch circuits @ kitchen, mechanical room & E3; work on lights in cafeteria & E1; mechanical equipment on roof of kitchen &			
Malone All Star JV, LLC				mezzanine; moved container			
Malone All Star JV, LLC  Malone All Star JV, LLC	4	32		ADS - pull wire in D1 & E1			
Malone All Star JV, LLC	19	156		ADS - pull wire in D1 & E1			
				branch circuits @ E3; work on lights in cafeteria; mechanical equipment on roof of kitchen & mezzanine; moved trailerr			
Malone All Star JV, LLC	2	16		Bonded - lightning protection on A, B & C			
Malone All Star JV, LLC	4	32		ADS - pull wire in D1 & E1			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							

Project:	Sherwood Forest Element 4801 Maid Marion Drive	tary Scho	ool			Job:	14-	02-002
Location:	4001 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	02/0	8/2016
Weather Dela	ays To Date:			Weather Condition:	sunny & windy	Day:	N	∕londay
Is Today Clair	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Work Effected?		N				38	56
Heritage Floorin	ng Inc.	9	81		demoing accent tile in girl's gang RR in C; prepping for grout in			
					D1 rr's; 2nd crew - working in north & south locker rooms			
Heritage Floorir	ng Inc.	13	126		Hector's crew (4) finished tiling gang restrooms in C1; Melissa's			
					crew (9) tiled the 3 restroom floors in D1, began tiling walls in			
					Girl's D1 gang, tiled and grouted in restrooms/locker rooms in C1			
Heritage Floorir	ng Inc.	13	126		Hector's crew (4) tiling gang restrooms in C1; Melissa's crew (9)			
					continue tiling walls in Girl's D1 gang, tiled and grouted in			
					restrooms/locker rooms in C1; working on wall tiles in 3 RR's in			
					D1			
Heritage Floorin	ng Inc.	14	132		Hector's crew (4) tiling gang restrooms in C1; Melissa's crew (10)			
					continue tiling walls in Girl's D1 gang, tiled and grouted in			
					restrooms/locker rooms in C1; working on wall tiles in 3 RR's in			
					D1			
Heritage Floorir	ng Inc.	14	132		Hector's crew (4) tiling gang restrooms in C1; Melissa's crew (10)			
					continue tiling walls in Girl's D1 gang, tiled and grouted in			
					restrooms/locker rooms in C1; working on wall tiles in 3 RR's in			
					D1			
		531	4338					

Remarks: 2 Bullet holes were found in the West Elevation of Area B glass. Police were called, no report yet.

Communication with Subcontractors: Brian with Phoenix did not show up.

Bubba was 20 minutes late.

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/	15/2016
Weather Dela	ays To Date:		Weather Condition:	partly cloudy/rain in afternoon	Day:	!	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				48	68

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:33-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:33-5:50) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:42-6:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-5:45) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:42-6:00) oversee site operation		
Marybeth Leonard								
Ellen Heck						(6:45-3:35) oversee site operation		
	Sub	Sub		2nd	2nd Tier			
Subcontractor	Wrkrs	Hrs	2nd Tier	Tier Wrkrs	Hrs	Work Accomplished	S	Q Sch

CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
CORE Construction Services, LLC				
Bernhard Mechanical Contractors, L.L.C.	13	104		cont overhead piping on D 2nd & 3rd floor; cont hooking up
				edf's; started up chiller and programed for start up; also started
				up units 6 & 8 in C to check them out
Bernhard Mechanical Contractors, L.L.C.	3	23	х	Atlas - misc duct work & install dishwash hood
Bernhard Mechanical Contractors, L.L.C.	9	72	х	ISS - repairing chill water on 2nd floor; insulating h/h/w on 2nd
				floor; insulating chill/h/h/w on 3rd floor
Bernhard Mechanical Contractors, L.L.C.	1	2		Synergy - starting AHU's 4, 5 &7

Project: Sherwood Forest Eleme 4801 Maid Marion Drive	=					Job: Report #:	14	-02-002 1
Fair Working Days To Date:						Date:	02/	16/2010
Weather Delays To Date:				Weather Condition:	sunny skies	Day:	-	Tuesday
s Today Claimed as Weather Day?		N	1	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		١	1				52	70
Bernhard Mechanical Contractors, L.L.C.	13	104	х		cont overhead piping on D 2nd & 3rd floor; began fixturing in			
					locker room restrooms			
Bernhard Mechanical Contractors, L.L.C.	4	30	Х		Atlas - finish dryer vent in girls C1 restroom; lay-in grilles in kitchen; received flex			
Bernhard Mechanical Contractors, L.L.C.	9	72	х		ISS -chill water & condensate drains on air handlers 1,2 & 3;			
					insulating h/h/w on 2nd floor; insulating chill/h/h/w on 3rd floor			
ernhard Mechanical Contractors, L.L.C.	1	5	х		Synergy - stairwell FCU's and RTU piping			
ernhard Mechanical Contractors, L.L.C.	15	120	х		cont overhead piping on D 2nd & 3rd floor; began fixturing in			
ernhard Mechanical Contractors, L.L.C.	4	30			locker room restrooms  Atlas - worked on louvers			
ernhard Mechanical Contractors, L.L.C.	9	72	х		ISS -chill water & condensate drains on air handlers 1,2 & 3;			
					insulating chill/h/h/w on 2nd & 3rd floor			
ernhard Mechanical Contractors, L.L.C.								
ernhard Mechanical Contractors, L.L.C.	13	104	Х		cont overhead piping on D 2nd & 3rd floor; fixturing in locker			
ernhard Mechanical Contractors, L.L.C.	4	30	х		room restrooms; hooking up fixtures in kitchen  Atlas - install flex in kitchen; installed flex and grilles in mock up			
·					offices on D2			
ernhard Mechanical Contractors, L.L.C.	8	64	х		ISS -finishing VAV on E3; finishing chill water on small air handler			
					on 3rd floor; insulating h/h/w in bathroom on 3rd floor; insulating domestic water on 2nd floor and repairing insulation all through			
					bldgs.			
rnhard Mechanical Contractors, L.L.C.								
rnhard Mechanical Contractors, L.L.C.	12	96	х		cont overhead piping on D 2nd & 3rd floor; fixturing in restrooms			
ernhard Mechanical Contractors, L.L.C.	2	15			in D1; hooking up fixtures in kitchen  Atlas - installing linear diffusers in stairwell and finishing up			
a	_	.5			diffusers in kitchen			
ernhard Mechanical Contractors, L.L.C.	7	56	х		ISS - insulating grills in admin offices on D2; H/h/w and vav in			
					admin on 2nd floor; insulating supply duct in maintenance room on 1st floor; repairing and touching up insulation on air handlers			
					for kitchen/cafeteria & gym			
ernhard Mechanical Contractors, L.L.C.	1	8	х		Synergy - pulling wire to exhaust fans			
ernhard Mechanical Contractors, L.L.C.								
ernhard Mechanical Contractors, L.L.C.								
ernhard Mechanical Contractors, L.L.C.								
ernhard Mechanical Contractors, L.L.C.								
&T Tile & Terrazzo Co. Inc.	3	24			grinding terrazzo in D			
&T Tile & Terrazzo Co. Inc.	3	12			finished grinding terrazzo in D2 and cleaned up			
&T Tile & Terrazzo Co. Inc.								
&T Tile & Terrazzo Co. Inc.								
&T Tile & Terrazzo Co. Inc.								
&T Tile & Terrazzo Co. Inc.								
restop International LLC	2	16			hanna and litina beigh anakad ika an kha adasiina akka anakada			
restop International LLC	2	16	.,		began caulking brick control jts on the exterior at the courtyard			
restop International LLC	2	16	х		caulking brick control jts on the exterior at the courtyard; smoke caulk on 2nd floor			
restop International LLC	2	16	х		caulking brick control jts on the exterior at the courtyard; smoke			
	_				caulk on 2nd floor			
restop International LLC	2	16	Х		caulking brick control jts on the exterior at the courtyard; smoke caulk on 2nd floor			
restop International LLC								
one Inc	2	8			finished up elevator for temporary use; scheduled inspection for			
					Wed or Thurs of this week with Carley			

Project: Sherwood Forest Elem	=	ol				Job:	14	1-02-002
<b>Location:</b> 4801 Maid Marion Driv	е					Report #:		1
Fair Working Days To Date:						Date:	02/	16/2016
Weather Delays To Date:		N		Weather Condition:	sunny skies	Day:		Tuesday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N					52	70
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Holi Services Inc	2	16			Eddie/ Mike - clean-up			
Holi Services Inc	2	16	Х		Eddie/ Mike - clean-up; unload materials			
Holi Services Inc	2	20	Х		Eddie/ Mike - clean-up; unload materials			
Holi Services Inc	2	19			Eddie/ Mike - clean-up; unload materials			
Holi Services Inc	2	13	Х		Eddie/ Mike - clean-up; unload materials			
Holi Services Inc								
Morris Drywall Systems Inc	15	135	Х		clean-up; rock 3rd; frame canopy @ loading dock; unload material			
Morris Drywall Systems Inc	14	112			clean-up; rock 3rd; install sheathing at courtyard canopy; install			
Morris Drywall Systems Inc	17	170	х		grid in dishwash room clean-up; rock 3rd in science rooms			
Morris Drywall Systems Inc	15	135	х		clean-up; rock 3rd in science rooms			
Morris Drywall Systems Inc	16	128			clean-up; rock 3rd in lab & misc. rooms; installing grid on 2nd floor			
Morris Drywall Systems Inc								
New Orleans Glass Company, Inc.	5	40	х		install angles and panels between windows in courtyard			
New Orleans Glass Company, Inc.	4	32	х		install angles and panels between windows in courtyard			
New Orleans Glass Company, Inc.	3	24	х		install angles and caulk breakmetal			
New Orleans Glass Company, Inc.	3	24	х		install angles and caulk breakmetal			
New Orleans Glass Company, Inc.	6	48	х		install angles and caulk breakmetal; set last piece of glass on 3rd floor @ D3			
New Orleans Glass Company, Inc.								
Phoenix Constructors LLC	5	40			grade dirt; erosion control			
Phoenix Constructors LLC	5	40			cut dirt at east end of north drive; repair storm line that Cordeiro broke at east end of north drive			
Phoenix Constructors LLC	4	32			cut dirt at east end of north drive; proof roll southeast section of north parking lot			
Phoenix Constructors LLC	6	57	х		cut dirt at south end of west drive; add dirt at bus lane in SE section of north parking lot.			
Phoenix Constructors LLC	7	56	х		past proof roll of south end of west drive; graded SE section of north paving area			
Phoenix Constructors LLC	9	54			installed filter fabric and sand @ south end of west drive; finished grading SE section of north paving; dressed up site; demoed sidewalk along Maid Marion			
Cordeiro LLC	5	35			moved mats; organize materials			
Cordeiro LLC	5	35	х		rub columns; prep light standards (2 at east end of north drive and 1 at south end of west drive)			
Cordeiro LLC	9	80	х		prep/pour 3 light standards; rub walls & columns; move materials			
Cordeiro LLC	8	48	х		wreck 3 light standards; rub walls & columns; form at SE section of north paving			
Cordeiro LLC	8	32	х		rubbed concrete by ramp @ area E			
Cordeiro LLC								
Rufino`s Painting & Construction Inc.	10	80	х		prime; taping/floating & priming on 2nd & 3rd floors			
Rufino`s Painting & Construction Inc.	11	88	х		prime; taping/floating & priming on 2nd & 3rd floors			
Dufine's Deletion & Construction to	12	00						

prime; taping/floating & priming on 2nd & 3rd floors

Rufino's Painting & Construction Inc.

12 96 x

Project: Location:	Sherwood Forest Elementar 4801 Maid Marion Drive	ry Scho	ool				Job: Report #:	14-	02-002 1
	Dave To Date:						Date:	02/1	8/2016
_	Days To Date:				Weather Condition:	sunny skies	Day:		ursday
Weather Dela	ned as Weather Day?		Ν	1	Precipitation Amount:	samy sixes	-	Low	-
-	Work Effected?		N		recipitation Amount.		Temp:	54	High 69
	g & Construction Inc.	12	96	х		prime; taping/floating & priming on 3rd floors; patching &			
Namio 31 aman	g & construction me.		30	^		painting in gym			
Rufino`s Paintin	g & Construction Inc.	11	88	х		prime; taping/floating & priming on 3rd floors; patching & painting in gym			
Rufino`s Paintin	g & Construction Inc.								
Peachtree Prote	ective Covers								
Peachtree Prote	ective Covers								
Peachtree Prote	ective Covers								
Peachtree Prote	ective Covers								
Peachtree Prote	ective Covers								
Peachtree Prote	ective Covers								
Quality Iron Fab	oricators Inc.								
Quality Iron Fab	oricators Inc.								
Quality Iron Fab	oricators Inc.								
Quality Iron Fab	oricators Inc.								
Quality Iron Fab	oricators Inc.								
Quality Iron Fab	oricators Inc.								
River City Fire P	rotection								
River City Fire P	rotection								
River City Fire P	rotection								
River City Fire P	rotection								
River City Fire P	rotection								
River City Fire P	rotection								
Roofing Solutio	ns LLC	10	90	х		working on west elevations with panels & installing panels on north side of $\ensuremath{gym}$			
Roofing Solutio	ns LLC	8	64	х		Sheet metal guys installing coping/cleats & counter flashing			
Roofing Solutio	ns LLC	8	72	х		working on west elevations with panels & installing panels on north side of $\operatorname{gym}$			
Roofing Solutio	ns LLC								
Roofing Solutio		8	72	х		working on west elevations with panels & installing panels on north side of gym			
Roofing Solutio									
Roofing Solutio	ns LLC	8	72	х		working on west elevations with panels & installing panels on north side of gym			
Roofing Solutio									
Roofing Solutio	ns LLC	9	72	Х		working on west elevations with panels $\&$ installing panels on north side of $\mbox{\rm gym}$			
Roofing Solutio									
Roofing Solutio	ns LLC	9	72			installing hat channels & began soffit panels @ main entrance; working on west elevations with panels & installing panels on north side of gym			
Roofing Solutio	ns LLC								
Multivista Cons	truction Documentation								
Multivista Cons	truction Documentation								
Multivista Cons	truction Documentation								
Multivista Cons	truction Documentation	1	1			took progress photos			
Multivista Cons	truction Documentation								
Multivista Cons	truction Documentation								
Alack Refrigerat	ion Company								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	02/1	6/2016
Fair Working Days To Date:			\\\+hC	sunny skies	Day:		uesday
Weather Delays To Date: Is Today Claimed as Weather Day?		N	Weather Condition: Precipitation Amount:	suriny sixes	-		-
Critical Path Work Effected?		N	r recipitation Amount.		Temp:	Low 52	High 70
Alack Refrigeration Company	2	12		Unloaded more kitchen equipment and set convection		32	
				oven/steamer, range, ice machine, & 3 compartment stainless steel tables			
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC	4	32	х	finished removing brick @ main entry to allow to waterproof; clean-up; demo and began replacing 3 sills above south eyebrow of E			
Allied Construction, LLC	3	24		demo sills above south eyebrow			
Allied Construction, LLC	3	24		reinstall brick sills above south eyebrow; remove materials from site			
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	2		take densities of stom line backfill; did proof roll on portion of			
Gulf South Engineering & Testing Inc				north paving			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	1		took densities			
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	25	190	х	branch circuits @ E2 & E3; work on lights in D1, gang bath &			
Malone All Star JV, LLC				cafeteria; worked on wiring up the mini-splits on the roof			
Malone All Star JV, LLC							
Malone All Star JV, LLC	17	136	х	branch circuits @ E2 & E3; overhead in E3; work on lights in cafeteria, canopy and watt stopper			
Malone All Star JV, LLC	2	16	X	ADS - pull wire			
Malone All Star JV, LLC							
Malone All Star JV, LLC	21	168	x	branch circuits @ E2 & E3; overhead in E3; work on lights in cooler/freezer& canopy; install watt stopper; wire mini splits on roof			
Malone All Star JV, LLC							
Malone All Star JV, LLC							

Project:	Sherwood Forest Element	ary Scho	ool				Job:	14-	-02-002
Location:	4801 Maid Marion Drive						Report #:		1
Fair Working	Days To Date:						Date:	02/1	18/2016
Weather Del	ays To Date:				Weather Condition:	sunny skies	Day:	TI	hursday
Is Today Clai	med as Weather Day?		Ν	1	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N	1				54	69
Malone All Star	· JV, LLC	20	160	х		branch circuits @ E2 & E3; trim out mock up offices on D2; work on cooler/freezer; lights at entrance canopy; install watt stopper; wire mini splits on roof			
Malone All Star	· JV, LLC	2	16	х		Data - install data outlets on D2 in mock up offices			
Malone All Star	JV, LLC	2	16	x		ADS - pulling wire			
Malone All Star	· JV, LLC	21	168	х		branch circuits @ mmedia center & music room; trim out mock up offices on D2; lights at loading dock canopy & D1 classrooms; install lamps in locker rooms & kitchen			
Malone All Star	· JV, LLC	2	16	х		Data - pulling wire for WAP's			
Malone All Star	· JV, LLC	1	1			ADS - installed 1 smoke detector in ahu #4			
Malone All Star	· JV, LLC								
Malone All Star	JV, LLC								
Malone All Star	JV, LLC								
Heritage Floori	ng Inc.	14	132			Hector's crew (2) grouting in kitchen RR; Melissa's crew (10) continue tiling walls in Girl's D1 gang; working on wall tiles in 3 RR's in D1			
Heritage Floori	ng Inc.	13	122	x		Hector's crew (5) grouting in kitchen RR and RR across from gang RR's in D1; Melissa's crew (8) continue tiling walls in Girl's D1 gang; grouting wall tiles in 3 RR's in D1; began laying floor tile in E1			
Heritage Floori	ng Inc.	13	122			Hector's crew (2) grout restroom in D1 by shower; Melissa's crew (11) tiling walls in Boyl's D1 gang;laying floor tile in E1; began wall tile on D2			
Heritage Floori	ng Inc.	11	99	х		Hector's crew (3) grout restroom in D236; Melissa's crew (8) tiling walls in Boyl's D1 gang;laying wall tile in E1; install wall tile on D2			
Heritage Floori	ng Inc.	11	99			Hector's crew (3) grout restroom in D236; Melissa's crew (8) tiling			
						walls in Boyl's D1 gang;laying wall tile in E1; install wall tile on D2			
Heritage Floori	ng Inc.	4	22			Hector's crew (2) grouted restroom inC103 & began grouting in C104; Melissa's crew (2)finished laying tile in gang restrooms on			
				_		D2			
		633	5097						

Remarks:

**Inspections:** Gulf South came and took densities at south end of west paving

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/7	22/2016
Weather Dela	ays To Date:		Weather Condition:	cloudy with rain in afternoon	Day:	ı	Monday
Is Today Clair	med as Weather Day?	Υ	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				57	68

Employee						Work Accomplished
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:25-5:30) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(5:35-5:00) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(5:45-5:00) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(5:45-4:15) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(5:45-4:35) oversee site operation
Marybeth Leonard						
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished S Q Sch
	4	22				Academic ? - received and unloaded science casework
	8	64				New Academic - hauled science casework to 3rd floor
	8	64				New Academic - hauled science casework to 3rd floor
	8	64	х			Protech - unloaded millwork
	7	56				Protech - distribute millwork to 2nd floor
CORE Construction Services, LLC	3	28				Rafael - clean-up/protect floors; Slim & Pops- clean-up;
CORE Construction Services, LLC	3	26				waterproof Rafael, Slim & Pops- began moving doors to 2nd floor; clean-up
CORE Construction Services, LLC	2	16				Rafael - install protection bds on elevator; Pops- clean-up
CORE Construction Services, LLC	2	16				Rafael - cut out sheetrock for FE cabinets; Pops- clean-up; Slim -
						move dumpsters & materials
CORE Construction Services, LLC	2	16				Rafael - cut out sheetrock & brick for canopy; Pops- clean-up;
CORE Construction Services, LLC	3	24				Slim - move dumpsters & materials Rafael - move doors to 3; Pops & Slim - cut lintels
· · · · · · · · · · · · · · · · · · ·						
Bernhard Mechanical Contractors, L.L.C.	14	112	X			cont overhead piping on D 2nd & 3rd floor; moving fixtures out
			х			of container to inside bldg
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	14 3 4	112 23 32	x x x			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	=	ool				Job: Report #:	14	-02-002 1
Fair Working Days To Date:						Date:	02/	22/2016
Weather Delays To Date:				Weather Condition:	cloudy with rain in afternoon	Day:		Monday
ls Today Claimed as Weather Day?		Y	,	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		١	1				57	68
Bernhard Mechanical Contractors, L.L.C.	5	28	Х		Synergy - pulling wire to exhaust fans & RTU's			
Bernhard Mechanical Contractors, L.L.C.	10	80			cont overhead piping on D 2nd & 3rd floor; moving fixtures out of container to inside bldg			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	4	32			ISS - install color coding jackets on air handlers on 1st & 2nd floors; insulating h/h/w and domestic water on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	4	32			Synergy - pulling wire on 3rd floor; mounting ahu devices; working on VAV's			
Bernhard Mechanical Contractors, L.L.C.	10	80			cont overhead piping on D 2nd & 3rd floor; hauling off fixtures that were wrong			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	4	32			ISS - install color coding jackets on air handlers on 1st & 2nd floors; insulating h/h/w and domestic water on 2nd floor; diffuser backs on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	4	32			Synergy - pulling wire on 3rd floor; 3rd floor termination			
Bernhard Mechanical Contractors, L.L.C.	12	96	х		cont overhead piping on D 2nd & 3rd floor			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	4	32			ISS - install color coding jackets on chill & h/h./w in mechanical rooms; insulating h/h/w and domestic water on 2nd floor;repairing damaged insulation on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	4	32	х		Synergy - pulling wire on 3rd floor; 3rd floor termination			
Bernhard Mechanical Contractors, L.L.C.	13	104			cont overhead piping on D 2nd & 3rd floor; start up of boiler and AHU's in A, B $$ & C $$			
Bernhard Mechanical Contractors, L.L.C.	3	23			Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	3	24			ISS - insulating h/h/w in band room 2nd floor; starting on air handler's on roof			
Bernhard Mechanical Contractors, L.L.C.	5	40			Synergy - pulling wire on RTU's and EF's; VAV start-up			
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
D&T Tile & Terrazzo Co. Inc.								
Firestop International LLC								
Firestop International LLC								
Firestop International LLC								
Firestop International LLC								
Firestop International LLC	1	8			installing brick caulking			
irestop International LLC								
Cone Inc								
Cone Inc								
Cone Inc								
Kone Inc								
Kone Inc								
Kone Inc								

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	itary Scho	)OI			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	02/	22/2016
Weather Delays To Date:			Weather Condition:	cloudy with rain in afternoon	Day:		Monday
s Today Claimed as Weather Day?		Υ	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				57	68
Holi Services Inc	2	19		Eddie/ Mike - clean-up			
Holi Services Inc	2	18		Eddie - monitor mud on Robin Hood due to concrete pour and clean-up; Mike - clean-up			
Holi Services Inc	2	16		Eddie - clean-up; Mike - clean-up			
Holi Services Inc	2	16		Eddie - clean-up; Mike - clean-up			
Holi Services Inc	2	15		Eddie - clean-up; Mike - clean-up			
Holi Services Inc	1	8		Eddie - move doors to 2nd & 3rd floors,clean-up			
Morris Drywall Systems Inc	15	136	х	clean-up; rock 3rd in lab & misc. rooms; installing grid on 2nd floor			
Morris Drywall Systems Inc	15	136		clean-up; rock 3rd in lab & misc. rooms; installing grid on 2nd floor			
Morris Drywall Systems Inc	15	136		clean-up; misc. rooms on 3rd floor; rock RR ceiling in C1; installing grid on 2nd floor			
Morris Drywall Systems Inc	15	136	x	clean-up; misc. rooms on 3rd floor; rock RR ceiling in C1; installing grid on 2nd floor; work on caulking smoke walls			
Morris Drywall Systems Inc	15	136		clean-up; misc. rooms on 3rd floor; rock RR ceiling in C1; installing grid on 2nd floor; work on caulking smoke walls			
Morris Drywall Systems Inc	2	6		haul off material			
New Orleans Glass Company, Inc.	5	40	X	set fire glass at main stairs; install breakmetal & caulk			
New Orleans Glass Company, Inc.	3	23		set fire glass at main stairs			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	8	48		graded out south end of west drive and hauled off materials			
Phoenix Constructors LLC	8	36		graded out south end of west drive and hauled off materials			
Phoenix Constructors LLC	7	67		graded out south end of west drive and cutting dirt $@$ east side of north drive			
Phoenix Constructors LLC	8	36		graded out south end of west drive and cutting dirt $@$ east side of north drive			
Phoenix Constructors LLC	8	36		graded out south end of west drive and cutting dirt @ east side of north drive			
Phoenix Constructors LLC	3	24		cutting dirt @ east side of north drive; work dirt on south & east sides			
Cordeiro LLC	8	32	х	installed forms @ south end of west drive; finished prepping SE section of north paving			
Cordeiro LLC	9	77		installed forms @ south end of west drive; finished prepping SE section of north paving			
Cordeiro LLC	6	45		clean-up; prepping @ south end of west drive			
Cordeiro LLC	9	36	X	clean-up			
Cordeiro LLC	8	64		prep south end of west drive			
Cordeiro LLC							
Rufino's Painting & Construction Inc.	10	80		prime; taping/floating & priming on 3rd floors; patching & painting in gym			
Rufino's Painting & Construction Inc.	10	80		prime; taping/floating & priming on 3rd floors			
Rufino`s Painting & Construction Inc.	11	88		prime; taping/floating & priming on 3rd floors			
Rufino`s Painting & Construction Inc.	11	88	X	prime; taping/floating & priming on 3rd floors; touching up			
Rufino`s Painting & Construction Inc.	11	88		beams in gym prime; taping/floating & priming on 3rd floors; touching up			
Rufino's Painting & Construction Inc.	4	32		beams in gym prime; taping/floating & priming on 3rd floors; touching up beams in gym			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:		1-02-002
Fair Working Days To Date:					Date:		22/2016
Weather Delays To Date:			Weather Condition:	cloudy with rain in afternoon	Day:		Monday
Is Today Claimed as Weather Day?		Y	recipitation Amount.		Temp:	Low	High
Critical Path Work Effected?		٨				57	68
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers	3	24		installed framing at gym canopy			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC	9	81	х	working on west elevations with panels & installing panels on north side of gym; finished hat channels @ main entry and began soffit panels.			
Roofing Solutions LLC							
Roofing Solutions LLC	9	86		working on west elevations with panels & installing panels on north side of gym; fixed hat channels @ main entry and installing soffit panels.			
Roofing Solutions LLC							
Roofing Solutions LLC	9	81		working on west elevations with panels; installing trim and beginning soffit panels @ loading dock			
Roofing Solutions LLC							
Roofing Solutions LLC	9	81	X	working on west elevations with panels; installing trim and soffit panels @ loading dock			
Roofing Solutions LLC				panels & loading dock			
Roofing Solutions LLC	9	81		working on east elevations with panels by loading dock; installing trim and soffit panels @ loading dock			
Roofing Solutions LLC							
Roofing Solutions LLC	9	81		working on east elevations with panels by loading dock; installing trim and soffit panels @ loading dock			
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							

Alack Refrigeration Company

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/2	26/2016
Weather Delay	ys To Date:		Weather Condition:	sunny	Day:		Friday
Is Today Claim	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path W	Vork Effected?	N				45	68
Alack Refrigerati	on Company						

Alack Refrigeration Company				
Alack Refrigeration Company				
Allied Construction, LLC				
Allied Construction, LLC				
Allied Construction, LLC				
Allied Construction, LLC				
Allied Construction, LLC				
Allied Construction, LLC				
CFI Insulation Inc				
CFI Insulation Inc				
CFI Insulation Inc				
CFI Insulation Inc				
CFI Insulation Inc				
CFI Insulation Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Ellison Builders	4	32		hung doors & installed hardware in A & C
Ellison Builders	4	32		hung doors and installed hardware in D2 mock-up rooms; began
				installing fire extinguishers
Ellison Builders				
Malone All Star JV, LLC	20	160	х	branch circuits E3; install lights @ E2 & D1; watt stopper; rough in
Malone All Star JV, LLC				light @ loading dock
Malone All Star JV, LLC	3	24	x	ADS - pulling wire in audio room by stage
Malone All Star JV, LLC	18	144		branch circuits E2 & C1; install lights @ E2; wire in mini-splits;
Malone All Star JV, LLC				teminate panels
Malone All Star JV, LLC				
Malone All Star JV, LLC	19	152		branch circuits E2, E3 & C1; install lights @ E2, cafeteria and gang
	.,	.52		RR's; trim out kitchen, cafeteria, watt stopper
Malone All Star JV, LLC				
Malone All Star JV, LLC	2	16		Bonded - installing lightning protection on A, B & C
Malone All Star JV, LLC	20	160	x	branch circuits E2, E3 & C1; install lights @ E2, cafeteria and gang
				RR's; trim outgym; watt stopper
Malone All Star JV, LLC				
Malone All Star JV, LLC				
Malone All Star JV, LLC	19	162		branch circuits E3 & C1; install lights @ E2,install duct detectors; install lights on E2, C, & D2
Malone All Star JV, LLC				
Malone All Star JV, LLC				
Malone All Star JV, LLC				

Project:	Sherwood Forest Elemen	tary Scho	ool				Job:	14-	-02-002
Location:	4801 Maid Marion Drive						Report #:		1
Fair Working	Days To Date:						Date:	02/2	27/2016
Weather Del	•				Weather Condition:	sunny	Day:	S	aturday
	med as Weather Day?		N	1	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		Ν	1	·		•	48	65
Malone All Star	r JV, LLC								
Malone All Star	r JV, LLC								
Heritage Floori	ng Inc.	11	99			Hector's crew (2) grout restroom in C104; Melissa's crew (9) tiling walls in Boyl's D3 gang;laying wall tile in E1			
Heritage Floori	ng Inc.	12	110			Hector's crew (2) grout restroom in C104 & installed last 2 rows of tile; Melissa's crew (10) tiling walls in Boyl's D3 gang;laying wall tile in E1			
Heritage Floori	ng Inc.	12	110			Hector's crew (2) grout restroom in C104 & installed last 2 rows of tile; Melissa's crew (10) tiling walls in Boy's & Girl's D3 gang;laying wall tile in E1; grouting walls in E1 and D2 gang RR's			
Heritage Floori	ng Inc.	12	91	х		Hector's crew (2) finished installing tile & grouting in all of the RR's they were doing; Melissa's crew (9) tiling walls in Boy's & Girl's D3 gang;laying wall tile in E1; grouting walls in E1 and D2 gang RR's			
Heritage Floori	ng Inc.	11	99			Hector's crew (2) installed base and grouted in kitchen and finished up RR in D2; Melissa's crew (9) tiling walls in Boy's & Girl's D3 gang;laying wall tile in E1; grouting walls in E1 and D2 gang RR's			
Heritage Floori	ng Inc.	5	40			Melissa's crew (9) tiling walls in Boy's & Girl's D3 gang;laying wall			
				_		tile in E1; grouting walls in E1 and D2 gang RR's			
		630	5046						

Remarks:

Project:	Sherwood Forest Elementary School				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	02/2	29/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	V	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				59	75

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(5:50-5:40) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-6:15) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45-5:10) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-4:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-3:45) oversee site operation		
Marybeth Leonard								
		٠.		2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
	3	12		WINIS	- 1113	GC Specialties		
	2	16				Protech - began installing millwork in classrooms on 2nd floor		
	2	16				Protech - began installing millwork in classrooms on 2nd floor		
	2	16				Protech - began installing millwork in classrooms on 1st floor		
						Covington- received and unloaded materials and began prepping		
	2	16				gym floor  Covington - began installing pad on floor		
	3	24				Covington - work on gym floor		
CORE Construction Services, LLC	3	27	x			Rafael - cut out sheetrock for fire extinguisher cabinets/ relocated 2 stacks of doors; worked on ladder cage; Pops & Slim - cut lintels at exterior of stairs D & E		
CORE Construction Services, LLC	3	27				Rafael - worked on roof ladders; Pops & Slim - cut last lintel at stair E		

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	03/0	)2/2016
Weather Delays To Date:			Weather Condition:	sunshine	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				52	67
CORE Construction Services, LLC	3	27		Rafael - wall expansion joints; Pops - clean basketball goals &			
CORE Construction Services, LLC	3	25		Slim - break out for pilaster at main entry canopy  Rafael - wall expansion joints/remove brick for clips for entrance  canopy; Pops - clean windows in gym; Slim - prep & pour pilaster  at main entry canopy			
CORE Construction Services, LLC	3	24		Rafael - help clean chiller roof; Pops - clean chiller roof; Slim - relocate rebar and power wash low roof of D			
CORE Construction Services, LLC							
Bernhard Mechanical Contractors, L.L.C.	14	104 x		cont overhead piping on D 2nd $\&$ 3rd floor; continue to run pipe to units on D $\&$ E roof			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - installing flex and diffusers on 1st floor on stage			
Bernhard Mechanical Contractors, L.L.C.	4	32 x		ISS - insulating fresh air duct in kitchen & chilled water in E3			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	14	104		cont overhead piping on D 2nd $\&$ 3rd floor; continue to run pipe to units on D $\&$ E roof			
Bernhard Mechanical Contractors, L.L.C.	3	23		Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - insulating domestic water, & h/h/w 2nd floor; chill water tie-in to roof top units; 3rd floor inatalling color jacket on piping			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	10	80		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; began piping in roof drains at area B			
Bernhard Mechanical Contractors, L.L.C.	2	16		Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - insulating grill's in classrooms; domestic hot/cold water on 2nd flnishing up installing color jacket on hot/cold chill water lines in mech rooms			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	10	80		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; installed clips for Core to support main entrance low canopy			
Bernhard Mechanical Contractors, L.L.C.	2	16		Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - insulating grill's in classrooms; domestic hot/cold water on 2nd flnishing up installing color jacket on hot/cold chill water lines in mech rooms			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	13	104		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; hook up 3 compartment sink and ice maker in kitchen			
Bernhard Mechanical Contractors, L.L.C.	2	16		Atlas - installing flex and diffusers on 1st floor; move materials			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - vav's on 2nd floor; insulating grilles in cafeteria; flnishing up installing color jacket on hot/cold chill water lines in mech rooms			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							

Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ary Schoo	ol				Job: Report #:	14-	-02-002 1
Fair Working Days To Date:						Date:	02/2	29/2016
Weather Delays To Date:				Weather Condition:	sunny	Day:	N	Monday
Is Today Claimed as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν					59	75
Firestop International LLC	2	16	х		installing brick caulking			
Firestop International LLC	3	24			installing brick caulking			
Firestop International LLC	2	16			installing brick caulking			
Firestop International LLC								
Firestop International LLC								
Firestop International LLC								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Holi Services Inc	2	17	х		Eddie - clean-up; Mike - clean-up			
Holi Services Inc	2	18			Eddie - clean-up; Mike - clean-up			
Holi Services Inc	2	17			Eddie - clean basket goals ; Mike - clean-up			
Holi Services Inc	2	16			Eddie - help clean windows in gym/misc ; Mike - clean-up			
Holi Services Inc	2	16			Eddie - work with Slim ; Mike - clean-up chiller roof			
Holi Services Inc								
Morris Drywall Systems Inc	10	90	х		clean-up; rock misc. rooms on 3rd floor; installing grid on 2nd			
Morris Drywall Systems Inc	10	90			floor; install blocking for Peachtree canopy @ gym storage clean-up; rock misc. rooms on all floors; installing grid on 2nd floor			
Morris Drywall Systems Inc	9	81			clean-up; rock misc. rooms on all floors; installing grid on 2nd floor			
Morris Drywall Systems Inc	12	108			clean-up; rock misc. rooms on all floors; installing grid on 2nd floor			
Morris Drywall Systems Inc	10	80			clean-up; rock misc. rooms on all floors; installing grid on 3rd floor			
Morris Drywall Systems Inc	7	56			insulate/install strapping @ dense glass @ car drop off canopy			
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
New Orleans Glass Company, Inc.								
Phoenix Constructors LLC	5	40			cutting/hauling dirt @ east side of north drive & did a proof roll of that area			
Phoenix Constructors LLC	5	50			installed fabric and sand at east end of north parking and worked with Corderio @ SW at south end of west drive; installed inverts in catch basins in courtyard			
Phoenix Constructors LLC	5	50			installed fabric and sand at east end of north parking and worked with Corderio @ SW at south end of west drive			
Phoenix Constructors LLC	5	50			installed sand and graded at east end of north parking			
Phoenix Constructors LLC	5	40			installed sand and graded at east end of north parking			
Phoenix Constructors LLC								
Cordeiro LLC	9	72	х		pour south end of west drive and east end of bus lane along with curb at north paving			
Cordeiro LLC	7	56			prep sidewalk along south end of west drive; wreck forms			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-	02-002
Fair Working Days To Date:					Date:	03/0	2/2016
Weather Delays To Date:			Weather Condition:	sunshine	Day:	Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	•		<b>p</b> .	52	67
Cordeiro LLC	7	56		pour sidewalk along south end of west drive; began			
60.46.10 226	•	30		prepping/forming north paving in NE corner			
Cordeiro LLC	7	56		pour sidewalk along south end of west drive; began			
				prepping/forming north paving in NE corner			
Cordeiro LLC	7	56		prepping/forming north paving in NE corner; wreck forms and clean-up			
Cordeiro LLC				clean up			
ProTech Fixture & Display LLC	2	16		installing millwork in classrooms on 1st floor			
ProTech Fixture & Display LLC							
Rufino's Painting & Construction Inc.	10	80 x		prime; taping/floating & priming on 3rd floors; touching up beams in gym			
Rufino's Painting & Construction Inc.	10	80		prime; taping/floating & priming on 3rd floors; touching up beams in gym			
Rufino's Painting & Construction Inc.	11	88		prime; taping/floating & priming on 3rd floors; touching up beams in gym			
Rufino's Painting & Construction Inc.	11	88		prime; taping/floating & priming on 3rd floors; touching up beams in gym			
Rufino's Painting & Construction Inc.	10	80		prime; taping/floating & priming on 3rd floors and misc. sheetrock ceilings			
Rufino's Painting & Construction Inc.							
Peachtree Protective Covers	3	30 s		continue to frame canopy @ gym and began deck installation			
Peachtree Protective Covers	3	30		continue to frame canopy @ gym and began deck installation			
Peachtree Protective Covers	3	30		continue to frame canopy @ gym and began deck installation			
Peachtree Protective Covers	3	30		hung small canopies in courtyard and finished canopy @ gym except for continuous plate next to wall; began standing supports at main entrance canopy			
Peachtree Protective Covers				• • • • • • • • • • • • • • • • • • • •			
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection	3	24		install heads at car drop off			
River City Fire Protection	2	16					
River City Fire Protection	3	24		finished instalingl heads at car drop off and worked in cafeteria installed heads			
,							
Roofing Solutions LLC	9	81		working on east elevations with panels by loading dock; installing trim and soffit panels @ loading dock; install panels at south elevation of B			
Roofing Solutions LLC							
Roofing Solutions LLC	2	16		working on north elevation at west end of gym and worked on loading dock canopy			
Roofing Solutions LLC	5	40					
Roofing Solutions LLC	3	24		worked on loading dock canopy			
Roofing Solutions LLC							
Roofing Solutions LLC	3	24		installed panels at east elevation of stairs @ E			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	03/0	03/2016
Weather Delays To Date:			Weather Condition:	cloudy	Day:	TI	hursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	•			54	76
Roofing Solutions LLC							
Roofing Solutions LLC	3	24		installed panels at south elevation of stairs @ E			
Roofing Solutions LLC				·			
Roofing Solutions LLC							
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company	5	22		3 guys installed dishwasher and SS dishwash counters; Fire &			
Alack Refrigeration Company				Safety Commodoties (2 guys) installed ansul system			
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC	2	2		cut brick for louver at D310			
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc	1	5		slumped concrete and took cylinders of concrete and then came back and witnessed proof roll of sub-grade at east end of north paving			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Malone All Star JV, LLC	17	136 x		branch circuits E3; terminate mini-splits; install lights on E2			
				classrooms and canopy at car drop off; install watt stopper			
14 L AUG: D/11G	-	40					

Data - delivered reals of cat 6 cable

Malone All Star JV, LLC

5 10

Project: Sherwood Forest Elementa	ary Scho	ool			Job:	14-	02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	02/2	9/2016
Weather Delays To Date:			Weather Condition:	sunny	Day:	M	1onday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				59	75
Malone All Star JV, LLC				Bonded - worked on D & E high roof			
Malone All Star JV, LLC	19	152		branch circuits E2; install lights on E2 classrooms and canopy at car drop off; install watt stopper; trim-out in A, B & C			
Malone All Star JV, LLC	6	48		Data - pulling cat 6 cables; terminate cables			
Malone All Star JV, LLC				ADS- worked on installing devices on 1st floor and pulling wire on 2nd floor			
Malone All Star JV, LLC	19	152		branch circuits E3; install lights on E2 classrooms and canopy at car drop off; install watt stopper; trim-out i nD1			
Malone All Star JV, LLC	7	56		Data - pulling cat 6 cables; terminate cables			
Malone All Star JV, LLC							
Malone All Star JV, LLC	20	160		branch circuits E3; terminate panels in E2; install lights in D1 & E2 and canopy at car drop off; trim-out i nD1			
Malone All Star JV, LLC	8	64		Data - pulling cat 6 cables; terminate cables; dress up cable runs			
Malone All Star JV, LLC							
Malone All Star JV, LLC	20	160		branch circuits E2 & E3; install lights in D1 & E2; trim-out i nD1; wattstopper			
Malone All Star JV, LLC	5	40		Data - pulling cat 6 cables; terminate cables; dress up cable runs			
Malone All Star JV, LLC	4	321		ADS - pull wire on 2nd floor; pull wire for cameras			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Heritage Flooring Inc.	5	48	· ·	Melissa's crew - tiling walls in Boy's & Girl's D3 gang;laying wall tile in E1; grouting walls in E1 and D2 boy's gang RR; repairing tile on walls in girl's gang in D2			
Heritage Flooring Inc.	7	67		Melissa's crew - finished tiling walls in Girl's D2 gang;grouting wall tile in E1; finished tiling gang restrooms on D3			
Heritage Flooring Inc.	7	67		Melissa's crew - finished tiling walls in Girl's D2 gang;grouting wall tile in E1; finished tiling gang restrooms on D3			
Heritage Flooring Inc.	4	32		Melissa's crew - finished tiling walls in Girl's D2 gang; grouting gang restrooms on D3			
Heritage Flooring Inc.	4	32		Melissa's crew - finished tiling walls in Girl's D2 gang; grouting			
Heritage Flooring Inc.	5	38		gang restrooms on D3 Melissa's crew - tile RR in D2			
	524	4529					

## Remarks:

Communication with Subcontractors: Met with Heritage and went over schedule.

Inspections: Glenn Tregre

Visitors: Lee Stansbury - checked out Willow tree on Maid Marion

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	03,	/07/2016
Weather Dela	ays To Date:		Weather Condition:	mostly sunny	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				65	76

**Work Accomplished** 

Ellen Heck						(6:00-5:50) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:40-5:40) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(5:33-4:15) oversee site operation		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:55-3:30) oversee site operation		
Marybeth Leonard								
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished	s	Q Sch
Subcontractor			Ziid iiei	Wrkrs	Hrs	·		
	2	18 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor		
	3					Covington - continueing to install gym nool		
		2/						
		27 27				Covington - continueing to install gym floor		
	3	27 27 16				Covington - continueing to install gym floor  Covington - continueing to install gym floor		
CORE Construction Services, LLC	3	27				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor		
CORE Construction Services, LLC	3 2	27 16				Covington - continueing to install gym floor  Covington - continueing to install gym floor		
CORE Construction Services, LLC CORE Construction Services, LLC	3 2	27 16				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard		
	3 2 3	27 16 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room		
CORE Construction Services, LLC	3 2 3	27 16 24 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard		
CORE Construction Services, LLC	3 2 3	27 16 24 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard		
CORE Construction Services, LLC CORE Construction Services, LLC	3 2 3 3	27 16 24 24 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	3 2 3 3 3	27 16 24 24 24 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	3 2 3 3 3 3 2 13	27 16 24 24 24 24 24				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour  Slim & Pop- cut plate; clean-up		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 2 3 3 3 3 2 13	27 16 24 24 24 24 24 16 104				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour  Slim & Pop- cut plate; clean-up  cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; began fixtures in area C gang RR's  Atlas - installing flex and diffusers on 1st floor; move materials		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.	3 2 3 3 3 3 2 13	27 16 24 24 24 24 24 16 104				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour  Slim & Pop- cut plate; clean-up  cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; began fixtures in area C gang RR's  Atlas - installing flex and diffusers on 1st floor; move materials  ISS - vav's on 2nd floor, insulating h/h/w 2nd floor and in chase;		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 2 3 3 3 3 2 13	27 16 24 24 24 24 24 16 104				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour  Slim & Pop- cut plate; clean-up  cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; began fixtures in area C gang RR's  Atlas - installing flex and diffusers on 1st floor; move materials		
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 2 3 3 3 3 2 13	27 16 24 24 24 24 24 16 104				Covington - continueing to install gym floor  Covington - continueing to install gym floor  Covington - painting striping/complete gym floor  Rafael - work on; Pops - clean yard; Slim - clean yard and cut clips at brick angle at main entry  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and install allthread support for operable wall in music room  Rafael - install expansion joint; Pops - clean yard; Slim - clean yard and all helped get east approach ready to pour  Slim & Pop- cut plate; clean-up  cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; began fixtures in area C gang RR's  Atlas - installing flex and diffusers on 1st floor; move materials  ISS - vav's on 2nd floor, insulating h/h/w 2nd floor and in chase;		

**Employee** 

Tanner Broughton

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	03/0	08/2016
Weather Delays To Date:			Weather Condition:	cloudy	Day:	7	uesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				66	75
Bernhard Mechanical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 1st floor; move materials			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - insulate h/h/w in band room in D2, 2nd floor corridor & 3rd floor corridor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	14	112		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; install fixtures in area C gang RR's			
Bernhard Mechanical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 1st floor; move materials			
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - insulate h/h/w on 2nd & 3rd floors; insulating grilles on 1st floor			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	16	128		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; install fixtures in area C gang RR's and began fixtures in D1 gang RR's			
Bernhard Mechanical Contractors, L.L.C.	3	24		Atlas - installing flex and diffusers on 1st floor			
Bernhard Mechanical Contractors, L.L.C.	5	40		ISS - insulate h/h/w on 1st, 2nd & 3rd floors			
Bernhard Mechanical Contractors, L.L.C.	3	24		Synergy - VAV & AHU start-up			
Bernhard Mechanical Contractors, L.L.C.	11	88		cont overhead piping on D 2nd & 3rd floor; continue to run pipe to units on D & E roof; install fixtures in area C gang RR's and D1			
Bernhard Mechanical Contractors, L.L.C.	2	10		Atlas - installing flex and diffusers on 2nd & 3rd floors			
Bernhard Mechanical Contractors, L.L.C.	3	24		ISS - insulate h/h/w on 2nd & 3rd floors; insulate grilles on 2nd floor			
Bernhard Mechanical Contractors, L.L.C.	2	16		Synergy - VAV & AHU start-up			
D&T Tile & Terrazzo Co. Inc. D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Firestop International LLC	2	16		sealing partitions in smoke and rated walls on 2nd floor			
Firestop International LLC	2	16		sealing partitions in smoke and rated walls on 2nd floor			
Firestop International LLC	2	16		sealing partitions in smoke and rated walls on 2nd floor			
Firestop International LLC	2	16		sealing partitions in smoke and rated walls on 2nd floor			
Firestop International LLC				seaming parations in smoke and rated mains on 2 nd noon			
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	1	8		Eddie - flagman & clean yard			
Holi Services Inc	2	16		Eddie & Mike - clean yard			
Holi Services Inc	2	16		Eddie & Mike - clean yard			
Holi Services Inc	1	8		Eddie – clean kitchen, helped prep east approach			
Holi Services Inc							
Morris Drywall Systems Inc	12	108		clean-up; rock misc. rooms on all floors; installing grid on 3rd floor; installing strapping/insulation and dense glass at car drop off canopy			
Morris Drywall Systems Inc	12	120		clean-up; installing grid on 3rd floor; installing strapping/insulation and dense glass at car drop off canopy			

Project: Sherwood Forest Element 4801 Maid Marion Drive	_	<i>,</i> 01			Job: Report #:	14-	-02-00 <i>2</i>
Fair Working Days To Date:					Date:	03/0	9/2016
Weather Delays To Date:			Weather Condition:	cloudy and breezy	Day:	Wed	lnesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				65	76
Morris Drywall Systems Inc	11	110		clean-up; installing grid on 3rd floor; finished installing strapping/insulation and dense glass at car drop off canopy; dropping in tile in kitchen and reception room in D1			
Morris Drywall Systems Inc	12	114		clean-up; installing grid on 3rd floor; finished installing strapping/insulation and dense glass at car drop off canopy; dropping in tile in kitchen and reception room in D1			
Morris Drywall Systems Inc	6	48		clean-up; installing border tiles in science rooms; installing grid			
New Orleans Glass Company, Inc.	3	24		caulk exterior frames at stairways; caulk interior frames at elev $$\operatorname{Sf-1}\ \&\ 5$$			
New Orleans Glass Company, Inc.	2	16		install and caulk break metal at elev Sf- 25 & 26			
New Orleans Glass Company, Inc.	4	32		install interior doors & glass			
New Orleans Glass Company, Inc.	3	24		install interior doors & glass			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	5	40		graded site; chipped and installed grates at downspouts			
Phoenix Constructors LLC	5	40		graded site; chipped and installed grates at downspouts; cut out for approach (broke water line			
Phoenix Constructors LLC	5	45		finished prepping at north paving			
Phoenix Constructors LLC	5	40					
Phoenix Constructors LLC							
Cordeiro LLC	9	56		pouring north paving in NE corner; installing forms at east entry to north drive			
Cordeiro LLC	7	56		prepping north paving in NE corner; installing forms at east entry to north drive			
Cordeiro LLC	7	63		prepping north paving in NE corner; installing forms at east entry to north drive			
Cordeiro LLC	7	63		poured north paving in NE corner & approach			
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	4	32		install millwork on 1st & 2nd floors; adjust handles and install shelves in millwork			
ProTech Fixture & Display LLC	4	32		install millwork on 1st & 2nd floors; adjust handles and install shelves in millwork			
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
Rufino`s Painting & Construction Inc.	12	96		prime; taping/floating & priming on 3rd floors and misc. sheetrock ceilings			
Rufino`s Painting & Construction Inc.	12	96		prime; taping/floating & priming on 3rd floors and misc. sheetrock ceilings			
Rufino`s Painting & Construction Inc.	12	96		prime; taping/floating & priming on 3rd floors and misc. sheetrock ceilings			
Rufino`s Painting & Construction Inc.	11	88		prime; taping/floating & priming on all floors and misc. sheetrock ceilings			
Rufino`s Painting & Construction Inc.	8	64		prime; taping/floating & priming on all floors and misc. sheetrock ceilings			
Peachtree Protective Covers							
Peachtree Protective Covers	4	38		install roof pans at main entrance canopy			
Peachtree Protective Covers	4	38		install roof pans at main entrance canopy			
Peachtree Protective Covers	4	32		pretty much completed canopy installation except for some misc trim (installed deck, flashing & wind straps			
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ool			Job: Report #:	14-	02-002 1
Fair Working Days To Date:					Date:	03/0	9/2016
Weather Delays To Date:			Weather Condition:	cloudy and breezy	Day:	Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	65	76
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection	2	19		relocating sprinkler pipe; installing heads			
River City Fire Protection	2	19		relocating sprinkler pipe; installing heads			
River City Fire Protection	_	.5		relocating sprinker pipe, installing reads			
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC	3	24		installed papels at main entry			
Roofing Solutions LLC	3	24		installed panels at main entry			
	2	24		installed angula at main auto.			
Roofing Solutions LLC	3	24		installed panels at main entry			
Roofing Solutions LLC	6	48		install roofing membrane at low D			
Roofing Solutions LLC	4	32		installed panels at main entry			
Roofing Solutions LLC	6	48		install roofing membrane at low D			
Roofing Solutions LLC	5	45		installed panels at main entry			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	4	28		installed gutters @ eyebrows			
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc	2	16		waterproofed soffits by courtyard and car drop off			
CFI Insulation Inc				. Verreinster			
Gulf South Engineering & Testing Inc	1	4		Jude was here for concrete pour			
Gulf South Engineering & Testing Inc	•						
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							

Ellison Builders

Project:	Sherwood Forest Element	tary Scho	ool			Job:	14	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	03/	08/2016
Weather Del	ays To Date:			Weather Condition:	cloudy	Day:	-	Tuesday
Is Today Clai	med as Weather Day?		Ν	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		Ν				66	75
Ellison Builders								
Ellison Builders								
Ellison Builders								
Ellison Builders								
Malone All Star	JV, LLC	20	160		branch circuits E2 & E3; install lights in main vestibule; trim-out i n kitchen & D1			
Malone All Star	JV, LLC	6	48		Data - pulling cat 6 cables; terminate cables; dress up cable runs			
Malone All Star	JV, LLC							
Malone All Star	JV, LLC	22	176		branch circuits E3; install lights in main vestibule, E1 & D1; wattstopper E1			
Malone All Star	· JV, LLC							
Malone All Star	· JV, LLC							
Malone All Star	· JV, LLC	20	160		branch circuits C1; install lights in E1 & E2;trim out D1; work on mechanical equipment			
Malone All Star	· JV, LLC	3	24		ADS - pulling wire			
Malone All Star	JV, LLC							
Malone All Star	· JV, LLC	23	184		branch circuits C1 & E2; install lights in D1, E1 & E2;trim out D1			
Malone All Star	JV, LLC	3	24		ADS - pulling wire			
Malone All Star	· JV, LLC							
Malone All Star	· JV, LLC	18	144		branch circuits C1 & E2; install lights in E2 & D3;trim out D1			
Malone All Star	JV, LLC							
Malone All Star	JV, LLC	2	10		ADS -			
Heritage Floori	ng Inc.	1	2		Melissa's crew - grout 2nd floor RR			
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
		487	3980					

**Remarks:** Weather is extremely bad. Numerous people did not come to work.

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	03/	14/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				64	80

Employee						Work Accomplished		
George Caillouet						·		
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard						(		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30-5:30) oversee site operation		
Marybeth Leonard						(1.5.1.5.)		
Chad Goubert								
George Caillouet								
Tanner Broughton						attended PSR meeting		
Ellen Heck						(6:30-5:40) oversee site operation; attended PSR meeting at main office in am		
Marybeth Leonard						(6.50 5.40) Oversee site operation, attended 1.5K meeting at main onice in airi		
George Caillouet								
Tanner Broughton						jury duty in morning		
Ellen Heck						(6:40-5:30) oversee site operation		
Marybeth Leonard						(c.10 3.30) etersee site operation		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:40-3:30) oversee site operation		
Marybeth Leonard						(6.40 3.50) Oversee site operation		
				2nd	2nd			
	Sub	Sub		Tier	Tier		_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
CORE Construction Services, LLC	3	24				Slim & Pop- clean-up site; Rafael - work on floor expansion jt.		
CORE Construction Services, LLC	3	24				covers  Slim & Pop- clean-up site; Rafael - work on floor expansion jt.		
						covers; clean-up		
CORE Construction Services, LLC	3	24				Slim & Pop- clean-up site; Rafael - work on floor expansion jt.		
CORE Construction Services, LLC	3	24				covers; clean-up Slim - grinding off angle at exterior of stair windows/installing		
						subsill framing in cafeteria/misc items; Pop- clean-up ; Rafael -		
						install proper bolts in handrails @ stair D & E		
CORE Construction Services, LLC	3	24				Slim - grinding off angle at exterior of stair windows; Pop- clean-up; Rafael - install proper bolts in handrails @ stair D & E,		
						waterproofed beam at front entry canopy behind brick		
Bernhard Mechanical Contractors, L.L.C.	11	88	х			cont overhead piping on D 2nd & 3rd floor; continue to run pipe		
Perphard Machanical Contractors 1.1.C	2	24				to units on D & E roof; install fixtures in area D1 gang RR's		
Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C.	3 5	24 40	x			Atlas - installing flex and diffusers on 2nd & 3rd floors  ISS - insulate h/h/w on 2nd & chill water h/h/w on roof top units;		
Derimara Mechanical Contractors, L.L.C.	,	+0	^			insulate grilles on 2nd floor		
Bernhard Mechanical Contractors, L.L.C.	3	24	х			Synergy - mounting stats on walls; pulling wire on C2		
Bernhard Mechanical Contractors, L.L.C.	13	104				turn on units in D & E and fix leaks in hot and chilled water lines		

Project: Location:	<b>Sherwood Forest Elemen</b> 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working	Days To Date:					Date:	03/1	5/2016
Weather Dela	ys To Date:			Weather Condition:	sunny	Day:	Т	uesday
Is Today Claim	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path W	ork Effected?		N				67	83
Bernhard Mecha	nical Contractors, L.L.C.	5	40		ISS - insulate h/h/w on 2nd & chill water h/h/w on roof top units; insulate grilles on 2nd floor			
Bernhard Mecha	nical Contractors, L.L.C.							
Bernhard Mecha	nical Contractors, L.L.C.	14	112		turn on units in D $\&$ E and fix leaks in hot and chilled water lines			
Bernhard Mecha	nical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
	nical Contractors, L.L.C.	5	40		ISS - insulate h/h/w on 2nd & chill water h/h/w on roof top units; maintenance room storage room in A1			
	nical Contractors, L.L.C.							
Bernhard Mecha	nical Contractors, L.L.C.	12	96		turn on units in D & E and finished fixing leaks in hot and chilled water lines; continue to install fixtures in D2 gang RR's and in D2 RR mock-up; clean-up			
Bernhard Mecha	nical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
	nical Contractors, L.L.C.	6	48		ISS - insulate h/h/w in band room & chill water h/h/w on roof top units			
	nical Contractors, L.L.C.	2	16					
Bernhard Mecha	nical Contractors, L.L.C.	12	96		turn on units in D & E and finished fixing leaks in hot and chilled water lines; continue to install fixtures in D2 gang RR's and in D2 RR mock-up; clean-up			
Bernhard Mecha	nical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
Bernhard Mecha	nical Contractors, L.L.C.	5	40		ISS - insulate h/h/w on 2nd & chill water h/h/w on roof top units; maintenance room storage room in A1; finishing h/h/w on 2nd floor			
Bernhard Mecha	nical Contractors, L.L.C.	2	16		Synergy - pulling wire to roof AHU's			
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.	3	15		grind main stairs; clean along base at walls on 1st floor			
D&T Tile & Terra								
D&T Tile & Terra								
Firestop Internat								
Firestop Internat		1	8		caulk exterior joints			
Firestop Internat								
Firestop Internat								
Firestop Internat  Kone Inc	ional EEC							
Kone Inc		3	24		installing partitions in C1 gang RR's			
Kone Inc		3	24		instailing partitions in Cr gang KK's			
Kone Inc								
Kone Inc								
Kone Inc								
Holi Services Inc		2	16		Mike & Eddie - clean site			
Holi Services Inc		2	16		Mike & Eddie - clean site			
Holi Services Inc		2	16		Mike & Eddie - clean site			
Holi Services Inc		2	16		Mike & Eddie - clean site			
Holi Services Inc		2	16		Mike & Eddie - clean site			
Morris Drywall S	ystems Inc	11	88 x		clean-up; 4 guys installing ceiling grid on 2nd & 3rd floors; 5 guys installing misc sheetrock on all floors			
Morris Drywall S	ystems Inc	12	96		clean-up; 4 guys installing ceiling grid on 2nd & 3rd floors; 6 guys installing misc sheetrock on all floors			

Project: Sherwood Forest Elementation: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14-	02-002 1
Fair Working Days To Date:					Date:	03/1	6/2016
Weather Delays To Date:			Weather Condition:	cloudy	Day:	Wed	nesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				68	79
Morris Drywall Systems Inc	12	96		clean-up; 4 guys installing ceiling grid on 3rd floor & began corridor on 1; 6 guys installing misc sheetrock on all floors			
Morris Drywall Systems Inc	12	96		clean-up; installing ceiling grid in corridor on 1 & 2; installing misc sheetrock on all floors; finished working on clouds in media room			
Morris Drywall Systems Inc	12	96		clean-up; 4 guys installing ceiling grid in corridor on 1; 6 guys installing misc sheetrock on all floors; finished working on clouds in media room			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	2	16		install interior storefront doors			
New Orleans Glass Company, Inc.	1	8		install interior storefront door hardware			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	3	23 x		installed sand @ sidewalk at east end of gym canopy; began working on storm drainline tie-ins on east side of gym			
Phoenix Constructors LLC	3	23		installed sand @ sidewalk at east end of gym canopy; demoed and hauled off old city sidewalk along Maid Marion			
Phoenix Constructors LLC	4	36		removed and hauled of concrete sidewalk along Robin Hood			
Phoenix Constructors LLC	4	36		graded sidewalk along Robin Hood			
Phoenix Constructors LLC	4	24		graded sidewalk along Robin Hood			
Cordeiro LLC	7	56 x		form/prep sidewalk at east end of gym canopy & city sidewalk along Maid Marion south of mid drive; form/prep curb at			
Cordeiro LLC	5	40		remainder of north parking lot form/prep sidewalk at east end of gym canopy & city sidewalk along Maid Marion south of mid drive; form/prep curb at remainder of north parking lot			
Cordeiro LLC	7	56		form/prep sidewalk on Maid Marion; pour sidewalk east of bus drop off and along Maid Marion			
Cordeiro LLC	8	64		form/prep sidewalk on Robin Hood and Maid Marion; wreck forms			
Cordeiro LLC	8	40		form/prep sidewalk on Robin Hood and Maid Marion; wreck forms			
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
Rufino's Painting & Construction Inc.	10	80 x		applying finish coat in kitchen area			
Rufino`s Painting & Construction Inc.	9	72		applying finish coat on ceilings in RR's			
Rufino's Painting & Construction Inc.	10	80		misc tape & float			
Rufino's Painting & Construction Inc.	11	88		misc tape & float			
Rufino's Painting & Construction Inc.	11	88		misc tape & float			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							

Project: Sherwood Forest Elemen	ntary Scho	ool			Job:	14-	02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	03/1	7/2016
Weather Delays To Date:			Weather Condition:	cloudy	Day:	Th	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				68	77
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC	6	60 x		Layout and begin installing soffit panels @ car drop off			
Roofing Solutions LLC							
Roofing Solutions LLC	7	67		Layout and begin installing soffit panels @ car drop off			
Roofing Solutions LLC				, , , , , , , , , , , , , , , , , , , ,			
Roofing Solutions LLC	9	81		Layout and begin installing soffit panels @ car drop off			
Roofing Solutions LLC	6	48		install gutters/downspouts & conductor heads			
Roofing Solutions LLC	6	48		install soffit panels near courtyard and finished soffit by cafeteria			
Roofing Solutions LLC	6	60		install gutters/downspouts & conductor heads			
Roofing Solutions LLC	6	48		install soffit panels near courtyard and finished soffit panels by			
				cafeteria			
Roofing Solutions LLC	6	27		install gutters/downspouts & conductor heads			
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company	5	36		install kitchen equipment and shelving			
Alack Refrigeration Company	5	36		install kitchen equipment and shelving & pass thru overhead			
				counter door			
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	1		came and took densities of sidewalk			
Gulf South Engineering & Testing Inc	1	4		came and took cylinders			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	2	3		Jude came and took densities of city sidewalks; put down floor			
Ellican Buildare				moisture tests			

Ellison Builders

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	03/	16/2016
Weather Delays To Date:			Weather Condition:	cloudy	Day:	Wed	dnesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				68	79
Ellison Builders	3	24		install toilet partitions in boys RR in D1			,
Ellison Builders							
Ellison Builders	3	6		install hardware on interior gym doors			
Malone All Star JV, LLC	21	168	х	branch circuits C1; install lights in E1 & E3;trim out D1 & E1			
Malone All Star JV, LLC							
Malone All Star JV, LLC	4	32	х	ADS - pulling wire			
Malone All Star JV, LLC	16	128		branch circuits C1 & E3; install lights in E1 & E3;trim out D1; fire pump room			
Malone All Star JV, LLC							
Malone All Star JV, LLC	4	20		ADS - pulling wire			
Malone All Star JV, LLC	22	136		branch circuits C1 & E3; install lights in E3; hook up kitchen equipment; began installing wire mold on E1			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	19	152		branch circuits C1; install lights in E3; hook up kitchen equipment; began installing wire mold on E1; work on fire pump controller; clean up			
Malone All Star JV, LLC	4	32		ADS - pulling wire			
Malone All Star JV, LLC							
Malone All Star JV, LLC	19	152		branch circuits C1; install lights in E3; hook up kitchen equipment; began installing wire mold on E1; work on fire pump controller; clean up			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Heritage Flooring Inc.	2	10		Install base tile in gang RR's on 3rd floor			
Heritage Flooring Inc.	3	12		received/unloaded some field VCT			
Heritage Flooring Inc.	4	32		Install base tile in gang RR's on 3rd floor			
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Heritage Flooring Inc.	3	20		install ceramic colored tile base in gang RR's; prep and install ct walls in C102			
Heritage Flooring Inc.							
Heritage Flooring Inc.	3	20		install ceramic colored tile base in gang RR's; prep and install ct walls in C102			
Heritage Flooring Inc.			_				
	498	3844					

Remarks

**Inspections:** densities taken for city sidewalks on Robin Hood **Material Delivered:** Morris Drywall received a load of ceiling tile

Visitors: Barney
Notes:

Project:	Sherwood Forest Elementary School	l			Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	03/2	21/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				49	63

Employee						Work Accomplished
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:45-6:00) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(6:45-5:30) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:45-5:30) oversee site operation
Marybeth Leonard						
George Caillouet						
Ellen Heck						(6:45-6:00) oversee site operation
Marybeth Leonard						(4.0.5.5) - 5.5.5.5.5.5.
George Caillouet						
Ellen Heck						(6:45-2:30) oversee site operation
Marybeth Leonard						(4.0 20.7 0 20.0
.,				2nd	2nd	
	Sub	Sub		Tier	Tier	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished S Q Sch
	1	10				New Academic - began installing science casework
	1	11				New Academic - install casework in science rooms
	1	11				New Academic - install casework in science rooms
	1	10				New Academic - install casework in science rooms
	3	24 20				Hahn - began installation of bleachers  Hahn - work on bleachers
CORE Construction Services, LLC	3	28				Slim - install temp handrails in main stairs, moved out dumpsters
CORE COnstruction Services, LEC	3	20				clean-up; Pop- clean-up; Rafael - install proper bolts in
						handrails @ stair D & E, waterproofed beam at front entry canopy
CORE Construction Services, LLC	3	24				behind brick
CORE COnstruction Services, LEC	3	24				Slim - cover gym floor, grade dirt at dumpsters, help with office move; Pop- clean-up; Rafael - install proper bolts in handrails @
						stair D & E
CORE Construction Services, LLC	3	24				Slim - cover gym floor, clean site, help with office move; Pop-
CORE Construction Services, LLC	3	24				clean-up; Rafael - waterproof @ car drop off patches  Slim - misc fire caulk/clean-up; Pop- clean-up; Rafael - chipped
						slab for NOG
CORE Construction Services, LLC	2	14				Slim & Pops - disperse materials to proper floors, clean-up and
Bernhard Mechanical Contractors, L.L.C.	13	130				help move offices continue to install fixtures in D2 gang RR's; install emergency
, , , , , , , , , , , , , , , , , , , ,						shower head in science room; install mop sink in laundry room in
<b>8</b> 1 1 <b>4</b> 1 1 1 <b>5</b> 1 1 1 1 <b>5</b>		_				C1; clean-up
Bernhard Mechanical Contractors, L.L.C.	1	8				Atlas - installing flex and diffusers on 2nd & 3rd floors
Bernhard Mechanical Contractors, L.L.C.	5	40				ISS - insulate roof top units; insulate diffusers on 3rd floor
Bernhard Mechanical Contractors, L.L.C.	2	16				Synergy - pulling wire to roof AHU's

-	Sherwood Forest Element 4801 Maid Marion Drive	ary Scho	ol			Job: Report #:	14-	·02-002
Fair Working D	avs To Date:					Date:	03/2	2/2016
Weather Delays	•			Weather Condition:	mostly sunny	Day:		uesday
-	ed as Weather Day?		N	Precipitation Amount:	, ,	Temp:	Low	High
Critical Path Wo	•		N			· o.i.p.	59	71
Bernhard Mechan	ical Contractors, L.L.C.	10	95		continue to install fixtures in D2 gang RR's; install emergency shower head in science room; install mop sink in laundry room in C1; clean-up			
Bernhard Mechan	ical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
Bernhard Mechan	ical Contractors, L.L.C.	5	40		ISS - insulate roof top units; insulate diffusers on 3rd floor; repair insulation throughout			
Bernhard Mechan	ical Contractors, L.L.C.	1	8		Synergy - installing devices			
Bernhard Mechan	ical Contractors, L.L.C.	12	138		continue to install fixtures in D2 gang RR's; install emergency shower head in science room; clean-up			
Bernhard Mechan	ical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
Bernhard Mechan	ical Contractors, L.L.C.	5	40		ISS - repair insulation throughout			
Bernhard Mechan	ical Contractors, L.L.C.							
	ical Contractors, L.L.C.	12	138		continue to install fixtures in D2 gang RR's; install emergency shower head in science rooms; check for leaks; clean-up			
	ical Contractors, L.L.C.	1	8		Atlas - installing flex and diffusers on 2nd & 3rd floors			
	ical Contractors, L.L.C.	6	48		ISS - repair insulation throughout; insulating diffusers; installing saddles			
	ical Contractors, L.L.C.	4	32		Synergy - start up RTU's & VAV's			
	ical Contractors, L.L.C.							
	ical Contractors, L.L.C.							
	ical Contractors, L.L.C.							
D&T Tile & Terraz	ical Contractors, L.L.C.							
D&T Tile & Terraz		3	23		polish floor adjacent to walls			
D&T Tile & Terraz		3	23		installing terrazzo base			
D&T Tile & Terraz		3	23		installing terrazzo base			
D&T Tile & Terraz					installing tendere base			
Firestop Internation		2	16		fire/smoke caulk on 3rd floor			
Firestop Internation	onal LLC	2	16		fire/smoke caulk on 3rd floor			
Firestop Internation		2	16		fire/smoke caulk on 3rd floor			
Firestop Internation		2	16		fire/smoke caulk on 3rd floor/ brick joints			
Firestop Internation	onal LLC							
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Holi Services Inc		2	20		Mike & Eddie - clean site			
Holi Services Inc		2	20		Mike - clean up; Eddie - work with Rafael installing handrails 2			
Holi Services Inc		2	20		Mike - clean up; Eddie - clean up			
Holi Services Inc		2	20		Mike - clean up; Eddie - clean up			
Holi Services Inc								
Morris Drywall Sys	stems Inc	11	110		clean-up; finished working on clouds in media room; began installation of accoustical frames; install border tiles on D1 & E1			
Morris Drywall Sys	stems Inc	11	110		clean-up; finished working on clouds in media room; began installation of accoustical frames; install border tiles on D1 & E1			
Morris Drywall Sys	stems Inc	12	120		clean-up; installation of accoustical frames; install border tiles on D2 & E2; install grid in corridor on D2 in front of elevato; install patches in dense glass @ car drop off where lights were relocated			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	03/2	24/2016
Weather Delays To Date:			Weather Condition:	cloudy skies	Day:	Tł	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				55	76
Morris Drywall Systems Inc	12	120		clean-up; install border tiles on D2 & E2; install grid in corridor on D2 in front of elevato; install misc grid			
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.	1	5		worked on hardware and some caulking			
New Orleans Glass Company, Inc.	3	24		install storefront doors at east side of main stairs and at east end of C1			
New Orleans Glass Company, Inc.	3	24		install storefront doors at east & south ends of main corridor			
New Orleans Glass Company, Inc.	3	21		install storefront doors and hardware			
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	4	36		install last catch basin			
Phoenix Constructors LLC	4	24		completed stormline work at east side of gym; graded city sidewalk on Robin Hood north end			
Phoenix Constructors LLC	3	27		graded city sidewalk on Robin Hood north end; backfill at islands			
Phoenix Constructors LLC	3	12		backfill at islands			
Phoenix Constructors LLC							
Cordeiro LLC	6	48		pour sidewalk on Robin Hood and Maid Marion			
Cordeiro LLC	5	40		form sidewalk on Robin Hood north half; form/prep pad around backflow preventers			
Cordeiro LLC							
Cordeiro LLC	8	56		pour city sidewalk along Robin Hood and pad around backflow preventer			
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	3	24		install misc millwork; install reception desk in D1			
ProTech Fixture & Display LLC	7	35		install misc millwork; install reception desk in D1			
ProTech Fixture & Display LLC	6	48		install misc millwork; install reception desk in D1			
ProTech Fixture & Display LLC	7	32		install misc millwork; install reception desk in D1			
Rufino's Painting & Construction Inc.	10	80		misc tape,float & paint on 3rd floor and t&f in media room			
Rufino's Painting & Construction Inc.	10	80		misc tape,float & paint on 1st floor and t&f in media room; sand 2nd floor slab			
Rufino's Painting & Construction Inc.	12	96		misc tape,float & paint on 1st floor and t&f in media room & music room; sand 2nd floor slab			
Rufino`s Painting & Construction Inc.	10	80		misc tape, float & paint on 1st floor and t&f in media room & music room; sand 2nd floor slab			
Rufino's Painting & Construction Inc.	12	84		misc tape,float & paint on all floors and t&f in media room & music room; sand 2nd floor slab			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							

River City Fire Protection

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	icary SCNC	וטנ			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	03/2	25/2016
Weather Delays To Date:			Weather Condition:	sunny	Day:		Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				58	72
River City Fire Protection							
Roofing Solutions LLC	4	40		install soffit panels near courtyard and continued installing hat channels @ car drop off			
Roofing Solutions LLC	1	1		Cody came by to investigate gutter failure issue at eyebrows			
Roofing Solutions LLC	8	76		finish soffit panels at loading dock and continued installing hat channels @ car drop off			
Roofing Solutions LLC							
Roofing Solutions LLC	8	76		finished installing hat channels @ car drop off and began installing panels; completed panels @ loading dock			
Roofing Solutions LLC	7	28		remove & repair damaged gutters @ eyebrows			
Roofing Solutions LLC	8	40		installing panels at narrow end of car drop off soffit			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC	2	16		cleaning mortar off of concrete; pointing up holes; punch			
Allied Construction, LLC	2	16		cleaning mortar off of concrete; pointing up holes; punch			
Allied Construction, LLC CFI Insulation Inc	2	10		cleaning mortar off of concrete; pointing up holes; punch			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc	2	4		came and picked up floor moisture tests; here for concrete pour			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	4		Monitored concrete pour			
Gulf South Engineering & Testing Inc				·			
Ellison Builders							
Ellison Builders	3	24		install doors & hardware on E1			
Ellison Builders	3	24		install doors & hardware on D1 & E1			
Ellison Builders	-						
Ellison Builders							
Malone All Star JV, LLC	21	168		branch circuits E2; hook up lights in E1, E2 & E3 including corridors; hook up kitchen equipment; installing wire mold on E2; clean up			

Project:	Sherwood Forest Elemen	ntary Scho	ool			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:						Date:	03/2	21/2016
Weather Del	lays To Date:			Weather Condition:	sunny	Day:	N	Monday
Is Today Clai	imed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N				49	63
Malone All Sta	r JV, LLC	3	24		ADS - pulling wire			
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC	21	168		hook up lights in E1, E2 & E3 including corridors; installing wire mold on E2 & E3; trim out E1			
Malone All Sta	r JV. LLC	4	32		ADS - installing spreakers in cafeteria; installing speakers in D1 &			
					E1			
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC	19	168		hook up lights in E1, E2 & E3 including corridors; installing wire			
Malana All Cta	* IV 11C	3	24		mold on E2 & E3; trim out E1; branch C2 & E3			
Malone All Sta Malone All Sta		3	24		ADS - installing devices			
Malone All Sta		19	172		hank we links in E4 E2. installing with model on E2. Site of E4.			
ividione Ali Sta	T JV, LLC	19	172		hook up lights in E1, E2; installing wire mold on E3; trim out E1; branch C2			
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC							
Malone All Sta	r JV, LLC							
Heritage Floor	ing Inc.	3	18		install ceramic colored tile base in gang RR's; prep and install ct walls in C102			
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
Heritage Floor	ing Inc.							
		438	3635					

**Remarks:** River City Fire did not show up on site as scheduled.

Rain hit when pouring concrete. Cordeiro was able to not loose anything during the pour of the city sidewalk and backflow preventer pour.

Project:	Sherwood Forest Elementary School				Job	1.	4-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	03	/28/2016
Weather Dela	ys To Date:		Weather Condition:	partly sunny	Day	:	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path V	Vork Effected?	N				59	74

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45-6:00) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45-5:10) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:20-7:00) oversee site operation/corporate safety meeting		
Marybeth Leonard								
Ellen Heck						(6:30-5:15) oversee site operation		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45-3:40) oversee site operation		
				2nd	2nd	(0.45 5.46) oversee site operation		
	Sub	Sub		Tier	Tier		_	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
	3	24				Hahn - installation of bleachers		
	3	24				Hahn - installation of bleachers		
	3	24				Hahn - installation of bleachers		
	1	2				Hahn - installed replacement basketball goal		
	3	9				Hahn - installation of bleachers		
CORE Construction Services, LLC	2	19				Slim - misc fire caulk/help move office; Pop- moving		
CORE Construction Services, LLC	3	25				Slim & Pops - moved offices/ fixed fence; Raphael - helped with		
5005 6	2	20				moving and worked on expansion jt.		
CORE Construction Services, LLC	3	30				Slim & Pops - installed gate & fixed fence; Raphael - install handrail at stage steps and chip at front entry door so threshold		
CORE Construction Services, LLC	3	27				would work  Slim & Pops - installed gate & fixed fence; Raphael - waterproof soffits at exterior alcoves		
CORE Construction Services, LLC	3	24				Slim & Rafael - caulk @ sound walls & cut holes for fire extinguisher cabinets as needed; Pops - clean-up		
Bernhard Mechanical Contractors, L.L.C.	14	112				continue to install fixtures in D2 gang RR's; fix multiple leaks in hot water piping		
Bernhard Mechanical Contractors, L.L.C.						-		
Bernhard Mechanical Contractors, L.L.C.	5	40				ISS - repair insulation throughout; insulating diffusers on 3rd floor; insulating condensate lines' on roof top units		
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.	11	88				plumb in sinks in science rooms; install fixtures in RR's on 2nd floor		
Bernhard Mechanical Contractors, L.L.C.						Synergy - Rafael- work on programming		

Project:	Sherwood Forest Element	tary Scho	ool			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	03/2	29/2016
Weather Dela	ys To Date:			Weather Condition:	cloudy	Day:	T	uesday
Is Today Clain	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				65	71
Bernhard Mecha	anical Contractors, L.L.C.	5	40		ISS - repair insulation throughout; insulating condensate lines' on			
Bernhard Mecha	anical Contractors, L.L.C.	2	14		roof top units  Johnson Controls - work on warranty work on one of the Chillers			
	anical Contractors, L.L.C.	13	104		plumb in sinks in science rooms; install fixtures in gang RR's on			
	•				3rd floor; began installing sinks in millwork on 1st floor			
Bernhard Mecha	anical Contractors, L.L.C.	3	24		Synergy - Corey- work on programming			
Bernhard Mecha	anical Contractors, L.L.C.	7	56		ISS - finishing putting on color jacket in mechanical rooms; installing saddle's and repairing insulation on 2nd & 3rd floors;			
Rernhard Mecha	anical Contractors, L.L.C.	2	8		finishing condensate drains on roof top units			
		15	120		Johnson Controls - work on warranty work on one of the Chillers			
berninaru iviecna	anical Contractors, L.L.C.	13	120		plumb in sinks in science rooms; installing sinks in millwork on 1st floor; turned on A/C's in D & E			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	7	56		ISS - finishing putting on color jacket in mechanical rooms; installing saddle's and repairing insulation on all floors; insulating diffuser backs on E2			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	10	80		plumb in sinks in science rooms; installing sinks in millwork on 1st floor			
Bernhard Mecha	anical Contractors, L.L.C.	2	16		Synergy - working on programming of units in D & E			
Bernhard Mecha	anical Contractors, L.L.C.	7	56		ISS - finishing putting on color jacket in mechanical rooms; installing saddle's and repairing insulation on all floors; insulating diffuser backs on E3			
Bernhard Mecha	anical Contractors, L.L.C.							
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.							
D&T Tile & Terra	azzo Co. Inc.							
Firestop Internat	tional LLC	2	16		fire/smoke caulk on 1st & 2nd floors/ brick joints			
Firestop Internat	tional LLC	2	16		fire/smoke caulk on 1st & 2nd floors/ brick joints			
Firestop Internat	tional LLC							
Firestop Internat	tional LLC	1	8		fire/smoke caulk on 3rd floor/ brick joints			
Firestop Internat	tional LLC	2	16		fire/smoke caulk on 3rd floor & misc			
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc								
Holi Services Inc		2	16		Mike - moving; Eddie - fire caulk and moving			
Holi Services Inc		2	16		Mike & Eddie - moved offices/fixed fence (last day)			
Holi Services Inc								
Holi Services Inc								
Holi Services Inc								
Morris Drywall S	systems Inc	10	80		clean-up; install border tiles on D2 & E2; install misc grid; fire/smoke caulk; rocked wall at C2 next to main stairs			
Morris Drywall S	Systems Inc	12	96		clean-up; misc rock on 2nd floor; install grid on north half of media room			
Morris Drywall S	Systems Inc	12	96		clean-up; misc rock on all floors; install grid on north half of media room; began grid in main corridor of B & C			

Project: Sherwood Forest Element 4801 Maid Marion Drive	=	<b>~</b> I			Job: Report #:	14-	02-00
Fair Working Days To Date:					Date:	03/3	1/201
Weather Delays To Date:			Weather Condition:	cloudy	Day:	Th	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				70	79
Morris Drywall Systems Inc	12	96		clean-up; misc rock on all floors; install grid on north half of media room; began grid in main corridor of B & C			
Morris Drywall Systems Inc	9	72		install grid in main corridor on B1 & C1, music room and locker room on D3; finish rocking walls in rr's across from elevator on 2 & 3; misc rock			
New Orleans Glass Company, Inc.	2	16		install hardware on exterior doors			
New Orleans Glass Company, Inc.	3	21		install hardware on exterior doors & set glass in wood doors			
New Orleans Glass Company, Inc.	3	24		install hardware on exterior doors			
New Orleans Glass Company, Inc.	3	24		install hardware on exterior doors			
New Orleans Glass Company, Inc.	2	16		install hardware on exterior doors			
Phoenix Constructors LLC	4	32		graded south side and prepped for downspouts			
Phoenix Constructors LLC	4	32		graded south side and prepped for downspouts			
Phoenix Constructors LLC	4	32		graded south side and prepped for downspouts			
Phoenix Constructors LLC	4	32		graded south side and backfilled @ islands			
Phoenix Constructors LLC							
Cordeiro LLC	4	32		wreck forms, clean-up, & form a splash blocks			
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	3	24		cut countertops for sinks and set cabinets on 2nd floor			
ProTech Fixture & Display LLC	3	24		cut countertops for sinks and set cabinets on 2nd floor			
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	3	24		install cabinets on 3rd floor and work on 1st and 2nd floor			
Rufino's Painting & Construction Inc.	6	48		misc tape,float & paint & music room			
Rufino's Painting & Construction Inc.	8	64		misc tape,float & paint, work in music room, sand/prime @ main vestibule ceiling and main stairwell			
Rufino's Painting & Construction Inc.	9	72		misc tape,float & paint, work in music room			
Rufino's Painting & Construction Inc.	9	72		misc tape,float & paint, work in music room			
Rufino's Painting & Construction Inc.	8	64		paint stage ceiling; misc finishing			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection	4	34		install heads in classrooms on E3			
River City Fire Protection	4	38		install heads on 2nd floor and cafeteria			
River City Fire Protection	4	20		install heads in classrooms on E3, cafeteria &			
River City Fire Protection							
Roofing Solutions LLC	4	38		installing panels at wide area of car drop off soffit			
	7						

Part	Project:	Sherwood Forest Elementa	ary Scho	ool			Job:	14-	-02-002
Weather Counting	Location:	4801 Maid Marion Drive					Report #:		1
Processed Members Day   Processed Members Day   Processed Members   Processed Member	Fair Working	Days To Date:					Date:	03/2	8/2016
Carbon   Post	Weather Del	ays To Date:			Weather Condition:	partly sunny	Day:	N	∕londay
Reciting Solutions LC  Recoting Solutions LC	Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Recoling Solutions ILC  Fig. 19 1	Critical Path	Work Effected?		N				59	74
Security Selections LLC	Roofing Solution	ons LLC							
Recing Solutions LCC Recing So	Roofing Solution	ons LLC	7	56		installing panels at wide area of car drop off soffit, infill on north			
Redning Salacians LCC 7 3 5 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D 6 6 1 4								
Access	Roofing Solutio	ons LLC	1	2					
Routing Solutions LCC         7         5         continue installing ponetial valid asset of carding off to fift and in extending particular backers.           Routing Solutions LCC         6         4         8         invasil was look paid and remainder of pank for lightning protection.           Routing Solutions LCC         6         4         8         invasil was look paid and remainder of pank for lightning protection.           Routing Solutions LCC         5         4         8         invasiling points at wide asset for dripp off roffe and in networn packers.           Routing Solutions LCC         2         2         2         Town and attacker gay came and checked out soot leads.           Multivisia Construction Documentation         3         2         2         A like came out and sook progress and editing covery photos.           Multivisia Construction Documentation Documentation Documentation Toward         4         4         A like came out and sook progress and editing covery photos.           Multivisia Construction Documentation Documentation Toward         4         4         4         A like came out and sook progress and editing covery photos.           Multivisia Construction Documentation Toward         5         4         4         4         4         4         4         4         4         4         4         4         4         4         4 <td< td=""><td>Roofing Solution</td><td>ons LLC</td><td>7</td><td>56</td><td></td><td>installing panels at wide area of car drop off soffit and in exterior</td><td></td><td></td><td></td></td<>	Roofing Solution	ons LLC	7	56		installing panels at wide area of car drop off soffit and in exterior			
Roofing Solutions LIC         7         5         insuling parents at wide area of car drop off solitis and in centric access           Roofing Solutions LIC         8         4         8         Install seal parks for lightning protection           Roofing Solutions LIC         6         48         8         Install seal parks at wide area of car drop off soffic and in enterior access           Roofing Solutions LIC         8         8         1         2         1         1         1         1         2         1         1         2         2         1         2         2<	Roofina Solutic	ons LLC	7	63					
Stock   Stoc									
Roofing Solutions LLC Roofing Solutions Roofing Roofing Roofing Roofing Roofing Up holes planch Roofing Solutions LLC Roofing Solutions Roofing									
Roofing Solutions LC         It allows panels at wide area of car drop off forfit and in octation           Roofing Solutions LC         Kooking Solutions LC           Roofing Solutions LC         2         2           Multivisias Construction Documentation         1         2           Alack Refrigeration Company         1         2           Alack Refrigeration Company         1         2           Alack Refrigeration Company         1         3           Alack Refrigeration Company         1         1	Roofing Solution	ons LLC							
Roufuig Solutions LLC  Roufuiguage Construction Documentation  Multivists Construction Documentation  Alack Refrigeration Company  A	Roofing Solution	ons LLC	6	48		Install walk pads and remainder of pads for lightning protection			
Roufing Solutions LLC 2 2 3 2 1 10 10 10 10 10 10 10 10 10 10 10 10 1	Roofing Solution	ons LLC	6	48					
Roofing Solutions LLC 2 2 3 2 Multivista Construction Documentation 1 2 2 4 Multivista Construction Company 1 2 2 4 Multivista Construction Company 1 2 2 4 Multivista Construction Company 1 2 2 4 Multivista Construction LLC 1 2 2 1 Multivista Construction LLC 1 2 2 1 Multivista Construction LLC 1 2 2 Multivista Construction LLC 1	Roofing Solutio	one II C				alcoves			
Mulbivista Construction Documentation  Mulbivista Construction Company  Alack Refrigeration Re			2	2		Tom and another guy came and checked out roof leaks			
Multivista Construction Documentation Multivista Construction Documentation Multivista Construction Documentation Multivista Construction Documentation Alack Refrigeration Company Alack Refrigeratio	_								
Multivisat Construction Documentation Multivisat Construction Documentation Multivisat Construction Documentation Multivisat Construction Documentation Alack Refrigeration Company Alack Refrigeratio			'	2		Nick carrie out and took progress and tening cover priotos			
Multivista Construction Documentation  Multivista Construction Documentation  Alack Refrigeration Company  Alack Refrigeration Compa									
Malikista Construction Documentation  Alack Refrigeration Company  Alled Construction, LLC  Allied Construction, LLC  CFI Insulation inc  CFI Insula									
Alack Refrigeration Company  Alack Refrigeration Com									
Alack Refrigeration Company  Alack Refrigerat									
Alack Refrigeration Company  Alack Refrigeration Company  Alack Refrigeration Company  Allied Construction, LLC  CFI Insulation Inc  CFI Insulation In									
Alack Refrigeration Company  Alack Refrigeration Company  Aliced Construction, LLC  Allied Construction, LLC  CFI Insulation Inc  CFI Insulati									
Allied Construction, LLC  CFI Insulation Inc									
Allied Construction, LLC  Allied Construction, LCC  Allied Constructio									
Allied Construction, LLC  CFI Insulation Inc  CFI Insulation I			2	16		cleaning mortar off of concrete; pointing up holes; punch			
Allied Construction, LLC  Allied Construction, LLC  CFI Insulation Inc  CHI South Engineering & Testing Inc  Culf South Engineering	Allied Construc	tion, LLC				3 1 3 1 1			
Allied Construction, LLC  Allied Construction, LLC  CFI Insulation Inc  CHI South Engineering & Testing Inc  Culf South Engineering	Allied Construc	tion, LLC	3	21		punch out			
CFI Insulation Inc  CHI In	Allied Construc	tion, LLC				•			
CFI Insulation Inc  CIII Security Engineering & Testing Inc  Guif South Engineering & Testing Inc  In I	Allied Construc	tion, LLC							
CFI Insulation Inc  CFI Insulation Inc  CFI Insulation Inc  CFI Insulation Inc  CIII South Engineering & Testing Inc  Culf South Engineering & Tes	CFI Insulation I	nc							
CFI Insulation Inc  CFI Insulation Inc  Gulf South Engineering & Testing Inc  Ellison Builders  Ellison Builders  Substantial fire extinguisher cabinets, mirrors & grab bars on all floors  work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Ellison Builders  Ellison Builders  Halone All Star JV, LLC  18 171	CFI Insulation I	nc							
CFI Insulation Inc  Gulf South Engineering & Testing Inc  Ellison Builders  Halone All Star JV, LLC  18 171  hook up lights in gang RR's; trim out in E1 classrooms; hang	CFI Insulation I	nc							
Gulf South Engineering & Testing Inc Ellison Builders Ellison Builders  Ellison Builders  3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors Ellison Builders Ellison Builders Ellison Builders  Ellison Builders  Ellison Builders  Ellison Builders  The work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Hook up lights in gang RR's; trim out in E1 classrooms; hang	CFI Insulation I	nc							
Gulf South Engineering & Testing Inc Ellison Builders Ellison Builders  Ellison Builders  3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors work on toilet partitions in C1 gang RR's Ellison Builders  Ellison Builders  Ellison Builders  Halone All Star JV, LLC  18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	CFI Insulation I	nc							
Gulf South Engineering & Testing Inc Ellison Builders Ellison Builders 3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors Ellison Builders Builders Ellison Builders Ellison Builders  Ellison Builders  Hook up lights in gang RR's; trim out in E1 classrooms; hang	Gulf South Eng	ineering & Testing Inc							
Gulf South Engineering & Testing Inc  Gulf South Engineering & Testing Inc  Ellison Builders  Ellison Builders  3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors  Ellison Builders  Builders  Ellison Builders  Ellison Builders  Hook up lights in gang RR's; trim out in E1 classrooms; hang	Gulf South Eng	ineering & Testing Inc							
Gulf South Engineering & Testing Inc  Ellison Builders  Ellison Builders  3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors  Ellison Builders 3 24 work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Halone All Star JV, LLC 18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Gulf South Eng	ineering & Testing Inc	1	1		came and set calcium cloride tests in areas A, B & C			
Ellison Builders  Ellison Builders  3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors  Ellison Builders  3 24 work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Malone All Star JV, LLC  18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Gulf South Eng	ineering & Testing Inc							
Ellison Builders 3 25 install fire extinguisher cabinets, mirrors & grab bars on all floors  Ellison Builders 3 24 work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Malone All Star JV, LLC 18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Gulf South Eng	ineering & Testing Inc							
Ellison Builders 3 24 work on toilet partitions in C1 gang RR's  Ellison Builders  Ellison Builders  Malone All Star JV, LLC 18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Ellison Builders								
Ellison Builders  Ellison Builders  Malone All Star JV, LLC  18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Ellison Builders		3	25		install fire extinguisher cabinets, mirrors & grab bars on all floors			
Ellison Builders  Malone All Star JV, LLC  18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Ellison Builders		3	24		work on toilet partitions in C1 gang RR's			
Malone All Star JV, LLC 18 171 hook up lights in gang RR's; trim out in E1 classrooms; hang	Ellison Builders								
	Ellison Builders								
	Malone All Star	JV, LLC	18	171					

Project:	Sherwood Forest Element	tary Scho	ol			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	03/2	28/2016
Weather Dela	ays To Date:			Weather Condition:	partly sunny	Day:	1	Monday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N				59	74
Malone All Star	JV, LLC	3	24		ADS - install call buttons			
Malone All Star	JV, LLC							
Malone All Star	· JV, LLC	19	181		hook up lights in gang RR's; trim out in E1 & E2 classrooms; install lights in E3 corridor			
Malone All Star	· JV, LLC	3	24		ADS - pull wire			
Malone All Star	JV, LLC	2	14		Bonded - worked on lightning protection			
Malone All Star	JV, LLC	18	181		hook up lights in E3 corridor; trim out in E1 & E2 classrooms;finish working above ceiling in corridors in B & C			
Malone All Star	· JV, LLC	3	24		ADS - pull wire			
Malone All Star	· JV, LLC	2	14		Bonded - worked on lightning protection			
Malone All Star	· JV, LLC	8	64		Data - sort & pull cables, install racks and terminate wires; place waps in classrooms on 1st floor			
Malone All Star	· JV, LLC	17	136		hook up lights in E3 corridor; trim out in E1, E2 & E3 classrooms; branch circuits in C2 & E3; working in mechanical rooms			
Malone All Star	JV, LLC	3	24		ADS - pull wire			
Malone All Star	· JV, LLC	2	14		Bonded - worked on lightning protection			
Malone All Star	· JV, LLC	6	54		Data - sort & pull cables, install racks and terminate wires			
Malone All Star	JV, LLC	18	148		hook up lights in E3 corridor; trim out in E2 $\&$ E3 classrooms; turn on circuits in E1 $\&$ E2			
Malone All Star	· JV, LLC	3	24		ADS - pull wire; install speakers in classrooms on 2nd floor			
Malone All Star	· JV, LLC	4	32		Data - routing and dressing up cables			
Malone All Star	· JV, LLC	6	54		Data - sort & pull cables, install racks and terminate wires			
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.	2	16		grout changing room in C1			
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.	2	2		install 5x4 samples for VCT			
Heritage Floori	ng Inc.	2	10		installing transitions next to ceramic tile floors on 1st & 2nd floors			
Heritage Floori	ng Inc.				Mitchel came by and took ph samples on the 1st floor in D $\&$ E			
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
Heritage Floori	ng Inc.							
		491	3963					

## Remarks

**Communication with Subcontractors:** Received notification from Protech about condition of bldg (too hot/no air). Air in fact was on; just heat was coming out. It did not get above 90 degrees.

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	04/0	04/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				58	76

Employee						Work Accomplished
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:45-5:45) oversee site operation
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:45-5:15) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:45-3:40) oversee site operation
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:40-5:15) oversee site operation
Marybeth Leonard						\(\lambda \cdot \c
George Caillouet						
Tanner Broughton						
Marybeth Leonard						
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished S Q Sch
	2	14				GC Specialties - install concession counter door and hood on OH
CORE Construction Services, LLC	3	25				door in maintenance room
		23				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on
CORE Construction Services, LLC	3	27				Slim & Pops - worked on closing up gaps so penetrations could
CORE Construction Services, LLC	3	27 27				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up
CORE Construction Services, LLC CORE Construction Services, LLC	3	27 27 27				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up
CORE Construction Services, LLC	3	27 27				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;
CORE Construction Services, LLC CORE Construction Services, LLC	3	27 27 27				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 3	27 27 27 24				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls;  Rafael - clean-up
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.	3 3	27 27 27 24				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  installing sinks in millwork on 1st floor & 2nd floor
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 3 13	27 27 27 24 104				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  installing sinks in millwork on 1st floor & 2nd floor
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 3 13	27 27 27 24 104				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer  Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up  installing sinks in millwork on 1st floor & 2nd floor
CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3 3 13	27 27 27 24 104 25				Slim & Pops - worked on closing up gaps so penetrations could be caulked/ worked on cleaning out trailer; Rafael - worked on trailer Slim & Pops -clean up/ worked on cleaning out trailer; Rafael - worked on trailer/ clean-up Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up Slim & Pops -clean up; seal/caulk at accoustical and smoke walls; Rafael - clean-up Slim & Pops -clean up; seal/caulk at acoustical and smoke walls; Rafael - clean-up installing sinks in millwork on 1st floor & 2nd floor

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-02-00
Fair Working Days To Date:					Date:	04/05/2010
Weather Delays To Date:			Weather Condition:	sunny	Day:	Tuesda
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low High
Critical Path Work Effected?		N				60 7
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	7	56 x		hooking up sinks in millwork on 2nd floor		
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	7	56		hooking up sinks in millwork on 2nd floor		
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	1	8		Synergy - pulling cat 5 to electric meter IT room; connecting		
				water meter; mounting DJP switches		
Bernhard Mechanical Contractors, L.L.C.	7	56		hooking up sinks in millwork on 3rd floor		
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
Firestop International LLC	1	8		fire/smoke caulk on 1st floor admin corridor/ brick caulk		
Firestop International LLC	2	16		fire/smoke caulk on 2nd & 3rd floor shaft walls & 1st floor admin corridor / brick caulk		
Firestop International LLC	1	4		fire/smoke caulk on 2nd & 3rd floor shaft walls & 1st floor admin corridor / brick caulk		
Firestop International LLC						
Firestop International LLC						
Kone Inc						
Kone Inc						
Kone Inc						
Kone Inc						
Kone Inc						
Holi Services Inc						
Holi Services Inc						
Holi Services Inc						
Holi Services Inc						
Holi Services Inc						
Morris Drywall Systems Inc	8	72		install grid in main corridor on B1 & C1, and did north section of music room; finish rocking walls in rr's across from elevator on 2 & 3		
Morris Drywall Systems Inc	9	81		install grid in main corridor on B1 & C1, and did center section of music room; install ceiling tile in cafeteria		
Morris Drywall Systems Inc	8	72 x		finish installing grid in main corridor on B1 & C1; install border tiles on 2nd floor		
Morris Drywall Systems Inc	9	81		install border tiles on all floors; began installing tile in classrooms on 2nd floor until I stopped them so that the waps could be relocated.		
Morris Drywall Systems Inc	9	72		install ceiling tiles in classrooms on 1st & 2nd floors		
New Orleans Glass Company, Inc.	2	16		install hardware on exterior doors		

Project: Location:	Sherwood Forest Elementa 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14-	02-002
Fair Working	Days To Date:					Date:	04/0	5/2016
Weather Dela	-			Weather Condition:	sunny	Day:		uesday
	med as Weather Day?		Ν	Precipitation Amount:	•	Temp:	Low	High
•	Work Effected?		N	•			60	77
New Orleans G	ass Company, Inc.	2	16		install hardware on exterior doors			
	ass Company, Inc.				install hardrate on exercise about			
	ass Company, Inc.	3	9		install glass on media room doors and fire glass in			
	ass Company, Inc.							
Phoenix Constr		4	32		grade south side and began removing dirt pile; backfill @ islands			
Phoenix Constr	uctors LLC	4	32		haul off dirt pile in SE corner of property; backfill at islands			
Phoenix Constr	uctors LLC	4	32		haul off dirt pile in SE corner of property; backfill at islands			
Phoenix Constr	uctors LLC	4	32		haul off dirt pile in SE corner of property; backfill at islands			
Phoenix Constr	uctors LLC	4	32		haul off dirt pile in SE corner of property; backfill at islands			
Cordeiro LLC								
Cordeiro LLC								
Cordeiro LLC		3	18		poured splash blocks at bottom of downspouts			
Cordeiro LLC								
Cordeiro LLC								
ProTech Fixture	& Display LLC							
ProTech Fixture	& Display LLC	3	24		install cabinets on 3rd floor and cut counters for sinks			
ProTech Fixture	& Display LLC							
ProTech Fixture	& Display LLC	3	15		install millwork in D216; finish installation of reception desk on D2			
ProTech Fixture	& Display LLC							
Rufino`s Paintin	g & Construction Inc.	4	30		paint stage ceiling; misc finishing			
Rufino`s Paintin	g & Construction Inc.	4	32		paint stage ceiling; misc finishing			
Rufino's Paintin	g & Construction Inc.	4	32	х	finish patching furdowns in cafeteria; misc painting			
Rufino's Paintin	g & Construction Inc.	3	24		misc patching & painting			
Rufino's Paintin	g & Construction Inc.	3	24		misc patching & painting			
Peachtree Prote	ective Covers							
Peachtree Prote	ective Covers							
Peachtree Prote	ective Covers							
Peachtree Prote	ective Covers							
Peachtree Prote	ective Covers							
Quality Iron Fab	pricators Inc.							
Quality Iron Fab	pricators Inc.							
Quality Iron Fab	pricators Inc.							
Quality Iron Fab	oricators Inc.							
Quality Iron Fab								
River City Fire P								
River City Fire P								
River City Fire P		3	29	х	installing heads on 1st floor			
River City Fire P		3	26		installing heads			
River City Fire P								
Roofing Solutio	ns LLC	6	57		installing panels at wide area of car drop off soffit and in exterior alcoves			
Roofing Solutio	ns LLC				acoves			
Roofing Solutio	ns LLC	6	48		installed walk pads on high roof of D & E			
Roofing Solutio	ns LLC	6	24		installing panels at wide area of car drop off soffit and in exterior alcoves			
Roofing Solutio	ns LLC							

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14-02-00
Fair Working Days To Date:					Date:	04/05/201
Weather Delays To Date:			Weather Condition:	sunny	Day:	Tuesda
s Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low Hig
Critical Path Work Effected?		N				60 7
Roofing Solutions LLC	6	48		installed walk pads on high roof of D & E		
Roofing Solutions LLC						
Roofing Solutions LLC						
Roofing Solutions LLC	6	48 x		installed walk pads on A & B		
Roofing Solutions LLC						
Roofing Solutions LLC						
Roofing Solutions LLC	6	48		installed walk pads on A & B		
Roofing Solutions LLC						
Roofing Solutions LLC						
Roofing Solutions LLC						
Multivista Construction Documentation						
Multivista Construction Documentation						
Multivista Construction Documentation						
Multivista Construction Documentation						
Multivista Construction Documentation						
Alack Refrigeration Company						
Nack Refrigeration Company						
lack Refrigeration Company						
slack Refrigeration Company	2	2		installed new switch to freezer		
Alack Refrigeration Company				instance new sinten to neezer		
Allied Construction, LLC	2	16		punch gym walls		
Allied Construction, LLC	2	16		installed brick next to curtainwall @ main entry to B		
Allied Construction, LLC	2	16		punch		
Allied Construction, LLC	2	16		punch		
Allied Construction, LLC	2	16		punch work on extrior.		
CFI Insulation Inc	-	10		puter work on extror.		
CFI Insulation Inc						
CFI Insulation Inc						
CFI Insulation Inc						
CFI Insulation Inc						
Gulf South Engineering & Testing Inc	1	2				
Gulf South Engineering & Testing Inc	1	2		put down calcium chloride tests for floor moisture		
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc						
Gulf South Engineering & Testing Inc	2	2.4				
Ellison Builders	3	24		began hanging doors on 2nd floor		
Ellison Builders	4	36		hanging doors on 2nd floor and began hanging doors on 3rd		
Ellison Builders	4	36		floor hanging doors on 2nd floor and began hanging doors on 3rd		
				floor		
Ellison Builders	4	36		hanging doors on 3rd floor		
Ilison Builders						
Malone All Star JV, LLC	18	148		hang lights in media room; trim out in E2 $\&$ E3 classrooms; turn off temp power		
Malone All Star JV, LLC	3	24		ADS - pull wire; install speakers in classrooms on 2nd floor		

Project:	Sherwood Forest Elementa	ary Scho	ool				Job:	14-	-02-002
Location:	4801 Maid Marion Drive						Report #:		1
Fair Working	Days To Date:						Date:	04/0	4/2016
Weather Del	ays To Date:				Weather Condition:	sunny	Day:	N	/londay
Is Today Clai	med as Weather Day?		N		Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N					58	76
Malone All Star	r JV, LLC								
Malone All Star	r JV, LLC	18	148			hang lights in media room; trim out in E3; remove temp wiring;			
Mala a All Cu	. N/ 11 C	2	2.4			install lights in music room			
Malone All Star		3 2	24 16			ADS - pull wire; trim out devices			
Malone All Star			8			Data - routing and dressing up cables			
Malone All Star		2				work on lightning protection			
Malone All Star	r JV, LLC	17	136	Х		hang lights in media room; trim out in E3; remove temp wiring; install lights in music room			
Malone All Star	r JV, LLC	3	24	х		ADS - pull wire; trim out devices			
Malone All Star	r JV, LLC	2	16			Data - routing and dressing up cables			
Malone All Star	r JV, LLC								
Malone All Star	r JV, LLC	18	144	х		work on lights in media room, music room & stage; trim out in			
						E3; remove temp wiring; install wire mold covers on 1st & 2nd			
Malone All Star	r IV II C	4	32			floors  ADS - pull wire; trim out devices			
Malone All Star		3	24			Data - routing and dressing up cables; moving waps in classrooms			
Malone All Star		3	24			Data - routing and dressing up cables, moving waps in classrooms			
Malone All Star		18	144			work on lights in media room & stage; trim out in E3; remove			
Walone 7th Star	77, 220	10	1-1-1			temp wiring; install wire mold covers on 3rd floor			
Malone All Star	r JV, LLC	4	32			ADS - pull wire; trim out devices			
Malone All Star	r JV, LLC	3	24			Data - routing and dressing up cables			
Heritage Floori	ng Inc.	2	16			cleaned/punched ceramic tile			
Heritage Floori	ng Inc.	4	32			prepped concession and both gym offices			
Heritage Floori	ng Inc.	3	18			cleaned/punched ceramic tile			
Heritage Floori	ng Inc.	4	32			layed vct in concession and both gym offices and prepped			
or a let a		2	10			kitchen office and maintenance office and locker room			
Heritage Floori	_	3	18			cleaned/punched ceramic tile			
Heritage Floori	ng Inc.	4	32			layed vct in kitchen office and maintenance office and locker room and began prepping cafeteria			
Heritage Floori	ng Inc.					.com and began propping careteria			
Heritage Floori		4	38			layed vct in maintance locker room and prepping and began			
						laying cafeteria			
Heritage Floori	ng Inc.	4	32	_		Installing VCT at Cafeteria			
		388	3072						

## Remarks

Verbal or Written Instruction from Architect or Engineer: Was directed by Jacobs to move WAPs at least 30' apart.

**Inspections:** SFM Scheduled for next Thursday.

Project:	Sherwood Forest Elementary School	I				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Rep	ort #:		1
Fair Working	Days To Date:					Date:	04/1	11/2016
Weather Dela	ays To Date:		Weather Condition:	cloudy		Day:	V	Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		7	Temp:	Low	High
Critical Path	Work Effected?	N					68	75

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:15) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:00) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:10) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:20) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:20) oversee site operations		
Marybeth Leonard								
Ellen Heck						(6:50 - 3:30) oversee site operations		
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier	Work Accomplished	s	Q Sch
	5	40	x	Wrkrs	Hrs	Wenger - install music storage units		
	2	16	*			GC Specialties - install lockers in locker rooms		
	4	32				GC Specialties - install lockers in locker rooms		
	·					Cospeciation install focation in focation for the focation in the focation in focation in focation in the foca		
CORE Construction Services, LLC	3	24				Slim & Pops -clean up exterior; Rafael - clean-up & install		
CORE Construction Services, LLC	3	24				expansion jt on 2nd floor  Slim & Pops -clean up; Rafael - clean-up & install expansion jt on		
CONTRACTION SELVICES, LLC	3	27				2nd floor		
CORE Construction Services, LLC	3	27				Slim & Pops -clean up, patch concrete around floor boxes in		
CORE Construction Services, LLC	3	23				media room; Rafael - clean-up, moved materials  Slim & Pops -clean up, patch concrete around floor boxes in		
CONE CONSTRUCTION SERVICES, LLC	э	23				media room/ install smoke caulk; Rafael - work on expansion		
						joints		
CORE Construction Services, LLC	3	24				Slim & Pops -clean up,install FRP at mop sinks, assist in above		
						ceiling inspection; Rafael - work on expansion joints		

Project: Sherwood Forest Elementary School Location: 4801 Maid Marion Drive				Job: Report #:	14-	02-002 1
Fair Working Days To Date:				Date:	04/1	6/2016
Weather Delays To Date:		Weather Condition:	cloudy	Day:	Sa	iturday
Is Today Claimed as Weather Day?	Ν	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?	N				66	72
CORE Construction Services, LLC						
Bernhard Mechanical Contractors, L.L.C. 7	56		hooking up sinks in millwork on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C. 1	8		Synergy - wiring up devices			
Bernhard Mechanical Contractors, L.L.C. 7	56		hooking up sinks in millwork on 3rd floor			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C. 2	6 x		Synergy - wiring VAV's & devices			
Bernhard Mechanical Contractors, L.L.C. 7	66 x		hooking up sinks in millwork on 3rd floor; working on condensate drain lines on small units			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C. 2	6 x		Synergy - putting devices on exhaust fans			
Bernhard Mechanical Contractors, L.L.C. 7	56		hooking up sinks in millwork on 3rd floor; working on condensate drain lines on small units			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C. 2	6		Synergy - putting devices on exhaust fans			
Bernhard Mechanical Contractors, L.L.C. 7	66		hooking up sinks in millwork on 3rd floor; working on condensate drain lines on small units			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C. 1	8		Synergy - putting devices on exhaust fans			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc. 1	7					
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
Firestop International LLC						
Firestop International LLC 1	8 x		fire/smoke caulking			
Firestop International LLC						
Firestop International LLC 3	3		install smoke & fire caulking on 3rd floor			
Firestop International LLC						
Firestop International LLC						
Kone Inc						
Kone Inc						
Kone Inc						
Kone Inc						
Kone Inc						
Kone Inc						

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	-	ol			Job: Report #:	14-	-02-002 1
					Date:	04/	11/2016
Fair Working Days To Date:			\\\4\Cdisi	cloudy	Date. Day:		Monday
Weather Delays To Date: Is Today Claimed as Weather Day?		N	Weather Condition: Precipitation Amount:	cloudy	-		-
Critical Path Work Effected?		N	riecipitation Amount.		Temp:	Low 68	High 75
Holi Services Inc							
Holi Services Inc							
Holi Services Inc Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
	7	53		install solling tiles in places on a 1st 0: 2nd flaces			
Morris Drywall Systems Inc	7			install ceiling tiles in classrooms on 1st & 2nd floors			
Morris Drywall Systems Inc	8	64		fix misc patches in sheetrock; install border tiles on 3rd floor; fix door frames			
Morris Drywall Systems Inc	8	64 x		fix misc patches in sheetrock; install border tiles on 3rd floor; fix			
				door frames; fire caulk in stairwells			
Morris Drywall Systems Inc	9	72		fix misc patches in sheetrock; install border tiles in music roomr;			
Marris Drawall Customs Inc	8	64		fire caulk in stairwells			
Morris Drywall Systems Inc  Morris Drywall Systems Inc	0	04		clean up			
•	2	16		Contail Control Control Control			
New Orleans Glass Company, Inc.	2	16		installing misc. glass in doors			
New Orleans Glass Company, Inc.	1	1		misc hardware			
New Orleans Glass Company, Inc.	3	8		misc hardware			
New Orleans Glass Company, Inc.	2	16		caulking and drill out jamb for electronic hardware			
New Orleans Glass Company, Inc.	2	3		came and changed out 1 piece of broken glass at back storefront doors and fixed locks to cafeteria			
New Orleans Glass Company, Inc.				doors and fixed focks to cureteria			
Phoenix Constructors LLC	4	32		haul off dirt pile in SE corner of property; backfill at islands			
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Phoenix Constructors LLC	4	8		help dry up site			
Phoenix Constructors LLC				- F - 2 - F			
Cordeiro LLC							
Cordeiro LLC	2	4		wreck forms at splash blocks and remove fuel tank from site			
Cordeiro LLC				meek forms at spash should and femore fact talk from site			
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	2	16 x		install counter top in concession area; install cubbies in E115;			
Trorect Made & Display LLC	_	10 X		install cabinets in maintenance storage; misc cabinets in other rooms			
ProTech Fixture & Display LLC	2	16		install millwork			
ProTech Fixture & Display LLC	2	13		install millwork			
ProTech Fixture & Display LLC	1	5		installed main reception desk; installed shelving in gym storage			
Rufino`s Painting & Construction Inc.	5	40		misc patching & painting; final coat in gym offices and storage room; sealed 1/2 of maintenance room			
Rufino's Painting & Construction Inc.	6	48 x		misc patching & painting			
Rufino's Painting & Construction Inc.	6	48 x		misc patching & painting; installed floor sealer in 3 rooms			
Rufino's Painting & Construction Inc.	6	48		misc patching & painting			
	_						

misc patching & painting

Rufino's Painting & Construction Inc.

5

40

Project:	Sherwood Forest Elementary School				Job:	14-	02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	04/1	6/2016
Weather Dela	ays To Date:		Weather Condition:	cloudy	Day:	Sa	aturday
Is Today Clair	ned as Weather Day?	Ν	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	N				66	72

Critical Path Work Effected?		ľ	N .	
Rufino`s Painting & Construction Inc.				
Peachtree Protective Covers				
Peachtree Protective Covers				
Peachtree Protective Covers				
Peachtree Protective Covers				
Peachtree Protective Covers				
Peachtree Protective Covers				
Quality Iron Fabricators Inc.				
Quality Iron Fabricators Inc.				
Quality Iron Fabricators Inc.				
Quality Iron Fabricators Inc.				
Quality Iron Fabricators Inc.				
Quality Iron Fabricators Inc.				
River City Fire Protection				
River City Fire Protection	2	18	х	install heads in 3rd floor classrooms
River City Fire Protection	2	19		install heads in 1st floor corridor and in classrooms on 3rd floor
River City Fire Protection	2	18		install heads on 3rd floor and cleaned up their trash
River City Fire Protection				
River City Fire Protection				
Roofing Solutions LLC	7	49		install conductor heads and downspouts; work on reinstallation of gutters @ eyebrows
Roofing Solutions LLC				
Roofing Solutions LLC				
Roofing Solutions LLC	2	18		remove plastic from soffit panels
Roofing Solutions LLC				
Roofing Solutions LLC				
Roofing Solutions LLC	2	6		remove plastic from soffit panels
Roofing Solutions LLC	2	1		Tom and another guy came by to see leaks
Roofing Solutions LLC				
Roofing Solutions LLC	5	40		install soffit panels @ car drop off
Roofing Solutions LLC	4	14		one guy came out to check out leaks and then 3 more arrived to make repairs
Roofing Solutions LLC				
Roofing Solutions LLC	5	40		install soffit panels @ car drop off
Roofing Solutions LLC	3	9		worked on repairing leaks
Roofing Solutions LLC				
Roofing Solutions LLC	4	16		finished installing soffit panels at car drop off
Roofing Solutions LLC	3	12		worked on repairing leaks @ eyebrow @ courtyard
Roofing Solutions LLC				
Multivista Construction Documentation				
Multivista Construction Documentation				
Multivista Construction Documentation				
Multivista Construction Documentation				
Multivista Construction Documentation				
Multivista Construction Documentation				
Alack Refrigeration Company				

Project: Sherwood Forest Elements Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:		-02-002 1
Fair Working Days To Date:					Date:	04/1	12/2016
Weather Delays To Date:			Weather Condition:	cloudy/rain	Day:	1	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				66	78
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC	2	16		punch work in gym			
Allied Construction, LLC	2	16		punch			
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders	4	26		Install toilet partition in gang restroom on 2nd floor			
Ellison Builders				, 3 3			
Ellison Builders	3	24		installed toilet accessories			
Ellison Builders							
Ellison Builders							
OPA Graphics Inc	2	12		install exterior school signage on top of canopy			
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	15	120		work on lights in music room & stage; trim out in E3; install wire mold covers on 3rd floor			
Malone All Star JV, LLC	6	48		ADS - pull wire; trim out devices			
Malone All Star JV, LLC	2	16		Data - routing and dressing up cables			
Malone All Star JV, LLC	18	144		work on lights in music room & stage; trim out in E3; install wire mold covers on 3rd floor			
Malone All Star JV, LLC	6	48	х	ADS - pull wire; trim out devices			
Malone All Star JV, LLC	2	16		Data - routing and dressing up cables			
Malone All Star JV, LLC	15	120	х	work on lights in music room & stage; trim out in E3; work on floor boxes in media room; finish removing temp lights on 1st floor; began installing lights in stairwell of D; working on lighting			

@ stage

Project: Sherwood Forest Elementary School				Job:	14-	-02-002	
<b>Location:</b> 4801 Maid Marion Dr	rive				Report #:		1
Fair Working Days To Date:					Date:	04/1	13/2016
Weather Delays To Date:			Weather Condition:	cloudy/rain	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			·	65	71
Malone All Star JV, LLC	4	32		ADS - pull wire; trim out devices			
Malone All Star JV, LLC	3	24		Data - routing and dressing up cables			
Malone All Star JV, LLC	17	136		work on lights in music room & stage; trim out in E3; work on floor boxes in media room; finish removing temp lights on 1st floor; began installing lights in stairwell of E; working on lighting @ stage			
Malone All Star JV, LLC	3	27		ADS - pull wire; trim out devices			
Malone All Star JV, LLC	3	24		Data - routing and dressing up cables			
Malone All Star JV, LLC	17	136		work on track lights in music room; trim out in E3; pull wires on stage; install lights in C1 corridor			
Malone All Star JV, LLC	4	32		ADS - pull wire; trim out devices			
Malone All Star JV, LLC	4	32		Data - routing and dressing up cables			
Malone All Star JV, LLC							
Malone All Star JV, LLC							
Malone All Star JV, LLC	3	20		Data - routing and dressing up cables on 1st floor			
Heritage Flooring Inc.	4	32		misc prep in cafeteria; lay vct in music storage			
Heritage Flooring Inc.	3	12		lay vct in cafeteria			
Heritage Flooring Inc.	4	36		lay vct in cafeteria			
Heritage Flooring Inc.	1	1		came and walked job - did not do any work			
Heritage Flooring Inc.	6	36		finish vct in cafeteria; prep in rooms adj to media room; 2nd crew			
				arrived about noon and began prepping classrooms on E1 (234.5)			
Heritage Flooring Inc.	6	48		prepped and began laying carpet tile in media room; began			
Heritage Flooring Inc.	5	24		laying vct in east classrooms of E1 layed carpet tile in media room;finished laying vct in east classrooms of E1 (2 guys for 1.5 hrs)			
	376	2769					

Remarks:

Project:	Sherwood Forest Elementary School				Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	04/	18/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	Ν				65	77

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:40 - 5:05) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:45) oversee site operations		
Marybeth Leonard								
Chad Goubert						came by and did a safety walk this morning		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:30) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:30) oversee site operations; went to office for class from 8:00-12:00		
Marybeth Leonard								
George Caillouet						went to class @ office		
Ellen Heck						(6:30 - 4:00) oversee site operations		
Marybeth Leonard								
				2nd	2nd			
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q Sch
				*******		·		
	7	48				SEC Casework - received and hauled up shelving and furniture for		
	4	12				media room  GC Specialties - finished installing lockers in kitchen, maintenance		
						and coaches offices		
	2	18	SEC Casework			Academic - installed splashes on cabinets in science labs		
	۷	10	SEC COSEWOIK			readenine installed spirastics off capillets ill science idus		
CORE Construction Services, LLC	3	27				Pops & Slim - haul trash; Rafael - install FRP, install rubber in		
CORE Construction Services 11.C	2	27				expansion jt in vestibule		
CORE Construction Services, LLC	3	27				Pops & Slim - haul trash/unload marker/tack bds; Rafael - install rubber in expansion jt in vestibule/help unload marker/tack bds		
CORE Construction Services, LLC	3	27				Pops & Slim - haul trash, work on fixing holes for trash		
						receptacles, clean-up; Rafael - install rubber in expansion jt in		
						vestibule, cut wood blocking on pump roof, seal accoustical wall penetrations on 3rd floor		
CORE Construction Services, LLC	3	29				Slim -cut holes for waste receptacles/ installed protection bd in		
						D1 classroom for MEP storage; Rafael - seal accoustical wall		
						penetrations on 3rd floor/ installed blocking for waste receptacles/completed expansion jt on 2nd floor; Pops - clean up		
						. 222p 22.22, 2011process expansion je on 21th floor, 1 opp Clean up		

Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	04/2	22/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:		Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		Ν	I		•	65	79
CORE Construction Services, LLC	3	24		Slim - clean-up/move dumpsters; Rafael - install window sills in			
				cafeteria; Pops - clean up			
Bernhard Mechanical Contractors, L.L.C.	6	48		install labels on pipes; worked on sinks & drains			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	3	24		Synergy -			
Bernhard Mechanical Contractors, L.L.C.	8	64	x	install labels on pipes; worked on sinks & drains; began fixing error in domestic water line loop			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	2	16		Tech Test - checking out exhaust fans			
Bernhard Mechanical Contractors, L.L.C.	3	24	x	Synergy - system checkout			
Bernhard Mechanical Contractors, L.L.C.	8	64		completed fixing error in domestic water line loop; fix misc leaks; work on commissioning items			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	4	28		Tech Test - checking out exhaust fans			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	7	56		fix misc leaks; work on commissioning items; caulk units on roof of E & D			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	2	16	Test Tech	gathering info on units and taking readings for exhaust fans			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	7	56		work on commissioning items; move materials to another room; set drains in showers; misc			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	6	45	Test Tech	gathering info on units and taking readings for exhaust fans			
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC	1	3		came and did some misc caulking			
Firestop International LLC							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Morris Drywall Systems Inc	5	40		install ceiling tiles in D1 & 2 & E1& 2 corridors			

Project: Sherwood Forest Elementa	ary Schoo	ol			Job:	14-	-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	04/1	19/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	T	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				65	77
Morris Drywall Systems Inc	5	40	х	installing smoke caulk in C2 and stairwells; fix window jambs; misc			
Morris Drywall Systems Inc	7	48		patch installed tile in science rooms; fixed door frames; misc.			
Morris Drywall Systems Inc	5	50		installed tile in classrooms on 3rd floor			
Morris Drywall Systems Inc	5	50		installed tile in classrooms on 3rd floor; fire caulk in C2; clean-up			
New Orleans Glass Company, Inc.				•			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	4	24		hauled off dirt			
Phoenix Constructors LLC	4	24		hauled off dirt			
Phoenix Constructors LLC	1	4		did some grading			
Phoenix Constructors LLC	4	32		did some grading and cut down downspout drains			
Phoenix Constructors LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC	1	1		came to site to remove concrete splatter but floor guy had			
Cordeiro LLC	1	1		already taken care of it. came to site to remove concrete splatter but floor guy had			
				already taken care of it.			
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC		40					
Rufino's Painting & Construction Inc.	6	48		cleaning floors; prepped main electrical on 2nd floor; sanded 1st floor rooms where he patched and primed; prepping for final coat			
				in 1st floor admin			
Rufino`s Painting & Construction Inc.	7	56	х	sealed main electrical on 2nd floor; prepping for final coat in 1st			
Rufino`s Painting & Construction Inc.	10	80		floor admin; prepping for final coat in cafeteria sealed storage room and mech/electrical rooms (7 total); final			
Name 31 anning & Construction Inc.	10	00		coat in offices in D1; touch up media and music area			
Rufino's Painting & Construction Inc.	9	72		sealed storage room and mech/electrical rooms (2 total); final			
				coat in offices in D1; touch up media and music area; prep for final coat in classrooms of E1			
Rufino`s Painting & Construction Inc.	9	72		final coat in classrooms of E1 final coat in clinic area of D1; paint final coat in classrooms of E1			
Peachtree Protective Covers				·			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.	3	29	CSI Construction Sv	install stainless steel midrails at main stairs from 2nd to 3rd floor			
Quality Iron Fabricators Inc.	3	24	CSI Construction Sv	install stainless steel midrails at main stairs from 1st to 2nd floor			
				and began welding to stringer			

Location: 4801 Maid Marion Drive  Fair Working Days To Date:  Weather Delays To Date: Weather Condition: Sunny  Is Today Claimed as Weather Day?  N Precipitation Amount: Tem	e: y:		1 3/2016
Weather Delays To Date:  Is Today Claimed as Weather Day?  N Precipitation Amount:  Tem	y:		
Is Today Claimed as Weather Day?  N Precipitation Amount:  Tem	_	IV	
Temperature at the state of the	р:	1	onday
Critical Path Work Effected?		Low 65	High 77
River City Fire Protection			
River City Fire Protection 2 16 continue installing heads on 3rd floor			
River City Fire Protection 2 16 installing heads on 1st floor main corridor by gym & cafeteria			
River City Fire Protection 2 16 installing heads throughout  River City Fire Protection 2 16 installing heads under bleachers; misc			
Roofing Solutions LLC 5 45 installing conductor heads and downspouts; installing coping  Roofing Solutions LLC			
Roofing Solutions LLC			
Roofing Solutions LLC			
Roofing Solutions LLC			
Roofing Solutions LLC			
Roofing Solutions LLC 7 34 work on gutters at courtyard, installing downspouts			
Roofing Solutions LLC 4 32 repairs on roofing			
Roofing Solutions LLC			
Roofing Solutions LLC 7 63 work on gutters, installing conductor heads & downspouts			
Roofing Solutions LLC			
Roofing Solutions LLC			
Roofing Solutions LLC 7 63 work on gutters, installing conductor heads & downspouts			
Roofing Solutions LLC 2 8 torch down roof on eyebrows			
Roofing Solutions LLC			
Multivista Construction Documentation			
Alack Refrigeration Company			
Allied Construction, LLC			
Allied Construction, LLC			
Allied Construction, LLC 2 16 remove and replace block @ header of cafeteria window			
Allied Construction, LLC 2 16 remove and replace block at window header in cafeteria			
Allied Construction, LLC 2 16 patch/rub block in gym			
CFI Insulation Inc			
Gulf South Engineering & Testing Inc 1 1 came and picked up calcium chloride tests			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	04/	18/2016
Weather Delays To Date:			Weather Condition:	sunny	Day:	1	Monday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	65	77
Ellison Builders							
Ellison Builders	3	27		install hardware on entrance doors to media room			
Ellison Builders	3	27		install toilet partitions at the 3rd floor gang bathrooms			
Ellison Builders	3	27		hung doors and installed hardware			
Ellison Builders	3	24		hung doors and installed hardware			
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	12	96		continue working on stage; ; trim out in media room; relocate outlet and data in mant. storage; began underground site for Cox; tie up wires above ceiling on 2nd & 3rd floors; install lights in stairs; punch-out A, B & C			
Malone All Star JV, LLC	5	40		ADS - punched out in gym, kitchen & cafeteria			
Malone All Star JV, LLC	6	51		Data - installed smurf tube from floor to floor			
Malone All Star JV, LLC  Malone All Star JV, LLC	16 5	128 40	х	install lights in stair E; punch out ceilings on 3rd floor; punch out  A, B & C; install underground for pole lights			
Malone All Star JV, LLC	2	18		ADS - punched out in gym, kitchen & cafeteria  Data - work in telecom closet on 1st floor			
Malone All Star JV, LLC	15	120		install lights in stair E and main stairs; install track lights in music			
Malone All Star JV, LLC	3	24		room; install lights in C1 & stage; punch out ceilings in E3  ADS - trim out			
Malone All Star JV, LLC	4	36		Data - work in telecom closet on 2nd & 3rd floors			
Malone All Star JV, LLC	13	104		punch out 3rd floor; lights in C1, punch out stage			
Malone All Star JV, LLC	5	40	ADS	trim out			
Malone All Star JV, LLC	1	8	All Star Tech	work in telecom closet on 2nd & 3rd floors			
Malone All Star JV, LLC	14	112		punch out C1,C2, E2 & E3; lights in C1, punch out stage			
Malone All Star JV, LLC	2	16	ADS	trim out			
Malone All Star JV, LLC	1	8	All Star Tech	work in telecom closet on 2nd floor			
Heritage Flooring Inc.	7	24		layed carpet tile & vct in rooms off of media room; prepping/ laying vct in D1			
Heritage Flooring Inc.	10	24		prepped and layed VCT on D1, E1 & E2; began prepping floors in admin 1st floor			
Heritage Flooring Inc.	8	70		prepped and layed VCT on D1, E1 & E2; began prepping floors in admin 1st floor			
Heritage Flooring Inc.	7	63		prepped and layed VCT on E1 & E2; prepped kiln room			
Heritage Flooring Inc.	2	16		grouted single RR on 3rd floor across from elevator			
Heritage Flooring Inc.	6	48		prepped and layed VCT on E1 & E2; layed kiln room			
Heritage Flooring Inc.	2	16	_	grouted floor in single RR on 3rd floor across from elevator; laid tile in showers			
	379	2914					

Remarks: Roofing solutions boom lifts were picked up (1 today and 1 yesterday)

Site is extremely muddy

Communication with Subcontractors: Micke Nicolay came and we discussed change under front canopy at main entrance.

Material Delivered: Heritage brought out 2 pallets of the green VCT.

Project:	Sherwood Forest Elementary School				Job:	14	1-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	04/	/25/2016
Weather Del	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				68	80

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30 - 5:30) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30 - 5:30) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:30 - 5:30) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:30) oversee site operations		
Marybeth Leonard								
George Caillouet								
Ellen Heck						(6:45 - 4:00) oversee site operations		
Marybeth Leonard								
				2nd	2nd			
Cubaantuaatan	Sub	Sub	2nd Tion	Tier	Tier	Worls Assessmilished	s	Q Sch
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished		Q Sui
	2	10						
CODE Construction Continue II C	2	19				Academic - installed library furniture		
CORE Construction Services, LLC CORE Construction Services, LLC	3	29 27				Slim - worked on kiln; Rafael -clean up; Pops - clean up		
CORE CONSTRUCTION Services, LLC	3	21				Slim - fixed curbs under storefront at main lobby; Rafael - install window sills in cafeteria; Pops - clean up		
CORE Construction Services, LLC	3	27				Slim - worked on walk-off mats in vestibule of B by mechanical		
						room; Rafael - install wood blocking for main stair handrail; Pops		
CORE Construction Services, LLC	3	27				- clean up Slim - worked on walk-off mats in vestibule of B by mechanical		
						room & began in gym; Rafael - install wood blocking for main		
CODE Construction Continue II C	2	27				stair handrail, install grab bar in kindergarten RR; Pops - clean up		
CORE Construction Services, LLC	3	27				Slim - worked on walk-off mats in vestibule of B by mechanical room & began in gym; Rafael - install wood blocking for main		
						stair handrail, install grab bar in kindergarten RR; Pops - clean up		
Bernhard Mechanical Contractors, L.L.C.	6	48				work on commissioning items; set fixtures in RR's on 2 & 3 across		
Bernhard Mechanical Contractors, L.L.C.						from elevator		
Bernhard Mechanical Contractors, L.L.C.	3	24	Test Tech			calibrate VAV's and set grilles		
Bernhard Mechanical Contractors, L.L.C.	-							
Bernhard Mechanical Contractors, L.L.C.	8	64				work on commissioning items; set fixtures in RR's on 2 & 3 across		
						from elevator; worked on fixing crossed water lines on 2nd floor		
Perphard Machanical Contractors 1.1.C	2	24	Cumore			across from elevator; backfilled at acid dilution tank		
Bernhard Mechanical Contractors, L.L.C.	3	24	Synergy			system checkout		

Project: Location:	Sherwood Forest Element 4801 Maid Marion Drive	ary Scho	ol			Job:	14-	-02-002 1
						Report #:	0.473	
Fair Working	Days To Date:					Date:		26/2016
Weather Dela	-		N	Weather Condition:	partly cloudy	Day:	ı	uesday
•	med as Weather Day?			i recipitation Amount.		Temp:	Low	High
Critical Path V	Work Effected?		N				71	81
Bernhard Mecha	anical Contractors, L.L.C.	3	24	Test Tech	calibrate VAV's and set grilles			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	6	48		work on commissioning items; set fixtures in RR's on 2 & 3 across			
Rorphard Moch	anical Contractors, L.L.C.	1	2	Supergy	from elevator; testing & caulking fixtures moved 1 thermostat & 2 CO2 sensors in media room to allow for			
bernilaru Mech	anicai Contractors, E.E.C.	'	۷	Synergy	shelving			
Bernhard Mecha	anical Contractors, L.L.C.	5	40	Test Tech	run boxes via control program; read airflow, calibrate box and set			
					grilles			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	8	64		work on commissioning items; working on kitchen equipment;			
Bernhard Mech	anical Contractors, L.L.C.			Synergy	testing & caulking fixtures			
	anical Contractors, L.L.C.	4	32	Test Tech	run boxes via control program; read airflow, calibrate box and set			
_ciara iviecili	and conductors, E.E.C.	7	<i>J</i> _	. 250 1001	grilles			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	8	64		work on commissioning items; working on kitchen equipment;			
					adjusting floor drains; installing mixing valves at sinks in			
Rorphard Mach	anical Contractors, L.L.C.			Supergy	classrooms			
	anical Contractors, L.L.C.	4	32	Synergy Test Tech	reading and adjusting subjust face			
	anical Contractors, L.L.C.	4	24	ISS	reading and adjusting exhaust fans			
D&T Tile & Terr		4	24	155	repairing insulation			
		2	۰		unaded come or minding model story for towards @ main stories			
D&T Tile & Terr		2	8		worked some on grinding metal steps for terrazzo @ main stairs			
D&T Tile & Terr			16		worked some on grinding metal steps for terrazzo @ main stairs			
D&T Tile & Terr		3	20 21		began installing terrazzo steps & risers @ main stairs			
D&T Tile & Terr					installing terrazzo steps & risers @ main stairs			
Firestop Interna		1	8		installed smoke and fire caulking in C2			
Firestop Interna		1	8		installed smoke and fire caulking in C2			
Firestop Interna								
Firestop Interna								
Firestop Interna	nional LLC							
Kone Inc								
Kone Inc								
Kone Inc								
Kone Inc		4	4		Mary and a state of the state o			
Kone Inc	_	1	1		Jeffrey came and got the elevator to work properly this afternoon			
Holi Services Inc								
Holi Services Inc								
Holi Services Inc								
Holi Services Inc								
Holi Services Inc		_						
Morris Drywall S		5	50		installed tile in classrooms on 3rd floor; fire caulk in C2; clean-up			
Morris Drywall S		5	40		installed misc ceiling tile; clean-up; haul off materials			
Morris Drywall S	Systems Inc	5	40		installed misc ceiling tile; clean-up; haul off materials; remove tiles in cafeteria for Test Tec			
Morris Drywall S	Systems Inc	6	48		received and stocked ceiling tile; clean-up; haul off materials; fix door frames			
Morris Drywall S	Systems Inc	6	48		installed ceiling tile in media room and main lobby and corridor			
•					on B1 & C1; work on door frames in 2nd floor admin			

Report #:   Pair Working Days To Date:   Weather Condition:   Partly cloudy   Partly cloudy	1 /25/2016
Weather Delays To Date: Is Today Claimed as Weather Day? N Precipitation Amount:  Critical Path Work Effected? N  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  2 16 install removeable mullions at entrance doors  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & workled on repairing equipment  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  2 2 1 2 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Is Today Claimed as Weather Day?  Critical Path Work Effected?  N  Precipitation Amount:  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & south side of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  4 20 began removing existing fence on south side of property until they got rained out; William fine graded the south area  Phoenix Constructors LLC  2 2 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC	
Critical Path Work Effected?  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs 8 west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs 8 west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs 8 south side of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  4 20 began removing existing fence on south side of property until they got rained out; William fine graded the south area  Phoenix Constructors LLC  Phoenix Constructors LLC  2 2 3 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	Monday
New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  A 20 began removing existing fence on south side of property until they got rained out; William fine graded the south area  Phoenix Constructors LLC  Phoenix Constructors LLC  Poenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	High
New Orleans Glass Company, Inc.  2 16  New Orleans Glass Company, Inc.  2 16  Install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16  New Orleans Glass Company, Inc.  2 16  Install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  2 2  Phoenix Constructors LLC  2 2  Showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	80
New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & west end of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  A 20 began removing existing fence on south side of property until they got rained out; William fine graded the south area  Phoenix Constructors LLC  Phoenix Constructors LLC  2 2 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & south side of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  A 20  began removing existing fence on south side of property until they got rained out; William fine graded the south area  Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
New Orleans Glass Company, Inc.  2 16 install removeable mullions at ext storefront doors at main stairs & south side of C1 corridor  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  2 2 began removing existing fence on south side of property until they got rained out; William fine graded the south area showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  2 2 began removing existing fence on south side of property until they got rained out; William fine graded the south area showed up and then left  Phoenix Constructors LLC  2 2 showed up and then left  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Phoenix Constructors LLC  2 2 2 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Phoenix Constructors LLC  2 2 3 showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Phoenix Constructors LLC  Phoenix Constructors LLC  2 2 2 showed up and then left  Take down chain link on north side of project  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
they got rained out; William fine graded the south area showed up and then left  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Phoenix Constructors LLC  Phoenix Constructors LLC  3 24 take down chain link on north side of project  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	
Cordeiro LLC Cordeiro LLC Cordeiro LLC	
Cordeiro LLC Cordeiro LLC	
Cordeiro LLC	
Cordeiro LLC	
ProTech Fixture & Display LLC	
ProTech Fixture & Display LLC	
ProTech Fixture & Display LLC	
ProTech Fixture & Display LLC	
ProTech Fixture & Display LLC	
Rufino's Painting & Construction Inc. 8 64 final coat in clinic area of D1; paint final coat in classrooms of E1	
Rufino`s Painting & Construction Inc.       8       64       paint final coat in classrooms of E1 & prepped in E2	
Rufino's Painting & Construction Inc.  8 64 prep/paint final coat in classrooms of E1 & prepped in E2; 1 guy	
working on galvanized handrails for Quality	
Rufino's Painting & Construction Inc. 8 64 prep/ paint final coat in classrooms of E1 & E2; 1 guy working on	
galvanized handrails for Quality	
Rufino's Painting & Construction Inc. 6 48 prep/ paint final coat door frames in kitchen & admin; 1 guy working on galvanized handrails for Quality	
Peachtree Protective Covers	
Quality Iron Fabricators Inc.  CSI Construction Svi	
Quality Iron Fabricators Inc.  CSI Construction Svi	
Quality Iron Fabricators Inc. 3 24 CSI Alabama began installing SS wall rails (1st set complete and 1/2 of 2nd)	
Quality Iron Fabricators Inc. 3 24 CSI Alabama installing SS wall rails	
Quality Iron Fabricators Inc.  CSI Alabama	
River City Fire Protection 4 23 installing heads under bleachers; put on preliminary tests on 2nd & 3rd floors	
River City Fire Protection 4 36 installing heads under bleachers; put on preliminary tests on 2nd & 3rd floors	
River City Fire Protection 4 36 put on preliminary tests on 2nd & 3rd floors; finished installing heads in cafeteria soffits and worked on testing line on 1st floor; install trim	

Project: Sherwood Forest Elemen Location: 4801 Maid Marion Drive	tary Scho	ool			Job: Report #:	14-	02-002
Fair Working Days To Date:					Date:	04/2	8/2016
Weather Delays To Date:			Weather Condition:	cloudy/rain	Day:	Th	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				72	82
River City Fire Protection	4	32		put on preliminary tests on 2nd & 3rd floors; running down leaks on 1st floor; worked on testing line on 1st floor; install trim			
River City Fire Protection							
Roofing Solutions LLC	2	8		torch down roof on eyebrows			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	2	14		install conductor heads and gutters			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	4	16		came out to work on south eyebrow but got rained out			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	3	24		came out to work on south eyebrow			
Roofing Solutions LLC							
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC	2	16		punch in gym			
Allied Construction, LLC	2	16		punch in gym			
Allied Construction, LLC	-	10		punch in gym			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc	_	1					
Gulf South Engineering & Testing Inc	2	1		decibal testing			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders	2	16		install tack & marker bds in areas A, B & C; misc accessories			
Ellison Builders	3	24		install tack & marker bds in areas in E1			
Ellison Builders	3	18		install tack & marker bds in areas in E1			

Project: Sherwood Forest Element 4801 Maid Marion Drive	itary Scho	Ю			Job: Report #:	14-	-02-002 1
					Date:	04/2	28/2016
Fair Working Days To Date:			Weather Condition:	cloudy/rain	Day:		nursday
Weather Delays To Date: Is Today Claimed as Weather Day?		N		cioudy, a.i.	Temp:	Low	_
Critical Path Work Effected?		N	<u>-</u>		remp.	72	High 82
Ellison Builders	3	24		install tack & marker bds in areas in E1			
Ellison Builders							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	13	104		punch out 1st & 2nd floor; stage lights; install canopy lights			
Malone All Star JV, LLC	2	16	ADS	trim out			
Malone All Star JV, LLC			All Star Tech				
Malone All Star JV, LLC	12	96		punch out 2nd floor & stage; work on corridor lights in C1; install			
				wall packs			
Malone All Star JV, LLC	7	56	ADS	trim out			
Malone All Star JV, LLC	1	8	All Star Tech	terminated in 3rd floor closet			
Malone All Star JV, LLC	12	96		punch; install wall packs; dig for site lighting; install exit signs			
Malone All Star JV, LLC	5	40	ADS	trim out			
Malone All Star JV, LLC	1	8	All Star Tech	finished terminating in 3rd floor closet; clean-up			
Malone All Star JV, LLC	9	72		punch E1; install wall packs; install exit signs			
Malone All Star JV, LLC	3	24	ADS	trim out			
Malone All Star JV, LLC			All Star Tech				
Malone All Star JV, LLC	12	96		punch all areas, install exterior wall packs, exit signs all areas, get			
				power to low voltage panels and work on lights in B1 & C1			
Malone All Star JV, LLC	3	24	ADS	trim out			
Malone All Star JV, LLC	2	16	Bonded	worked on lightning protection on roofs			
Sonitrol of New Orleans Inc	2	16		Sonitrol - went through orientation and began layout			
Sonitrol of New Orleans Inc							
New Academics LLC	2	19		Academic - installed library furniture			
New Academics LLC	2	19		installed library furniture			
New Academics LLC							
Heritage Flooring Inc.	6	54		layed carpet in admin on 1st floor; installed VCT and prepped classrooms on E1 & E2			
Heritage Flooring Inc.	2	16		grouted floor in single RR on 3rd floor across from elevator, laid tile in showers			
Heritage Flooring Inc.	6	54		finished laying carpet in admin in D1; layed VCT on E1 & E2; prepped science lab on E3			
Heritage Flooring Inc.	2	16		installed mud bed in showers			
Heritage Flooring Inc.	13	97		prepped on 2nd floor; layed VCT on E1 & E2; prepped science lab			
				on E3; install base in admin and in E1 classrooms			
Heritage Flooring Inc.	2	16		installed tile in showers			
Heritage Flooring Inc.	11	97		prepped on 2nd floor; layed VCT on E1 & E2;layed science lab on E3; install base in areas A, C and a few spots in D & E			
Heritage Flooring Inc.	2	16		grouted tile in showers and worked on punch			
Heritage Flooring Inc.	11	88		prepped/layed on D2 & E3; layed scienceroom on E3; prepped stage install base in areas A, C and a few spots in D & E			
Heritage Flooring Inc.	2	16	_	punch			
	372	2916					

 $\textbf{Remarks:} \ \text{Purchased commercial washer \& dryer from Home Depot today}.$ 

Project:	Sherwood Forest Elementary School				Jo	b:	14-0	02-002
Location:	4801 Maid Marion Drive				Report	#:		1
Fair Working	Days To Date:				Da	te:	04/29	9/2016
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	D	ıy:		Friday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Ten	p: L	-OW	High
Critical Path \	Work Effected?	N					71	84

**Communication with Subcontractors:** John Kent came and talked with me concerning final clean schedule.

I called and spoke with Jonathan Bissbee today with AMCO and told them that we would be ready on Tuesday for them to begin **Notes:** 

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	05/	/02/2016
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	Ν	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				71	81

Employee						Work Accomplished		
George Caillouet						•		
Tanner Broughton								
Ellen Heck						(6:45 - 5:30) oversee site operations		
Marybeth Leonard						(U.4.) - J.JO) oversee site operations		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 5:00) oversee site operations		
Marybeth Leonard						(0.43 3.00) oversee site operations		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:25) oversee site operations		
Marybeth Leonard						(U.33 - 3.23) oversee site operations		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 -2:30) oversee site operations		
Marybeth Leonard						(0.33 -2.30) Oversee site operations		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:40 -4:30) oversee site operations		
Marybeth Leonard						(0.40 -4.50) Oversee Site operations		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:50 -3:30) oversee site operations		
Marybeth Leonard						(0.30 3.30) oversee site operations		
Mary Sectification and				2nd	2nd			
	Sub	Sub		Tier	Tier			
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sc
	2	8	WonDoor			began installation of fire partition on the 3rd floor		
	2	8	WonDoor			installation of fire partition on the 3rd floor and began 2nd floor		
	2	8	WonDoor			installation of fire partition on the 3rd floor and began 2nd floor		
CORE Construction Services, LLC	3	27				Slim - worked on walk-off mats in gym; Rafael - install wood at		
						curbs below interior storefrontl, install grab bar in kindergarten		
CORE Construction Services, LLC	3	27				RR; Pops - clean up		
COME CONSTRUCTION SERVICES, LLC	э	۷.				Slim - worked on walk-off mats in gym; Rafael - install wood at curbs below interior storefrontl, install grab bar in kindergarten		
						RR; Pops - clean up; distribute tack/marker bds; unload trucks		
CORE Construction Services, LLC	3	27				Slim - clean/grade @ south side, worked on walk-off mats in gym,		
						helped moved tack/marker boards; Rafael - install wood at curbs below interior storefrontl,install blocking at trophy case and for		
						fire extinguisher cabinets; Pops - clean up;		
CORE Construction Services, LLC	3	27				Slim - relocate tack/marker bds, work on walk-off mats; Rafael -		

Project:	Sherwood Forest Elementa	ry Scho	ol			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	05/0	06/2016
Weather Dela	ys To Date:			Weather Condition:	clear skies	Day:		Friday
Is Today Clair	ned as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N				61	80
CORE Construct	ion Services, LLC	3	27		Slim - patch brick @ canopy, work on walk-off mats; Rafael -			
					install wood at fire extinguisher cabinets; Pops - clean up;			
CORE Construct	ion Services, LLC	2	16		Slim - work on walk-off mats; move tack/marker bds; Pops -			
Bernhard Mecha	anical Contractors, L.L.C.	7	56		clean up work on commissioning items; working on kitchen equipment;			
					adjusting floor drains; installing mixing valves at sinks in			
					classrooms			
	anical Contractors, L.L.C.	2	2.4	Synergy				
	anical Contractors, L.L.C.	3	24	Test Tech	begin testing units			
	anical Contractors, L.L.C.							
Bernnard Mech	anical Contractors, L.L.C.	6	48		work on commissioning items; working on kitchen equipment; adjusting floor drains; installing mixing valves at sinks in			
					classrooms			
Bernhard Mecha	anical Contractors, L.L.C.	2	16	Synergy	worked on programming			
Bernhard Mecha	anical Contractors, L.L.C.	3	24	Test Tech	testing static pressure, amps and total air @ A/C units			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	6	48		work on commissioning items; working on boiler and water			
					heater vents through roof; installing mixing valves at sinks in classrooms			
Bernhard Mecha	anical Contractors, L.L.C.	1	6	Synergy	worked on programming			
Bernhard Mecha	anical Contractors, L.L.C.	5	40	Test Tech	testing AHU's			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.	6	48		work on commissioning items;installing mixing valves at sinks in			
					classrooms			
	anical Contractors, L.L.C.	1	7	Synergy	programming			
	anical Contractors, L.L.C.	3	24	Test Tech	testing AHU's			
	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.	6	48		work on commissioning items; clean out office trailer and container; installing mixing valves at sinks in classrooms			
Bernhard Mecha	anical Contractors, L.L.C.			Synergy	container, instaining mixing varies at sinite in classiconis			
Bernhard Mecha	anical Contractors, L.L.C.	3	24	Test Tech	testing AHU's			
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.							
Bernhard Mecha	anical Contractors, L.L.C.			Synergy				
Bernhard Mecha	anical Contractors, L.L.C.			Test Tech				
Bernhard Mecha	anical Contractors, L.L.C.							
D&T Tile & Terr	azzo Co. Inc.	2	16		installing terrazzo steps & risers @ main stairs			
D&T Tile & Terr	azzo Co. Inc.	2	16		installing terrazzo steps & risers @ main stairs			
D&T Tile & Terr	azzo Co. Inc.	2	16		installing terrazzo steps & risers @ main stairs			
D&T Tile & Terr	azzo Co. Inc.	3	24		grouting terrazzo steps & risers @ main stairs			
D&T Tile & Terr	azzo Co. Inc.	3	24		grouting terrazzo steps & risers @ main stairs			
D&T Tile & Terr	azzo Co. Inc.	3	15		polishing in corridors D1 & D2			
Firestop Interna	tional LLC							
Firestop Interna	tional LLC							
Firestop Interna								
Firestop Interna								
Firestop Interna		2	16		fire caulk & exterior brick joints			
Firestop Interna	tional LLC							
Kone Inc								

Project:	Sherwood Forest Elementary School	Job:	14-02-002				
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	05/0	3/2016
Weather Dela	ys To Date:		Weather Condition:	partly cloudy	Day:	7	Tuesday
Is Today Clain	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				63	77
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							

Kone Inc			
Kone Inc			
Holi Services Inc			
Holi Services Inc			
Holi Services Inc			
Holi Services Inc			
Holi Services Inc			
Holi Services Inc	5	36	move tack/marker bds; clean-up interior & exterior
Morris Drywall Systems Inc	6	34	installed ceiling tile in corridor on B1 & C1
Morris Drywall Systems Inc	3	24	install clips for accoustical panels in gym
Morris Drywall Systems Inc	2	16	install clips for accoustical panels in gym
Morris Drywall Systems Inc	3	20	
Morris Drywall Systems Inc	3	20	patch walls at stage and misc
Morris Drywall Systems Inc			
New Orleans Glass Company, Inc.			
New Orleans Glass Company, Inc.			
New Orleans Glass Company, Inc.			
New Orleans Glass Company, Inc.			
New Orleans Glass Company, Inc.	3	2	remove door on 2nd floor that was dragging
New Orleans Glass Company, Inc.			
Phoenix Constructors LLC	3	24	take down chain link on north side of project; take down trees on south side of property
Phoenix Constructors LLC	4	32	move dirt @ SE corner of property to allow for fence; clean road; clean fence line
Phoenix Constructors LLC	5	34	move dirt @ SE corner of property to allow for fence; clean road; clean fence line
Phoenix Constructors LLC	4	32	move dirt; remove fence; clean road; grade at west side of site
Phoenix Constructors LLC	4	32	move dirt; remove fence; clean road; grade at west side of site
Phoenix Constructors LLC			
Cordeiro LLC			
Cordeiro LLC			
Cordeiro LLC			
Cordeiro LLC			
Cordeiro LLC			
Cordeiro LLC			
ProTech Fixture & Display LLC			
ProTech Fixture & Display LLC			
ProTech Fixture & Display LLC			
ProTech Fixture & Display LLC			
ProTech Fixture & Display LLC			
ProTech Fixture & Display LLC			
Rufino's Painting & Construction Inc.	11	88	prep/ paint final coat door frames in kitchen & admin; 1 guy

prep/ paint final coat door frames in kitchen & admin; 1 guy working on galvanized handrails for Quality; final coat of paint in science rooms.

Project:	Sherwood Forest Elementar	y Scho	ol				Job:	14-	02-002
Location:	4801 Maid Marion Drive						Report #:		1
Fair Working	Days To Date:						Date:	05/0	3/2016
Weather Dela	-			Weather Cond	dition:	partly cloudy	Day:	Т	uesday
Is Today Clain	ned as Weather Day?		N	Precipitation A	Amount:		Temp:	Low	High
Critical Path V	Vork Effected?		N					63	77
Rufino`s Paintin	g & Construction Inc.	11	88			final coat paint in cafeteria; work in gym; final coat in admin			
Rufino`s Paintin	g & Construction Inc.	12	96			final coat paint in cafeteria; final coat chair storage and sound			
						closet by gym; final coat frames in D1 & E1; final coat some rooms on E3			
Rufino`s Paintin	g & Construction Inc.	9	72			final coat paint in cafeteria & gym			
Rufino`s Paintin	g & Construction Inc.	8	64			final coat paint on stage and gym			
Rufino`s Paintin	g & Construction Inc.								
Peachtree Prote	ctive Covers								
Peachtree Prote	ctive Covers								
Peachtree Prote									
Peachtree Prote	ctive Covers								
Peachtree Prote									
Peachtree Prote									
Quality Iron Fab				CSI Alabama					
Quality Iron Fab				CSI Alabama					
Quality Iron Fab				CSI Alabama					
Quality Iron Fab				CSI Alabama					
Quality Iron Fab				CSI Alabama					
Quality Iron Fab		2	16	CSI Alabama		finish installing stainless steel wall rails in main stairs			
River City Fire P									
River City Fire P									
River City Fire P									
River City Fire P		2	8			put water on system			
River City Fire P									
River City Fire P			40						
Roofing Solution	ns llc	6	48			installing collector heads and downspouts at west side of property			
Roofing Solution	ns LLC					r - r - 9			
Roofing Solution	ns LLC								
Roofing Solution	ns LLC	9	81			continue installation of collector heads, down spouts, coping & coverplates			
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC	1	3			removed 2 downspouts and moved material			
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Roofing Solution	ns LLC								
Multivista Const	ruction Documentation								
Multivista Const	ruction Documentation								

Project: Sherwood Forest Elemer  4801 Maid Marion Drive	ntary Scho	ol			Job:	14	-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:		04/2016
Weather Delays To Date:			Weather Condition:	sunny skies	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				64	76
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Alack Refrigeration Company							
Alack Refrigeration Company	2	8		removed protective film from kitchen stainless steel items and reset up kitchen			
Alack Refrigeration Company	1	2	Hobart	started up dishwash machine			
Alack Refrigeration Company	2	6		started up steamers, tilt, burner & oven			
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC	1	5		rub/punch walls in C1 laundry & gym			
Allied Construction, LLC							
Allied Construction, LLC	2	8		interior & exterior punch			
Allied Construction, LLC	1	3		exterior punch			
Allied Construction, LLC	1	4		exterior punch			
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders	3	21		install tack & marker boards on 1st floor			
Ellison Builders	3	21		install tack & marker boards on 2ndt floor			
Ellison Builders	3	15		instal clips for tack & marker boards on 2ndt floor			
Ellison Builders	3	15		install tack & marker bds on 2nd floor			
Ellison Builders							
Ellison Builders							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	12	96		punch all areas, install exterior wall packs, lights in C1 corridor; wattstopper			
Malone All Star JV, LLC	3	24	ADS	trim out			

Malone All Star JV, LLC

				Date:	05/	03/201
		Weather Condition:	partly cloudy	Day:		Tuesda
	N	Precipitation Amount:		Temp:	Low	Hig
	N				63	7
12	96		punch all areas, install exterior wall packs, lights in C1 corridor;			
3	24	ΔDS	wattstopper trim out			
		bolided				
	•		building; punch out; work in IT rooms			
4	36	ADS	trim out			
10	80		work on pole lights; pull wire for site lighting; punch out;			
4	32	ADS	trim out			
10	80		stand pole lights; pull wire for site lighting; punch out;			
			wattstopper			
4	32	ADS	trim out			
3	18		work on lightning protection			
		ADS				
2	16		began pulling wire in 1st floor corridors			
3	24		pull wires			
3	24		pull wire			
2	4		install benches			
2	21	SEC	finish putting together library shelving and reception desk			
2	8	SEC	unloaded and distributed media room chairs			
		SEC				
		SEC				
		SEC				
		SEC				
8	60		prepped/layed on D2 & E3; prepped stage and adjacent rooms; install base in areas A, C and a few spots in D & E			
2	16		punch			
11	88		prepped/layed on D2 & E3; layed stage and adjacent rooms; install base in all areas			
1	8		punch			
11	88		prepped/layed on D2 & E3; began prepping stair E			
3	24		punch			
11	88					
	10 4 10 4 3 2 2 2 2 2 2 11 11 11 3	2 16 10 80 4 36 10 80 4 32 10 80 4 32 3 18 2 16 3 24 3 24 2 4 2 4 2 16 11 88 11 88 11 88 11 88 3 24	2 16 Bonded 10 80  4 36 ADS  10 80  4 32 ADS  10 80  4 32 ADS  3 18 ADS  2 16  3 24 3 24 3 24  2 16 5EC 5EC 5EC 5EC 5EC 5EC 8 60 2 16 11 88 11 88 11 88 11 88 11 88 11 88 11 88	work on lightning protection work on pole lights; install pull cord for telephone line into building; punch out; work in IT rooms trim out  work on pole lights; pull wire for site lighting; punch out; wattstopper trim out  work on pole lights; pull wire for site lighting; punch out; wattstopper trim out  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  ADS  and S  trim out  ADS  began pulling wire in 1st floor corridors  pull wire  pull wire  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  ADS  finiout  ADS  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  also began pulling wire in 1st floor corridors  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  also began pulling wire in 1st floor corridors  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  also began pulling wire in 1st floor corridors  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  also began pulling wire in 1st floor corridors  sinstall benches  finish putting together library shelving and reception desk unloaded and distributed media noom chairs  stand pole lights; pull wire for site lighting; punch out; wattstopper trim out  also began pulling wire in 1st floor corridors  install benches	work on lightning protection work on lightning protection work on pole lights; install pull card for telephone line into buildings punch out; work in IT reams trim out  North on pole lights; pull wire for site lighting; punch out; watstopper trim out  Stand pole lights; pull wire for site lighting; punch out; watstopper trim out  Stand pole lights; pull wire for site lighting; punch out; watstopper  A 32 ADS trim out  ADS  It in out  North on lightning protection  ADS  Degan pulling wire in 1st floor comidors  pull wires  pull wire  pull wire  SEC  SEC  SEC  SEC  SEC  SEC  SEC  SE	2 16 Bonded work on lightning protection work on pole lights; tristall pull cord for telephone line into buildings punch out; work in IT rooms trim out  10 80 work on pole lights; pull wire for site lighting; punch out; wattropper trim out  11 80 stand pole lights; pull wire for site lighting; punch out; wattropper trim out  12 ADS trim out  13 18 work on lightning protection  ADS  2 16 began pulling wire in 1st floor corridors  3 24 pull wire  2 4 install benches  2 15 SEC finish putting together library shelving and reception desk unloaded and distributed media room chairs  5 SEC

Project:	Sherwood Forest Eleme	ntary Scho	ol			Job:	14-	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	05/0	05/2016
Weather Dela	ays To Date:			Weather Condition:	sunny skies	Day:	TI	hursday
Is Today Clair	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?		N				60	76
Heritage Floorin	ng Inc.	2	16		punch			
Heritage Floorii	ng Inc.	11	88		began laying corridors on 2nd & 3rd floors; complete installation of treads and risers in stair D; install misc base			
Heritage Floori	ng Inc.	2	16		punch			
Heritage Floorii	ng Inc.	5	15		prepped corridor on 2nd & a classroom on 3rd; installed cut tiles on east end of corridor on 3			
Heritage Floori	ng Inc.							
		388	2910					

**Remarks:** Phoenix reported to the police that their skidstir was stolen last night.

2 of Heritage's crews left by 10:30 because they ran out of floor patch. I was unable to contact Mitchel to get more.

Project:	Sherwood Forest Elementary School	ol			Jo	b:	14-02	-002
Location:	4801 Maid Marion Drive				Repor	; <b>#:</b>		1
Fair Working	Days To Date:				Da	<b>ite:</b> 0	05/09/2	2016
Weather Dela	ays To Date:		Weather Condition:	overcast	D	ay:	Mor	nday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Ter	<b>np:</b> Low	, I	High
Critical Path	Work Effected?	N				7	1	80

Employee						Work Accomplished			
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:35 -5:15) oversee site operations			
Marybeth Leonard									
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:45 -5:15) oversee site operations			
Marybeth Leonard									
George Caillouet									
Tanner Broughton						punch out of main admin area			
Ellen Heck						(6:50 -5:15) oversee site operations; punched out main admin area			
Marybeth Leonard									
Chad Goubert						stopped by this morning and walked			
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:42 -5:15) oversee site operations; walked with fire marshall			
Marybeth Leonard									
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:42 -5:15) oversee site operations; worked on making punch list			
Marybeth Leonard									
George Caillouet									
Tanner Broughton									
Ellen Heck						(6:42 -1:00) oversee site operations; clean-up			
Marybeth Leonard									
				2nd	2nd				
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier Wrkrs	Tier Hrs	Work Accomplished	s	Q	Sch
	1	2		AALKIS	піз	began coring for rails at gym			
	4	27	KMT			coring for rails			
	3	21	KMT			coring for rails			
	3	3	KMT			coring for rails			
CORE Construction Services, LLC	3	19				Slim - installed portable stage/ moved things out of corridor,			
CORE Construction Services, LLC	5	48				Pops - clean up; Slim - clean up exterior; Pops - clean up; Rafael & Jose - work on			
CORE Construction Services, LLC	5	48				trophy case; Raul - cut tubing for canopy light supports  Slim, Jose & Raul - installed exterior & interior wall rails; Pops -			
	-					installed pour rock at exterior rails; Rafael - installed misc missing			
						blocking for rails, dispersed appliances to where they are needed			
CORE Construction Services, LLC	3	29				Slim & Jose - installed exterior & interior wall rails; Pops -			

Project: Location:	Sherwood Forest Elementa 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14-	-02-002 1
						<u>-</u>	0E /1	
•	Days To Date:				manths alosads.	Date:	05/1	13/2016
Weather Dela	•		N	Weather Condition:	partly cloudy	Day:		Friday
-	ned as Weather Day?		N	recipitation Amount.		Temp:	Low 68	High 84
	Vork Effected?							04
CORE Construct	ion Services, LLC	4	32		Slim & Raul - installed exterior & interior wall rails; Pops -pour between column and paving at downspout drains on west side of bldg; Rafael - install corner gaurds in areas A & B			
CORE Construct	ion Services, LLC	3	24		Rafael, Jose & Raul - installed wire cages in maintenance storage			
Bernhard Mech	anical Contractors, L.L.C.	5	40		work on commissioning items; installing mixing valves at sinks			
Bernhard Mech	anical Contractors, L.L.C.			Synergy				
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.	6	48		working on running condensates for water heaters; caulking fixtures			
Bernhard Mech	anical Contractors, L.L.C.			Synergy				
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.	6	48		working on mini split systems; caulking fixtures			
Bernhard Mech	anical Contractors, L.L.C.	1	8	Synergy	work on programing			
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.	5	40	X	working on mini split systems; caulking fixtures			
Bernhard Mech	anical Contractors, L.L.C.	1	8	Synergy	work on programing			
Bernhard Mech	anical Contractors, L.L.C.	1	6	Tech Test	gather data on vav boxes			
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.	5	40		punch; clean-up			
Bernhard Mech	anical Contractors, L.L.C.	1	3	Synergy	worked on water heater			
Bernhard Mech	anical Contractors, L.L.C.			Tech Test				
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.							
Bernhard Mech	anical Contractors, L.L.C.			Synergy				
Bernhard Mech	anical Contractors, L.L.C.			Tech Test				
Bernhard Mech	anical Contractors, L.L.C.							
D&T Tile & Terr	azzo Co. Inc.	3	24		polishing corridor on B1 & C1 and completed the west side of the main stair			
D&T Tile & Terr	azzo Co. Inc.	3	24		began working on other half of main stair steps			
D&T Tile & Terr	azzo Co. Inc.	3	24		working on east half of main stair steps			
D&T Tile & Terr	azzo Co. Inc.	3	24		working on east half of main stair steps			
D&T Tile & Terr	azzo Co. Inc.	3	14		working on east half of main stair steps			
D&T Tile & Terr	azzo Co. Inc.	5	33		installing base, began sealing			
Firestop Interna	tional LLC							
Firestop Interna	tional LLC	2	16		fire caulk			
Firestop Interna	tional LLC							
Firestop Interna	tional LLC	2	9		here for fire marshall walk			
Firestop Interna	tional LLC							
Firestop Interna	tional LLC							
Kone Inc		1	1		Mike came by about 2:00 and shut down elevator so that we could finish the shaft work.			
Kone Inc								
Kone Inc		1	1		came and turned elevator back on for service			
Kone Inc								

Project: Sherwood Forest Elementary School Location: 4801 Maid Marion Drive	Job: 1. Report #:	4-02-002 1
Frie Westing Door To Date:	·	5/13/2016
Fair Working Days To Date:		Friday
Weather Delays To Date: Weather Condi		_
	mount: Temp: Low 68	High 84
		04
Kone Inc		
Holi Services Inc 2 16	helped with portable stage & clean-up	
Holi Services Inc 2 10	clean-up	
Holi Services Inc 1 10	helped Pops with pour rock, clean-up	
Holi Services Inc 1 10	helped Pops with pour rock, clean-up	
Holi Services Inc 1 8	helped Pops with pour rock, clean-up	
Holi Services Inc 3 16	Carey (7:00), Cornelius (8:15) & Claude (9:30) worked on clean-up	
	of gym, cafeteria & kitchen	
Morris Drywall Systems Inc 3 20	reinstall misc ceiling tiles	
Morris Drywall Systems Inc 3 20	fire caulk elevator shaft	
Morris Drywall Systems Inc 5 25	fire caulk elevator shaft	
Morris Drywall Systems Inc 4 32 x	install accoustical panels in gym	
Morris Drywall Systems Inc	install accoustical panels in gym	
Morris Drywall Systems Inc		
New Orleans Glass Company, Inc.		
New Orleans Glass Company, Inc.		
New Orleans Glass Company, Inc.		
New Orleans Glass Company, Inc. 2 16 x	install misc hardware; install a couple of pieces of glass	
New Orleans Glass Company, Inc.		
New Orleans Glass Company, Inc.		
Phoenix Constructors LLC		
Phoenix Constructors LLC 5 38	continue to remove old chain link fence; cut and prep Robin Hood St for pourback	
Phoenix Constructors LLC 5 38	continue to remove old chain link fence; cut and prep Robin Hood St for pourback	
Phoenix Constructors LLC 4 32 x	continue to remove old chain link fence; cut and prep Robin  Hood St for pourback	
Phoenix Constructors LLC 2 16	redo drain lines on west side of cafeteria so they line up with downspouts	
Phoenix Constructors LLC	·	
Cordeiro LLC		
ProTech Fixture & Display LLC 2 16	adjust hardware, clean & caulk classrooms on 3rd floor; finish installation of millwork in maintenance storage; installed shelves	
ProTech Fixture & Display LLC 2 14	adjust hardware, clean & caulk classrooms on 2nd floor; installed shelves	
ProTech Fixture & Display LLC		
ProTech Fixture & Display LLC		
ProTech Fixture & Display LLC		
ProTech Fixture & Display LLC		
Rufino's Painting & Construction Inc. 9 81	final coat classrooms on 2nd & 3rd floor	
Rufino's Painting & Construction Inc. 13 104	final coat classrooms; began prepping corridors on 2nd & 3rd	

floors; prep/paint HM frames in music room

Project: Sherwood Forest Elementary Location: 4801 Maid Marion Drive		ool			Job: Report #:	14-02-002 1		
Fair Working Days To Date:					Date:	05/1	1/2016	
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	Wedi	nesday	
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High	
Critical Path Work Effected?		N				70	86	
Rufino's Painting & Construction Inc.	11	88		final coat classrooms; prepping corridors on 2nd & 3rd floors;				
Rufino's Painting & Construction Inc.	13	104 x		final coat misc rooms; prepping corridors on 2nd & 3rd floors;				
Rufino's Painting & Construction Inc.	14	112		final coat misc rooms; prepping corridors on 2nd & 3rd floors;				
Rufino's Painting & Construction Inc.	4	32		final coat frames in gym area; seal mechanical room and C2 corridor				
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Peachtree Protective Covers								
Quality Iron Fabricators Inc.	4	32		unloaded rails and began layout of cores				
Quality Iron Fabricators Inc.	2	4		unloaded wall rails				
Quality Iron Fabricators Inc.	4	32		install exterior handrails				
Quality Iron Fabricators Inc.	4	32 x		install exterior handrails				
Quality Iron Fabricators Inc.								
Quality Iron Fabricators Inc.								
River City Fire Protection								
River City Fire Protection	3	14		start-up fire pump and check system; trim				
River City Fire Protection	2	6		came to site and ran tests with ADS; install trim plates				
River City Fire Protection	2	8 x		came to site and ran tests with ADS; install trim plates				
River City Fire Protection								
River City Fire Protection								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC	8	40		work on misc sheetmetal work				
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Roofing Solutions LLC								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								
Multivista Construction Documentation								

Project: Location:	<b>Sherwood Forest Elementa</b> 4801 Maid Marion Drive	ary Scho	ol			Job: Report #:		-02-002 1
Fair Working	Days To Date:					Date:	05/	14/2016
Weather Del	ays To Date:			Weather Condition:	mainly sunny	Day:	S	aturday
Is Today Clai	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?		N				68	87
Multivista Cons	struction Documentation							
Alack Refrigera	tion Company							
Alack Refrigera	ition Company	1	1		punch-out			
Alack Refrigera	tion Company							
Alack Refrigera	ition Company	2	5		here for fire marshall walk			
Alack Refrigera	ition Company							
Alack Refrigera	tion Company							
Allied Construc	ction, LLC							
Allied Construc	ction, LLC							
Allied Construc	ction, LLC							
Allied Construc	ction, LLC							
Allied Construc	ction, LLC							
Allied Construc	ction, LLC							
CFI Insulation I	nc							
CFI Insulation I	nc							
CFI Insulation I	nc	1	1		came by to pick up materials			
CFI Insulation I	nc							
CFI Insulation I	nc							
CFI Insulation I	nc							
Gulf South Eng	ineering & Testing Inc							
Gulf South Eng	ineering & Testing Inc							
Gulf South Eng	ineering & Testing Inc							
Gulf South Eng	ineering & Testing Inc							
Gulf South Eng	ineering & Testing Inc							
Gulf South Eng	ineering & Testing Inc							
Ellison Builders	i	2	16		hooked up door closures; misc hardware			
Ellison Builders	:	2	9		misc hardware			
Ellison Builders	;	2	6		misc hardware @ kitchen; install changing stations			
Ellison Builders	;	2	8		misc hardware @ kitchen; install misc accessories			
Ellison Builders	;	2	14		misc hardware @ kitchen; install misc accessories			
Ellison Builders	:							
OPA Graphics I	Inc							
OPA Graphics I	Inc							
OPA Graphics I	Inc							
OPA Graphics I								
OPA Graphics I								
OPA Graphics I								
Malone All Star		12	96		punch out; underground for pole lights; fix/troubleshoot lights			
Malone All Star		4	32	ADS	trim out fire and access controls			
Malone All Star		2	8	Bonded	work on lightning protection			
Malone All Star		11	88		punch out; underground for pole lights; fix/troubleshoot lights			
Malone All Star		4	24	ADS	trim out fire			
Malone All Star		2	8	Bonded	work on lighting protection			
Malone All Star		11	88		punch out; underground for pole lights; fix/troubleshoot lights			
Malone All Star	r JV, LLC	7	56	ADS	trim out fire, speakers & sound			

Project: Sherwood Forest Elementary Sch Location: 4801 Maid Marion Drive		ool			Job: Report #:	14-02-002		
Fair Working Days To Date:					Date:	05/1	1/2016	
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	Wed	nesday	
Is Today Claimed as Weather Day?		N			Temp:	Low	High	
Critical Path Work Effected?		N	•			70	86	
Malone All Star JV, LLC	2	8	Bonded	work on lighting protection				
Malone All Star JV, LLC	8	64	х	punch out; underground for pole lights; fix/troubleshoot lights				
Malone All Star JV, LLC	7	37	ADS	trim out fire, speakers & sound				
Malone All Star JV, LLC			Bonded					
Malone All Star JV, LLC	9	72		punch out; clean-up				
Malone All Star JV, LLC	3	24	ADS	trim out fire, speakers & sound				
Malone All Star JV, LLC			Bonded					
Malone All Star JV, LLC								
Malone All Star JV, LLC			ADS					
Malone All Star JV, LLC			Bonded					
Sonitrol of New Orleans Inc	3	24		pull wire on 3rd floor				
Sonitrol of New Orleans Inc	3	24		pull wire on 3rd floor				
Sonitrol of New Orleans Inc								
Sonitrol of New Orleans Inc								
Sonitrol of New Orleans Inc								
Sonitrol of New Orleans Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
Atlas-Edco Inc								
New Academics LLC			SEC					
New Academics LLC			SEC					
New Academics LLC			SEC					
New Academics LLC			SEC					
New Academics LLC			SEC					
New Academics LLC			SEC					
Amko Fence-Kenner, LLC	2	17		began installation of fence poles for the wood fence on the south side				
Amko Fence-Kenner, LLC	2	19		completed installation of fence poles for the wood fence on the south side				
Amko Fence-Kenner, LLC	1	9		installed rails on wood fence on south side				
Amko Fence-Kenner, LLC	2	20		installed rails on wood fence on south side and began with pickets				
Amko Fence-Kenner, LLC								
Amko Fence-Kenner, LLC								
Heritage Flooring Inc.	4	32		finished prepping SW science room; prepped and glued a section of 2nd floor corridor; installed treads & risers in stair D and began prepping landings in stair E				
Heritage Flooring Inc.	1	8		punch 2nd & 3rd gang restrooms				
Heritage Flooring Inc.	11	80		began laying VCT in last science room; continue laying tile on 2nd floor corridor; prep another section of the2nd & 3rd floor corridors; installed base				
Heritage Flooring Inc.	2	16		punch 2nd & 3rd gang restrooms				

Project: Sherwood	Forest Elementary Scho	ool			Job:	14-	-02-002
<b>Location:</b> 4801 Maid	Marion Drive				Report #:		1
Fair Working Days To Date	e:				Date:	05/1	1/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	Wed	Inesday
Is Today Claimed as Weath	her Day?	Ν	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected	<b>i</b> ?	N				70	86
Heritage Flooring Inc.	9	81		prepping 3rd floor corridor and locker room and lay a section of 3rd floor corridoe; prepping/laying 2nd floor corridor; prepping music room; installation of base throughout; prep office across from elevator on 1st floor and layed carpet tile; prep landings in stair E			
Heritage Flooring Inc.	2	16		punch 2nd & 3rd gang restrooms			
Heritage Flooring Inc.	8	72		lay 3rd floor corridor and locker room and prep a section of 3rd floor corridoe; prepping/laying 2nd floor music room; installation of base throughout; lay tile landings in stair E			
Heritage Flooring Inc.	2	16		punch 2nd & 3rd gang restrooms			
Heritage Flooring Inc.	10	80		lay last section of 3rd floor corridor; prepping/laying 2nd floor music room; installation of base throughout; lay tile landings in stair E			
Heritage Flooring Inc.	4	32		punch ceramic tile			
Heritage Flooring Inc.	10	80		laying 2nd floor music room; installation of base throughout; prep/lay last section of corridor on 2; prep and lay E1 corridor and prepped other half; prep/lay office at back side of music room			
Heritage Flooring Inc.	2	16		punch ceramic tile			
	405	2992					

Remarks:

Project:	Sherwood Forest Elementary School				Job:	14	-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	05/	15/2016
Weather Dela	ays To Date:		Weather Condition:	sunny	Day:		Sunday
Is Today Clair	ned as Weather Day?	Ν	Precipitation Amount:		Temp:	Low	High
Critical Path \	Work Effected?	Ν				69	83

 Q Sc
S

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	-	ool			Job: Report #:	14-02-0
Fair Working Days To Date:					Date:	05/19/20
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	Thurso
Is Today Claimed as Weather Day?		Ν	Precipitation Amount:		Temp:	Low Hi
Critical Path Work Effected?		Ν	I			73
CORE Construction Services, LLC	5	48		Slim & Pops -work on walk off mat frames at main entry; Rafael-help with handrails & downspout boots; Jose & Raul -		
CORE Construction Services, LLC	5	48		worked on handrails and installed downspout boots  Slim & Pops -work on walk off mat frames at main entry and gym exterior; Rafael-help with handrails & downspout boots; Jose &  Raul - worked on handrails and installed downspout boots		
CORE Construction Services, LLC	4	32		Slim & Pops -poured at walk off mat frames at main entry and worked gym exterior; Jose & Raul - worked on cages in gym storage		
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.			Synergy			
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	5	40		punch; clean-up		
Bernhard Mechanical Contractors, L.L.C.			Synergy			
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	5	40		punch; worked on getting mini splits completed		
Bernhard Mechanical Contractors, L.L.C.	1	6	Synergy	controls for boilers		
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	4	32		fix leaks, install exterior drinking fountains, punch		
Bernhard Mechanical Contractors, L.L.C.	1	6	Synergy	controls for boilers		
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	4	32		fix leaks, install clean out covers, punch		
Bernhard Mechanical Contractors, L.L.C.	3	21	Synergy	controls		
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.	5	40	x	install access covers; clean-up		
Bernhard Mechanical Contractors, L.L.C.	1	8	Synergy	installing thermostat cover guards		
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.			Tech Test			
Bernhard Mechanical Contractors, L.L.C.						
D&T Tile & Terrazzo Co. Inc.	5	40		Sealing and Polishing on 1 and 2.		
D&T Tile & Terrazzo Co. Inc.	4	32		working on east half of main stair steps & seal/polish remainder of corridor in B1		
D&T Tile & Terrazzo Co. Inc.	4	32		install and caulk base		
D&T Tile & Terrazzo Co. Inc.	4	32		polishing east half of main stairs		
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
Firestop International LLC						
Firestop International LLC						

Medical Delay To Delice	Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14	-02-002 1	
Methodo plays to Date   1	Fair Working Days To Date:					Date:	05/	17/2016	
Post	• •			Weather Condition:	cloudy/rain	Day:		Tuesday	
Timeson   Profession	-		١			-		-	
Freedop International LC  Freedop Internatio			١	•				_	
Freedop International LC  Freedop Internatio	Firestop International LLC								
Freeting International LG Freeting Internati	•								
Frestgo Intensifical LC   Final Process   Fina	•								
Formation									
Kore Inc         Kore Inc           Red Services Inc         10         10         Colon Up           Red Services Inc         11         10         Colon Up           Red Services Inc         12         10         Colon Up           Morth Dynall Systems Red         25         10         Colon Up           Morth Dynall Systems Red         27         10         Accounted Services In Services In Colon Up           Morth Dynall Systems Red         27         10         Accounted Services In Colon Up           New Orleans Class Company, Inc         Kore Orleans Class Company, Inc         Kore Orleans Clas	•								
Name   10   1	•								
Name   10   1									
Kone Inc           Kone Inc           Kone Inc           Kone Inc           Kone Inc           Hot Services Inc           Hot Services Inc           100 Services Inc         1         2         1         2         1         2         2         2         2         2         2         2         2         2         2         2         2         2         2 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
Kore Inc           Kore Inc           Hort Scrives Inc           Holl Services Inc         1									
Kone Inc.  For I									
Konservices Inc.         Food Services Inc.         10 Inc. Services Inc. <th col<="" td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	<td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Holi Services Inc.   Holi Services Inc.   1									
Heli Services Inte									
Holis Services inc		1	10		helped Slim & Pops and helped move temp offices across the hall				
Holi Services Inc.									
Maniferices Inc.					•				
Holi Services Inc									
Holis Services Inc					•				
Morris Dywall Systems Inc  Morris Dywall Systems Inc  Morris Dywall Systems Inc  2 2 16									
Morris Drywall Systems Inc  2 2 16 2 install accoustical wall panels in gym  Morris Drywall Systems Inc  2 2 16 2 install accoustical wall panels in gym  Morris Drywall Systems Inc  3 2 24 2 install accoustical wall panels in gym  Morris Drywall Systems Inc  3 2 24 2 install accoustical wall panels in music room  Morris Drywall Systems Inc  Morris Drywall Systems Inc  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc  New Orlea		'	Ü		clean up				
Morris Dywall Systems Inc New Orleans Glass Company, Inc. New Orleans Glass Co		3	20		close up and caulk in ctairs				
Morris Drywall Systems Inc  New Orleans Glass Company, Inc.  New Orleans Glass Company									
Morris Drywall Systems Inc  3 24 x  install accoustical wall panels in music room  Morris Drywall Systems Inc  New Orleans Glass Company, Inc  New Orleans Gla									
Morris Dywall Systems Inc  Morris Dywall Systems Inc  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  New Orleans Glass Company, Inc.					·				
Morris Drywall Systems Inc  New Orleans Glass Company, Inc.  New O				v					
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  A 1 2 work on grading at west side until it began raining  work on grading at west side  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC		3	24	*	ilistali accoustical wali paneis ili filusic footii				
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Ordeiro LCC  Cordeiro LLC  Ordeiro LLC  Ordeiro LLC  New Orleans Glass Company, Inc.  I a la la work on grading at west side until it began raining  work on grading at west side until it began raining  work on grading at west side until it began raining  work on grading at west side  work on grading at west side until it began raining  to show the more discovered to show the more	* *								
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  A 2 32									
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  A 2 32  help clean north fence line (Core did over half of the work assisting/prompting them to get it done)  Phoenix Constructors LLC  work on grading at west side until it began raining  Phoenix Constructors LLC  A 4 12  work on grading at west side until it began raining  work on grading at west side until it began raining  Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  S 3 18  rub light standards  Cordeiro LLC									
New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  4 12 work on grading at west side until it began raining  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  4 12  work on grading at west side until it began raining  work on grading at west side  Work on grading at west side									
New Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoe									
New Orleans Glass Company, Inc.  Phoenix Constructors LLC  Phoenix Con									
Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  A 32  help clean north fence line (Core did over half of the work assisting/prompting them to get it done)  Phoenix Constructors LLC  A 12  work on grading at west side until it began raining  Phoenix Constructors LLC  A 4 12  work on grading at west side until it began raining  work on grading at west side  work on grading at west side  Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC									
Phoenix Constructors LLC432help clean north fence line (Core did over half of the work assisting/prompting them to get it done)Phoenix Constructors LLC412work on grading at west side until it began rainingPhoenix Constructors LLC648work on grading at west sidePhoenix Constructors LLCwork on grading at west sidePhoenix Constructors LLCPhoenix Constructors LLCCordeiro LLCCordeiro LLCCordeiro LLCCordeiro LLCCordeiro LLC Tub light standards	• •								
Assisting/prompting them to get it done)  Phoenix Constructors LLC Cordeiro LLC Cordeir			22						
Phoenix Constructors LLC       4       12       work on grading at west side until it began raining         Phoenix Constructors LLC       6       48       work on grading at west side until it began raining         Phoenix Constructors LLC       Work on grading at west side         Phoenix Constructors LLC       Very Constructors LLC         Cordeiro LLC       Very Cordeiro LLC         Cordeiro LLC       18       rub light standards         Cordeiro LLC       Very Cordeiro LLC	Phoenix Constructors LLC	4	32						
Phoenix Constructors LLC  Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	Phoenix Constructors LLC	4	12						
Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	Phoenix Constructors LLC	4	12		work on grading at west side until it began raining				
Phoenix Constructors LLC  Phoenix Constructors LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC  Cordeiro LLC	Phoenix Constructors LLC	6	48						
Cordeiro LLC  Cordeiro LLC  3 18 rub light standards  Cordeiro LLC	Phoenix Constructors LLC								
Cordeiro LLC 3 18 rub light standards  Cordeiro LLC	Phoenix Constructors LLC								
Cordeiro LLC	Cordeiro LLC								
Cordeiro LLC	Cordeiro LLC	3	18		rub light standards				
Cordeiro LLC 4 32 rub light standards;form sidewalks	Cordeiro LLC								
	Cordeiro LLC	4	32		rub light standards;form sidewalks				

rub light standards;form/pour sidewalks

4 32

Cordeiro LLC

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	05/2	20/2010
Weather Delays To Date:			Weather Condition:	cloudy	Day:		Frida
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	71	80
Cordeiro LLC	4	32 x					
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	2	16		punch out millwork; adjust doors and hardware throughout; install hard surface end caps at C1 gang restrooms			
ProTech Fixture & Display LLC				, 33			
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC	2	14		install shelf in art room, install wood trim @ stage, remove tape from drawers			
Rufino`s Painting & Construction Inc.							
Rufino`s Painting & Construction Inc.	9	81		final coat corridor on 3; prepping corridor on 2nd floors			
Rufino`s Painting & Construction Inc.	9	81		final coat corridor on 3; prepping corridors on 1st & 2nd floors			
Rufino's Painting & Construction Inc.	14	112		final coat corridor on 2 & 3; prepping corridors on 1st & 2nd floors			
Rufino`s Painting & Construction Inc.	14	112		final coat corridor on 1 & 2			
Rufino`s Painting & Construction Inc.	14	112		final coat corridor on1 &2			
Rufino`s Painting & Construction Inc.	6	48		final coat corridor on1			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.	6	60		worked on handrails			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.	5	40		unloaded and laid out handrails at front entrance			
Quality Iron Fabricators Inc.	4	12 x		finished setting handrails @ car drop off			
Quality Iron Fabricators Inc.				- ·			
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection	2	18		install missing sprinkler heads			
River City Fire Protection	1	3		fix leaks			
River City Fire Protection							
River City Fire Protection	6	48		began running pipe down corridor E1 for standpipe			
River City Fire Protection	6	48		working on standpipes			
Roofing Solutions LLC	-			Sign of the state			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive		ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	05/	17/2016
Weather Delays To Date:			Weather Condition:	cloudy/rain	Day:	-	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N			•	72	79
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	6	24		finish installing downspouts and collector heads			
Roofing Solutions LLC				, .			
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation	1	2		came and took progress photos			
Multivista Construction Documentation				, , ,			
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation	1	1		take progress photos			
Multivista Construction Documentation							
Crescent Professional Janitorial LLC	5	53		cleaned gang restrooms; mopped cafeteria; began final cleaning			
Crescent Professional Janitorial LLC	4	44		3rd floor final cleaning 3rd floor			
Crescent Professional Janitorial LLC	3	29		final cleaning 3rd floor			
Crescent Professional Janitorial LLC	3	24		final cleaning 3rd floor			
Crescent Professional Janitorial LLC	3	24		final cleaning 2nd floor			
Alack Refrigeration Company	3	2-1		inal dealing 2nd noor			
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company	2	6		caulk in kitchen			
Alack Refrigeration Company	_	Ü		COUNTY ARCHEM			
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC	3	24		install precast benches on 1st & 2nd floors; fix elevation of			
	3			flashing at eyebrow			
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							

CFI Insulation Inc

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	05/	18/2016
Weather Delays To Date:			Weather Condition:	mostly cloudy	Day:	We	dnesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				73	85
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders	2	16		Installed Marker Boards on 3.		F	
Ellison Builders	2	16		install hand dryers in gang restrooms; install tack/marker boards			
Ellison Builders	2	18		install hand dryers in gang restrooms; install thresholds at exterior			
Zinson Banders	_			gym doors			
Ellison Builders	2	18		install misc hardware			
Ellison Builders	2	8		install music room doors			
Ellison Builders	2	8		install tack/marker boards			
Ellison Builders	2	8		install tack/marker boards			
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc	2	12		install signage			
OPA Graphics Inc	1	8		install signage			
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC							
Malone All Star JV, LLC			ADS				
Malone All Star JV, LLC			Bonded				
Malone All Star JV, LLC	10	80		punch out; outside canopy lights			
Malone All Star JV, LLC	3	24	ADS	test speakers & sound			
Malone All Star JV, LLC	_		Bonded	test speakers a sound			
Malone All Star JV, LLC	10	80	bonded	punch out			
Malone All Star JV, LLC	4	32	ADS	test speakers & sound; punch fire alarm			
Malone All Star JV, LLC	7	32	Bonded	test speakers & sound, punch me alaim			
Malone All Star JV, LLC	7	56	bonded	and a strong and a second lights at a sign actions			
	2		ADC.	punch out; work on canopy lights at main entrance			
Malone All Star JV, LLC		16	ADS	punch fire alarm			
Malone All Star IV, LLC	1	8	Wattstopper	program lights			
Malone All Star IV, LLC	6	48 16	ADS	punch out; work on canopy lights at main entrance			
Malone All Star JV, LLC	2	16	ADS	punch fire alarm			
Malone All Star JV, LLC	1	6	Wattstopper	program lights			
Malone All Star JV, LLC	7	56	X	punch out; work on canopy lights at bus drop off			
Malone All Star JV, LLC	2	16	ADS	test speaker system			
Malone All Star JV, LLC	1	6	Wattstopper	program lights			
Malone All Star JV, LLC							

Malone All Star JV, LLC

Project: Sherwood Forest Elemental Location: 4801 Maid Marion Drive	y Scho	ool			Job: Report #:	14	1-02-002 1
200410:11					<u>-</u>	0.5	
Fair Working Days To Date:					Date:		21/2016
Weather Delays To Date:		N	Weather Condition:	mainly sunny	Day:	:	Saturday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				71	86
Malone All Star JV, LLC							
Sonitrol of New Orleans Inc							
Sonitrol of New Orleans Inc							
Sonitrol of New Orleans Inc							
Sonitrol of New Orleans Inc	3	24		installing devices on 2nd floor			
Sonitrol of New Orleans Inc	3	24		installing devices			
Sonitrol of New Orleans Inc	3	24		installing devices			
Sonitrol of New Orleans Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
New Academics LLC		9	SEC				
Amko Fence-Kenner, LLC							
Amko Fence-Kenner, LLC	1	9		began setting poles at north fence line			
Amko Fence-Kenner, LLC	1	3		began setting poles at north fence line			
Amko Fence-Kenner, LLC	1	3		setting poles at north fence line			
Amko Fence-Kenner, LLC	1	4		setting poles at north fence line			
Amko Fence-Kenner, LLC	1	4		began setting rails at north fence			
Amko Fence-Kenner, LLC							
Heritage Flooring Inc.	4	32		Prepped and glued 1st floor corridor. Left at Lunch.		F	
Heritage Flooring Inc.	2	16		., 3			
Heritage Flooring Inc.	7	56		lay last section of 3rd floor corridor; prepping/laying 2nd floor			
				music room; installation of base throughout; lay tile landings in stair E			
Heritage Flooring Inc.	3	24		punch ceramic tile			
Heritage Flooring Inc.	7	56		install base in 3rd floor corridor; prepping/laying 2nd floor music side rooms; installation of base on stage (partial)			
Heritage Flooring Inc.	2	16		punch 2nd floor gang restrooms			
Heritage Flooring Inc.	7	56		install base in 3rd floor corridor; prepping/laying 2nd floor music side rooms; installation of base on stage (partial); lay vct in gym storage			
Heritage Flooring Inc.	4	32		punch in restrooms			
Heritage Flooring Inc.	7	56		install base in misc rooms; prepping/laying in D stairway;began prepping in stair E			
Heritage Flooring Inc.	4	32		punch in restrooms			
Heritage Flooring Inc.	7	56		install base in misc rooms; prepping/laying in D stairway;began prepping in stair E			

punch in restrooms

4 32

Heritage Flooring Inc.

Project:	Sherwood Forest Elementa	ary Scho	ool			Job:	14	-02-002
Location:	4801 Maid Marion Drive					Report #:		1
Fair Working	Days To Date:					Date:	05/	21/2016
Weather Dela	ays To Date:			Weather Condition:	mainly sunny	Day:	S	Saturday
Is Today Clain	med as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Work Effected?		N				71	86
Heritage Floorin	ng Inc.	7	56		install base in misc rooms; prepping/laying in D stairway;began			
					prepping in stair E			
Heritage Floorin	ng Inc.	4	32		punch in restrooms			
Sun Tropic Land	dscapes	2	12		hydromulch at islands at north parking lot			
		425	3311					

Remarks:

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	05,	/23/2016
Weather Dela	ys To Date:		Weather Condition:	partly cloudy	Day	•	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp	: Low	High
Critical Path V	Vork Effected?	N				72	85

**Work Accomplished** 

George Caillouet								
Ellen Heck						(6:35 - 6:00) oversee site operations		
Marybeth Leonard								
Dennis Hoffman								
George Caillouet								
Ellen Heck						(6:35 - 5:45) oversee site operations		
Marybeth Leonard								
Dennis Hoffman								
George Caillouet								
Ellen Heck						(6:35 - 5:45) oversee site operations		
Marybeth Leonard						(100 5.0) 5.00		
Dennis Hoffman								
George Caillouet								
Ellen Heck						(6:35 - 5:30) oversee site operations		
Marybeth Leonard						(0.55 5.50) Oversee site operations		
Dennis Hoffman								
George Caillouet								
Ellen Heck						(6:35 - 4:00) oversee site operations		
Marybeth Leonard						(0.55 - 4.00) oversee site operations		
Dennis Hoffman								
George Caillouet								
Ellen Heck						(625-140)		
Ellell neck						(6:35 - 4:00) oversee site operations		
Marchards Lancard								
Marybeth Leonard								
Marybeth Leonard  Dennis Hoffman				o J	0-1			
•	Sub	Sub		2nd Tier	2nd Tier			
•	Sub Wrkrs	Sub Hrs	2nd Tier	2nd Tier Wrkrs	2nd Tier Hrs	Work Accomplished	S	Q Sch
Dennis Hoffman			2nd Tier	Tier	Tier	Work Accomplished  Slim & Pops -work on walk off mat frames at gym exterior;	s	Q Sch
Dennis Hoffman  Subcontractor	Wrkrs	Hrs	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul -	s	Q Sch
Dennis Hoffman  Subcontractor	Wrkrs	Hrs	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork	s	Q Sch
Dennis Hoffman  Subcontractor	Wrkrs	Hrs	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks	s	Q Sch
Dennis Hoffman  Subcontractor  CORE Construction Services, LLC	Wrkrs 5	<b>Hrs</b> 48	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs 5 5	<b>Hrs</b> 48	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc.	S	Q Sch
Dennis Hoffman  Subcontractor  CORE Construction Services, LLC	Wrkrs 5	<b>Hrs</b> 48	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael-	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs 5 5	<b>Hrs</b> 48	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc.	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs 5 5	<b>Hrs</b> 48	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael- work on kiln; Jose & Raul - install pour rock at rails,work on walk	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs           5           5	<b>Hrs</b> 48 48 36	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael- work on kiln; Jose & Raul - install pour rock at rails,work on walk off mat frame @ gym; Pops - run elevator, clean up Rafael- install corner guards, worked on kiln; Jose & Raul - install frames @ ext of gym walk off mats, patch block in fire pump	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs           5           5	<b>Hrs</b> 48 48 36	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael- work on kiln; Jose & Raul - install pour rock at rails,work on walk off mat frame @ gym; Pops - run elevator, clean up Rafael- install corner guards, worked on kiln; Jose & Raul - install frames @ ext of gym walk off mats, patch block in fire pump room; Pops - run elevator, helped move containers, pour at walk	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs           5           5	<b>Hrs</b> 48 48 36	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael- work on kiln; Jose & Raul - install pour rock at rails,work on walk off mat frame @ gym; Pops - run elevator, clean up Rafael- install corner guards, worked on kiln; Jose & Raul - install frames @ ext of gym walk off mats, patch block in fire pump	S	Q Sch
Subcontractor  CORE Construction Services, LLC  CORE Construction Services, LLC  CORE Construction Services, LLC	Wrkrs           5           5	<b>Hrs</b> 48 48 36	2nd Tier	Tier	Tier	Slim & Pops -work on walk off mat frames at gym exterior; Rafael-install corner guards on 3rd & 2nd floors; Jose & Raul - install pour rock at rails, remove kick bds off doors at millwork sinks Slim -work on walk off mat frames at gym exterior; Rafael-install corner guards on 1st & 2nd floors; Jose & Raul - install pour rock at rails; Pops - clean courtyard and misc. Slim - install frame for walk off mat @ extrior of gym; Rafael- work on kiln; Jose & Raul - install pour rock at rails,work on walk off mat frame @ gym; Pops - run elevator, clean up Rafael- install corner guards, worked on kiln; Jose & Raul - install frames @ ext of gym walk off mats, patch block in fire pump room; Pops - run elevator, helped move containers, pour at walk off mats; Slim - move containers, pour self leveling at ext gym	S	Q Sch

**Employee** 

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	=	<b>701</b>			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	05/2	28/2016
Weather Delays To Date:			Weather Condition:	sunshine	Day:		aturday
Is Today Claimed as Weather Day?		N			Temp:	Low	High
Critical Path Work Effected?		N	•		remp.	73	86
CORE Construction Services, LLC	5	40		Slim & Pops - install walk off mats/ clean up			
Bernhard Mechanical Contractors, L.L.C.	4	32		install access covers; clean-up			
Bernhard Mechanical Contractors, L.L.C.	2	16	Synergy	installing thermostat cover guards			
Bernhard Mechanical Contractors, L.L.C.			Tech Test				
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	4	32		install access covers; commissioning items			
Bernhard Mechanical Contractors, L.L.C.	2	16	Synergy	installing thermostat cover guards			
Bernhard Mechanical Contractors, L.L.C.			Tech Test				
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	4	32		install access covers; commissioning items			
Bernhard Mechanical Contractors, L.L.C.	2	18	Synergy	commissioning			
Bernhard Mechanical Contractors, L.L.C.	2	16	Tech Test	commissioning			
Bernhard Mechanical Contractors, L.L.C.				5			
Bernhard Mechanical Contractors, L.L.C.	3	25		install access covers; commissioning items			
Bernhard Mechanical Contractors, L.L.C.	2	18	Synergy	commissioning			
Bernhard Mechanical Contractors, L.L.C.	1	8	start up guy	commissioning			
Bernhard Mechanical Contractors, L.L.C.			g-)	commissioning			
Bernhard Mechanical Contractors, L.L.C.	3	24		install access covers; commissioning items			
Bernhard Mechanical Contractors, L.L.C.	2	16	Synergy	commissioning			
Bernhard Mechanical Contractors, L.L.C.	1	8	start up guy	commissioning			
Bernhard Mechanical Contractors, L.L.C.		O	start up guy	Commissioning			
Bernhard Mechanical Contractors, L.L.C.							
			Cymaray				
Bernhard Mechanical Contractors, L.L.C.			Synergy				
Bernhard Mechanical Contractors, L.L.C.			start up guy				
Bernhard Mechanical Contractors, L.L.C.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
G.C. Specialties Inc.	4	28		install accordian door in music room, install hood at kitchen			
G.C. Specialties Inc.	2	6		came and worked on installing panels for accordian wall but did			
G.C. Specialties Inc.	4	8		not finish finished installation of moveable wall in music room			
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
Kone Inc							
Kone Inc							

Project: Sherwood Forest Eleme 4801 Maid Marion Drive	=	ol			Job:	14-	-02-002
<b>Location:</b> 4801 Maid Marion Drive	2				Report #:		1
Fair Working Days To Date:					Date:	05/2	25/2016
Weather Delays To Date:			Weather Condition:	sunshine	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				72	86
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	1	10		clean up			
Holi Services Inc	1	10		clean up			
Holi Services Inc	1	9		clean up			
Holi Services Inc	1	10		clean up			
Holi Services Inc	1	8		clean up			
Holi Services Inc	1	8		clean up			
Morris Drywall Systems Inc	3	20		punch			
Morris Drywall Systems Inc	3	20		punch			
Morris Drywall Systems Inc	3	20		punch			
Morris Drywall Systems Inc	2	10		punch			
Morris Drywall Systems Inc	1	8		punch			
Morris Drywall Systems Inc				parter			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC	2	16		clean up Dobin Hood: haul off diet			
				clean up Robin Hood; haul off dirt			
Phoenix Constructors LLC	2	16		clean up Robin Hood; haul off dirt			
Phoenix Constructors LLC	3	24		clean up Robin Hood; haul off dirt			
Phoenix Constructors LLC	5	40		grade next to north fence; touched up other grading			
Phoenix Constructors LLC	2	16		cut out for base for grassy pavers			
Phoenix Constructors LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
Cordeiro LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
Rufino's Painting & Construction Inc.	7	56		final coat corridor on1; paint rails in stairway of E			
Rufino`s Painting & Construction Inc.	7	56		final coat corridor on1; paint rails in stairway of E			
Rufino's Painting & Construction Inc.	7	56		final coat corridor on1; paint rails in stairway of E			
Rufino's Painting & Construction Inc.	5	40		final coat trophy case; misc painting; clean-up			

misc painting; clean-up

Rufino's Painting & Construction Inc.

6 48

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	ool			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	05/2	28/2016
Weather Delays To Date:			Weather Condition:	sunshine	Day:	S	aturday
s Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	·		•	73	86
Rufino`s Painting & Construction Inc.							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.	5	45		installing gates at transformer; modify rail at chiller platform			
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection	5	45		complete standpipe system with exception of FDC connection outside of building			
River City Fire Protection							
River City Fire Protection	2	8		install missing heads in elec room in E2 and move one in music storage, fix leaks			
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	2	20		working on eyebrows and installing collector heads and downspouts			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	2	19		finished installing metal panels at bus drop off and began at main entrance			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	2	19		installing metal panels at bus drop off			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							

Multivista Construction Documentation

Feir Working Days To Date:  Weather Delays To Date: Is Today Claimed as Weather Day?  Critical Path Work Effected?  Crescent Professional Janitorial LLC  3 24  Crescent Professional Janitorial LLC  4 32  Grescent Professional Janitorial LLC  5 4  Grescent Professional Janitorial LLC  5 5 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	Job: Report #:		1
Weather Delays To Date: Is Today Claimed as Weather Day?  Precipitation Amount:  Critical Path Work Effected?  N  Crescent Professional Janitorial LLC  3 24 final cleaning 3rd floor  Crescent Professional Janitorial LLC  3 24  Crescent Professional Janitorial LLC  3 24  Crescent Professional Janitorial LLC  4 32  Crescent Professional Janitorial LLC  4 32  final cleaning windows  Crescent Professional Janitorial LLC  4 32  final cleaning  Crescent Professional Janitorial LLC  Alack Refrigeration Company  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  CFI Insulation Inc	Date:	05/23/	/2016
Is Today Claimed as Weather Day? Critical Path Work Effected?  Crescent Professional Janitorial LLC  Grescent Professional Janitorial LLC  Grescen	Day:		onday
Critical Path Work Effected?  N  Crescent Professional Janitorial LLC 3 24 final cleaning 3rd floor  Crescent Professional Janitorial LLC 3 24 Crescent Professional Janitorial LLC 3 24 Crescent Professional Janitorial LLC 1 8 final cleaning windows  Crescent Professional Janitorial LLC 1 8 final cleaning windows  Crescent Professional Janitorial LLC 4 32 final cleaning  Crescent Professional Janitorial LLC 4 32 final cleaning  Alack Refrigeration Company  Alack Refrigeration	_		-
Crescent Professional Janitorial LLC Crescent Professional Janitorial LLC 3 24	Temp:	Low 72	High 85
Crescent Professional Janitorial LLC  3 24  Crescent Professional Janitorial LLC  1 8  final cleaning 3rd floor  Crescent Professional Janitorial LLC  1 8  final cleaning windows  Crescent Professional Janitorial LLC  4 32  final cleaning  Crescent Professional Janitorial LLC  4 32  final cleaning  Alack Refrigeration Company  Alack			
Crescent Professional Janitorial LLC  3 24  Crescent Professional Janitorial LLC  1 8 final cleaning windows  Crescent Professional Janitorial LLC  4 32 final cleaning  Crescent Professional Janitorial LLC  4 32 final cleaning  Alack Refrigeration Company  Alleid Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  CFI Insulation Inc			
Crescent Professional Janitorial LLC  1 8 final cleaning Crescent Professional Janitorial LLC 4 32 final cleaning Crescent Professional Janitorial LLC 4 32 final cleaning Alack Refrigeration Company Allied Construction, LLC Allied Construction, LLC CRI Insulation Inc CFI Insulation Inc			
Crescent Professional Janitorial LLC  4 32 final cleaning  Crescent Professional Janitorial LLC  Alack Refrigeration Company  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  Cell Insulation Inc  Cerl Insulation Inc			
Crescent Professional Janitorial LLC  4 32 final cleaning  Alack Refrigeration Company  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  Allied Construction, LLC  Cell Insulation Inc  Cerl Insulation Inc			
Alack Refrigeration Company Alied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Construction,			
Alack Refrigeration Company Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Cons			
Alack Refrigeration Company Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Construction, LLC Allied Construction, LLC			
Alack Refrigeration Company Alack Refrigeration Company Alack Refrigeration Company Allied Construction, LLC C			
Alack Refrigeration Company Alack Refrigeration Company Allied Construction, LLC Construction Inc Co			
Alack Refrigeration Company Allied Construction, LLC Construction,			
Allied Construction, LLC CFI Insulation Inc			
Allied Construction, LLC CFI Insulation Inc			
Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC CFI Insulation Inc			
Allied Construction, LLC Allied Construction, LLC Allied Construction, LLC CFI Insulation Inc			
Allied Construction, LLC Allied Construction, LLC CFI Insulation Inc			
Allied Construction, LLC CFI Insulation Inc			
CFI Insulation Inc			
CFI Insulation Inc			
CFI Insulation Inc CFI Insulation Inc CFI Insulation Inc			
CFI Insulation Inc CFI Insulation Inc CFI Insulation Inc			
CFI Insulation Inc			
CFI Insulation Inc			
CIT III SUBLION INC			
Gulf South Engineering & Torting Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Gulf South Engineering & Testing Inc			
Ellison Builders 2 8 misc hardware			
Ellison Builders			
Ellison Builders 2 8 install hardware on music entrance doors			
Ellison Builders 2 8 install closures on fire rated doors; work on single musi entrance door	c room		
Ellison Builders 2 8 install closures on fire rated doors; work on single musi entrance door	c room		
Ellison Builders 2 8 install closures on fire rated doors; work on single musi entrance door	c room		
OPA Graphics Inc			
OPA Graphics Inc			
OPA Graphics Inc 1 8 finished installing interior signage			
OPA Graphics Inc 1 8 installing signage on 1st floor			
OPA Graphics Inc			
OPA Graphics Inc			
Malone All Star JV, LLC 5 40 install ballasts; work on canopy lights at bus drop off; in	istall		
conduit for tampers at backflow preventer			

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	tary Scho	ol			Job: Report #:	14-	·02-002
Fair Working Days To Date:					Date:	05/2	3/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	N	∕londay
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				72	85
Malone All Star JV, LLC	2	18	data	install equipment in racks			
Malone All Star JV, LLC	1	1	Wattstopper	check lights			
Malone All Star JV, LLC	5	40		punch out and tamper switches			
Malone All Star JV, LLC			data				
Malone All Star JV, LLC	1	5	Wattstopper	check lights			
Malone All Star JV, LLC	5	40		punch; canopy lights @ bus drop off			
Malone All Star JV, LLC			data				
Malone All Star JV, LLC			Wattstopper				
Malone All Star JV, LLC	4	28		punch; canopy lights @ bus drop off			
Malone All Star JV, LLC			data				
Malone All Star JV, LLC			Wattstopper				
Malone All Star JV, LLC	4	32		punch; canopy lights @ bus drop off			
Malone All Star JV, LLC			data				
Malone All Star JV, LLC	1	2	Wattstopper	discuss commissioning			
Malone All Star JV, LLC		32					
Malone All Star JV, LLC			data				
Malone All Star JV, LLC			Wattstopper				
Sonitrol of New Orleans Inc	4	32		installing devices			
Sonitrol of New Orleans Inc	2	16		installing devices			
Sonitrol of New Orleans Inc	2	10		installing devices			
Sonitrol of New Orleans Inc	2	10		installing devices			
Sonitrol of New Orleans Inc	1	8		installing devices			
Sonitrol of New Orleans Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc	4	32		brought in lockers for 3rd floor			
Atlas-Edco Inc	4	32		brought in lockers for 3rd floor			
Atlas-Edco Inc	2	16		install lockers on 3rd floor			
Atlas-Edco Inc							
New Academics LLC			SEC				
New Academics LLC	3	27	SEC	put together chairs and tables in science lab and installed stools and also installed chairs in media room			
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
Amko Fence-Kenner, LLC	2	16		setting rails at north fence			
Amko Fence-Kenner, LLC	1	8		installing pickets @ north fence			
Amko Fence-Kenner, LLC	2	16		finished installing pickets on north fence			
Amko Fence-Kenner, LLC							
Amko Fence-Kenner, LLC							
Amko Fence-Kenner, LLC							
Heritage Flooring Inc.	5	40		install base on 2nd floor corridors and rooms; finished laying corridor on D1 and last classroom in D1			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	5	40		install base beneath millwork			

Project: Sherwood Forest Elemen	-	ool			Job:	14	-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	05/2	24/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	٦	Tuesday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				71	85
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	3	24		prep/lay vct in storage room in D2 admin area; install base in 1st floor corridor			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	2	13		install base beneath millwork; install vct in storage room in D2			
				admin & prepped storage across from elevator on 1st floor			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	3	22		install base on 1st floor corridor; install vct in storage room			
Heritage Flooring Inc.	2	16		across from elevator on 1st floor punch in restrooms			
ÿ ÿ				•			
Heritage Flooring Inc.	3	22		install base on 1st floor corridor; install vct in storage room across from elevator on 1st floor			
Heritage Flooring Inc.	2	16		punch in restrooms			
Sun Tropic Landscapes	4	16		received trees and watered them			
Sun Tropic Landscapes	5	40		received shrubs and began planting			
Sun Tropic Landscapes	5	40		received shrubs and began planting			
	288	2230					

Remarks:

Project:	Sherwood Forest Elementary School					Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Re	eport #:		1
Fair Working	Days To Date:					Date:	05/3	31/2016
Weather Dela	ays To Date:		Weather Condition:	sunshine		Day:	Т	Гuesday
Is Today Clair	ned as Weather Day?	Ν	Precipitation Amount:			Temp:	Low	High
Critical Path \	Work Effected?	Ν					73	90

Employee						Work Accomplished		
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:35 - 5:00) oversee site operations		
Marybeth Leonard						(0.55 5.00) Oversee site operations		
Chad Goubert						(10:00, 11:00) size well-		
George Caillouet						(10:00 -11:00) site walk		
_								
Tanner Broughton								
Ellen Heck						(6:50 - 5:00) oversee site operations		
Marybeth Leonard								
Dennis Hoffman								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:50 - 4:00) oversee site operations		
Marybeth Leonard								
George Caillouet								
Tanner Broughton								
Ellen Heck						(6:45 - 3:30) oversee site operations		
Marybeth Leonard								
				2nd	2nd			
Cubcontractor	Sub	Sub	2nd Tier	Tier	Tier	Work Assemblished	s	Q Sch
Subcontractor	Wrkrs	Hrs	Zna Her	Wrkrs	Hrs	Work Accomplished		
CORE Construction Services, LLC	5	40				Rafael-misc.; Jose & Raul - install walk off mats; Pops - clean up exterior; Slim - bondo HM frames and doors		
CORE Construction Services, LLC	5	40				Rafael-install standards at trophy case & misc.; Jose & Raul -		
						install top of cage in gym storage, install closures on doors B102C		
						& C111A; Pops - clean up exterior; Slim - bondo HM frames and		
CORE Construction Services, LLC	5	40				doors  Rafael - misc.; Jose & Raul - reinstall handrails, move stage ramp,		
						remove temp paper from under bleachers; Pops - clean up		
						exterior; Slim - bondo HM frames and doors		
CORE Construction Services, LLC	3	21				Rafael, Pops & Slim - misc., form/pour city sidewalks		
Bernhard Mechanical Contractors, L.L.C.	3	24				install access covers; commissioning items		
Bernhard Mechanical Contractors, L.L.C.	2	16	Synergy			commissioning		
Bernhard Mechanical Contractors, L.L.C.	1	8	start up guy			commissioning		
Bernhard Mechanical Contractors, L.L.C.	2	10						
Bernhard Mechanical Contractors, L.L.C.	2	16				install access covers; commissioning items		
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3	15	syperay			commissioning of lights		
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3	15 24	synergy			commissoning of lights		
Bernhard Mechanical Contractors, L.L.C.	э	24				install access covers;clean-up		
Bernhard Mechanical Contractors, L.L.C.								
Definition (vicentarilear Contractors, E.L.C.								
Bernhard Mechanical Contractors LLC			synergy					
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	3	24	synergy			install access covers;clean-up		

Product Calamed as Weather Doys	Project: Sherwood Forest Element 4801 Maid Marion Drive	itary SCNO	iUI			Job: Report #:	14	-02-00
Monther Days	Fair Working Days To Date:					Date:	06/0	03/201
Trough Carlow Meather Day	• •			Weather Condition:	partly cloudy	Day:		Frida
Circle   Provide Mode Effected   Provide Mode Effected   Provide Mode Indicators   LCC   LCC   Provide Mode Indicators   LCC	<del>-</del>		N	Precipitation Amount:		Temp:	Low	Higl
Service of Michanical Contractors, LLC   Service   Ser			N			•	75	8-
Service Mechanical Contractors, LLC.  ***Part Tes Ferranzo Can Inc.  ***Part Tes Ferranzo Can	Bernhard Mechanical Contractors, L.L.C.							
### 2007 Tile & Terraszo Co. Inc.    2007 Tile & Terraszo Co. Inc.   2007 Tile & Terraszo Co.	Bernhard Mechanical Contractors, L.L.C.							
### Time ## Termazon Co. Inc.  ### Time ## Time	Bernhard Mechanical Contractors, L.L.C.		syı	nergy				
### 100 Fire Reference Co. Inc.	0&T Tile & Terrazzo Co. Inc.							
28 Time is Timorano in LC investigation formation of LC investigat	0&T Tile & Terrazzo Co. Inc.	3	2		grind hump out of 2nd floor in front of music room dbl doors			
Treating International LLC  ***Treating International LLC  **Treating International LLC  **Treat	0&T Tile & Terrazzo Co. Inc.							
Trestage International LLC Trestage Internationa	0&T Tile & Terrazzo Co. Inc.							
Trestage International LLC  1. Specialities Inc.  1. Specialities	irestop International LLC							
Time Lange   International LLC  EC. Specialisties Inc.  EC. Specialisties Inc.	irestop International LLC							
S.C. Specialities Inc.	irestop International LLC							
S.C. Speciallities Inc. 3.C. Speciallities Inc. 3.C. Speciallities Inc. 3.C. Speciallities Inc. 4.C. Speciallities Inc. 4.C. Speciallities Inc. 5.C. Special Inc. 5.C. Special Inc. 5.C. Special Inc. 5.C. Special Inc. 5.C. S	irestop International LLC							
S.C. Specialities Inc.	G.C. Specialties Inc.							
Come Inc.	G.C. Specialties Inc.							
cone inc  fore i	i.C. Specialties Inc.							
one Inc one	i.C. Specialties Inc.							
come Inc  fore I	one Inc	2	1		check out elevator			
elevator inspection  ledi Services Inc  oil Serv	one Inc							
coli Services Inc.  1 8 6 clean up 7 clean up 8 clean up 9 clean u	one Inc							
celi Services Inc. 1 8 8 clean up  celi Services Inc. 1 7 7 clean up.  celi Services Inc. 1 7 7 clean up. help prep/pour city sidewalks  celoris Drywall Systems Inc. 3 2 24 punch  celoris Drywall Systems Inc. 3 2 20 punch  celoris Drywall Systems Inc. 3 2 20 punch  celoris Drywall Systems Inc. 4 2 24 punch  celoris Drywall Systems Inc. 4 2 24 punch  celoris Company, Inc.  celor Orleans Glass Compan	one Inc	2	8		elevator inspection			
coli Services Inc 1 8 dean up dean up; help prep/pour city sidewalks dean up; help prep/pour cit	Ioli Services Inc	1	8		clean up			
deri Sprywall Systems Inc 3 24 punch	Ioli Services Inc	1	8		clean up			
for is Drywall Systems Inc. 3 20 punch for is Drywall Systems Inc. 3 20 punch for is Drywall Systems Inc. 3 20 punch for is Drywall Systems Inc. 4 24 punch for is Drywall Systems Inc. 5 24 punch for is Drywall Sys	Ioli Services Inc	1	8		clean up			
Adorris Drywall Systems Inc Ad	łoli Services Inc	1	7		clean up; help prep/pour city sidewalks			
Address Drywall Systems Inc.  Alew Orleans Glass Company, Inc.  New Orleans Glass Company, Inc.  Ne	Лorris Drywall Systems Inc	3	24		punch			
New Orleans Glass Company, Inc. New Orleans Glass Company, Inc	Norris Drywall Systems Inc	3	20		punch			
New Orleans Glass Company, Inc. New Orleans Glass Company, Inc	Лorris Drywall Systems Inc	3	20		punch			
New Orleans Glass Company, Inc. New Orleans Glass Company, Inc	Morris Drywall Systems Inc	4	24		punch			
New Orleans Glass Company, Inc. New Orleans Glass Country Glass Spaces Cut out for base for grassy pavers Cut out f	New Orleans Glass Company, Inc.							
lew Orleans Glass Company, Inc.  hoenix Constructors LLC 6 48 cut out for base for grassy pavers  hoenix Constructors LLC 5 40 finish installing base for grassy pavers  hoenix Constructors LLC 5 40 remove sidewalk and prep new  ordeiro LLC  ordeiro LLC	lew Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.  Thoenix Constructors LLC  6 48 cut out for base for grassy pavers  Thoenix Constructors LLC  5 40 finish installing base for grassy pavers  Thoenix Constructors LLC  5 40 remove sidewalk and prep new  Thoenix Constructors LLC  Tordeiro	lew Orleans Glass Company, Inc.							
Phoenix Constructors LLC  6 48  cut out for base for grassy pavers finish installing base for grassy pavers remove sidewalk and prep new  cordeiro LLC  cord								
choenix Constructors LLC  5 40  finish installing base for grassy pavers choenix Constructors LLC  5 40  remove sidewalk and prep new  cordeiro LLC  cordeir		6	48		cut out for base for grassy pavers			
thoenix Constructors LLC 5 40 finish installing base for grassy pavers remove sidewalk and prep new foodeiro LLC fordeiro	hoenix Constructors LLC	6	48					
hoenix Constructors LLC  5 40 remove sidewalk and prep new  fordeiro LLC  fordeiro LLC	hoenix Constructors LLC	5	40					
Cordeiro LLC Corde	Phoenix Constructors LLC	5	40					
Cordeiro LLC Corde	Cordeiro LLC							
fordeiro LLC roTech Fixture & Display LLC roT	ordeiro LLC							
Fordeiro LLC  roTech Fixture & Display LLC  roTech Fixture & Displ								
roTech Fixture & Display LLC								
roTech Fixture & Display LLC 2 10 misc. ufino's Painting & Construction Inc. 5 40 misc painting; clean-up								
roTech Fixture & Display LLC roTech Fixture & Display LLC 2 10 misc. ufino's Painting & Construction Inc. 5 40 misc painting; clean-up								
roTech Fixture & Display LLC 2 10 misc. ufino's Painting & Construction Inc. 5 40 misc painting; clean-up								
ufino's Painting & Construction Inc. 5 40 misc painting; clean-up		2	10		misc			
Rufino's Painting & Construction Inc. 5 40 misc painting; clean-up	Rufino's Painting & Construction Inc.	5	40					

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ol			Job: Report #:	14-	-02-002 1
Fair Working Days To Date:					Date:	06/0	2/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	Tł	nursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				74	86
Rufino`s Painting & Construction Inc.	5	40		misc painting; clean-up			
Rufino`s Painting & Construction Inc.	5	40		misc painting; clean-up			
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.	3	15		reworked wall rails			
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
River City Fire Protection							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	2	8		installed trim at overhead door to maintenance storage			
Roofing Solutions LLC							
Roofing Solutions LLC	2	4		work on eyebrow			
Roofing Solutions LLC	2	16		install metal facia at main entrance			
Roofing Solutions LLC							
Roofing Solutions LLC	4	16		work on eyebrow			
Roofing Solutions LLC	2	16		install metal facia at main entrance			
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Crescent Professional Janitorial LLC	5	23		final cleaning			
Crescent Professional Janitorial LLC	6	23		final cleaning - wax stage, clean windows			
Crescent Professional Janitorial LLC	6	60		final cleaning -			
Crescent Professional Janitorial LLC	1	6		final cleaning -			
Alack Refrigeration Company				5			
Alack Refrigeration Company							
Alack Refrigeration Company	2	1		installed missing parts			
Alack Refrigeration Company				<del>-</del> ·			
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ol			Job: Report #:	14-	·02-002 1
Fair Working Days To Date:					Date:	06/0	3/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:		Friday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	·		•	75	84
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc	1	1		check densities for grassy paver base			
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders	2	14		install hardware			
Ellison Builders	2	13		install hardware; install tack & marker boards			
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	3	24		punch; canopy lights @ bus drop off			
Malone All Star JV, LLC			data	panar, and program of and and pan			
Malone All Star JV, LLC	1	3	Wattstopper	check out lighting controls			
Malone All Star JV, LLC	3	24		punch; canopy lights @ bus drop off			
Malone All Star JV, LLC	3		data	panel, carrepy lights @ bas drop on			
Malone All Star JV, LLC	1	8	Wattstopper	check out lighting controls			
Malone All Star JV, LLC	3	24	такжерре	rewire lights in media room; canopy lights @ bus drop off			
Malone All Star JV, LLC	1	1	data	hooked up phone lines			
Malone All Star JV, LLC	2	14	ADS	install clocks			
Malone All Star JV, LLC	3	24		rewire lights in media room; canopy lights @ bus drop off			
Malone All Star JV, LLC			data	reme again media room, carrept again e pas drop on			
Malone All Star JV, LLC	2	10	ADS	install clocks			
Sonitrol of New Orleans Inc	_			instance de la constance de la			
Sonitrol of New Orleans Inc							
Sonitrol of New Orleans Inc							
Sonitrol of New Orleans Inc							
Atlas-Edco Inc	3	24		install lockers on 3rd floor			
Atlas-Edco Inc	3	15		install locks and finish installation of benches			
Atlas-Edco Inc	3	.5		install focks and infish installation of seriences			
Atlas-Edco Inc							
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
Amko Fence-Kenner, LLC			525				
Amko Fence-Kenner, LLC	2	13		began installation of pre-k & k fence			
Amko Fence-Kenner, LLC	5	28		installation of pre-k & k fence; unloaded gates and fencing			
Amko Fence-Kenner, LLC	2	16					
Heritage Flooring Inc.	1	8		installation of pre-k & k fence; unloaded gates and fencing			
nemage riconing IIIc.	1	U		install base on 1st floor corridor; install vct in storage room across from elevator on 1st floor			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	2	10		misc base			
and the second of the second o	2						

punch in restrooms

16

Heritage Flooring Inc.

Project: Sherwood Forest Elemen	tary Scho	ol			Job:	14	1-02-002
<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	06/	02/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:	T	hursday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				74	86
Heritage Flooring Inc.	1	8		misc base			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	1	8		misc base; installed vct in elevator			
Heritage Flooring Inc.	2	16		punch in restrooms			
Sun Tropic Landscapes							
Sun Tropic Landscapes							
Sun Tropic Landscapes							
Sun Tropic Landscapes	4	16		water plants			
	194	1302					

## Remarks:

Communication with Subcontractors: Frank with Heritage came to look at carpet tile. He will have a rep out here next week.

**Inspections:** Mr. Carly came and inspected the elevator.

Material Delivered: Dillon Bros. sent out 5.5 cyds of concrete for city sidewalks.

Visitors: Mr. Carlon Zimmerman with the city of NO.

Project:	Sherwood Forest Elementary School					Job:	14-	-02-002
Location:	4801 Maid Marion Drive				Re	port #:		1
Fair Working	Days To Date:					Date:	06/0	06/2016
Weather Dela	nys To Date:		Weather Condition:	mostly sunny		Day:	1	Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:			Temp:	Low	High
Critical Path V	Vork Effected?	Ν					75	87

Employee						Work Accomplished		
Tanner Broughton								
Ellen Heck						(6:30 - 4:15) oversee site operations		
Marybeth Leonard								
Tanner Broughton								
Ellen Heck						(6:50 - 4:30) oversee site operations		
Marybeth Leonard						· · ·		
Tanner Broughton								
Ellen Heck						(6:30 - 4:30) oversee site operations		
Marybeth Leonard						(		
Tanner Broughton								
Ellen Heck						(6:32 - 4:00) oversee site operations		
Marybeth Leonard						(dd2 idd) oversee site apertalons		
Tanner Broughton								
Ellen Heck						(6:32 - 3:30) oversee site operations		
Marybeth Leonard						(0.52 - 5.50) oversee site operations		
waryseth Econard				2nd	2nd			
	Sub	Sub		Tier	Tier			
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished	S	Q Sch
CORE Construction Services, LLC	2	13				Rafael - misc; Slim - bondo		
CORE Construction Services, LLC	3	24				Rafael - misc; Slim - bondo; Pops- clean-up		
CORE Construction Services, LLC	3	24				Rafael - misc; Slim - bondo; Pops- clean-up		
CORE Construction Services, LLC	3	24				Rafael - misc; Slim - bondo; Pops- clean-up		
CORE Construction Services, LLC	3	24				Rafael - misc; Slim - bondo; Pops- clean street		
CORE Construction Services, LLC	2	16				Slim - bondo; Pops- clean street		
Bernhard Mechanical Contractors, L.L.C.	2	16				install lav guards;clean-up		
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.			synergy					
Bernhard Mechanical Contractors, L.L.C.	2	16				fix hot water leak;clean-up		
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.		24	synergy					
Bernhard Mechanical Contractors, L.L.C.	4	24				install access panels		
Bernhard Mechanical Contractors, L.L.C.  Bernhard Mechanical Contractors, L.L.C.	2	12				start us aver have to blow sub-lines		
Bernhard Mechanical Contractors, L.L.C.	2	12	syneray			start-up guys - here to blow out lines		
Bernhard Mechanical Contractors, L.L.C.	2	16	synergy			install access panels; punch		
Bernhard Mechanical Contractors, L.L.C.	2	10				ilistali access paneis, puncii		
Bernhard Mechanical Contractors, L.L.C.								
Bernhard Mechanical Contractors, L.L.C.			synergy					
Bernhard Mechanical Contractors, L.L.C.	2	16	-1 31			change filters		
Bernhard Mechanical Contractors, L.L.C.	_					<del> </del>		
and the second s								

Project: Sherwood Forest Elementa Location: 4801 Maid Marion Drive	ary Scho	ol			Job: Report #:		-02-002 1
Fair Working Days To Date:					Date:	06/	10/2016
Weather Delays To Date:			Weather Condition:	partly cloudy	Day:		Friday
Is Today Claimed as Weather Day?		N	r realpreadon / arroana		Temp:	Low	High
Critical Path Work Effected?		N				77	87
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.			synergy				
Bernhard Mechanical Contractors, L.L.C.	2	16					
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.			synergy				
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.	3	6		caulk base to floor			
D&T Tile & Terrazzo Co. Inc.							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc. Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Kone Inc							
Holi Services Inc	1	8		clean up			
Holi Services Inc	1	8		clean up			
Holi Services Inc	1	8		clean up			
Holi Services Inc	1	8		clean up			
Holi Services Inc	1	8		clean street			
Holi Services Inc							
Morris Drywall Systems Inc	3	20		punch			
Morris Drywall Systems Inc	3	20		punch			
Morris Drywall Systems Inc	3	18		punch			
Morris Drywall Systems Inc	3	12		punch; here to walk with fire marshal			
Morris Drywall Systems Inc							
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							

New Orleans Glass Company, Inc.

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ary Scho	OOI			Job: Report #:	14	-02-002 1
Fair Working Days To Date:					Date:	06/0	09/2016
Weather Delays To Date:			Weather Condition:	partly sunny	Day:	Т	hursday
ls Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N				77	89
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Phoenix Constructors LLC	5	20		install grates at boot locations			
Phoenix Constructors LLC	3	22		install grates at boot locations			
Phoenix Constructors LLC							
Phoenix Constructors LLC							
Cordeiro LLC							
Cordeiro LLC	3	24		sawcut paving joints			
Cordeiro LLC	3	24		sawcut paving joints			
Cordeiro LLC	3	24		sawcut paving joints			
Cordeiro LLC	3	24		sawcut paving joints			
Cordeiro LLC	3	24					
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
ProTech Fixture & Display LLC							
Rufino`s Painting & Construction Inc.	4	32		misc painting; clean-up			
Rufino`s Painting & Construction Inc.	4	32		misc painting; clean-up			
Rufino`s Painting & Construction Inc.	6	38		punch; install VWC and caulk at precast benches			
Rufino`s Painting & Construction Inc.	4	32		Punch			
Rufino`s Painting & Construction Inc.	4	32		Punch			
Rufino`s Painting & Construction Inc.							
eachtree Protective Covers							
eachtree Protective Covers							
eachtree Protective Covers							
Peachtree Protective Covers							
eachtree Protective Covers							
Peachtree Protective Covers							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
Quality Iron Fabricators Inc.							
River City Fire Protection							
River City Fire Protection							
tiver City Fire Protection							
iver City Fire Protection	2	4		installed FDC connections for standpipes and walked with fire			
				marshal			
iver City Fire Protection							

River City Fire Protection

Project: Sherwood Forest Eleme Location: 4801 Maid Marion Drive	=	ol			Job: Report #:	14-02-	-002 1
Fair Working Days To Date:					Date:	06/06/2	016
Fair Working Days To Date:			Weether Conditions	mostly sunny	Day:	Mon	
Weather Delays To Date: Is Today Claimed as Weather Day?		N	Weather Condition: Precipitation Amount:	osty say			High
Critical Path Work Effected?		N	recipitation Amount.		Temp:	75	87
Roofing Solutions LLC							_
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC	3	9		finish installing metal panels at main entry			
Roofing Solutions LLC				, , , , , , , , , , , , , , , , , , ,			
Roofing Solutions LLC							
Roofing Solutions LLC							
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Crescent Professional Janitorial LLC	4	28		final cleaning -			
Crescent Professional Janitorial LLC	6	40		final cleaning -			
Crescent Professional Janitorial LLC	6	56		final cleaning - waxed cafeteria and 3rd floor corridors			
Crescent Professional Janitorial LLC	6	56		final cleaning - waxed 2nd floor corridors			
Crescent Professional Janitorial LLC	6	56		final cleaning - waxed 2nd floor corridors & cafeteria			
Crescent Professional Janitorial LLC	6	56		final cleaning - waxed 2nd floor corridors & cafeteria			
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CEL Inculation Inc							

CFI Insulation Inc

Project:	<b>Sherwood Forest Elementary School</b>				Jo	ob:	14-0	02-002
Location:	4801 Maid Marion Drive				Repor	t #:		1
Fair Working	Days To Date:				Da	ate:	06/09	9/2016
Weather Delay	ys To Date:		Weather Condition:	partly sunny	D	ay:	Th	ursday
Is Today Claim	ned as Weather Day?	N	Precipitation Amount:		Ter	np:	Low	High
Critical Path V	Vork Effected?	N					77	89
CFI Insulation Inc	С							

CFI Insulation Inc				
CFI Insulation Inc				
CFI Insulation Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Gulf South Engineering & Testing Inc				
Ellison Builders	2	10		misc.
Ellison Builders				
OPA Graphics Inc				
OPA Graphics Inc				
OPA Graphics Inc				
OPA Graphics Inc				
OPA Graphics Inc				
OPA Graphics Inc				
Malone All Star JV, LLC	4	32		rewire lights in media room; canopy lights @ bus drop off
Malone All Star JV, LLC			data	
Malone All Star JV, LLC			ADS	
Malone All Star JV, LLC	1	8		misc
Malone All Star JV, LLC			data	
Malone All Star JV, LLC			ADS	
Malone All Star JV, LLC	1	8		misc
Malone All Star JV, LLC			data	
Malone All Star JV, LLC	3	9	ADS	hook-up tamper switch @ backflow preventer; move call buttons
Malone All Star JV, LLC	1	8		misc
Malone All Star JV, LLC			data	
Malone All Star JV, LLC	2	4	ADS	here to walk with fire marshal
Malone All Star JV, LLC	1	8		misc
Malone All Star JV, LLC			data	
Malone All Star JV, LLC			ADS	
Malone All Star JV, LLC	1	8		
Malone All Star JV, LLC			data	
Malone All Star JV, LLC			ADS	
Sonitrol of New Orleans Inc	2	14		programming
Sonitrol of New Orleans Inc	1	8		trouble shooting; test system
Sonitrol of New Orleans Inc	1	2		dbl check all panels
Sonitrol of New Orleans Inc				
Sonitrol of New Orleans Inc				
Sonitrol of New Orleans Inc				

<b>Location:</b> 4801 Maid Marion Drive					Report #:		1
Fair Working Days To Date:					Date:	06/0	06/2016
Weather Delays To Date:			Weather Condition:	mostly sunny	Day:		Monday
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	High
Critical Path Work Effected?		N	•		. ср.	75	87
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
Atlas-Edco Inc							
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
New Academics LLC			SEC				
Amko Fence-Kenner, LLC	2	16		began installation of east metal fence			
Amko Fence-Kenner, LLC	2	16		installation of east metal fence			
Amko Fence-Kenner, LLC							
Amko Fence-Kenner, LLC	2	16		continue installing metal fence along Robin Hood			
Amko Fence-Kenner, LLC	1	1		rained out			
Amko Fence-Kenner, LLC							
Heritage Flooring Inc.	1	8		misc base			
Heritage Flooring Inc.	2	16		punch in restrooms			
Heritage Flooring Inc.	1	6		misc base			
Heritage Flooring Inc.	1	8		punch in restrooms			
Heritage Flooring Inc.							
Heritage Flooring Inc.	1	8		punch in restrooms			
Heritage Flooring Inc.	1	6		install base			
Heritage Flooring Inc.	1	8		punch in restrooms			
Heritage Flooring Inc.							
Heritage Flooring Inc.	1	8		punch in restrooms			
Heritage Flooring Inc.							
Heritage Flooring Inc.							
Sun Tropic Landscapes	6	36		install pavers and fringetrees and remaining plants			
Sun Tropic Landscapes	2	10		work on pavers; touch up hydroseeding			
Sun Tropic Landscapes	5	40		lay sod at pavers			
Sun Tropic Landscapes	5	15		finished installing sod and misc touch-up			
Sun Tropic Landscapes							
Sun Tropic Landscapes			_				
	190	1327	•				

Job:

14-02-002

Remarks:

Project:

**Sherwood Forest Elementary School** 

Project:	Sherwood Forest Elementary Schoo				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date:	06/	/13/2016
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path	Work Effected?	N				77	88

**Work Accomplished** 

(6:32 - 4:30) oversee site operations

Marybeth Leonard							
George Caillouet							
Ellen Heck						(6:30 - 5:00) oversee site operations	
Marybeth Leonard							
George Caillouet							
Tanner Broughton							
Ellen Heck						(6:43 - 3:00) oversee site operations; went to main office for kick-off meeting	
						for Franklin Ave Baptist Church	
Marybeth Leonard							
George Caillouet							
Tanner Broughton							
Ellen Heck						(6:43 - 3:35) oversee site operations	
Marybeth Leonard							
George Caillouet							
Tanner Broughton							
Ellen Heck						(6:43 - 3:35) oversee site operations	
Marybeth Leonard							
				2nd	2nd		
Subcontractor	Sub Wrkrs	Sub Hrs	2nd Tier	Tier	Tier Hrs	Work Accomplished	Q So
CORE Construction Services, LLC	2	16	2.1.4 1.0.	Wrkrs	піз		
CORE Construction Services, LLC	3	24				Slim -clean; Pops- clean Slim - bondo doors; Pops- clean; Rafael - work on toilet	
CONE CONSTITUCION SOLVICOS, EEC	3					partitions, marker/tack bds, remove base off 1 cabinet, work on	
						installing mirror in kindergarten RR (E105)	
CORE Construction Services, LLC	3	24				Slim - bondo doors; Pops- clean; Rafael - marker/tack bds, remove base off 1 cabinet, work on installing mirror in	
						kindergarten RR (E105)	
CORE Construction Services, LLC	3	24				Slim - bondo doors; Pops- clean; Rafael - marker/tack bds	
CORE Construction Services, LLC	2	24					
	3	24				Slim - bondo doors; Pops- clean; Rafael - installing shoes on	
Rernhard Mechanical Contractors 1.1.C						toilet partitions	
	2	16					
Bernhard Mechanical Contractors, L.L.C.						toilet partitions	
Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C.			synergy			toilet partitions	
Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C.			synergy			toilet partitions	
Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C. Bernhard Mechanical Contractors, L.L.C.	2	16	synergy			toilet partitions change valve actuators on 3 AHU's; misc	
Bernhard Mechanical Contractors, L.L.C.	2	16	synergy			toilet partitions change valve actuators on 3 AHU's; misc	
Bernhard Mechanical Contractors, L.L.C.	2	16	synergy			toilet partitions change valve actuators on 3 AHU's; misc	
Bernhard Mechanical Contractors, L.L.C.	2	16				toilet partitions change valve actuators on 3 AHU's; misc	
Bernhard Mechanical Contractors, L.L.C.	2	16				toilet partitions change valve actuators on 3 AHU's; misc misc	

**Employee** 

George Caillouet

Tanner Broughton

Ellen Heck

Marybeth Leonard

Project: Sherwood Forest Element Location: 4801 Maid Marion Drive	ntary Scho	ol			Job: Report #:		02-002
Fair Working Days To Date:					Date:		5/2016
Weather Delays To Date:			Weather Condition:	mostly cloudy	Day:	Wed	Inesday
Is Today Claimed as Weather Day?		N			Temp:	Low	High
Critical Path Work Effected?		N				78	90
Bernhard Mechanical Contractors, L.L.C.			synergy				
Bernhard Mechanical Contractors, L.L.C.	2	16		misc.			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.			synergy				
Bernhard Mechanical Contractors, L.L.C.	2	16		misc.			
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.							
Bernhard Mechanical Contractors, L.L.C.	1	3	synergy	trained on BAS system			
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
D&T Tile & Terrazzo Co. Inc.							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
Firestop International LLC							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
G.C. Specialties Inc.							
Kone Inc							
Kone Inc	3	12		tried to fivelesk at car drop off worked on EDC connections for			
Notice inic	3	12		tried to fix leak at car drop off, worked on FDC connections for standpipe system, demonstration of system to school			
Kone Inc	3	2		came and sealed pipes @ FDC connection for standpipe system			
Kone Inc							
Kone Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Holi Services Inc							
Morris Drywall Systems Inc							
Morris Drywall Systems Inc							
Morris Drywall Systems Inc							
Morris Drywall Systems Inc							
Morris Drywall Systems Inc							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	2	16		Install glass @ trophy case, punch			
New Orleans Glass Company, Inc.							
New Orleans Glass Company, Inc.	5	36		install glass at trophy case and install trim at front entry			

Phoenix Constructors LLC

Project: Location:	<b>Sherwood Forest Elemer</b> 4801 Maid Marion Drive	ntary Scho	ool			Job: Report #:	14	1-02-002 1
Fair Working	Days To Date:					Date:	06/	14/2016
Weather Del				Weather Condition:	cloudy/rain in afternoon	Day:		Tuesda
	med as Weather Day?		N	Precipitation Amount:	,	Temp:	Low	Higl
_	Work Effected?		N			· ·····p·	78	89
Phoenix Constr	ructors LLC							
Phoenix Constr	ructors LLC							
Phoenix Constr	ructors LLC							
Phoenix Constr	ructors LLC							
Cordeiro LLC		3	11		sawcut paving joints			
Cordeiro LLC								
Cordeiro LLC								
Cordeiro LLC								
Cordeiro LLC								
ProTech Fixture	e & Display LLC							
ProTech Fixture	e & Display LLC							
ProTech Fixture	e & Display LLC							
ProTech Fixture	e & Display LLC							
ProTech Fixture	e & Display LLC							
Rufino`s Paintir	ng & Construction Inc.	4	32		Punch			
Rufino`s Paintir	ng & Construction Inc.	4	32		Punch			
Rufino`s Paintir	ng & Construction Inc.	3	32		Punch			
Rufino`s Paintir	ng & Construction Inc.	4	32		Punch; sand exterior galvanized rails (2 guys)			
Rufino`s Paintir	ng & Construction Inc.	5	40		Punch; sand exterior galvanized rails (2 guys)			
Peachtree Prot	ective Covers							
Peachtree Prot	ective Covers							
Peachtree Prot	ective Covers							
Peachtree Prot	ective Covers							
Peachtree Prot	ective Covers							
Quality Iron Fa	bricators Inc.							
Quality Iron Fa	bricators Inc.							
Quality Iron Fa	bricators Inc.							
Quality Iron Fa	bricators Inc.							
Quality Iron Fa	bricators Inc.							
River City Fire I	Protection							
River City Fire I	Protection							
River City Fire I	Protection							
River City Fire I	Protection							
River City Fire I	Protection							
Roofing Solution	ons LLC							
Roofing Solution	ons LLC							
Roofing Solution	ons LLC							
D C C L .:	11.6							

Roofing Solutions LLC

Project: Sherwood Forest Element	tary Scho	ool			Job:	14-	-02-00
<b>Location:</b> 4801 Maid Marion Drive					Report #:		
Fair Working Days To Date:					Date:	06/1	16/2010
Weather Delays To Date:			Weather Condition:	partly sunny	Day:	Tł	hursda
Is Today Claimed as Weather Day?		N	Precipitation Amount:		Temp:	Low	Higl
Critical Path Work Effected?		N				79	9
Roofing Solutions LLC							
Roofing Solutions LLC	4	6		checked roof for leaks			
Roofing Solutions LLC							
Roofing Solutions LLC							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Multivista Construction Documentation							
Crescent Professional Janitorial LLC	3	32		final cleaning - waxed stage floor and cleaned windows			
Crescent Professional Janitorial LLC	3	32		final cleaning - cleaned windows and waxed last classroom			
Crescent Professional Janitorial LLC	1	7		final cleaning - cleaned windows			
Crescent Professional Janitorial LLC	1	7		final cleaning - cleaned windows			
Crescent Professional Janitorial LLC	1	7		final cleaning - cleaned windows			
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Alack Refrigeration Company							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
Allied Construction, LLC							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
CFI Insulation Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Gulf South Engineering & Testing Inc							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
Ellison Builders							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
OPA Graphics Inc							
Malone All Star JV, LLC	2						

Project: Sherwood Forest Elementary School Location: 4801 Maid Marion Drive		ool				Job: Report #:	14-02-002 1		
Fair Working Days To Date:						Date:	06/1	3/2016	
Weather Delays To Date:				Weather Condition:	partly cloudy	Day:	N	Иonday	
Is Today Claimed as Weather Day?		N	I	Precipitation Amount:		Temp:	Low	High	
Critical Path Work Effected?	N		I				77	88	
Malone All Star JV, LLC	3	24	data		testing lines				
Malone All Star JV, LLC									
Malone All Star JV, LLC									
Malone All Star JV, LLC	1	8			work on main entry door handicap access				
Malone All Star JV, LLC	7	49	data		testing lines				
Malone All Star JV, LLC	2	6	ADS		training sessions				
Malone All Star JV, LLC									
Malone All Star JV, LLC	2	16			work on main entry door handicap access				
Malone All Star JV, LLC	2	16	data		testing lines				
Malone All Star JV, LLC			ADS						
Malone All Star JV, LLC									
Malone All Star JV, LLC	1	8			worked on freezer; misc punch				
Malone All Star JV, LLC	4	32	data		testing lines				
Malone All Star JV, LLC	2	16	ADS		install exterior cameras				
Malone All Star JV, LLC									
Malone All Star JV, LLC	1	8			misc.				
Malone All Star JV, LLC	4	32	data		testing lines				
Malone All Star JV, LLC			ADS						
Malone All Star JV, LLC									
Sonitrol of New Orleans Inc									
Sonitrol of New Orleans Inc									
Sonitrol of New Orleans Inc									
Sonitrol of New Orleans Inc									
Sonitrol of New Orleans Inc									
Atlas-Edco Inc									
Atlas-Edco Inc									
Atlas-Edco Inc									
Atlas-Edco Inc									
Atlas-Edco Inc									
New Academics LLC			SEC						
New Academics LLC			SEC						
New Academics LLC			SEC						
New Academics LLC			SEC						
New Academics LLC	2	8	SEC		punch				
Amko Fence-Kenner, LLC	1	5			began west ornamental metal fence on south end				
Amko Fence-Kenner, LLC	1	8			work on west ornamental metal fence on south end				
Amko Fence-Kenner, LLC	1	5			work on west ornamental metal fence on north end				
Amko Fence-Kenner, LLC	1	8			work on west ornamental metal fence on north end				
Amko Fence-Kenner, LLC	2	16			work on west ornamental metal fence on north end				
Heritage Flooring Inc.									
Heritage Flooring Inc.									
Heritage Flooring Inc.									
Heritage Flooring Inc.									
Heritage Flooring Inc.									
Heritage Flooring Inc.									
emage Hooming IIIC.									

Project:	Sherwood Forest Elementary School				Job	:	14-0	02-002
Location:	4801 Maid Marion Drive				Report :	t:		1
Fair Working	Days To Date:				Date	<b>:</b>	06/16/2016	
Weather Delays To Date:			Weather Condition: partly sunny	Da	r:	Thursday		
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Tem	): L	ow	High
Critical Path \	Work Effected?	N					79	95
Heritage Floorin	ng Inc.							
Heritage Flooring	ng Inc.							
Heritage Flooring	ng Inc.							
Heritage Flooring	ng Inc.							
Sun Tropic Land	dscapes							
Sun Tropic Land	dscapes							
Sun Tropic Land	dscapes							
Sun Tropic Land	dscapes							
Sun Tropic Land	dscapes							

**Remarks:** Continued with training.

Ahu on west end of high D roof is leaking. Condensate is entering into the bldg.

Nick with Jacobs stated to me on the phone that we would get their punch list no later than Monday.

113

805

Inspections:

**Visitors:** Darius and various members of the school for training

Project:	Sherwood Forest Elementary School				Job:	14	4-02-002
Location:	4801 Maid Marion Drive				Report #:		1
Fair Working	Days To Date:				Date	06,	/20/2016
Weather Dela	ys To Date:		Weather Condition:	partly cloudy	Day:		Monday
Is Today Clair	ned as Weather Day?	N	Precipitation Amount:		Temp:	Low	High
Critical Path V	Vork Effected?	N				76	86

Employee						Work Accomplished
George Caillouet						
Tanner Broughton						
Ellen Heck						(6:43 - 3:35) oversee site operations
Marybeth Leonard						
George Caillouet						
Tanner Broughton						
Ellen Heck						(6.12, 2.25)
						(6:43 - 3:35) oversee site operations
Marybeth Leonard				2-4	2-4	
	Sub	Sub		2nd Tier	2nd Tier	
Subcontractor	Wrkrs	Hrs	2nd Tier	Wrkrs	Hrs	Work Accomplished S Q Sch
CORE Construction Services, LLC	3	24				Slim - bondo doors; Pops- clean; Rafael -
CORE Construction Services, LLC	3	24				Slim - bondo doors; Pops- clean; Rafael - misc
Bernhard Mechanical Contractors, L.L.C.	2	16				misc.
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.			synergy			
Bernhard Mechanical Contractors, L.L.C.	1	8				misc.
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.						
Bernhard Mechanical Contractors, L.L.C.			synergy			
D&T Tile & Terrazzo Co. Inc.						
D&T Tile & Terrazzo Co. Inc.						
Firestop International LLC						
Firestop International LLC						
G.C. Specialties Inc.						
G.C. Specialties Inc.						
Kone Inc						
Kone Inc						
Holi Services Inc						
Holi Services Inc						
Morris Drywall Systems Inc	3	17				recieve material & began framing at standpipes
Morris Drywall Systems Inc	2	16				recieve material & began framing at standpipes
New Orleans Glass Company, Inc.	5	36				install glass at trophy case and install trim at front entry
New Orleans Glass Company, Inc.						
Phoenix Constructors LLC						
Phoenix Constructors LLC						
Cordeiro LLC						
Cordeiro LLC						
ProTech Fixture & Display LLC						
ProTech Fixture & Display LLC						
Rufino's Painting & Construction Inc.	4	32				Punch; sand exterior galvanized rails (2 guys)
Rufino`s Painting & Construction Inc.	3	24				Punch; sand exterior galvanized rails (2 guys)

Project:	Sherwood Forest Elementary School				Job:	1	4-02-002
Location:	4801 Maid Marion Drive				Report #	:	1
Fair Working	Days To Date:				Date	: 06	/21/2016
Weather Dela	ays To Date:		Weather Condition:	partly cloudy	Day	•	Tuesday
Is Today Clair	med as Weather Day?	N	Precipitation Amount:		Temp	Low	High
Critical Path V	Vork Effected?	N				75	86
Peachtree Prote	ective Covers						

Peachtree Protective Covers Quality Iron Fabricators Inc. Quality Iron Fabricators Inc. River City Fire Protection River City Fire Protection Roofing Solutions LLC Multivista Construction Documentation Multivista Construction Documentation Crescent Professional Janitorial LLC 7 final cleaning - cleaned windows 2 Crescent Professional Janitorial LLC 14 final cleaning - cleaned windows Alack Refrigeration Company Alack Refrigeration Company Allied Construction, LLC Allied Construction, LLC CFI Insulation Inc CFI Insulation Inc Gulf South Engineering & Testing Inc Gulf South Engineering & Testing Inc Ellison Builders Ellison Builders OPA Graphics Inc OPA Graphics Inc Malone All Star JV, LLC Malone All Star JV, LLC 32 data testing lines Malone All Star JV, LLC ADS Malone All Star JV, LLC Malone All Star JV, LLC Malone All Star JV, LLC 2 16 data testing lines Malone All Star JV, LLC 2 16 ADS working on access controls Malone All Star JV, LLC Sonitrol of New Orleans Inc Sonitrol of New Orleans Inc 1 1 training Atlas-Edco Inc Atlas-Edco Inc New Academics LLC SEC New Academics LLC SEC Amko Fence-Kenner, LLC 2 16 work on west ornamental metal fence on north end Amko Fence-Kenner, LLC 8 work on west ornamental metal fence on north end Heritage Flooring Inc.

Project:	Sherwood Forest Elementary School			Job:	14-02-002		
Location:	4801 Maid Marion Drive				Report #:	1	
Fair Working	g Days To Date:			Date:	06/2	06/20/2016	
Weather Delays To Date: Is Today Claimed as Weather Day?			Weather Condition:	partly cloudy	Day:	Monday	
		N	Precipitation Amount:		Temp:	Low	High
Critical Path	Critical Path Work Effected?					76	86
Heritage Floori	ing Inc.						
Heritage Floori	ing Inc.						
Heritage Floori	ing Inc.						
Sun Tropic Lan	ndscapes						

Remarks: Held turnover meeting with Jacobs, RSD & Einstien Charter. We handed over various items including grand master keys.

Inspections:

Sun Tropic Landscapes

**Material Delivered:** School received more furniture and smart bds. **Visitors:** Darius and various members of the school for training

41

307