2359 'Motor overload warning'

• "ID114 Overload limit motor" is reached • Switching off the drive with "2360 Motor overload error" at 100% overload			
Device			
Description			
Class	Warning		
Drive Behaviour			
Device Behaviour			
Additional Error Information (AMK Service)			
Error Removal	Recheck parameter: • ID32920 Overload time motor • ID34168 'Time maximum current motor' • ID109 'Motor peak current'		

© AMK Arnold Müller GmbH & Co. KG, Gaußstraße 37-39, D-73230 Kirchheim/Teck