2360 'Motor overload error'

• The thermal overload limit of the motor is reached • 100% overload • Previously "2359 Motor overload warning"			
Device			
Description			
Class	Error		
Drive Behaviour	Controlled braking		
Device Behaviour			
Additional Error Information (AMK Service)			
Error Removal			

© AMK Arnold Müller GmbH & Co. KG, Gaußstraße 37-39, D-73230 Kirchheim/Teck