

Signal Lines

**Ground Wires** 

## ECE 375 Lab 1 Wiring Diagram

Motor Wires

Port D/Pin 0 -> Right Whisker Port D/Pin 1 -> Left Whisker

Power Wires

Port B/Pin 4 -> Right Motor Enable Port B/Pin 5 -> Right Motor Direction Port B/Pin 6 -> Left Motor Direction

Port B/Pin 7 -> Left Motor Enable