

FIELD SAFETY NOTICE (FSN)

Issue Date: 04 MAY 2018

FSN #: 20180504 FRGMIN

PURPOSE: Labelling error on catheter's tube length

PRODUCT RANGE: FARGO

PRODUCT REF: FRGMIN4.2F120MP and FRGMIN4.2F135

LOT #: from 00243032 to 00312502 (included)

Who may be affected: Distributors, Safety Officers, Vigilance Coordinators and Head of Neuroradiology

Department in Healthcare Centers

Dear Partners,

We detected a documentary error on the labels of the products "FARGO" ref. **FRGMIN4.2F120MP** and **FRGMIN4.2F135** for the lot numbers above-mentioned.

It appears that they mention a catheter's tube length (A') in mm while it shall be considered in cm.



This documentary error does not represent any risk since it is easily detectable by users and cannot lead to a misinterpretation: the catheter's length including the hub (A) is in <u>cm</u> and it is obvious for any user that the tube length cannot be 129 <u>mm</u> or 114 <u>mm</u>.

Thus, no specific field safety corrective action are needed, but BALT Extrusion can supply corrective stickers upon request. In this case, a specific relabeling instruction will be sent.

The label template for both references has been updated from lot number # 00314633.



We ask you to communicate this field safety notice to your affected end-users and to your local competent authority.

Should you require any additional information about this field safety notice, do not hesitate to contact our Quality Department.

Contact:

Quality Department

☑: claim@balt.fr

BALT EXTRUSION

10 RUE DE LA CROIX VIGNERON

95160 MONTMORENCY - France

: +33.1.39.89.46.41 Fax: +33.1.34.17.03.46

We confirm that the French competent authority "ANSM" has been beforehand informed about this field safety notice.

We apologize for any inconvenience that this action may cause and we thank you for your cooperation.

Sophie REHAULT Quality and Regulatory Affairs Director

- End of document -