
Homework 7

1. Transformer on an Iron Core with an Air Gap [12 Points]

The transformer below consists of two coils on an iron core with an air gap. The iron core portion has a perimeter of 475cm and the air gap is 25cm wide, giving a total perimeter through the iron core region and air gap of 500cm. Additionally, the iron core has a square cross-sectional profile with side lengths of 25cm. The permeability of the iron core region is $3000\mu_0$ and the permeability of the air gap region is μ_0 . The exciting winding has 1000 turns and the second winding has 3000 turns.



- a) Draw a magnetic circuit to represent the structure when the current through the coil is 400mA DC and calculate and label the following:
 - i. the MMF
 - ii. the reluctance of the iron core and air gap region
 - iii. the total magnetic flux through the core. (For this part of the problem, ignore the second winding.)

i)
$$m.m.f. = N \cdot I = 1000 \cdot .400A = 400 A$$
 (+1)
ii) $R = \frac{L}{UA} \Rightarrow R_{iron} = \frac{0.475 m}{3000 \mu_0 \cdot (.25 m)^2} = \frac{2016 H^{-1}}{(+1)}$

$$R_{air} = \frac{0.25 m}{M_0 \cdot (0.25 m)^2} = \frac{3.18 \times 10^{6} H^{-1}}{(+1)}$$

7)7)
$$f_{in}^{b} = \frac{V_{in}}{R_{iron} + R_{air}} = \frac{400A}{2010 + 1 + 3.16 \times 10^{6} H^{-1}} = \frac{1.26 \times 10^{-4} \text{ wb}}{(+1)}$$

$$\frac{12_{100} + 2010 + 1}{(+1)} = \frac{1.26 \times 10^{-4} \text{ wb}}{(+1)}$$

$$\frac{12_{100} + 2010 + 1}{(+1)} = \frac{1.26 \times 10^{-4} \text{ wb}}{(+1)}$$

$$\frac{12_{100} + 2010 + 1}{(+1)} = \frac{1.26 \times 10^{-4} \text{ wb}}{(+1)}$$

b) Calculate the magnitude of the H field in the air gap.

$$H = \frac{B}{\mu_0} = \frac{4m/A}{\mu_0} = \frac{4m}{\mu_0} = \frac{1.26\times0^4}{4\pi\times10^{-9} + 1.60\times5} = 1604 \text{ A/m}$$

c) Calculate the magnetic force felt by the two pieces of the core on either side of the air gap. Is this an attractive or repulsive force?

$$F_{m} = \frac{B_{\text{air}}^{2}}{\partial \mu} = \frac{(\mu_{0} \cdot k_{0})^{2} + \mu_{0}^{2}}{2\mu_{0}} = \frac{35.9 \, \text{M}}{2\mu_{0}}$$
attractive force, as F points in the direction of the region with higher energy durity, which is in the air gap.
$$F = -\frac{1}{2} \left(\frac{B^{2}}{2\mu_{0}} \right)$$

d) Suppose that the 400mA DC current is replaced with a 400mA 100Hz AC current. What is the resulting emf across the secondary coil?


emf =
$$-\frac{\partial L}{\partial t}$$
 = $-\frac{\partial}{\partial t}$ {Nserondary Ym(t)} (+1) equation
=-3000 · 1.26×10⁻⁴ Wb $\frac{\partial}{\partial t}$ (2πft)}
=-0.378 (2π· 100 Hz) (ωs(200 πt))
= -237.5 (ωs (200 πt) V (+1)

e) Is it preferable to use a hard or a soft ferromagnetic material for the core of this transformer? Why?

It is prefueble to use a soft magnetic material for this core because it " suffer fewer losses due to hysteresis effects than a hard core would. (+1) soft magnetic material (+1) justification

2. Displacement Current and the Quasi-static Approximation [16 Points]

For a coax-cable capacitor, the volume between the cylindrical copper conductors is filled with a lossy dielectric with permittivity ε_r and conductivity σ . The radius of the inner conductor is a and the effective inner radius for the outer conductor is b. The cable length l is much shorter than the wavelength, but $l \gg b$. The voltage applied across the coax-cable capacitor is $V(t) = V_0 \cos(\omega t) V$.



a) Determine the displacement field \vec{D} between the conductors, the displacement current I_d and the conduction current I_c passing through the capacitor. What is the phase angle between I_c and I_d ? Which current leads (or which one lags)? Hint: you can use either time domain or phasor domain; you need to integrate the current passing through a cylindrical surface.

displacement field
$$\vec{D} = \vec{E}$$

Via Sauss's Saw: Note: can also be solved

$$\iint_{\vec{D}} \cdot d\vec{S} = Q_{imen} \quad \text{Poisson's} \quad \text{Equation}$$

$$2 \cdot \vec{E} \cdot \vec{L} \cdot 2\pi r = Q_{imen} \quad r \quad \text{Expression}$$

$$\vec{E} = \frac{Q_{imen}}{2\pi E L r} \quad r \quad \text{(+1)} \quad \vec{E} \cdot \vec{f} \cdot \vec{e} \cdot \vec{l} \cdot \vec{l}$$

$$\vec{V(r)} - \vec{V(D)} = -\int_{\vec{L}} \frac{Q_{imen}}{2\pi E L r} \, dr = -Q_{imen} \quad L_{I}(\vec{V_{D}}) \quad \text{(+1)}$$

$$\vec{V(r=a)} = \vec{V_0} = -\frac{Q_{imen}}{2\pi E L} \quad L_{I}(\vec{v_D}) \quad \text{(+1)}$$

$$\vec{Q_{imen}} = -\frac{2\pi E l \cdot V_{D}}{2\pi E L} \quad \text{(+1)} \quad \vec{Q_{imen}}$$

$$\vec{D} = \vec{E} = \frac{e}{2\pi \ell \ell r} \frac{2\pi \ell \ell V_{\ell}(os(wt))}{\ln(a|b)} = \frac{e}{2\pi \ell \ell r} \frac{v_{\ell}(os(wt))}{\ln(a|b)} = \frac{e}{2\pi \ell r} \frac{v_{\ell}(os(wt))}{\ln(a|$$

b) Evaluate I_d , I_c and the ratio of their amplitudes when $\varepsilon_r = 27$, $\sigma = 2 \times 10^{-8}$ S/m, a = 0.45 mm, b = 1.57 mm, l = 100 m, $V_0 = 10$ V and f = 1MHz.

$$|Id| = \frac{2\pi w l \, e \, V. \, sin(wt)}{ln(9b)} = 7.54 \, sin(2\pi \times 10^{6} t) [A]$$

$$= 7.54 \, cos(2\pi \times 10^{6} t + \frac{\pi}{2}) [A] (+1)$$

$$|I_{c}| = \frac{2\pi \sigma \cdot l \, V_{0}}{ln(9b)} \, cos(wt) = 0.0001 \, (os(wt) \, A)$$

$$= 100 \, cos(wt) \, \mu A \quad (+1)$$

$$|I_{d}|_{2} = \frac{7.54A}{10090^{-6}A} = \frac{7.54 \times 10^{4}}{(+1)} \rightarrow \begin{array}{c} Displacement \\ Current \\ Dominates \end{array}$$

c) Using your answer from part b, determine at which frequency the amplitudes of I_d and I_c are equal.

When does
$$I_D = I_C$$
?

Structor = $\frac{8\pi \sigma L K}{L_0 L_0 L_0}$ $\Rightarrow WE = \sigma \Rightarrow f = \frac{\sigma}{2\pi E}$

Lylator $\int = \frac{2 \times 10^{-8} S/m}{2\pi \cdot 27 \cdot 8.85 \times 10^{-27} L_0} \approx 13.3 Hz$ (+1)

d) Using your knowledge from circuit theory, calculate I_d and I_c , then compare them with your results from part a. *Hint*: you will need the expressions for capacitance and conductance per unit length of a coaxial cable to calculate these quantities.

3. Plane Wave in a Lossy Medium [13 Points]

Today's computer microprocessors (and many other electronic and photonic devices) are built on a silicon (Si) substrate. For pure Si, $\varepsilon_r \approx 12$. Assume the Si substrate resistivity is $\rho = 10 \ \Omega \cdot \text{cm}$.

a) Determine the frequency range in which the Si substrate can be treated as a good insulator (dielectric), and the frequency range in which the Si substrate can be treated as a good conductor.

$$\rho = 1052 \cdot \text{cm} \times \frac{1 \text{m}}{100 \text{cm}} = 0.152 \cdot \text{m}$$
for a good insulator: $\frac{\xi''}{\xi'} = \frac{\sigma}{W\xi'} << 0.01$

so $f >> \frac{\sigma}{2\pi\xi'} = \frac{1}{0.01 \cdot 2\pi\xi' \rho} \approx 1.5 \times 10^{12} \text{Hz}$

good insulator when $f >> 1.5 \text{ THz}$ (+1)

for a good conductor: $\frac{\xi''}{\xi'} = \frac{\sigma}{W\xi'} >> 100$

So $f \ll \frac{1}{100 \cdot 2\pi \cdot \xi' \cdot \rho} = 1.5 \times 10^{8} \text{ Hz} \rightarrow f \ll 150 \text{ GHz}$ (+1)

b) If a plane wave is traveling in the Si substrate at 100 MHz, find the attenuation constant and phase constant (α and β), wavelength, and intrinsic impedance (η).

at
$$f = 100 \text{ MHz}$$
, Si acts like a good conductor, so: (H) correct regime $d = \sqrt{\Pi f_{\mu} \sigma} = \frac{20 \pi \text{ NP/m}}{100} \text{ (H)}$

$$\beta = \alpha = \frac{2\pi}{3} = \frac{2\pi}{20\pi} = 0.1 \text{ m} \text{ (H)}$$

$$\gamma = (1+j) \frac{d}{\sigma} = \frac{20\pi}{10} \sqrt{2} e^{i\frac{\pi}{4}} = 2\sqrt{2\pi} e^{i\frac{\pi}{4}} \Omega \text{ (H)}$$

c) Using your results from b, if the wave is traveling in the y-direction with an **E**-field amplitude of 10 V/m measured at y = 0, find **E** and **H** for the wave in the phasor domain. $\vec{E} = E\hat{x}$.

$$|\dot{E}| = |OV/m|$$

$$\tilde{E} = |OV/m|e^{-20\pi y} e^{-j20\pi y} \hat{\chi}| \text{ (H) correct } \tilde{E}$$

$$\tilde{H} = \frac{\hat{K}}{N} \times \tilde{E} = (+\hat{y}) \times (10e^{-20\pi y} e^{-j20\pi y} \hat{\chi})$$

$$2\sqrt{2}\pi e^{j\pi y}$$

$$\tilde{H} = -\frac{5}{\sqrt{2}\pi} e^{-20\pi y} e^{-j(20\pi y - \pi y)} \hat{\chi}$$

$$(+1) \text{ correct } H \text{ magnitude}$$

$$(+1) \text{ correct } H \text{ direction}$$

$$(+1) \text{ correct } H \text{ phase}$$

4. Wave Polarization [12 Points]

Determine the polarization of the following waves (i.e., linear, circular or elliptical) and their propagation direction. If a wave is linearly polarized, also determine the inclination angle. For non-linear polarization, determine the rotation direction (LH or RH). Draw a polarization diagram for each case with a few data points to show your work.

a)
$$\tilde{E}(z) = (3\hat{x} - j3\hat{y})e^{j25\pi z}$$
 [V/m]

$$\widetilde{E}(\overline{z}) = (3\hat{x} - j3\hat{g}) e^{j2S\Pi\overline{z}} [V/m]$$
· direction of propagation: $-\overline{z}$ (+1)
· polarization:
$$\widetilde{E}(\overline{z}) = (3\hat{x} + 3\hat{y}e^{-j\frac{\pi}{2}}) e^{j2S\Pi\overline{z}}$$

$$\xrightarrow{E}(\overline{z}) = (3\hat{x} + 3\hat{y}e^{-j\frac{\pi}{2}}) e^{j2S\Pi\overline{z}}$$

b)
$$\tilde{E}(z,t) = 2\cos(10^6\pi t - 0.5z + 45^\circ)\hat{x} + \sin(10^6\pi t - 0.5z - 45^\circ)\hat{y}$$
 [V/m]
$$E(z,t) = 2\cos(10^6\pi t - 0.5z + 45^\circ)\hat{x}$$

$$+ \sin(10^6\pi t - 0.5z + 45^\circ)\hat{y}$$
 [Y/m]
$$\cdot \text{direction of propagation: } \pm 2 \quad (+1)$$

$$\cdot \text{polarization: } 2\cos(10^6\pi t - 0.5z + \pi/4)\hat{x}$$

$$- \cos(10^6\pi t - 0.5z + \pi/4)\hat{y}$$

$$\Rightarrow E_x \text{ is } \pm \pi \text{ out of phase with } E_y, \text{ so it is linearly polarized } (+1)$$

$$\Rightarrow \text{Angle of inclination: } \tan^{-1}(1/-2) = -26.6^\circ \text{ (+1)}$$

c)
$$\tilde{E}(z) = \left(3e^{j\frac{\pi}{6}}\hat{x} - 3e^{j\frac{\pi}{3}}\hat{y}\right)e^{-j3\pi z} [V/m]$$

$$\widetilde{E}(z) = \left(3e^{j\frac{\pi}{6}}\hat{x} - 3e^{j\frac{\pi}{3}}\hat{y}\right)e^{-j^{2\pi}z}$$
· direction of propagation: +2 (+1)

· polarization: Ex is to out of phase with Ey

-> elliptical planization (+1)

 $wt = 0: 3\cos(1\%) \hat{x} - 3\cos(1\%) \hat{y} = 0.6\hat{x} - 1.5\hat{y}$ $wt = 1\%2: 3\cos(4\%) \hat{x} - 3\cos(5\%) \hat{y} = -1.5\hat{x} + 2.6\hat{y}$ $wt = 1 : 3\cos(7\%) \hat{x} - 3\cos(4\%) \hat{y} = -2.6\hat{x} + 1.5\hat{y}$ $wt = 3 : 3\cos(1\%) \hat{x} - 3\cos(1\%) \hat{y} = 1.5\hat{x} - 2.6\hat{y}$ $wt = 3 : 3\cos(1\%) \hat{x} - 3\cos(1\%) \hat{y} = 1.5\hat{x} - 2.6\hat{y}$

