

COMMAND NEXUS · CIT 140 · WEEK 1

Problem Brief

Meridian Forge Robotics · The Process Below

LEARNER

Alexandra Rodriguez

ARTIFACT

Problem Brief

STATUS

Working document

SECTION 01

Visible Failure

Supervisor noticed an outdated test MK-44 on loop start at 2:13 according to incident log. The system was sent a stop request, and system denied stop request to continue K-44 on loop.

SECTION 02

Verified Facts

Scheduling records from lab terminal show test k-44 was not scheduled to run currently and same records shows MR-17 has no current, active tests.

Maintenance records show K-44 was retired 186 days ago and removed from active workflow.

Elias says command was in format MR-17 accepts and is labeled legacy_sync.exe.

SECTION 03

Assumptions and Open Questions

Assumption: Nia reported MR-17 was working normally before.

Would need logs of what happened before MR-17 accepted the test k-44.

Question: If K-44 was retired from the system but was not completely removed from copy, service, or schedule, what components still have access to test k-44 for it to still be processed in the system?

SECTION 04**System Environment Map****SECTION 04A****People and Roles**

Mara Ilyan manages production.

Elias Chen is the robotics system engineer.

Nia Voss is the Night QA supervisor.

SECTION 04B**Processes and Rules**

The command coming from an unknown source and MR-17's approval is what led to the incident happening.

SECTION 04C**Information and Data**

The incident logs show the error in which k-44 was in process. Scheduling and maintenance records show that the scheduler did not send k-44 to be processed and k-44 was removed but not entirely. The command telemetry is very important because it gives us source label but does not say where it comes from.

SECTION 04D**Technology and Tools**

Elias says command came through internal interface, was a format MR-17 accepts, and was labeled legacy_sync.exe. The telemetry is unable to find its service owner or why it was sent at all.

SECTION 04E

Environment and Constraints

The inability to accurately locate where the command came from that led to the incident, thus leading to pause in production in affected cell impacts productivity.

SECTION 05

Investigation Boundary

Inside the Investigation

The team should investigate the broader cause of where the command came from and who is the service owner.

Outside for Now

Current evidence not required yet is current scheduling logs because it does not give us information about the command.

SECTION 06

Organizational Impact

Mara says the work stopped in the affected Qa cell.

SECTION 07

Problem Statement

MR-17 is currently on loop with the retired test k-44 which has put Qa cell production on pause.

SECTION 08

Next Investigation Step

One action would be to check every copy, service, and schedule to see which ones had test k-44 completely removed and which one had the possibility of sending the test through for more information of where it came from.

SHARED ARTIFACT

Working Document Link

[Not entered](#)

WEEK 1 STOPPING RULE

Define before designing.

This Problem Brief records the problem that requires investigation. It does not recommend a solution.