

HAZARD MANAGEMENT – SAFE OPERATING PROCEDURE (SOP)

Only to be completed where required as a control measure under a Risk Assessment

A document setting out the requirements to carry out the work in a safe and healthy manner and in a logical sequence. It must be able to be easily read by those who need to know what has been planned. It is relevant to the following people: - the worker carrying out the work; and - the person who has management and control over the work.	A SOP, if identified as a control measure, is to: - identify the work; - specify/address the identified hazards relating to the work; - describe the measures to be implemented to control the risks; - take into account the circumstances at the workplace that may affect the way in which the work is carried out; - take into account emergency management arrangements where applicable; and - be communicated to all workers who carry out the work.
---	---

NAME OF THE TASK/ACTIVITY	HANDLING OF SHARPS AND GLASS	DATE: 18/11/24
LOCATION	BADGER UNDERGRADUATE TEACHING LABS – G10, 115 AND 212 (NORTH TERRACE CAMPUS)	
RISK ASSESSMENT (RA) NAME	Sharps and Glass	
Residual risk rating on the RA	☒ Low ☐ Medium ☐ High ☐ Very High	
Hazards identified on the RA	Chemical exposure, contact with sharps	

PERSONAL PROTECTIVE EQUIPMENT (BE SPECIFIC AND SPECIFY PPE TO BE WORN DURING THE TASK) (DELETE THE ROW IF NOT APPLICABLE)

	Eye protection: ☒ Safety glasses ☐ Eye shields ☐ Safety goggles ☐ Other:
	☒ Long hair must be contained or covered ☐ Other:
	Hand protection: ☐ Rubber ☐ Cut resistant ☐ Leather ☐ Vinyl ☐ Neoprene ☒ Nitrile ☐ Barrier creams ☐ Other:
	☒ Enclosed footwear: ☐ Footwear that is resistant to spills of hazardous substances ☐ Boots with steel caps ☐ Other:
	Protective clothing: ☒ Lab coat ☐ Gown ☐ Long sleeves ☐ Long pants ☐ High visibility ☐ Helmet ☐ Sun protection ☐ Other:

DESCRIBE, IN SEQUENCE, STEPS TO COMPLETE THE ACTIVITY SAFELY

Needle use:

- Disposable needles and syringes should be disposed of in the sharps container immediately after use – ensure these are quenched if they were used to handle unstable or highly reactive compounds.
- Never leave uncapped disposable syringes lying around.
- Never walk around with uncapped needles.
- Never recap needles.
- If using needles connected to balloons (e.g. Nitrogen balloons), never aim an uncapped needle out of fume cupboard towards people, as they may be ejected if not attached securely.

General glassware use:

- Keep glassware away from bench edges, store round bottom flasks on cork rings or in draws.
- Do not transfer hot glassware to a cold environment, and vice versa, as glassware may shatter.
- Inspect all glassware for cracks and chips before use. Do not use cracked or weakened glassware at non-atmospheric pressure. Reduced (< 1 atm), or increased pressure (> 1 atm) may cause weakened glassware to shatter.
- If possible, use plastic alternatives to glassware – for example plastic Pasteur pipettes, plastic vials etc.

Cleaning up broken glass:

- Students should not clean up broken glassware – this should be reported to a demonstrator or technical officer to clean up.
- Use a dust-pan and broom to handle broken glassware – do not use your hands.
- Any chemical residue should be carefully washed off glassware before disposing in the designated glass bin in the servery.

HSW Handbook	Hazard Management	Effective Date:	1 December 2020	Version 4.0
Authorised by	Chief Operating Officer (University Operations)	Review Date:	1 December 2023	Page 1 of 2
Warning	This process is uncontrolled when printed. The current version of this document is available on the HSW Website.			

On completion of work – steps to make safe (including clean up, any waste disposal & service/maintenance requirements)			
1. Ensure used needles are disposed in the sharps container. 2. Ensure all glassware is washed appropriately and returned to its storage location.			
Emergency and Spill Procedures, Transport or storage requirements (where relevant), First aid/Medical			
• Any needlestick injuries, cuts or other injuries from other sharps such as broken glassware, must be reported to the lab supervisor. • Ensure any broken glassware is reported to a demonstrator, swept up and disposed in the glass bin.			
Prepared by			
People involved in the drafting of this SOP	xxxxxx		
Person authorising the SOP	Name:	xxxxxxxxxx	Signature
	Position:	Senior Technical Officer	
This SOP must be reviewed after any incident/injury associated with this activity or when a Risk assessment is reviewed.			
File your completed SOP as instructed by the Supervisor/Person in control of the area/activity and retain the SOP in accordance with the State Records of SA, General disposal Schedule No. 30 issued under the State Records Act 1997. (Contact the University's Records Management Office for further assistance/information if required.)			