




usb connect to PC



I²C address 0x36@400kHz

A55600

I²C address 0x36@400kHz

INA219


GPIO ~30kHz
+ GPIO 14, 15 for direction

L298N

GPIO bit-bang
80kHz

Hx711

Force Sensor



Motor
out1/out2

