
3.3 Auto operation stop/restart

The following three methods can stop auto operation.

- (1) Press [STOP] key.
- (2) Press [Q.STOP] switch.
- (3) Press EMO switch.



(1) [STOP] key:

Pressing [STOP] key stops the machine after the wafers in processing have been put into the cassette.

<To restart auto operation>

Press [START] key on "MAIN SCREEN".

(2) [Q. STOP] switch:

Pressing [Q. STOP] switch stops the machine promptly.

- <To restart auto operation>
- (1) Press [RESET] key on "MAIN SCREEN".
- (2) Press [START] key on "MAIN SCREEN".

(3) EMO switch:

Pressing EMO switch cuts the power off and stops the machine promptly.

- <To restart auto operation>
- (1) Remove materials, such as wafers and tools left in the machine.
- (2) Pull the EMO switch to recover from the emergency stop state
- (3) Perform 2.3 Power on and 3.3 Auto operation stop/restart in the Installation manual.

3.4 Auto operation end procedure



Turn off [MAIN POWER] switch. The light of POWER is put out.