## 8. Robot teaching


#### 8.1 Outline of the robot



# **WARNING**

Non-authorized persons are not allowed to perform the robot teaching.

Failure to observe the warning could cause of serious injuries to human body and damage/performance decrement of the equipment.



#### <Operation of the robot>

### Auto operation

- (1) Gets the wafer from the cassette.
- (2) Transfers the wafer to the aligner.
- (3) Gets the wafer from the aligner after alignment has been finished.
- (4) Transfers the wafer to the chuck table.
- (5) Gets the wafer from the chuck table after the BG tape has been peeled.
- (6) Puts the wafer into the cassette.

#### <Press down plate>

Press the wafer warpage when vacuum error due to warpage of the wafer is occurred.

#### <Data count of the robot>

R-axis: 1 pulse = 0.0271 mm (27.1 micrometer) Expansion and Contraction

Z-axis: 1 pulse = 0.0250 mm (25 micrometer) Move up and down T-axis (theta): 1 pulse = 0.0072 degrees Rotation direction