6. PM (Preventive Maintenance)



WARNING

Turn off the machine power before the cleaning and lubrication. Failure to observe the warning could cause of serious injuries to human body and damage/performance decrement of the equipment.

6.1 Cleaning

Clean the machine regularly according to the table below.

Section	Cleaning	Term
Rubber rollers	Clean the surface with deionized water-saturated clothes.	1 week
Robot arm	Clean the surface with deionized water-saturated clothes.	1 week
Chuck table / Table pad	Clean the surface with deionized water-saturated clothes.	1 week
Aligner	Clean the surface with deionized water-saturated clothes.	1 week
Other equipments	Clean the cassette and other equipments when necessary.	As necessary







