
5.2 MAIN SCREEN



The screen is touch screen type. Press the key to operate.

CASSETTE: Shows which cassette (Right / Left) is processing with .

TOTAL: Shows the number of processed wafers. [START] key: Pressing the key starts auto operation.

[STOP] key: Pressing the key stops the machine after the wafers in processing have been put

into the cassette.

[AUTO] key: Pressing the key displays MAIN SCREEN from "1st page of the setting screen" or

"2nd page of the setting screen".

[MAN.] key: Pressing the key displays "1st page of the setting screen". Pressing the key resets the error or stopped condition.

[ESC] key: Pressing the key displays the previous screen of currently displayed.

[BUZZER STOP] key: Pressing the key stops the buzzer sounds.

[UV OFF] key: Turn on the UV irradiation. [UV ON] key: Turn off the UV irradiation.

[TEACH MODE] key: Pressing the key after connecting the teach pendant enables operation with it.

[SET] key: Pressing the key displays "INDIVIDUAL OPERATION PANEL".

[IRRA. CHK] key: Check the UV irradiation condition.

[INIT.RESET] key: Pressing the key starts initial reset. The each unit moves to auto operation

starting position.

[TAPE FEED] key: BG tape is fed while the key is pressed.

[CASSETTE] key: Press the key when 2 cassettes or more are processed continuously.

UV POWER: • is displayed when the UV irradiation is ON status.

UV STABLE: • is displayed when the UV ray is stable.
UV SELECTION: • is displayed when the UV lamp is in use.

N2 PURGE: • is displayed when the N2 is fill up.

IRRA.: • is displayed during irradiating UV ray to the wafer.

[TEACH MODE] key: Pressing the key after connecting the teach pendant enables operation with

it.

5.2 MAIN SCREEN (Continued)

[T. CHANGE] key:

Pressing the key displays "SCREEN FOR TABLE CHANGE SETING". The screen is for table replacement when the chuck table is damaged. Press [TABLE ORIGIN P.], and then press [TABLE CHANGE P.]. The applying unit moves to right end and table pin moves downward.

