Y52 PLC Alarm Codes & Sensor Tag Index

Alarm Code	PLC Tag Identifier	Severity	Description	Standard Remediation Action
ALM-3025	Y52-ENC-FB	HIGH	Servo Optical Communication Interrupted	Inspect fiber cable routing and transceiver p
ALM-4102	Y52-OIL-PRS01	CRITICAL	Main Lubrication Pressure Low (<3.2 bar)	Verify circulation pump P-01 operation and
ALM-2011	Y52-TEMP-MTR01	MEDIUM	Drive Motor Stator Over-temperature (>115 °C)	Check cooling fan airflow and clean radiato
ALM-1050	Y52-TNS-LOD01	LOW	Tension Cell Measurement Zero Drift	Execute tare re-zero procedure when mill s

Diagnostic Flowchart for Alarm ALM-3025

1. Check optical signal power at receiver RX02.
2. If signal power is below -18 dBm, replace fiber optic patch cord.
3. Re-seat communication daughtercard COM-Y52.